


HANSER



Sample Pages

Injection Molding Advanced Troubleshooting Guide

Randy Kerkstra and Steve Brammer

ISBN (Book): 978-1-56990-834-1

ISBN (E-Book): 978-1-56990-835-8

For further information and order see

www.hanserpublications.com (in the Americas)

www.hanser-fachbuch.de (outside the Americas)

© Carl Hanser Verlag, München

Preface

Why a book dedicated to troubleshooting? The answer to that lies in frustrations that the authors have experienced over the years in launching and maintaining injection molds and processes for those molds. Have you ever experienced any of the following?

- High scrap rates
- Excess down time
- Slow cycle times
- Customer rejections (both internal and external)
- Processing around tooling issues
- Damage to molds
- Defects that seem to show up out of nowhere
- Defects that keep reoccurring
- “Fixed” problems that keep coming back
- Molds that run fine in one machine but not in another

The goal of this book is to help provide tools and information that will help truly address these types of concerns.

Often times in the plastics industry there is a great deal of learning through the “school of hard knocks” and both of the authors have had the opportunity to learn a lot this way. What the industry has not done well is passing along these lessons to others. We have reached a point where we are interested in passing along the lessons we have learned through experience in the trenches.

One thing that the authors have noticed in the industry is a disconnect between processing and tooling. We come at troubleshooting with different backgrounds, one in tooling and one in materials and processing. However, we both approach a problem with the same thought process. We felt it was time to provide a resource that dives deep into the interaction of tooling, processing, and materials and have sought to create that in this work. There would not be a value in this book if it was just regurgitation of the same information that has been documented in

“troubleshooting guides” over the years. The strength of this book lies in combining hands-on experience of making molds and processes run successfully even and especially when the “by-the-books” approach did not resolve the problem.

This book is broken down into specific sections:

1. Troubleshooting methodology and tools (Chapters 1 and 2)
2. Focused discussion of key areas impacting troubleshooting including the mold, machine, material, and molding process (Chapters 3–14)
3. In-depth alphabetical troubleshooting guide for various defects (Chapters 15–47)

Again the key differences in this troubleshooting guide come down to the efforts to bridge the gaps between tooling, processing, and materials and provide in-depth feedback from designing, building, processing, maintaining, and troubleshooting 1000s of molds over the last 25+ years.

Writing this book was a humbling experience. We obviously have not seen every mold, material, and machine combination and could come up with “what if?” cases forever, but we feel this book well represents our experience. We believe that keeping an open mind to solutions is critical to successful troubleshooting. We would never believe that we have all the answers. Remember there is always more to learn!

Many of the fundamental processing and design methods that are the industry standards have come from the development and training efforts of many individuals including Rod Groleau, John Bozzelli, Don Paulson, Glenn Beall, and John Beaumont. Steve was fortunate to have Richard Brammer, a mold maker, development engineer, and Ferris State University Instructor as a father who provided guiding influence along the “plastics road”. Steve is also thankful for the Plastics Engineering Instructors at Ferris State University and Grand Rapids Community College. The above people have been educating the plastics industry for many years and through their writing and instruction the industry has learned and improved. We have also had the opportunity to work with many excellent processors, maintenance people, mold builders, designers, and material scientists who have added to our learning over our careers. We would also like to thank Mark Smith and the team at Hanser Publishers for helping bring this book to reality.

As you move down the troubleshooting road keep learning, always ask why, never assume, and stay open minded!

Randy Kerkstra

Steve Brammer

About the Authors

Randy Kerkstra has worked in the plastics industry for over 29 years, with specialism in troubleshooting injection molding. He also has much experience with injection molds, with 14 years in the tool shop environment as a mold maker/designer and over 15 maintaining and repairing/troubleshooting thousands of molds in the production environment. He has years of research with gate geometry, runner/sprue waste, and reducing part defects with a focus on the mold and how it impacts these issues. He also co-owns KB Molding Solutions, a training and consulting company (www.kbmoldingsolutions@gmail.com).



Steve Brammer has held a variety of positions for multiple custom and captive molders working in the furniture, appliance, automotive, and consumer products markets. He is currently Molding Technical Manager for a Tier One automotive component supplier. Steve is also an Instructor at Grand Rapids Community College, teaching courses in applied injection molding, plastics processing, and manufacturing. He also co-owns KB Molding Solutions, a training and consulting company. Steve has a Bachelor of Science degree in Plastics Engineering Technology from Ferris State University.



Contents

Preface	V
About the Authors	VII
1 Troubleshooting Methodology	1
1.1 Troubleshooting	1
1.2 What Makes an Effective Troubleshooter?	1
1.3 What Makes an Ineffective Troubleshooter?	3
1.4 Troubleshooting Methodology	3
1.4.1 STOP: Systematically	4
1.4.2 STOP: Think	6
1.4.3 STOP: Observe	7
1.4.4 STOP: Proceed	10
1.4.5 STOP: Troubleshooting Cycle	12
1.4.6 Hard Fix versus Processing around Problem	13
1.4.7 Troubleshooting Tools	13
1.4.8 Troubleshooting Methodology Summary	18
2 Troubleshooting Tool Kit	21
2.1 Lockout/Tagout	21
2.2 Hand Tools	21
2.3 Pyrometer	22
2.4 Spotting Blue	22
2.5 Measurement Tools	22
2.6 Multimeter	22
2.7 Process Monitoring Equipment	23
2.8 Moisture Analyzer	23

2.9	Dew Point Meter	23
2.10	Flashlight	24
2.11	Microscope/Magnifying Glass	24
2.12	Silly Putty	24
2.13	Inspection Mirror	24
2.14	Thermal Imaging Camera	25
2.15	Aluminum Tape	25
2.16	Dial Indicator	25
2.17	Purging Compound	25
2.18	Grinder/Stones	26
2.19	Camera	26
2.20	Material Data	26
2.21	Scale	26
2.22	Flow Meter	27
2.23	Mold Cleaning Supplies	27
2.24	Miscellaneous Supplies	27
3	Decoupled® or Scientific Molding	29
4	Gating Details	33
4.1	Gating	33
4.2	Gate Size, Shape, and Taper	35
4.3	Mental Picture Volume versus Pressure	40
5	Mold Hydraulics	41
5.1	Hydraulic Uses	41
5.2	Set and Pull Pressure	41
5.3	Cylinder Sizing	42
5.4	Hydraulic Cores or Slides	44
5.5	Multiple Sequences	44
5.6	Mounting	45
5.7	Switches	45

6	Mold Texture and Polish	47
6.1	Mold Texture	47
6.2	Mold Polish	50
7	Venting	53
7.1	Venting Basics	53
7.2	Alternate Venting	58
7.3	Venting Conclusion	61
8	Machine Performance	63
8.1	Load Sensitivity	65
8.2	Dynamic Check Valve Study	66
8.3	Velocity Linearity	67
8.4	10-Cycle Overlay	70
8.5	Cycle Variation	72
8.6	Velocity to Pressure Transfer	74
8.6.1	Machine Control	77
8.7	Machine Documentation	80
9	Drying	83
9.1	Introduction	83
9.2	Keys to Drying	83
9.2.1	Temperature	85
9.2.2	Dry Air	85
9.2.3	Air Flow	87
9.2.4	Time	87
9.3	Moisture Analysis	88
9.4	Material Handling	90
9.5	Material Concerns	92
10	Purging	93
10.1	Purging Impact	93
10.2	Purging Method Example	94
10.3	Purging Compounds	95

11 Hot Runners 97

11.1 Hot Runner Advantages 97

11.2 Heaters and Thermocouples 97

11.3 Hang Up Areas 98

11.4 Hot Drop Tips 98

11.5 Drooling, Stringing, and Sprue Sticking 99

11.6 Freeze Off 99

11.7 Orifice Size 99

11.8 Leakage 100

11.9 Zones and Wiring 101

11.10 Hot Runner Troubleshooting 101

12 Cavity Balance 103

12.1 Flow Length 105

12.2 Flow Diameter 105

12.3 Shear 105

12.4 Cooling 107

12.5 Venting 108

12.6 Clamp Pressure 108

12.7 Cavity Fill Balance Study 109

12.8 Artificial Balance 110

 12.8.1 Family Molds 111

13 Cavity Instrumentation 113

13.1 Cavity Pressure Technology 113

13.2 Cavity Thermocouples 120

13.3 Process Documentation 123

13.4 Process Control 124

13.5 Additional Monitoring Options 125

14 Mold Cooling 127

14.1 Mold Cooling Importance 127

14.2 Water Flow 128

14.3 Documentation 129

14.4 Tooling Techniques 130

14.5	Additive Manufacturing	132
14.6	Other Cooling Concerns	134
15	Black or Brown Specks	135
15.1	Description	135
15.2	Black Specks Troubleshooting Chart	136
15.3	Black Specks Troubleshooting	136
15.3.1	Black Specks Troubleshooting Molding Process Issues	136
15.3.2	Black Specks Troubleshooting Mold Issues	137
15.3.3	Black Specks Troubleshooting Machine Issues	139
15.3.4	Black Specks Troubleshooting Material Issues	141
16	Blush	145
16.1	Description	145
16.2	Blush Troubleshooting Chart	146
16.3	Blush Troubleshooting	146
16.3.1	Blush Troubleshooting Molding Process Issues	146
16.3.2	Blush Troubleshooting Tooling Issues	149
16.3.3	Blush Troubleshooting Machine Issues	152
16.3.4	Blush Troubleshooting Material Issues	153
17	Brown Streaks	155
17.1	Description	155
17.2	Brown Streak Troubleshooting Chart	156
17.3	Brown Streak Troubleshooting	156
17.3.1	Brown Streak Troubleshooting Molding Process Issues	156
17.3.2	Brown Streak Troubleshooting Mold Issues	160
17.3.3	Brown Streak Troubleshooting Machine Issues	163
17.3.4	Brown Streak Troubleshooting Material Issues	166
18	Bubbles	169
18.1	Description	169
18.2	Bubbles Troubleshooting Chart	170
18.3	Bubbles Troubleshooting	170
18.3.1	Bubbles Troubleshooting Molding Process Issues	171
18.3.2	Bubbles Troubleshooting Mold Issues	172
18.3.3	Bubbles Troubleshooting Machine Issues	174
18.3.4	Bubbles Troubleshooting Material Issues	175

19	Buildup	179
19.1	Description	179
19.2	Buildup Troubleshooting Chart	180
19.3	Buildup Troubleshooting	180
19.3.1	Buildup Troubleshooting Molding Process Issues	180
19.3.2	Buildup Troubleshooting Mold Issues	181
19.3.3	Buildup Troubleshooting Machine Issues	183
19.3.4	Buildup Troubleshooting Material Issues	183
20	Burns	187
20.1	Description	187
20.2	Burns Troubleshooting Chart	188
20.3	Burns Troubleshooting	188
20.3.1	Burns Troubleshooting Molding Process Issues	188
20.3.2	Burns Troubleshooting Mold Issues	191
20.3.3	Burns Troubleshooting Machine Issues	192
20.3.4	Burns Troubleshooting Material Issues	195
21	Cloudiness	199
21.1	Description	199
21.2	Cloudiness Troubleshooting Chart	200
21.3	Cloudiness Troubleshooting	200
21.3.1	Cloudiness Troubleshooting Molding Process Issues	200
21.3.2	Cloudiness Troubleshooting Mold Issues	202
21.3.3	Cloudiness Troubleshooting Machine Issues	203
21.3.4	Cloudiness Troubleshooting Material Issues	204
22	Color Swirls	207
22.1	Description	207
22.2	Color Swirls Troubleshooting Chart	208
22.3	Color Swirls Troubleshooting	208
22.3.1	Color Swirls Troubleshooting Molding Process Issues	208
22.3.2	Color Swirls Troubleshooting Mold Issues	210
22.3.3	Color Swirls Troubleshooting Machine Issues	210
22.3.4	Color Swirls Troubleshooting Material Issues	212
23	Contamination	217
23.1	Description	217

23.2	Contamination Troubleshooting Chart	218
23.3	Contamination Troubleshooting	218
23.3.1	Contamination Troubleshooting Molding Process Issues	218
23.3.2	Contamination Troubleshooting Mold Issues	220
23.3.3	Contamination Troubleshooting Machine Issues	223
23.3.4	Contamination Troubleshooting Material Issues	225
24	Cracking	231
24.1	Description	231
24.2	Cracking Troubleshooting Chart	232
24.3	Cracking Troubleshooting	232
24.3.1	Cracking Troubleshooting Molding Process Issues	232
24.3.2	Cracking Troubleshooting Mold Issues	236
24.3.3	Cracking Troubleshooting Machine Issues	237
24.3.4	Cracking Troubleshooting Material Issues	238
25	Delamination	241
25.1	Description	241
25.2	Delamination Troubleshooting Chart	242
25.3	Delamination Troubleshooting	242
25.3.1	Delamination Troubleshooting Molding Process Issues	242
25.3.2	Delamination Troubleshooting Mold Issues	243
25.3.3	Delamination Troubleshooting Machine Issues	244
25.3.4	Delamination Troubleshooting Material Issues	245
26	Dimensions	247
26.1	Description	247
26.2	Dimensions Troubleshooting Chart	247
26.3	Dimensions Troubleshooting	248
26.3.1	Dimensions Troubleshooting Molding Process Issues	248
26.3.2	Dimensions Troubleshooting Mold Issues	253
26.3.3	Dimensions Troubleshooting Machine Issues	256
26.3.4	Dimensions Troubleshooting Material Issues	259
27	Excessive Cycle Time	263
27.1	Description	263
27.2	Excessive Cycle Time Troubleshooting Chart	263
27.3	Excessive Cycle Time Troubleshooting	264

- 27.3.1 Excessive Cycle Time Troubleshooting Molding Process Issues 264
 - 27.3.2 Excessive Cycle Time Troubleshooting Mold Issues 267
 - 27.3.3 Excessive Cycle Time Troubleshooting Machine Issues 271
 - 27.3.4 Excessive Cycle Time Troubleshooting Material Issues 273
- 28 High Fill Pressure 275**
 - 28.1 Description 275
 - 28.2 High Fill Pressure Troubleshooting Chart 275
 - 28.3 High Fill Pressure Troubleshooting 276
 - 28.3.1 High Fill Pressure Troubleshooting Molding Process Issues .. 276
 - 28.3.2 High Fill Pressure Troubleshooting Mold Issues 277
 - 28.3.3 High Fill Pressure Troubleshooting Machine Issues 280
 - 28.3.4 High Fill Pressure Troubleshooting Material Issues 284
- 29 Flaking 287**
 - 29.1 Description 287
 - 29.2 Flaking Troubleshooting Chart 288
 - 29.3 Flaking Troubleshooting 288
 - 29.3.1 Flaking Troubleshooting Molding Process Issues 288
 - 29.3.2 Flaking Troubleshooting Mold Issues 288
 - 29.3.3 Flaking Troubleshooting Machine Issues 290
 - 29.3.4 Flaking Troubleshooting Material Issues 290
- 30 Flash 291**
 - 30.1 Description 291
 - 30.2 Flash Troubleshooting Chart 292
 - 30.3 Flash Troubleshooting 292
 - 30.3.1 Flash Troubleshooting Molding Process Issues 293
 - 30.3.2 Flash Troubleshooting Mold Issues 297
 - 30.3.3 Flash Troubleshooting Machine Issues 302
 - 30.3.4 Flash Troubleshooting Material Issues 306
- 31 Flow Lines 309**
 - 31.1 Description 309
 - 31.2 Flow Lines Troubleshooting Chart 309
 - 31.3 Flow Lines Troubleshooting 310
 - 31.3.1 Flow Lines Troubleshooting Molding Process Issues 310

31.3.2	Flow Lines Troubleshooting Mold Issues	312
31.3.3	Flow Lines Troubleshooting Machine Issues	314
31.3.4	Flow Lines Troubleshooting Material Issues	316
32	Glass Fibers on Surface	319
32.1	Description	319
32.2	Glass Fibers on Surface Troubleshooting Chart	320
32.3	Glass Fibers on Surface Troubleshooting	320
32.3.1	Glass Fibers on Surface Troubleshooting Molding Process Issues	320
32.3.2	Glass Fibers on Surface Troubleshooting Mold Issues	322
32.3.3	Glass Fibers on Surface Troubleshooting Machine Issues	324
32.3.4	Glass Fibers on Surface Troubleshooting Material Issues	325
33	Gloss Variation	329
33.1	Description	329
33.2	Gloss Variation Troubleshooting Chart	330
33.3	Gloss Variation Troubleshooting	330
33.3.1	Gloss Variation Troubleshooting Molding Process Issues	330
33.3.2	Gloss Variation Troubleshooting Mold Issues	334
33.3.3	Gloss Variation Troubleshooting Machine Issues	338
33.3.4	Gloss Variation Troubleshooting Material Issues	338
34	Jetting	341
34.1	Description	341
34.2	Jetting Troubleshooting Chart	342
34.3	Jetting Troubleshooting	342
34.3.1	Jetting Troubleshooting Molding Process Issues	343
34.3.2	Jetting Troubleshooting Mold Issues	344
34.3.3	Jetting Troubleshooting Machine Issues	346
34.3.4	Jetting Troubleshooting Material Issues	346
35	Part Sticking on Cover	347
35.1	Description	347
35.2	Part Sticking on Cover Troubleshooting Chart	347
35.3	Part Sticking on Cover Troubleshooting	348
35.3.1	Part Sticking on Cover Troubleshooting Molding Process Issues	348

- 35.3.2 Part Sticking on Cover Troubleshooting Mold Issues 349
- 35.3.3 Part Sticking on Cover Troubleshooting Machine Issues 353
- 35.3.4 Part Sticking on Cover Troubleshooting Material Issues 353

- 36 Part Sticking on Ejector 357**
- 36.1 Description 357
- 36.2 Part Sticking on Ejector Troubleshooting Chart 358
- 36.3 Part Sticking on Ejector Troubleshooting 358
 - 36.3.1 Part Sticking on Ejector Molding Process Issues 358
 - 36.3.2 Part Sticking on Ejector Troubleshooting Mold Issues 361
 - 36.3.3 Part Sticking on Ejector Troubleshooting Machine Issues 363
 - 36.3.4 Part Sticking on Ejector Troubleshooting Material Issues 364

- 37 Pin Push 367**
- 37.1 Description 367
- 37.2 Pin Push Troubleshooting Chart 368
- 37.3 Pin Push Troubleshooting 368
 - 37.3.1 Pin Push Troubleshooting Molding Process Issues 368
 - 37.3.2 Pin Push Troubleshooting Mold Issues 370
 - 37.3.3 Pin Push Troubleshooting Machine Issues 372
 - 37.3.4 Pin Push Troubleshooting Material Issues 373

- 38 Read-through 375**
- 38.1 Description 375
- 38.2 Read-through Troubleshooting Chart 376
- 38.3 Read-through Troubleshooting 376
 - 38.3.1 Read-through Troubleshooting Molding Process Issues 376
 - 38.3.2 Read-through Troubleshooting Mold Issues 377
 - 38.3.3 Read-through Troubleshooting Machine Issues 380
 - 38.3.4 Read-through Troubleshooting Material Issues 380

- 39 Scuffs and Scratches 381**
- 39.1 Description 381
- 39.2 Scuffs and Scratches Troubleshooting Chart 382
- 39.3 Scuffs and Scratches Troubleshooting 382
 - 39.3.1 Scuffs and Scratches Troubleshooting Molding Process
Issues 382
 - 39.3.2 Scuffs and Scratches Troubleshooting Mold Issues 385

39.3.3	Scuffs and Scratches Troubleshooting Machine Issues	387
39.3.4	Scuffs and Scratches Troubleshooting Material Issues	387
40	Short Shot	389
40.1	Description	389
40.2	Short Shot Troubleshooting Chart	390
40.3	Short Shot Troubleshooting	390
40.3.1	Short Shot Troubleshooting Molding Process Issues	390
40.3.2	Short Shot Troubleshooting Mold Issues	397
40.3.3	Short Shot Troubleshooting Machine Issues	401
40.3.4	Short Shot Troubleshooting Material Issues	405
41	Sink	409
41.1	Description	409
41.2	Sink Troubleshooting Chart	410
41.3	Sink Troubleshooting	410
41.3.1	Sink Troubleshooting Molding Process Issues	410
41.3.2	Sink Troubleshooting Mold Issues	416
41.3.3	Sink Troubleshooting Machine Issues	420
41.3.4	Sink Troubleshooting Material Issues	423
42	Splay	425
42.1	Description	425
42.2	Splay Troubleshooting Chart	426
42.3	Splay Troubleshooting	426
42.3.1	Splay Troubleshooting Molding Process Issues	427
42.3.2	Splay Troubleshooting Mold Issues	432
42.3.3	Splay Troubleshooting Machine Issues	437
42.3.4	Splay Troubleshooting Material Issues	439
43	Sprue Sticking	443
43.1	Description	443
43.2	Sprue Sticking Troubleshooting Chart	444
43.3	Sprue Sticking Troubleshooting	444
43.3.1	Sprue Sticking Troubleshooting Molding Process Issues	444
43.3.2	Sprue Sticking Troubleshooting Mold Issues	447
43.3.3	Sprue Sticking Troubleshooting Machine Issues	451
43.3.4	Sprue Sticking Troubleshooting Material Issues	453

44 Stringers 455

44.1 Description 455

44.2 Stringers Troubleshooting Chart 456

44.3 Stringers Troubleshooting 456

 44.3.1 Stringers Troubleshooting Molding Process Issues 456

 44.3.2 Stringers Troubleshooting Mold Issues 458

 44.3.3 Stringers Troubleshooting Machine Issues 460

 44.3.4 Stringers Troubleshooting Material Issues 462

45 Voids 463

45.1 Description 463

45.2 Voids Troubleshooting Chart 464

45.3 Voids Troubleshooting 464

 45.3.1 Voids Troubleshooting Molding Process Issues 464

 45.3.2 Voids Troubleshooting Mold Issues 466

 45.3.3 Voids Troubleshooting Machine Issues 468

 45.3.4 Voids Troubleshooting Material Issues 468

46 Warp 469

46.1 Description 469

46.2 Warp Troubleshooting Chart 469

46.3 Warp Troubleshooting 470

 46.3.1 Warp Troubleshooting Molding Process Issues 471

 46.3.2 Warp Troubleshooting Mold Issues 477

 46.3.3 Warp Troubleshooting Machine Issues 479

 46.3.4 Warp Troubleshooting Material Issues 480

47 Weld Lines 483

47.1 Description 483

47.2 Weld Lines Troubleshooting Chart 484

47.3 Weld Lines Troubleshooting 484

 47.3.1 Weld Lines Troubleshooting Molding Process Issues 485

 47.3.2 Weld Lines Troubleshooting Mold Issues 487

 47.3.3 Weld Lines Troubleshooting Machine Issues 489

 47.3.4 Weld Lines Troubleshooting Material Issues 490

Index 493

1

Troubleshooting Methodology

■ 1.1 Troubleshooting

Troubleshooting is problem solving. Molding troubleshooters are called upon to resolve problems with the part, mold, machine, or process. There are many problems encountered in injection molding including these general categories:

- Cosmetic defects
- Dimensional problems
- Part breakage
- Long cycle times
- High scrap rate

All of the above lead to increased cost to manufacture a molded part, which often makes the difference between profit and loss. A molding operation that is consistently running high scrap or long cycles is going to struggle to succeed.

■ 1.2 What Makes an Effective Troubleshooter?

The role of a troubleshooter is to find the root cause of a problem and do what is necessary to resolve the problem. Effective troubleshooters will look beyond their initial impressions and ensure that the true root cause has been addressed. Good troubleshooters take a great deal of pride in having the perseverance to solve a problem and ensure that it does not reoccur.

The Merriam-Webster dictionary defines a troubleshooter as:

A skilled worker employed to locate trouble and make repairs in machinery and technical equipment.

A person skilled at solving or anticipating problems or difficulties.

Troubleshooting is a skill that can be learned and this book is intended to help convey some of the knowledge that the authors have learned through many years of troubleshooting. Some of the key things that will help anyone improve at troubleshooting include:

- Willingness to listen to others. Anyone can provide the crucial piece of information that helps solve a problem. A good troubleshooter will listen to people.
- Being observant. A good troubleshooter will always be looking for what might have changed. Good observation skills are critical to troubleshooting. Good troubleshooters live by the motto “show me” rather than trusting that things have been set up correctly. Anyone who has spent time troubleshooting will tell you that there are plenty of cases where they were told that the material was dry or the mold was clean but verification showed otherwise.
- Willingness to learn. Many times when working on a problem a troubleshooter will have to dig deep into a subject to learn what the root cause really is. Be open to learning and use all resources available to become better at troubleshooting. There is always more to learn.
- Perseverance. This is critical to being a good troubleshooter. There are many times when standing at a molding machine for hours gets very tiring. A good troubleshooter is willing to put the time and effort in to ensure the problem is corrected. This also means that they will check back on the problem to ensure that it is corrected.
- Willingness to try things. If a troubleshooter is afraid to try something out of fear of a negative result they will struggle to reach the solution of the problem. A perfect example is a processor who is afraid to open up vents on a mold because of flash. If you do not try to fix the problem it will not be resolved.
- Taking a systematic approach. A good troubleshooter works through a problem using a systematic methodology. Change one thing at a time in an organized fashion and give the change a chance to stabilize.
- Being data driven. Good troubleshooters utilize data to make decisions, and do not rely on assumptions or opinions. If a change is made the data should provide feedback on the whether or not there was an improvement.
- Patience. This may be one of the hardest parts of troubleshooting. Often times a change is made but the troubleshooter is not patient enough to determine the effect and immediately makes another change. Allow processes to stabilize during troubleshooting to determine the ultimate impact.

■ 1.3 What Makes an Ineffective Troubleshooter?

Many of the above characteristics help people to become effective troubleshooters. There are also many traits that make people struggle when troubleshooting including:

- The “know it all”. People that believe they know everything about every aspect of injection molding will one day be in for a rude awakening. Injection molding problems tend to have a humbling effect on troubleshooters, and everyone has something more to learn. Remember every mold, machine, and material combination can create a new opportunity.
- The “this worked last time” syndrome. Many times people get caught in an approach that completely relies on what they have experienced, which in turn puts blinders on them. First understand the problem before trying to implement what worked last time.
- The “Band-Aids and duct tape fixes everything” troubleshooter. This type of person will always look for the simplest thing that can be done whether or not they solve the problem. This mentality often happens in production where the approach can be just “get me the parts I need to make shipment.” While a “duct tape” type of fix may help to limp through a run, the root cause must be addressed and corrected. Putting “Band-Aids” on top of duct tape to keep a job running will lead to scrap and downtime.
- The “flavor of the month”. This often happens when a specific problem is identified and corrected on a given mold in the plant. Often since this solution solved that problem people will try to implement that solution everywhere whether it fits or not.

Overall many people that struggle to effectively troubleshoot are lacking either the time or the tools to be successful. There is always only going to be 24 hours in every day and customer demand for quality parts will persist. This book was written to help provide some tools that can make troubleshooting more efficient and hopefully help people wisely use their time spent troubleshooting.

■ 1.4 Troubleshooting Methodology

As mentioned in Section 1.2, a good troubleshooter uses a systematic approach. The following is a reminder to help with keeping a systematic approach to troubleshooting;

Systematically

Think

Observe

Proceed

This STOP methodology of troubleshooting is meant to do exactly what it says and stop before jumping to conclusions.



Development of STOP

This thought process came years ago while interviewing process engineers and technicians. I would always try to gauge their knowledge by asking questions about how they would handle a problem such as a short shot. The answers I received were usually correct to a point but obviously quite diverse. Often times the answers provided could be the right ones, but, without knowing what was happening, could also lead to disaster. When I reviewed my own mentality, I came to understand that the first thing I would do when troubleshooting was to stop and really examine what was happening. The concept of STOP troubleshooting came about as an easy way to train people in the methodology of troubleshooting.

1.4.1 STOP: Systematically

In the STOP methodology, the S stands for systematically. All troubleshooting should be conducted in an organized and systematic approach. Having a systematic approach will help ensure the root cause of the problem is truly resolved. As a problem is addressed a systematic approach will make it easier to avoid missing a potential cause.

Part of the systematic approach to troubleshooting breaks the problem into four key categories. Many people are familiar with the 5M's often used for fishbone diagrams which are man, method, machine, measurement, and material. For systematic injection molding troubleshooting the 4M's we focus on are:

1. Molding process
2. Mold
3. Machine
4. Material

These 4M's are the key items that a troubleshooter can impact. The "man" is not included because a person can impact any of the 4M's. Each of the 4M's must be considered for potential root causes when troubleshooting. By reviewing the 4M's

it is much easier to troubleshoot with a systematic approach. By considering which of the 4M's could contribute and working through one category at a time a list of potential root causes can quickly be gathered.

All of the defects discussed in this book will use the 4M method for description of potential causes. Utilize the possible causes to systematically work through resolving the problem. Keep asking which of the 4M's could be contributing to the defect and why. Always try to drive deeper to get to the root cause of the problem. An example of using the 4M's is when troubleshooting sink: the natural place to start is with second-stage pressure; however, if the pressure is raised to compensate for a machine problem, was the true issue resolved or are you processing around another issue? The goal of the 4M method is to avoid processing around issues. Often times molders are left trying to work "process magic" to get good parts when a tooling improvement should have been implemented. Using the 4M method helps to keep process windows as wide as possible and will lead to less scrap, waste, and PPM (defective parts per million) in the long run.

Most people are familiar with the "5 Why" approach that was developed at Toyota. This approach is a tool that systematically drives toward asking questions about the root cause. In this approach, the goal is to get to the true root cause by asking why after every answer when problem solving. Many people find this technique useful.

One key to a systematic approach to troubleshooting is to review what has possibly changed in the mold, molding process, material, or machine. Frequently people will work on trying to fix a problem but not address what had actually changed that originally led to the problem. In other words, sometimes technicians are struggling to solve the wrong problem. A common example of this is someone slowing first-stage velocity to fix a burn that was actually caused by dirty mold vents. Using a systematic approach will help to focus on the true root cause of the problem and not to process around an issue.

The mentality to keep when troubleshooting should be to try to remove one potential root cause at a time. Until an issue has been proven to have no effect it remains a potential root cause. Using a systematic approach allows a troubleshooter to remove one cause at a time, focusing initially on the most likely causes and working from there. Always remember though that data is key to proving a root cause.

Change one thing at a time and determine the impact. If a troubleshooter changes multiple things at a time it is impossible to determine what the root cause was. After making a change, always give the molding machine time to stabilize before evaluating the impact of the change. If the process change shows no impact on the defect, it can be reset to the original documented process.

It is also vital to make changes that are large enough to have a potential impact. Frequently processors will make an adjustment to a process and when they do not

see an impact they scratch that variable off the list of potential causes. Remember that if the change is too large and causes other concerns it can be adjusted back towards the original setting. Make sure a parameter has been thoroughly evaluated before it is removed as a potential root cause.

1.4.2 STOP: Think

Think is the step to make sure that a troubleshooter has mentally reviewed the defect and the potential causes that were systematically determined. Before making a change, it is critical to think through what the expected result is as well as potential side effects. Always begin the think step with the question of “is this a new problem or has it been ongoing?” If it is a new problem focus on what changed; with an ongoing problem the focus is more on what needs to be corrected.

Sometimes in the think step of troubleshooting it is necessary to think outside of the box. Many problems encountered in molding are not easily solved and may require a creative approach to resolve. Willingness to not be constrained by comments such as “that’s not the way we do it” is key to resolving problems. As Albert Einstein said, “we cannot solve our problems with the same thinking we used when we created them.” There are many examples of molds where someone said that an area cannot be vented or cooled but through some ingenuity a solution was found. Remember that there are many exceptions to the general “rules of thumb”; critical thinking is vital.

Also, when thinking through a problem, think bigger than the current defect that is in front of you. Always ask if this problem may be happening elsewhere but has not been detected there. In the case of the 4M machine category, any mold that runs in that particular machine may be having problems but some will be worse than others. If one drying hopper is feeding multiple machines a splay problem may start to show up in multiple parts. Think about the root cause and what else it may impact and examine other parts that could be experiencing similar problems.

When thinking about a problem look for opportunities to push the thought process as far up front as possible. Effort put into part and mold design will result in improved process windows, reduced scrap, and more efficient launches. It is much more cost effective to ensure that the initial design is suitable for manufacturing rather than trying to correct mistakes after the mold has been built and run.

1.4.3 STOP: Observe

Observation is critical to solving problems. Much like Sherlock Holmes, a good molding troubleshooter must observe as much as they can regarding the problem and environment.

Observation should be a multiple sense process, meaning look, listen, and even smell what is happening at the molding machine. Visual examination of the parts, the equipment, and the process will most often provide valuable clues. However, when observing a molding machine in operation, the smell of degraded plastic may be an overwhelming indicator of a problem. Strange noises can also be an indication of something wrong in the process. Always observe with all senses to try to discover any clues to the cause.

When observing a molding process, a walk around the machine is usually a good practice. A quick walk can often highlight a concern that must be addressed. Key things to look for include:

- Auxiliary setpoints and actual values
 - Hot runner controllers
 - Thermolator
 - Chiller
 - Dryer
 - Gas assist equipment
- Clamp and robot movements
- Trimming operations
- Operator handling
- Material identified and correct
- Clear standards available?
- Anything that is damaged or out of place

Figure 1.1 shows a simple chart called the 4M Basic 8. These are the basic items that need to be observed during initial troubleshooting. Many problems can be resolved by simply working through these eight questions, and a “no” answer for any of these questions indicates a likely starting point for resolving the problem. The 4M Basic 8 is a very simple procedure that all molders should be able to work through and answer prior to calling for technical support. Utilizing the 4M Basic 8 or something similar as a starting point for troubleshooting puts good habits in place for troubleshooters.

4M Basic 8		Y/N
	Molding Process	
1	Match documented setup?	
2	Fill Only Weight?	
	Mold	
3	Vents clean and open?	
4	Mold not damaged?	
	Machine	
5	Same machine?	
6	Machine achieving setpoints?	
	Material	
7	Correct material?	
8	Dry?	

Figure 1.1 4M Basic 8

Another key to the observation step of the STOP methodology is to ensure that good baseline data is available. Scrap reports are a critical piece of data to determine what the baseline defect rate is. Figure 1.2 shows a pie chart that provides a breakdown of the key scrap items for a particular job. Based on the Pareto Principle a likely expectation is that 80% of the scrap is a result of 20% of the potential root causes. This pie chart provides an easy reference tool to determine where the troubleshooting efforts should be focused.




Figure 1.2 Pie chart breakdown of scrap percentage

A key observation task when reviewing data during troubleshooting is to evaluate if the problem has been an ongoing issue or has just recently started to occur. Figure 1.3 shows a graph that greatly illustrates an example of a sudden appearance of a defect. The part had been running with very little contamination scrap (less than 10% of total scrap) but then in June the contamination scrap numbers started to rapidly increase. The job continued to run poorly for approximately 5 months until the root cause was determined (problem with agglomeration of colorant components in the color concentrate). Validation of the improvement was simple due to the rapid drop of scrap in November.




Figure 1.3 Graph showing a sudden increase in scrap and a corresponding sudden drop off in scrap after the problem was fixed

If a problem suddenly occurs the most important question to answer is “what has changed?” The power of observation is critical to determining what potentially changed. The 4M Basic 8 helps to evaluate possible changes and this simple step should always be done before diving deeper into the problem-solving process. It is important to understand that a sudden change may not have been something that someone did intentionally. Things that must be observed for possible unintentional change include:

- Shop environment
- Material variation

1.4.7.6 Is/Is Not

Is/is not can be applied as a simple tool to help narrow the scope of a problem. The way to conduct an is/is not evaluation is to make a chart with headings of “is” and “is not”. The problem is then broken down into statements about what it is or is not, as shown in Figure 1.7.

Issue: *Splay on mold #1234*

Is	Is Not
<i>Occurring only on mold #1234</i>	<i>Occurring on any other molds</i>
<i>Located randomly on part</i>	<i>Isolated to specific areas</i>
<i>Happening all day long</i>	<i>Happening at specific times</i>

Figure 1.7 Is/Is Not example

1.4.7.7 Change Log

A change log can be used to help keep troubleshooting systematic by providing a way to track the changes made. A change log can be something such as Figure 1.8, which provides a simple sheet to record any changes and the impact that they had on the defect. This can be handy for communicating across shifts so everyone can see what was adjusted and the impact the change had on the problem.

- Distance between tie bars
- Screw type
- Screw L/D
- Screw compression ratio
- Screw diameter
- Intensification ratio
- Tonnage
- Shot size
- Maximum fill rate
- Maximum injection pressure

For ease of access create plaques that can be mounted on the machine to provide key data. Figure 8.18 is an example of machine data that can be posted on a molding machine. A key to people using machine data is making it readily accessible.

Machine #15	
Screw diameter	80mm
Peak pressure	31,000psi
Shot size (GPPS)	51 oz
Screw type	Mixing
Ri	15.5:1
L/D	20:1
Peak flow rate	44 in3/sec

Figure 8.18 Example of a machine data plaque

Repeatable molded parts need to be produced with a repeatable process and a repeatable process requires a repeatable machine. Avoid processing around machine problems or otherwise the process window will be reduced, which will result in scrap and PPM problems.

If a mold is to be validated in multiple machines the lowest common denominator will be what the process should be established at. For example, if a mold is validated in a primary and secondary machine the first-stage speed cannot be set faster than both machines can obtain. Clear documentation of machine details provides for quick analysis of whether a job will run in a given machine.

References

- [1] Bozzelli J., Groleau R., and Ward N. "The Machine Audit: A Systematic Evaluation of Injection Molding Machines: How to Tell a Good Machine—Old or New" Antec 1993.
- [2] Doyle K., "Know Your Machine", *Plastics Technology*, May 2014.
- [3] Bozzelli J., "Know the Basics of Machine Evaluation, Part 1", *Plastics Technology*, June 2010.

9

Drying

■ 9.1 Introduction

Removal of moisture prior to processing is absolutely critical for molding success. Moisture in plastic pellets will turn to gas when subjected to molding temperatures. This gas will be contained in the plastic melt until the plastic enters the mold where the depressurization on the melt stream will allow the gas bubbles to reach the surface of the mold, leaving behind the streak of splay. Hygroscopic materials such as ABS, polycarbonate, nylon, TPU, polyesters, cellulose, or PC/ABS absorb moisture from the environment and require drying.

Some additives including fillers and impact modifiers can result in non-hygroscopic materials needing to be dried. There will be cases when non-hygroscopic materials are literally soaking wet (for example from a roof leak), and in these cases the material will need to be dried prior to molding.

Material suppliers will provide a recommended drying temperature and time for hygroscopic materials. It is critical to follow these drying specifications to ensure that the material is dry enough to successfully process (see below for drying requirements).

■ 9.2 Keys to Drying

Successful drying requires the following:

- Correct temperature
- Dry air
- Air flow
- Time under the above conditions

To ensure adequate drying it is critical to have all four of these conditions met. Four hours of drying time is meaningless if the temperature requirement is not met. A typical desiccant dryer will provide an air dew point of -40°F . Keep in mind that the dryer temperature will help release the moisture from the pellets, the low dew point will allow the air to pick up the moisture, and the air flow exposes more of the pellets to the warm/dry air. Figure 9.1 shows an example of a typical drying hopper.



Figure 9.1 Typical drying hopper

There are many ways that incomplete drying can occur that relate back to the four key drying parameters.

9.2.1 Temperature

Too low a temperature can come from the following problems:

- Drying temperature set too low:

It is vital to follow the material suppliers recommended dryer temperature settings. If the temperature is set too low the moisture will not be released by the plastic resulting in lack of drying.

- Incorrect location of dryer control thermocouple or RTD:

The temperature should be measured at the hopper inlet. If the temperature is measured at the dryer outlet there will be a drop in temperature before the air reaches the material. The temperature set point must account for this temperature drop if you are controlling based on dryer outlet rather than hopper inlet. For improved efficiency use insulated hoses between the dryer outlet and the hopper inlet as this will limit the amount of heat loss.

- A burned-out heater can prevent a dryer from achieving the set process temperature. If the dryer is alarming for low temperature the heater may need to be checked and possibly replaced.

Bear in mind that a higher drying temperature is not the route to faster drying! If a material is dried at too high of a temperature it will become tacky or even melt, which will result in what is often called a “hard ball”, which is when the material pellets stick together and will not feed through the drying hopper. A “hard balled” or “rocked” drying hopper means hours’ worth of difficult work trying to remove the stuck plastic. This is an experience that creates a wonderful learning opportunity, and the person who set the temperature too high should be the one who has to remove the melted plastic; chances are they will not repeat this mistake!

9.2.2 Dry Air

As the moisture is released from the material by heating the moisture must be carried away. Moving dry air through the drying hopper will allow the moisture to be carried away from the plastic. Without providing the dry air the water molecules have nowhere to go and as a result the material will stay wet.

The dryness of air is measured by its dew point, the temperature at which moisture in the air will condense. The dew point of the air should be between -20 and -40 °F for effective drying. Common reasons for not reaching the required dew point include:

- Bad desiccant, either due to the age of the desiccant or desiccant that has been contaminated with plastic fines or byproducts not filtered out of return air. As desiccant pellets can and will go bad, use a dew point meter to determine if there

are issues achieving a low enough dew point. Some dryers have dew point meters built into them or portable units can be utilized to monitor a dryer.

- On dryers with multiple desiccant beds you must verify the dew point from each of the beds, and you may find one bad and one good desiccant bed. This means that you will need to verify the dew point over a time period. One way to verify the dew point over time is to purchase a chart recorder to connect to the dew point meter. Another method is to connect the dew point meter to a data monitoring system such as RJG eDART®.

- Return air too hot:

For optimal performance of a desiccant the return air should be between 120 and 150 °F. If drying set points are above 180 °F the return air will probably be too high for optimal performance. When drying at temperatures above 180 °F an after cooler should be used to cool the return air to below 150 °F. Also keep in mind that return air hoses should not be insulated as this will allow the return air to cool as it travels back to the dryer.

- Burned out regeneration heaters will not provide enough heat to remove the absorbed water from the desiccant. If the regeneration heaters are not working you will see a high dew point.
- Make sure that there are no leaking seals or holes in the drying hoses that would allow moist ambient air to be introduced into the drying hopper.



How to Use an RJG eDART® as a Dryer Monitor

Connect the output from the dew point meter to a 0–10 V analog input module. You can also use a dew point meter from RJG that will connect directly to the eDART® without the analog input module.

Anywhere that you wish to collect temperature data from can have a thermocouple installed, and the thermocouples can then be connected to an RJG Quad Temp Module. You could measure hopper inlet temperature, dryer outlet temperature, and maybe even regeneration temperature.

With the above information you can establish full time monitoring with a permanent eDART® or setup a portable dryer qualification methodology where you monitor the dryer for 24 hours to determine how well it is working.

Checking Desiccant

To verify if a desiccant is working conduct the following experiment: Dry desiccant can be taken from a dryer desiccant canister or it can be dried in an oven for 2 hours at 400 °F (placed in an appropriate container). Allow the desiccant to cool to room temperature and then pour some water into the container with the desiccant. If the desiccant is active there will be a violent exothermic reaction (use caution!) as the desiccant absorbs the water, steam will be observed, and a significant temperature rise will be detected (> 20 °F). If the desiccant is not active there will be no reaction or temperature rise.

An inactive desiccant should be replaced in the dryer because it will not obtain an adequate dew point with a bad desiccant.

9.2.3 Air Flow

Poor air flow can come from the following issues:

- Plugged filters restricting the air flow:
All dryer filters must be kept clean. Do not run dryers without filters or the desiccant bed will become contaminated and not be capable of achieving adequate dew points.
- Feed hoses can become crushed, which restricts the air flow. Verify that all hoses are free of crushed areas and holes.
- Too small of a dryer for the drying hopper:
Dryers are measured in cubic feet per minute (CFM) of airflow. If the dryer is undersized relative to the hopper there will not be enough air movement in the hopper to effectively reach much of the material.
- A burned-out blower will result in no air flow. Check that the blower is running and has not burned out. Verify that the dryer is not wired with reverse polarity or the blower will run backwards.
- Most modern dryers will alarm if the airflow is inadequate. Do not make a habit out of silencing alarms on equipment: It is ringing to tell you something.

9.2.4 Time

Lack of drying time typically comes from the following:

- Simply starting up the machine prior to the required amount of drying time:
This is a plant discipline issue, and processors must know that the material has had adequate residence before starting the press.
- Allowing hoppers to run down before filling them:
If they run too low you will have material that has not dried long enough. This is also a plant discipline issue. Material handlers cannot be allowed to let hopper volumes run down.
- Material flow:
Molding expert John Bozzelli has conducted studies that show that some dryer designs will tend to have a “rat hole” flow where the center pellets travel much faster than the outer pellets in the hopper [1]. This is a hopper design problem

3. Valve gates are used to direct the gate onto the part with minimal vestige and are also used to control the flow when using multiple valve gates. Because they can be shut off independently you can control flow fronts and knit line. When doing a color change with a valve gate the previous color may stick to the pin and continue to drag out. Cycling the valve open and closed can help with breaking free of the previous material or color.

■ 11.5 Drooling, Stringing, and Sprue Sticking

Drooling from the hot drop tip or sprue is usually a result of a lack of cooling or lack of bearing surface. Tip designs over the years have incorporated insulator gaps and minimal contact with the tip to prevent freeze off and heat transfer to the cavity blocks. In many cases and with some materials this is a good thing. But with some materials an increased contact surface with the cavity steel along with cooling lines around the hot drop is necessary to prevent drooling, stringing, and sprues from sticking.

■ 11.6 Freeze Off

Freeze off in the tip area is usually caused by a lack of heat or the orifice size being too small. With some materials, especially semi-crystalline polymers such as nylon, temperature control at the tip is critical. This is when you want minimal contact surface with the tip and the cavity steel. Many hot runner suppliers use different tip designs to increase temperature control at the orifice. Low vestige tips have a pointed insert, typically called a spreader tip, that is designed to maintain temperature control at the orifice to prevent freeze off. The location of this spreader tip in relation to the orifice is critical and manufacturer specifications should be followed.

■ 11.7 Orifice Size

The orifice size will depend on the material, wall stock, and tip style being used. It is important to keep an open mind with orifice sizes when addressing issues with pressures, high gates, drooling, freeze off, and scrap.

Selection of proper orifice size must be analyzed carefully to ensure a balance between all factors. Computer-aided flow analysis can help with predictions of how well a given gate orifice will be at filling and packing a mold. Consult with material suppliers and hot runner manufacturers for recommendations on orifice sizes.



Case Study

This concerns a part having a scrap issue with splay where the orifice size ended up being the solution. This was a part with four low vestige tips that had a spreader tip in the center of the gate orifice. Many will just consider the orifice diameter and not include the area of the spreader tip that reduces the volume. In this case the orifice diameter was 0.050" and the spreader tip in the center of the gate was 0.025" diameter. The area of the spreader tip reduced the area/volume by 25%. The fill speeds with this gate needed to be on the high end to make a good part but we struggled with a lot of splay. We opened the orifice diameter to 0.060", which was an increase of 55% in area/volume when considering the area that the spreader tip took away. This allowed us to adjust the fill speed and eliminate our splay/shear issue.

11.8 Leakage

Hot runner leakage can be a major problem that will shut down a mold. A big development toward reducing hot runner leakage occurred when the hot drops started being threaded to the manifold versus relying on the stack height, seal rings, and bolt patterns in the mold plates to hold the hot runner together. Some toolmakers complained from a maintenance perspective that this was more difficult to work on when the drops had to be removed for service. In some cases this was true with threads getting galled up and creating another mess. But improvements with thread designs and coatings have reduced this concern among toolmakers. So in the big picture of hot runner issues this has been a big improvement for maintaining molds.

Another observation over the years, but not a common one recently, is with support in the hot half. If the areas cleared out for the hot runner are excessive, cavity pressure can lead to deflection within the mold plates leading to leakage.

■ 11.9 Zones and Wiring

Hot runners have zones, typically identified with numbers, which are dependently controlled with a heater and a thermocouple. It is important to have the wires labeled for each zone so it is easier to troubleshoot versus having to chase wires down, especially when multiple zones are used. A hot runner schematic should be on the side of the tool showing each zone, location, and the heater watts.

The power plug/connection and the thermocouple plug/connection are also identified by zones. So, for example, the zone 1 heater leads would be to zone 1 on the power plug and the thermocouple to zone 1 on the thermocouple plug. The two wires coming off the heater are the same but on the thermocouple they are not. The thermocouple has a positive and negative wire that must be wired to the correct location on the plug or it will not function properly. Similar to the battery in your car, it is not complicated but will not work if wired in reverse. Also, thermocouples come in different types but the J type with the red and white wires is most common. The positive wire is magnetic, and is the white wire for the typical J type, and the red one is the negative. If you are ever in doubt which one is the positive wire you can use a magnet to find out. Make sure to use the proper thermocouple for the chosen hot runner controller. With thermocouples be cautious adding wire extensions unless you are experienced with proper methods and problems with cold junctions. With the heater and thermocouple any connections with extensions must be insulated.

■ 11.10 Hot Runner Troubleshooting

There are some things you can do in the molding machine to troubleshoot hot runners instead of pulling the mold for repair. A first thing to try when having hot runner issues is to change out the cables and controller. Long experience has shown that the controller or cables are often the source of the issue. Also, just because the controller shows a zone at the proper set temperature does not necessarily mean that this is the case if you are having an issue. Also verify the pins in the plugs, because at times they can get pushed in not making contact with the connection on the cable plug.

Use a pyrometer with a 0.040"–0.060" diameter sheath thermocouple to verify temperatures inside the hot drops or the inlet channel. With valve gates you pull the valve pin back to get inside the drop flow channel (note: always use proper safety precautions including face shields and move the injection unit away from the mold to avoid a blowout while probing tips). Make sure to contact the steel in

■ 23.1 Description

Contamination is a broad term that covers visual defects that appear in a molded part. Contamination may show up as specks of discoloration, streaks, splay, delamination, etc. See Figure 23.1 for an example of material contamination.

Also known as: black specks, black/brown streaks, color swirls

Mistaken identity: splay



Figure 23.1 Material contamination

■ 23.2 Contamination Troubleshooting Chart

Table 23.1 shows the contamination troubleshooting chart.

Table 23.1 Contamination Troubleshooting Chart

Molding Process	Mold	Machine	Material
poor changeover	hot runner hang up	hang up areas	improper storage
high melt temperature	high hot runner temperature	anti-seize	regrind
	wear surfaces	robot contamination	incoming contamination
	lubricants		mixed materials
	cleaning		

■ 23.3 Contamination Troubleshooting

There are a wide variety of ways that material can become contaminated. It can be a major challenge to try to work through all the possible routes of contamination. Most of the time the best place to start is with the material being brought to the molding machine and work backward from there.

23.3.1 Contamination Troubleshooting Molding Process Issues

Contamination can be brought on by several process issues including:

- Poor changeover
- High melt temperature

23.3.1.1 Molding Process: Poor Changeover

When a molding machine is stopped and goes through a material or color change there are many opportunities for contamination to occur. The entire feed system and melt delivery system must be thoroughly cleaned out to ensure that there is no residue of the prior material. Some of the key areas to examine include:

- Drying hopper. The drying hopper has several hang up areas including along the door edge, in the hopper loader, around the dispersion cone, the sample/drain tube, and in the distribution box. When conducting a material change all of these areas must be cleaned of all remains of the previous material. Hoppers can be

vacuumed out to help with clean out. Watch out for areas such as the sample tube because this is a spot that is often forgotten.

- **Feed lines.** Whether feeding the machine from the drying hopper, gaylord, or bag, it is critical to ensure that all of the material has been cleaned out. This is usually as simple as removing the feed line and allowing the vacuum loader to suck all of the material out of the feed lines. There have been cases where the material handler does a nice job of cleaning everything out but forgot the feed lines and when the new material was introduced all of the previous material was pulled in with it, contaminating the material.
- **Machine hopper.** The machine hopper will have a variety of locations where material can collect. Make sure to remove the magnet and clean out around the magnet drawer (see Figure 23.2). The hopper should be completely cleaned of all residue from the previous material. Also be sure to watch for any mismatch ledges between components such as the feed throat and hopper.
- **Loaders.** Loaders can also be a location that will trap material pellets. All loaders must be cleaned as part of the material changeover process.
- **Additive feeder bins.** Additive feeder bins must be cleaned when swapping colors. The feed screw on a volumetric feeder must also be removed and cleaned to avoid contamination.



Figure 23.2 Pellets stuck in magnet drawer

Often times molding shops will provide very little training for material handlers. If a material handler does not understand the importance of thorough cleaning during material changes they may cut corners which will lead to contamination. Provide a formal training for everyone in the shop that is responsible for loading materials to ensure that changeovers are executed correctly.

23.3.1.2 Molding Process: High Melt Temperature

When plastics are overheated they can degrade and contaminate the material with black specks or streaks. See Chapter 15 on black specks for more information about this problem.

23.3.2 Contamination Troubleshooting Mold Issues

Mold-related concerns that can cause contamination include:

- Hot runner hang up
- High hot runner temperatures
- Wear surfaces
- Lubricants
- Cleaning

23.3.2.1 Mold: Hot Runner Hang Up

Any areas in a hot runner system that can trap material can lead to contamination. Material trapped in hang up areas can continue to bleed into the melt stream long after the material change has been completed. When dealing with materials that are more temperature sensitive the trapped material may degrade and contaminate the parts with charred black specks. Figure 23.3 shows contamination from a hot drop tip.

Hot runner assemblies should be built in a way that at running temperatures there will be neither ledges nor mismatch locations that would hang up material. Drops must be securely assembled to the manifold so as to not leave any gaps between the drop and the manifold body.

Corners in hot runner manifolds can easily lead to dead spots where material hangs up. Depending on the hot runner design some manifolds will have corners that are gun drilled at 90° intersections. With a 90° intersection the outside of the corner will end up as a dead spot and material will be trapped in this location. Better designs have machined corner plugs with a curved corner, no dead spots.




Figure 23.3 Contamination at hot tip

A manifold can be damaged and cracked which will provide a gap at the crack that will allow material to become trapped. Cracking a manifold is usually a result of a cold start where the manifold was not given enough time to heat soak. Cracked manifolds often need expensive and time-consuming repairs; therefore, educate process technicians to give a hot runner plenty of soak time before injecting plastic through the manifold.

23.3.2.2 Mold: High Hot Runner Temperatures

When hot runners are running at higher temperatures than is required for a material the odds of degrading material increase. As the material degrades in the hot runner system the result can be brown streaks or black specks contaminating the part.

Verify that the hot runner temperatures are set correctly and that actual temperatures are reading accurately. If a hot runner zone is constantly calling for heat it may indicate that a zone is either wired incorrectly or has a thermocouple misplaced.

23.3.2.3 Mold: Wear Surfaces

Any surfaces on a mold that rub against another surface have the opportunity to wear. Over time the metal dust or flakes that are worn from the surface can contaminate the cavity of the mold. This metallic dust will contaminate the molded part and may produce a visual defect.

Wear surfaces to keep an eye on include gibs, wear plates, die locks, cavity locking angles, and shutoffs. The dust that appears is often an early sign of galling starting so it is important to address any wear problems when they are detected.

23.3.2.4 Mold: Lubricants

Any of the lubricants used on a mold can lead to contamination of a molded part. Whether it is grease or oil, when excess lubricants reach the cavity they can contaminate the part producing scrap.

A key item to watch for is over-lubricating a mold. Frequently when a mold comes back from service, all moving components will have too much grease on them. There can be cases where a mold will bleed grease for hours of molding, producing nothing but scrap. Work with tooling sources to establish a standard method of lubricating a mold. It is not as simple as smearing some grease on the pins; grease should be lightly applied because over-greasing can lead to problems.

It is also important to find lubricants that work best for a given application. There is a wide variety of lubricants available and some perform better for specific applications.

23.3.2.5 Mold: Cleaning

Mold cleaning or lack of cleaning can both lead to contamination. For optimized processing a mold should be kept clean. Molds that are dirty can lead to surface contamination of molded parts. Caution must be used when cleaning molds, though, because mold wipes can leave behind fibers that can then be molded onto the surface of a part resulting in a squiggly, worm-like defect (see Figure 23.4).




Figure 23.4 Surface scan of a mold wipe fiber molded onto a part surface

When wiping a mold surface, use clean lint-free wipes to minimize the opportunity for contaminating the mold surface. A dirty wipe not only leaves behind contaminants but may also scratch the mold surface.

Be aware that there are cases where the grease in the mold breaks down due to chemical contact. This can be magnified if someone sprays mold cleaner directly on the ejector half of the mold. The cleaner solvents can impact the viscosity of the grease leading to contamination of the molded part from the broken-down grease.

23.3.3 Contamination Troubleshooting Machine Issues

Some of the machine factors that can lead to contamination include:

- Hang up areas
- Anti-seize
- Robot contamination

23.3.3.1 Machine: Hang Up Areas

Any areas in the melt delivery system that have a mismatch can cause material to hang up. Some of the key areas that should be evaluated for hang ups include:

- Hopper to feed throat
- End cap to barrel
- Nozzle adapter to end cap
- Nozzle to nozzle adapter
- Nozzle tip to nozzle
- Nozzle tip to sprue bushing
- Damaged spots on screw, barrel, non-return valve, and end cap

It is a time-consuming process to disassemble these components and inspect for hang up areas but sometimes it is necessary to get to the root cause. Prior to shutting down for disassembly run another color of material through the barrel. This alternate color can help highlight spots where the original color is being trapped. Also look for areas of charred material when conducting this inspection. Again, this is a time-consuming process so make sure other potential causes are investigated first.

Examination of nozzle tips of different style will show locations where material can become trapped. See Figure 23.5 for cross sections of common nozzle tips: notice the potential dead spot at the ball end of the general-purpose style tip. General-purpose tips can cause contamination and streaking issues due to this dead spot.



Figure 23.5 Nozzle tips: general purpose, nylon, and full taper

23.3.3.2 Machine: Anti-seize

If people are conducting proper installation of new nozzles and nozzle tips they are applying thread anti-seize molded onto the nozzle threads to prior to assembly. If too much anti-seize is applied to the component it is possible to contaminate the plastic melt stream with the anti-seize (see Figure 23.6, for example). Anti-seize will usually result in dark streaks in the part.



Figure 23.6 Nozzle tip with excess anti-seize (top) and appropriate amount of anti-seize (bottom)

Anti-seize is an item where “if a little is good a lot is better” does not apply. Teach processors to use an appropriate amount of anti-seize to avoid running scrap at startup.

23.3.3.3 Machine: Robot Contamination

Take a look at the robots in the shop. Are they dusty with grease drips in various locations? When a robot enters the mold to pick a part it can contaminate the mold. One example of this is when a dirty air line brushes up against the cavity, because this will transfer some of the dirt and potentially lead to a cosmetic defect.

Another factor to consider with the robot is the condition of the end-of-arm tooling. If it is very dirty the vacuum cups can leave a surface contamination on the part. Also if components from the end of arm tooling touch the mold surface they may leave behind contamination that can end up in the cavity.



Case Study: Robot Contamination

This example was on a single-cavity ABS part that was experiencing what appeared to be splay. Examinations of drying conditions, moisture content, venting, process settings, and melt temperatures all led nowhere. Utilizing the STOP methodology and observing the process showed that when the robot picked the part it backed away from the ejector and a dirty air line brushed against the cavity. The cycle was stopped and a small smudge of grease/dirt was detected on the cavity. The part was molded and it was scrap due to the contamination. A couple of cable ties and some cleaning resolved the issue. In this case utilizing the STOP methodology earlier would have led to quicker effective troubleshooting.

23.3.4 Contamination Troubleshooting Material Issues

There are many ways that a material can become contaminated including:

- Improper storage
- Regrind
- Incoming contamination
- Mixed materials

23.3.4.1 Material: Improper Storage

In every molding shop there are a wide variety of foreign contaminants including:

- Dirt, dust, and pollen
- Other plastics

■ 33.1 Description

Variations in gloss on a part will lead to cosmetically unacceptable parts. If the part has areas that are glossy and areas that are dull the variation in appearance can be very unattractive. Figure 33.1 shows an example of gloss variation.

Also known as: spotty, glossy, dull

Mistaken identities: sink, scuff



Figure 33.1 Gloss variation

■ 33.2 Gloss Variation Troubleshooting Chart

Table 33.1 shows the gloss variation troubleshooting chart.

Table 33.1 Gloss Variation Troubleshooting Chart

Molding Process	Mold	Machine	Material
second-stage pressure	mold surface finish	machine performance	material type
second-stage time	cooling		additives
fill velocity	venting		
fill only weight	inconsistent wall stock		
mold temperature			
melt temperature			

■ 33.3 Gloss Variation Troubleshooting

Gloss is determined by the nature of the surface of the mold, i.e. polished or grained, and how well the plastic replicates the mold surface. The first step of troubleshooting gloss problems is to establish if the mold surface is being replicated. As an example, if a mold surface is a sand-blast finish the part will be dull no matter what the process is (see Chapter 6 for more on mold finish).

Another item to keep in mind when reviewing gloss callouts is that parts that are on the two ends of the gloss spectrum will tend to show scratch and mar defects easier than parts with a more mid-range of gloss. Sometimes the difference between a 2.5 and 3.5 gloss reading can make a major difference in the appearance of the part and the ability of the part to look good after handling. Extremely low gloss levels such as a 2.5 can make it very challenging to get a good-looking part.

It is important to understand that in many cases gloss problems are actually truly a read-through (difference in gloss due to differential pack and shrink at wall stock transitions).

33.3.1 Gloss Variation Troubleshooting Molding Process Issues

Common molding process related problems include:

- Second-stage pressure
- Second-stage time

- Fill velocity
- Fill only weight
- Mold temperature
- Melt temperature

33.3.1.1 Molding Process: Second-Stage Pressure

The most important process setting for gloss on molded parts is the pressure applied to the plastic in the cavity. If not enough pressure is applied to the plastic the molded part will not replicate the finish of the mold well. This applies for polished surfaces, textures, and sand-blasted finishes. Think about the surface of the molded part compared to the mold surface: is the plastic being packed into all of the microscopic surface detail of the surface of the mold?

Examining mold surfaces under magnification will show a series of polish scratches on polished surfaces and a series of peaks and valleys on a textured part. To have adequate replication of these microscopic surface details the plastic has to be pressurized at the appropriate levels. If the pressure is not high enough, the surface will not reflect the details of the mold surface.

Variation in pressure across a mold will result in a potential variation in gloss levels across the part. Low-pressure areas will not replicate the surface as well, and will typically have a different gloss appearance when compared to better-pressurized areas. This can often manifest as a distinct difference between areas near and farthest from the gate. Also watch for areas that fill quickly and freeze before being packed out.

One of the challenges faced in injection molding is trying to minimize the pressure drop across the mold cavity. Some of the keys to minimizing pressure drop include filling fast to avoid viscosity variations during first-stage injection. Proper gate placement is also critical to ensuring a minimized pressure drop. To determine gate quantity and location a flow analysis software such as Moldflow® is a valuable first step before steel is cut.

When troubleshooting for gloss problems check that the second-stage pressure is set at the correct value (do not forget to account for intensification ratio). Also check to see if the correct nozzle and nozzle tip are being used because a mixing nozzle will result in a large pressure drop between the machine and the end of the cavity.

Cavity pressure transducers will provide very useful data on the actual pressure within the mold. If a transducer is located near the gate and at the end of fill location, accurate data on what is occurring in the cavity will be easy to obtain.

33.3.1.2 Molding Process: Second-Stage Time

Second-stage time that is not long enough to ensure gate seal can lead to a glossy area near the gate. If the plastic is not retained in the cavity until gate seal there will be a depressurization of the plastic near the gate. The release of plastic near the gate will create a localized low-pressure area that will typically have a different gloss level than the rest of the part.

Verify that the second-stage time is set correctly per the documented process. A gate seal study should be conducted during process development to determine the appropriate second-stage time. If a gate seal study was not conducted take the time to complete a gate seal study to understand the correct time required for establishing gate seal.

33.3.1.3 Molding Process: Fill Velocity

Generally, a faster fill velocity will provide less pressure drop and yield better surface replication. Faster fill rates tend to provide a glossier surface whereas surfaces obtained with slow fill rates tend to be duller. Faster fill velocities also lead to a part that will pack out more uniformly.

Verify that the fill time is correct according to the documented process. Fill velocity settings may not match, but fill time should. If fill time and fill only weight replicate the desired process that ensures that the same volumetric flow rate occurred.

33.3.1.4 Molding Process: Fill Only Weight

If the fill only (95–98%) shot is too light due to an early transfer there may be a gloss difference that forms in a sharp line where transfer occurred. An early transfer can create a very distinct area at end of fill that looks different.

Check the fill only weight to ensure that the part is filled to 95–98% during first stage. If the shot is short the transfer position should be adjusted to provide an adequate fill shot. Be aware that filling too short can lead to a lag in second-stage pressurization. Figure 33.2 shows process monitoring data on a process with an early transfer. Note how the screw travel curve moves significantly after transfer. As the screw continues to move forward the machine is trying to reach the set second-stage pressure but it takes several seconds. Early transfer creates many issues but gloss variation is an often-overlooked problem.




Figure 33.2 Process monitoring curves showing an early transfer

33.3.1.5 Molding Process: Mold Temperature

A low mold temperature can tend to produce a lower gloss level whereas a higher mold temperature can produce a higher gloss level. However, this is another factor that impacts how well the plastic replicates the mold surface, and hotter mold surfaces lead to better replication of the mold surface.

In recent years rapid mold heating and cooling systems have been used to improve the replication of the mold surface. The extra heat that is applied to the mold surface allows the plastic to pack out against the steel much better. Use of rapid mold heating and cooling can yield very high-gloss surfaces when molded on a polished surface. If the mold has a micro texture the replicated surface can be very low in gloss.

There are times when high mold temperatures lead to a rippled surface that will show variation in gloss. The heat of the mold creates an effect where the wall is collapsing away from the mold surface that is sometimes referred to as “heat sink”. Reducing the mold temperature or adding second-stage pressure will often resolve this defect.

33.3.1.6 Molding Process: Melt Temperature

When molding with a low melt temperature the pressure drop across the mold will be increased. With the increase in pressure drop many times a variation in gloss will occur. If the mold is not pressurized at a uniform level there is likely going to be variation in gloss levels.

Verify that the melt temperature matches the documented process. If the melt temperature is wrong then evaluate the following:

- Barrel temperatures set point versus actual
- Back pressure
- Screw recovery rate

33.3.2 Gloss Variation Troubleshooting Mold Issues

One of the biggest impacts on gloss levels of a molded part is the mold itself. The main factors that impact the gloss level are:

- Mold surface finish/texture
- Cooling
- Venting
- Inconsistent wall stock

33.3.2.1 Mold: Surface Finish/Texture

One of the biggest contributors to the gloss of a molded part is the mold surface finish. A sand-blasted mold surface will not produce a high-gloss piano black gloss level no matter what is done to the process.

There is a wide range of finishes that can be used for an injection mold. They include:

- Polish
- Texture
- Sand/glass blast

All three of the above options also have many different levels that can impact the part appearance. For example, a polished surface can be polished to a variety of gloss finishes.

If nonuniform gloss is a problem on a part, the surface of the mold should be inspected for areas of variation on the surface. To effectively do this a strong light is often needed to avoid shadows on the surface. Many times upon inspecting the mold surface, areas of worn texture or buildup will be visible. Sometimes a thorough cleaning of the mold surface will eliminate the variation and other times the mold will need to be sand blasted. Inspecting the mold surface can eliminate a lot of troubleshooting time because if the gloss problem is on the mold surface, processing will not resolve it. Buildup can also be an issue on polished surfaces (see Figure 33.3).




Figure 33.3 Mold surface buildup (right) versus clean surface (left)



Case Study: Polish Buildup

In this case the material being molded was a wood-filled polypropylene. The mold had a polish level of approximately SPI A3, which produced nice glossy black parts when molded with straight polypropylene. An extended run was conducted for a special order of wood-filled polypropylene parts that molded well; however, when the material was changed over to the black polypropylene the gloss level of the parts was dull and inconsistent. Examination of the mold surface showed there was a large amount of buildup on the mold surface and the steel had even tarnished from the gases from the wood-filled material. After many hours of scrubbing with polishing paste, the mold was finally ready for running at high gloss.

Often when a mold texture is used there will either be a secondary micro texture or a sand-blasted finish that creates additional small details that the plastic must be packed into. Under magnification these peaks and valleys will be easy to see and examine for detail. In Figure 33.4 texture details can be viewed under 200× magnification: notice the peaks and valleys that the material must replicate.

Index

Symbols

4M 4
4M Basic 8 7, 311, 395
4M method 18, 32
4M troubleshooting 152, 478
5 Why 5, 13

A

abrasive 453
ABS 37, 83, 148, 153, 185, 225, 227, 245, 339, 427, 448, 491
acetal 159, 175, 196, 229, 243, 255, 282, 407
acid flush 134, 416
acrylic 339
actuated vent pins 59
additive feeder bins 219
additives 83, 197, 306, 339, 428
agglomerates 228
airflow 87
air poppets 352, 437
alarms 395
alloys 290
aluminum oxide 48, 49
amorphous 259, 260, 276, 354, 480
analog input 125
anisotropic 480, 482
anisotropic shrink 261
anti-seize 164, 224
ASA 339
aspect ratio 492

B

backfill 58, 393
backfilled 311, 312

back pressure 78, 160, 171, 181, 190, 209, 211, 237, 276, 321, 334, 395, 415, 427, 429, 431, 466, 486
baffle 416, 417
ball-style non-return valve 258
barrel 139
barrel heaters 141
barrel shot capacity 267
barrel temperatures 157, 171, 190, 194, 276, 321, 415, 466, 486
bead blasted 454
bearing surface 55, 99, 459
Beaumont Effect 106
Beaumont Inc. 106
Beaumont, John 106
bimetallic carbide barrels 403
black/brown streaking 93, 217
black or brown specks 135
black specks 93, 193, 217
blades 268
blast media 47
blend 313, 336
blisters 169, 244, 463
blowing agent 424, 439, 441
blush 145
bore 42
bosses 350, 359
Bozzelli, John 29, 63, 87
brainstorming 15
brass tools 350
breakaway distance 272
breakaway speeds 349
breaking 231
brittle 233
brown streaking 141, 155, 187, 193
bubblers 130, 268, 380, 417
bubbles 83, 169, 306, 463

buildup 134, 179, 193, 202, 334, 352, 362, 399
 burning 122, 321, 414
 burns 53, 103, 187, 266
 burrs 236, 350, 362
 byproducts 193

C

CAD model 313
 CAE 279
 CAE flow analysis 475
 CAE software 471
 calibration 77, 284
 capacity issues 263
 caprolactam 185
 carbon 228
 carbon buildup 135, 139
 Carl Fischer titration 88, 428
 cashew gate 34, 110, 152, 243, 287, 289, 371, 420
 cavity 250, 350
 cavity balance 30, 31, 103, 118, 302, 372, 397, 407, 419
 cavity cooling 105
 cavity fill balance 109
 cavity fill rates 105
 cavity fill time 117
 cavity imbalance 33, 478
 cavity instrumentation 113
 cavity locking angles 222
 cavity pressure 59, 105, 251, 252, 267, 277, 292, 300, 302, 348, 465, 474, 485
 cavity pressure curve 373, 420
 cavity pressure transducers 113, 249, 331, 359, 411
 cell packed 385
 cellulosic 83
 change log 17
 changeover 196, 201, 204, 218
 changeovers 208
 charred 189, 196
 check valves 66
 chicken scratches 309
 chiller 415
 chute 234, 384
 clamp force 108, 292, 295
 clamp open 272
 clamp parallelism 303
 clamp pressure 292
 clamp tonnage 295
 clamp velocities 271
 cleaning 334
 cleanout 239
 cloudiness 93, 199
 cold slugs 287, 448
 cold slug well 151, 279, 435
 cold starts 221, 401
 colorant 185, 317, 454
 colorant concentrate 165
 color changes 98, 202
 color concentrate 167, 196, 209, 212, 239, 246
 color mixing 211, 282, 431
 color streaking 93, 207
 color swirls 187, 207, 217
 component deflection 255
 compression ratio 165, 175, 193, 438
 computer-aided flow analysis 100
 computer flow analysis 314, 489
 computer flow simulation 468
 condensation 432
 containers 204
 contaminants 142, 166, 192
 contamination 93, 161, 176, 199, 204, 210, 214, 217, 230, 239, 241, 245, 403, 407, 439
 conveyor 234, 272, 383, 384
 cooling 105, 108, 127, 255, 264, 265, 337, 363, 379, 466, 467, 472, 478
 cooling capacity 415
 cooling circuits 416
 cooling rate 117, 336, 470, 471, 475
 cooling time 250, 253, 264, 267, 269, 270, 360, 370, 446, 476
 cooling tower 415
 copper alloys 379, 450
 copper-based alloys 130, 417
 core 234, 268, 304
 core circuit 304
 cored out 380
 core half 234
 core pin 271, 418, 488
 core pressure 300
 core pull cylinders 300
 core pulls 44
 cores 130, 350
 coring 467
 cost 263
 cover half 233
 cover side detail 348
 crack 173, 174, 202, 436
 cracking 231

crazing 235
 crystallinity 255
 cushion 66, 161, 253, 257, 395, 413
 cushion monitoring 395, 400
 cycle time 127, 209, 234, 253, 254, 305, 431, 451, 467
 cylinder bore gauge 404
 cylinders 41
 cylinder size 300

D

damage 223, 350, 362
 decompression 172, 190, 253, 427, 430, 457
 Decoupled® II 32
 Decoupled® II molding process 266
 Decoupled® III processing 124
 Decoupled®/scientific molding 29, 30, 251
 deep draw 270
 deep rib 350
 deflection 292, 376
 deformation 370
 degating 287
 degradation 155, 171, 233, 348, 429, 438
 degrade 190, 196, 220, 237, 453
 degraded 93, 135, 209, 399
 delamination 93, 217, 239, 241, 426
 depression 409
 desiccant 84, 85, 86, 428
 desiccant beds 86
 design 149, 235, 307, 313, 317, 323, 361, 363, 380, 410, 418, 464, 467, 470, 484, 489
 Design of Experiments 16
 dew point 84, 85, 428, 454
 dew point meter 85
 dew point monitors 23
 D-gate 35
 dial indicator 295
 diamond 202
 diamond chrome 183
 diamond polish 51
 die blue 378
 die height 295
 die locks 222
 dieseling 187
 differential cavity pressures 376
 differential cooling 255
 differential shrink 271, 376, 379, 470
 dimensional 267
 dimensional issues 74, 103, 255
 dimensions 247, 250, 293

dings 381
 direct gating 97
 discoloration 155
 dispersion tip 282
 distort 348
 distortion 359, 369, 469
 donuts 386
 downtime 193, 354
 draft 44, 270, 350, 371, 385
 draft analysis 350
 draft angles 236, 350, 361, 364
 drag 371, 385
 drags 236
 draw polish 51, 351, 361, 371, 386, 447, 448
 drool 172, 190, 430, 457, 462
 drooling 99
 drop 220
 dryer monitoring 125
 drying 83, 427
 drying hopper 218
 dull 145, 319, 329
 durometer 352
 duty cycle 283
 dynamic check valve study 66

E

eDART® 412, 421
 EDM 236, 361, 399, 420
 ejected 267
 ejection 233, 234, 270, 289, 476
 ejection force 371
 ejection speed 360
 ejection stroke 270, 362, 384
 ejection surface area 361, 371
 ejection temperature 467, 476
 ejector area 386
 ejector box 299
 ejector pins 114, 238, 289, 377
 ejector plate 273, 299, 363, 372, 377
 ejector plate stop buttons 377
 ejector side 353, 368
 ejector speed 369
 end cap 139, 193, 223, 244
 end of arm tooling 225, 382
 end of fill 189, 312, 320
 end of fill cavity pressure 281
 end-of-fill transducer 116
 environment 261
 environmental stress cracking 235, 471
 erosion 192, 298, 300, 362, 452, 453

F

family molds 111, 302
 feed lines 219, 246, 273
 feed throat 174, 223, 273, 416, 427, 432, 438
 fiber orientation 490
 filled material 259, 260
 fillers 83, 317, 374, 481, 490
 fill only 65, 147, 320
 fill only shot 29, 251, 258, 294
 fill only weight 30, 74, 277, 311, 332, 391, 412, 422
 fill pressure 254
 fill time 266, 277, 316, 320, 393, 414
 fill velocity 146, 189, 251, 266, 275, 276, 310, 320, 332, 343, 485
 filters 87
 fines 143
 first stage 251
 first-stage fill 294
 first-stage injection velocity 393
 first-stage velocity 414
 fishbone diagram 4, 14
 flaking 287, 436
 flame-retardant 339
 flame retardants 185
 flash 54, 74, 103, 267, 289, 291, 307
 flow 268
 flow analysis 313
 flow analysis software 254, 331
 flow defects 317
 flow distance 254
 flow front 312, 313, 343, 487, 490
 flow front velocity 322
 flow leader 313
 flow length 105, 261, 278, 302, 312, 323, 392, 479
 flow lines 145, 309, 426
 flow marks 145
 flow meter 27, 125, 414
 flow pattern 313
 flow rates 337, 466
 foreign material 228, 258, 279, 398
 fountain flow 34, 485
 fracture 231
 freeze 254
 frozen layer 396, 479
 frozen layer plot 254, 468
 full taper tip 280

G

galling 222
 gallons per minute 414
 gas assist 303, 437
 gas assist control 124
 gas assist injection molding 423
 gas booster 423
 gas counter pressure 441
 gas traps 169, 187, 190, 463
 gate 145, 156, 269, 277, 313, 323, 489
 gate design 110
 gate flaking 432
 gate freeze 278
 gate land 34, 278
 gate land length 150, 344
 gate location 278, 344
 gates 261, 289, 398, 407, 418, 479
 gate seal 30, 33, 38, 116, 150, 235, 250, 264, 269, 332, 411, 445, 475
 gate seal study 29, 332, 465
 gate seal time 445, 467
 gate size 146, 254, 344, 419
 gate spacing 254
 gate style 392
 gate thickness 149
 gate vestige 34
 gating 33, 265, 323
 gating thin to thick 470
 gaylord 226
 gaylord tipper 406
 gel tape analysis 228
 general-purpose screw 210, 211
 gibs 222
 glass 260
 glass bead 48
 glass content 326
 glass fibers 319, 320
 glass-filled 33, 34, 39, 50, 59, 130, 258, 267, 317, 319, 321, 339, 403, 448, 452, 453, 454
 glass-filled materials 172
 glass transition temperature 360
 glassy 319, 320
 glassy surface 325
 gloss 47, 53, 103, 146, 329, 375
 gloss variation 74, 319, 339
 glossy 329, 367
 grained 330
 grease 161, 192, 222
 grinder 143
 grinding 167

gripper fingers 364
 grippers 364, 383
 Groleau, Rod 29, 63, 113
 guided ejection 386
 gusset ribs 451

H

halo 145
 handling 235, 381
 hang up 98, 139, 156, 196, 202, 203, 212, 218, 223, 234, 243, 244
 hang up areas 164, 220, 223
 heat deflection temperature 471
 heater 97, 101
 heater band 163, 190, 460
 heater band burnout 163
 heat exchanger 416
 heat sink 333
 heel block 300
 hesitation 309, 312, 488
 hesitation lines 310
 high fill pressure 275
 high-gate 35
 high-gloss 339
 high melt temperature 136, 233
 high pressure 278
 high temperature 180
 hob 300
 hold volume 411, 421, 422
 hopper 223, 230, 246, 406
 hopper loader 218
 horn pins 44, 300
 hot drops 33, 34, 40, 399, 458
 hot drop tips 98, 435
 hot oil 322
 hot runner 95, 97, 150, 173, 196, 202, 220, 234, 243, 254, 271, 278, 313, 395, 434, 458
 hot runner cables 400
 hot runner controller 122, 255
 hot runner leakage 100
 hot runner manifold 122, 299, 413, 434
 hot runner plugs 158, 400
 hot runner system 157, 210
 hot runner temperatures 138, 323, 400, 417, 432
 hot runner tip 150
 hot sprue 450
 hot tip 93, 398, 455, 460
 hydraulic 192
 hydraulic cylinders 244, 363

hydraulic gauge 304
 hydraulic leaks 303
 hydraulic pressure 304
 hydraulic pressure gauge 78
 hydraulic response 76
 hydraulics 41
 hydraulic system 316
 hydrolysis 92, 238, 285, 306, 325, 453
 hygroscopic 83, 91, 175, 196, 205, 428, 453, 492

I

imbalance 103
 impact modifiers 83, 240
 impinge 344
 infrared (IR) 79
 injection compression 60
 injection fill velocity 181
 inserts 130, 417
 insulator 457, 460, 461, 467
 insulator caps 98
 insulator gaps 99, 162
 intensification ratio 171, 211, 348, 394, 487
 IR temperature gun 209
 IR thermal imaging 141
 is/is not 17
 ISO pipes 130

J

jetting 34, 145, 200, 341

K

Kistler Group 114
 knit lines 191, 322, 483
 knock-out bars 273, 363, 372

L

$L \cdot a \cdot b \cdot$ 215
 label 214, 230, 246
 labeling 204
 laminar flow 106, 128
 land length 149
 larger tonnage machine 293
 laser welding 298
 L/D 193
 L/D ratio 438
 leader pin 384

leakage 258
 leaking 244, 253, 395
 leaking hot runner manifolds 401
 letdown ratio 212, 317, 365, 424
 lifter 191, 237, 255, 287, 289, 360, 362, 386
 lifter pocket 378
 lifter read 375
 lifter rods 377
 linear thermal expansion 261
 line of draw 300, 350
 loaders 219, 432
 loading of pack 385
 load sensitivity 65
 lock angle 41
 locking angle 300
 lockout/tagout 21
 lockup 298, 305
 long flow lengths 265
 long glass fibers 321
 long glass-filled 406
 loop 309
 loss on weight 88, 428
 low back pressure 172
 low-gloss 339
 low-vestige-style hot tip 278
 low vestige tip 98, 398
 lubricants 186, 222, 244, 273, 365, 373, 433, 436

M

machine controllers 77
 machine hopper 219
 machine shutdown 136
 machine testing 63
 machining/cutter marks 370
 machining marks 361
 magnets 228, 282
 maintenance 72
 manifold 220
 marbling 207
 marring 386
 masterbatch 186, 424, 454
 material change 193, 201, 220
 material contamination 135
 material feed 252, 406, 427
 material leaking 413
 mechanical switches 45
 meld lines 310, 313, 322, 483
 melt consistency 279
 MeltFlipper® 106

melt flow index 240, 306
 melt front 276
 melt index 492
 melt probe 209, 321
 melt stream 171
 melt temperature 125, 148, 171, 180, 190, 200, 209, 233, 242, 251, 264, 273, 276, 296, 311, 321, 333, 348, 360, 369, 396, 415, 427, 457, 466, 474, 485
 metal 279
 metal inserts 228
 metallic flaked 491
 metallic flakes 317
 metal shavings 416
 microcellular foam 441
 microetching 48
 micro texture 333, 335
 milkiness 199
 mineral 260, 339
 mineral deposits 416
 minimum mold size 305
 mismatch 139, 164, 173, 193, 202, 203, 220, 223, 244, 289, 301
 miter locks 138
 mixing 209
 mixing elements 165
 mixing nozzles 210, 281, 403
 mixing screw 165, 211
 mixing style screws 210
 mixing tips 152, 210
 moisture 83, 88, 175, 184, 196, 205, 427, 462
 moisture analyzer 23, 88, 354, 428
 moisture content 238, 285, 316, 325, 354, 453
 mold breakaway speeds 235
 mold cleaner 161, 223
 mold cleaning 192, 222
 mold component deflection 376, 377
 mold cooling 253
 mold deflection 25, 295, 299
 mold design 173, 261, 265, 337, 344, 361, 362, 377, 380
 Moldflow® 331, 343
 mold inserts 161
 mold open speed 349
 mold release 355
 mold steel temperature 130
 mold surface 330
 mold surface finish 334
 mold surface temperatures 312

mold temperature 121, 122, 148, 201, 252,
255, 264, 321, 333, 359, 369, 377, 396, 414,
465, 471, 487
mold temperature control unit 124
molecular weight 92, 240, 284, 306, 317, 354
MuCell® 303
multicavity 103, 302, 352, 397
multimeter 22
multiple ejector strokes 272

N

nippers 383
nitrogen 423
nominal wall 464, 467, 470, 487
nominal wall stock 265, 270, 350, 380, 418,
489
non-return valve 66, 253, 257, 391, 395, 401,
413, 422, 438
nonuniform 209
nonuniform wall stock 265
nozzle 139, 152, 193, 223, 244, 402, 451, 460
nozzle adapter 223
nozzle drool 447
nozzle leak 404
nozzle lengths 282
nozzle orifice 244
nozzle temperature 148, 456
nozzle tip 173, 223, 256, 280, 395, 402, 413,
422, 430, 432, 435, 451, 455, 461
nozzle tip orifice 139, 403
nucleated 205, 424
nucleating agents 260, 273, 481
nucleation 374, 454
nylon 39, 83, 88, 91, 99, 175, 185, 186, 239,
282, 285, 298, 316, 325, 406, 427, 448, 453
nylon 6 322, 327
nylon tip 280

O

oil 192, 222
opaque 205, 468
operator 384
orientation 470, 481, 482, 491
orifice 99, 100
orifice gauge 152
outgassing 53, 196
overflow 59, 124, 322, 423, 491
overheated 209
overheating 80, 98, 194

over-packed 359
over-packing 348

P

pack 293
packaging 384, 481
packed 251
pack rate 117
part design 232, 270, 350, 371, 380, 386, 410
part design issues 265
part detail 371
part ejection temperature 130, 377, 380
parting line 290, 292, 296, 297, 350, 386,
395, 456, 478
parting line bearing surface 437
parting line flash 192
part out temperature 267, 369, 397
path of least resistance 393
Paulson, Don 29
PC/ABS 34, 83, 148, 153, 165, 211, 229, 243,
285, 427, 478
peak injection pressure 391
peak pressure 284
perimeter venting 437
perpendicular 393
piano black 334
pigments 215
pin deflection 361
pin marks 367
pin push 74, 270, 367, 371
pin read 375
pins 287
plastication 181, 183, 273, 285
plasticizers 197
plastic pressure 211
platen 299, 303
platen deflection 108, 299
platen parallelism 108
platen wrap 305
plate out 179, 397
plugged 279, 416
PMMA 175
poka-yoke 246
polish 202, 330, 331, 334
polished 50, 236
polishing 47, 298
polycarbonate 83, 137, 153, 175, 185, 339,
354, 364, 427, 435, 448, 453, 463
polyesters 83, 175, 238, 325, 354, 364, 427,
453

polyethylene 159, 245
 polypropylene 38, 92, 136, 150, 159, 201, 205,
 215, 245, 282, 351, 371, 378, 385, 437, 441,
 448, 474, 477, 481
 polystyrene 204
 poppet valve 414
 porous steel 58
 post-gate cavity pressure 412
 post-gate transducer 116
 post-mold handling 476
 post-molding 232
 post-mold shrinkage 251, 252
 PP 35, 212, 213
 PPO 185
 preload 300
 preloaded push pins 353
 pressure 78
 pressure differential 251
 pressure drop 105, 117, 150, 210, 254, 276,
 280, 331, 391, 415, 465, 474
 pressure-drop study 38, 39
 pressure gauge 283
 pressure limited 29, 38, 39, 88, 211, 275, 276,
 316, 320, 391
 pressure limiting 68
 pressure loss 34, 98
 pressure profile 411
 pressure relief valve 43, 304
 pressure response 296
 pressure-sensitive film 452
 preventative maintenance 439
 Priamus System Technologies 114
 process control 124, 438
 process monitoring 23, 73, 119
 process monitoring curves 391
 process monitoring system 78
 process window 233
 profile 243
 profiled first-stage fill velocity 343
 projected area 293, 302
 proximity switches 45
 pullers 370
 pull sink 420
 purge 93, 136, 352
 purging 167, 172, 193, 208
 purging compound 94, 204
 PVC 136, 159, 175, 196, 229, 243, 453
 pyrometer 22, 101, 108, 122, 377, 472

R

radius 232, 236, 418
 rapid mold heating 487
 rapid mold heating and cooling 333
 read-through 271, 330, 336, 375, 377, 378
 record grooves 309, 310
 recording 309
 recovery speeds 160
 regeneration heaters 86
 regrind 97, 142, 167, 183, 204, 227, 239, 273,
 282, 307, 317, 406, 462
 release 349
 release agents 186, 197, 240, 273, 354, 365,
 373, 454
 relief 54
 residence time 136, 159, 193, 196, 215, 233,
 243, 427, 431, 486
 resin remover 352
 restriction 282
 return air 86
 reverse-flow thermolator 173, 436
 Reynolds number 128
 ribs 359, 393
 rib to wall 410
 rib to wall ratio 470
 ring gate 37
 ring vent 433
 rippled surface 333
 RJG Decoupled® process 394
 RJG Decoupled III® process 406
 RJG Decoupled Molding® 294, 391, 412
 RJG eDART® 23, 76, 86, 115, 211, 252, 283,
 296, 422
 RJG Technologies 113, 124
 robot 80, 225, 234, 272, 364, 382, 477, 480
 root cause 1
 rubber gels 228
 rubber modifiers 339
 ruby stone 386
 runner 250, 254, 269, 278, 307, 323
 runner length 392

S

sand-blasted 330, 334, 335, 353
 sand/glass blast 334
 scale buildup 125, 416, 446
 scientific molding 30
 scrapes 289, 381
 scrap recording sheets 14

- scratch 310, 426
- scratch and mar 330
- scratches 381
- screw 139, 165, 175, 193, 209, 438
- screw design 437, 466, 486
- screw L/D 165
- screw recovery 209, 429
- screw recovery rate 334, 466
- screw recovery speed 171, 181, 415, 486
- screw rotate 267
- screw rotate delay 209
- screw rotate speed 276
- screw rotational speed 190
- screw speed 237
- scuffing 350
- scuffs 382
- second-stage pressure 233, 238, 248, 293, 294, 331, 359, 368, 376, 394, 411, 445, 465, 486
- second-stage time 250, 332, 411, 465
- second-stage velocity 315
- second-stage volume 294, 315
- self-locking cylinder 43
- semi-crystalline 99, 205, 252, 259, 260, 273, 279, 354, 359, 407, 415, 424, 438, 454, 475, 480
- sequentially valve gated 313
- sequential valve gates 97, 489
- sharp corners 232, 236
- shear 150, 160, 181, 190, 237, 243, 429, 431, 439
- shear imbalance 106
- shear rates 38, 105, 280, 397
- shear viscosity study 310
- short shot analysis 310
- short shots 53, 74, 103, 121, 170, 200, 282, 389, 395
- shot size 253, 258, 267, 391, 431
- shrink 234, 247, 255, 359, 411, 415, 418, 465, 467
- shrinkage 293, 470, 475
- shrink factor 261, 293
- shrinking 348, 349
- shrink on 270
- shrink rates 270, 424
- shutdown 193, 194
- shut off 44, 222, 292, 297, 299
- shutoff surfaces 138
- silo 214, 230, 246
- silver streaks 425
- sink 74, 103, 271, 293, 409, 414, 424, 464, 466
- sink index 479
- sintered metal 488
- sizing agents 326
- sleeves 371
- slides 44, 191, 237, 287, 289, 300, 362, 386
- sliding ring 258
- snapping 231
- solenoid 418
- solvents 235
- splay 53, 92, 93, 100, 122, 141, 193, 205, 217, 239, 425, 433, 435, 457
- spotted 378
- spotting blue 22
- spotty 329
- spreader tip 99, 202, 279
- sprue 151, 250, 254, 269, 278, 443
- sprue break 446
- sprue bushing 173, 223, 244, 395, 413, 446
- sprue bushing seat 162
- sprue opening 280
- sprue picker 384
- sprue puller 446, 448
- sprue sticking 435
- stalling 309, 313
- startup 396
- startup parts 312
- steel temperature 337, 349
- steel tools 298
- stick 233
- sticking 47, 74, 103, 192, 347, 353, 357, 359, 368, 370, 465, 477
- sticking on cover 347
- sticking on ejector 358
- STOP 4, 18, 233, 261, 270, 290, 292
- STOP analysis 298
- STOP method 151, 382, 390, 478
- STOP methodology 225, 313, 395
- STOP process 150, 349, 360, 385
- STOP troubleshooting 235, 239, 251, 254, 376
- straight lifters 361
- straight through sprue style 98
- stratification 241
- streakiness 199
- streaking 207, 239
- streaks 217
- stress 235, 470, 471
- stress concentrations 236
- stress risers 232
- string 462
- stringers 298, 455

stringing 172, 190, 271
 stuck plastic 399
 styrene-butadiene copolymer 204
 styrenic 212
 sub gate 35, 36, 110, 243, 287, 289, 420
 sub gated 371
 suicide/crash condition 44
 support pillars 299
 surface area 42
 surface finish 237
 switches 45
 systematic 3

T

talc 339, 474
 TCU 130
 Teflon thread tape 416
 temperature 78
 temperature control 437
 template 394, 465
 texture 47, 331, 334, 339, 353, 370, 385
 texture depth 350, 386
 thermal control 237
 thermal image 268, 337, 415
 thermal imaging 446, 473
 thermal imaging camera 25, 108, 267
 thermally stable 196
 thermocouple 85, 97, 101, 151, 171, 190, 400, 434
 thermocouples 78, 80, 113, 120, 160, 163, 237, 458, 460
 thermolator 108, 265, 321, 377, 466, 471, 473
 thermoplastic elastomers 50
 thermoplastic polyurethane 50
 thick wall sections 410
 thin sections 312
 thin wall 303, 313
 thin wall sections 265
 throughput 245
 tie bar 303, 304
 timing out 391
 TiO₂ 229
 tip radius 452
 toggle links 305
 toggle machine 295
 toggle wear 305
 tonnage 302, 489
 tonnage per square inch 302
 TPE 351, 453
 TPO 148, 153, 229, 339, 340

TPU 83, 92, 351, 352, 354, 364, 427, 429, 448, 453, 454
 tracer pellets 159
 training 352
 transfer 251, 332, 475
 transfer position 258, 294, 332, 391
 transfer pressure 311, 423
 transferring 277, 315
 transparent 175, 199, 468
 trapped plastic 298
 travel 237, 362
 trimming 385
 T-slot coupler 42, 44
 tuning 72, 76
 turbulent flow 128, 268, 363, 415
 turbulent water flow 472

U

unbalanced flow 313
 uncovered containers 245
 undercut 236, 290, 349, 353, 447
 uniformity 172
 uniform melt 209
 uniform nominal wall stock 248, 313
 unmelted 258
 unmelted pellets 279
 unmelts 169, 176, 282, 407
 unmelt test 407
 unsupported length 377
 UV stabilizers 186

V

vacuum 170, 183, 272, 349, 351, 463
 vacuum cups 225, 383
 vacuum venting 58
 valve gate 97, 98, 121, 255, 417, 459, 460
 valve gate control 124
 valve gating 489
 valve pin 202, 417
 valve pin actuation 313
 valve tuning 422
 vapor locks 414
 velocity 67
 velocity linearity 68, 324
 velocity to pressure response 421
 velocity to pressure transfer 74, 257, 296, 315, 394, 420, 490
 velocity to pressure transition 373
 vent 53, 179

vent depth 54, 298
venting 108, 172, 181, 188, 191, 266, 298, 311,
321, 322, 337, 393, 397, 432, 433, 485, 487
venting ejector pins 56
vent inserts 58
vent land 182
Venturi effect 173, 433, 437
viscosity 30, 189, 276, 284, 306, 317, 326,
405, 423, 462, 485, 492
voids 103, 169, 409, 445, 463
volatiles 176, 179, 196, 462
volume 40, 74
volumetric additive feeders 212
volumetric feeder 219
volumetric flow rate 251, 283, 323, 391

W

wall stock 147, 205, 254, 261, 279, 312, 336,
488
wall stock transition 336
wall thickness 254, 302, 475
Ward, Norm 63
warp 103, 252, 255, 265, 267, 469
water circuit 466
water diagrams 108, 337
water flow 125, 129, 414, 416, 446

water flow rate 473
water leaks 102, 202
water line 173
water line layout 129
water temperature 129, 446, 473
water treatment 416
wear 221, 258, 267, 413
wear plates 138, 222
weld line 53, 59, 483
weld line plot 484
wet 439
white imprints 367
white streaks 199
witness line 315
wood-filled 339
worm tracks 341
worn barrel 403

X

X-ray inspection 468

Z

Zapox 202, 352
zero draft 350
zinc stearate 355, 374