

Content Overview

1	Introduction	1
2	Your Own CNC Router	43
3	Milling Tools	139
4	2D Milling in Practice	157
5	Machine Upgrades	193
6	Advanced Milling Techniques	233
7	Looking Ahead	265
	Glossary	269
	Index	277

Table of Contents

1	Introduction	1
1.1	What Is Milling?	2
1.2	Gantry Milling for Hobbyists	6
1.2.1	The Machine Table	8
1.2.2	The Milling Motor	9
1.2.3	Feed Rate	12
1.2.4	All About Milling Tools.	15
1.2.5	Features and Add-ons	21
1.3	Raw Materials.	31
1.4	CNC Milling	31
1.4.1	CAD	32
1.4.2	CAM.	35
1.4.3	Machine Control Systems	38
1.5	Alternatives to Milling.	39
1.6	Personal Safety and Risks	40
1.6.1	Motor and Cutters	40
1.6.2	Electricity	41
1.6.3	Fire Hazards	41
1.6.4	Hazardous Materials.	41
1.6.5	Safety in the Workplace.	42
2	Your Own CNC Router	43
2.1	Choosing the Machine for this Book	45
2.1.1	Inventables X-Carve	48
2.1.2	Stepcraft-2/600	49
2.1.3	Other Models	51
2.1.4	Making a Decision	52
2.2	Assembling the Kit	53
2.3	Step 1: Assembling the X-Z Connector	56

Table of Contents

2.4	Step 2: Mounting the Z Axis	68
2.5	Step 3: Assembling the X Lead Screw and the Sides of the Gantry . . .	74
2.6	Step 4: Assembling the Gantry	82
2.7	Step 5: Assembling the Main Frame	89
2.8	Step 6: Final Mechanical Assembly	99
2.9	Step 7: Installing the Electronics	102
2.10	Step 8: Assemble the Machine Table (5 minutes)	110
2.11	Step 9: Installation and Startup (30 minutes)	111
2.11.1	Grease the Rails and the Lead Screws	111
2.11.2	Install the Software	112
2.11.3	Prepare to Align the Lead Screws	113
2.11.4	Connect Your Machine	113
2.11.5	Align the Lead Screws	115
2.12	Alternative Software	117
2.12.1	Installing the Hardware	118
2.12.2	Installing and Configuring UCCNC	121
2.12.3	Running a Test Job	126
2.13	Your First Workpiece	131
3	Milling Tools	139
3.1	Milling Tools	140
3.1.1	Teeth and Flutes	141
3.1.2	Cutting Length and Shank Types	142
3.1.3	End Mill Materials	143
3.1.4	Cutting Speed and Feed Rate	144
3.1.5	Cooling and Lubrication	148
3.2	Which Tool for Which Material?	151
3.2.1	Solid Carbide End Mills	151
3.2.2	Unusual Types of Cutters	153
3.2.3	Long Mills	154
3.2.4	Forming Cutters	154
3.3	Upcut and Downcut Milling	155
3.4	Tool Maintenance	155

4	2D Milling in Practice	157
4.1	Clamping the Workpiece	160
4.2	Softwood.....	162
4.2.1	Example #1: MDF.....	163
4.2.2	Example #2: Poplar Plywood (using inappropriate parameters).....	164
4.2.3	Example #3: Poplar Plywood (using appropriate parameters).....	166
4.3	Hardwood.....	168
4.3.1	Example #1: Solid Beech (right-hand spiral)	168
4.3.2	Example #2: Solid Beech (left-hand spiral)	169
4.4	Perspex and Polycarbonates	170
4.4.1	Example #1: Perspex.....	171
4.5	Extruded Foam	173
4.5.1	Example #1: PVC	173
4.6	Engraving Plastic.....	175
4.6.1	Example #1: Engraving Plastic	176
4.7	Aluminum	177
4.7.1	Example #1: Aluminum.....	178
4.7.2	Example #2: Facing an Aluminum Blank.....	181
4.8	Brass	183
4.8.1	Example #1: Brass.....	184
4.9	Aluminum Dibond	186
4.9.1	Example #1: Aluminum Dibond	187
4.10	Glass.....	189
5	Machine Upgrades	193
5.1	Enclosure.....	194
5.2	Vacuum System	199
5.2.1	Centrifugal (Cyclone) Separator	200
5.2.2	Vacuum and Connectors	201
5.2.3	Dust Extraction in the Enclosure and at the Tool	202
5.3	Aluminum T-slot Machine table	206
5.4	Clamps and Clamping Blocks	207

Table of Contents

5.5	Machine Vise	212
5.6	Tool Length Sensor	214
5.6.1	Fitting a Tool Length Sensor	215
5.6.2	Configuring the Tool Length Sensor in WinPC-NC	216
5.6.3	Using and Adjusting the Sensor	219
5.6.4	Using the tool length sensor with UCCNC	220
5.7	Underwater Milling Using a Water Bath	225
5.8	Additional Emergency Stop Button	229
6	Advanced Milling Techniques	233
6.1	Isolation Milling	234
6.1.1	How to Configure Eagle	237
6.1.2	Milling a PCB Using WinPC-NC USB	242
6.2	Underwater Milling	245
6.3	2.5D Milling	249
6.3.1	CAD	250
6.3.2	CAM	253
6.3.3	Milling	259
6.3.4	Slots, Pockets, and Facing	262
7	Looking Ahead	265
7.1	Replacement Parts	266
	Glossary	269
	Index	277