Contents

Preface —— VII

Acknowledgements —— IX

1 Introduction —— 1
1.1 The big picture —— 1
1.2 Introduction to injection moulding —— 1
1.3 The injection moulding process —— 3
1.3.1 Piston injection unit —— 4
1.3.2 Reciprocating screw machine —— 5
1.3.3 Breaking down the injection moulding cycle —— 7
1.3.3.1 Plastication —— 7
1.3.3.2 Filling —— 7
1.3.3.3 Packing and Solidification —— 8
1.4 Comparison with other moulding methods —— 8
1.4.1 Extrusion —— 8
1.4.2 Compression moulding —— 10
1.4.3 Transfer moulding —— 10
1.4.4 Blow moulding —— 11
1.4.5 Film blowing —— 13
1.4.6 Injection-compression —— 14
1.4.7 Additive manufacturing —— 15
1.5 Conclusion —— 16
Suggested further reading —— 16

2 Introduction to plastics —— 19
2.1 Introduction —— 19
2.2 Structure and typical properties of polymers —— 21
2.3 Formation of macromolecules —— 23
2.4 Molecular weight —— 24
2.5 Plastics —— 24
2.5.1 Thermoplastic —— 25
2.5.2 Thermosets —— 26
2.5.3 Elastomers —— 27
2.5.3.1 Thermoplastic elastomers —— 27
2.5.4 The formulation of plastics —— 29
2.5.5 The binding structure of plastics —— 30
2.6 The effects of processing on thermoplastics —— 30
2.6.1 Rheology —— 31
2.6.2 Heat and heat transfer —— 32

2.6.3 Physical and chemical change — 32
2.6.4 Fountain flow — 33
2.7 Conclusion — 35
Reference — 35

3 Injection moulding machinery — 37
3.1 Injection units — 38
3.2 Piston (plunger) injection unit — 38
3.3 Reciprocating screw injection unit — 39
3.3.1 Shot capacity — 40
3.3.2 Plasticising capacity — 40
3.3.3 The feeding hopper — 40
3.3.4 The injection cylinder — 41
3.4 Selection of the injection unit — 41
3.5 Length/diameter ratio — 43
3.5.1 Mixing screws for additives and fast cycling machines — 46
3.5.1.1 Mixing elements — 46
3.5.1.2 Extended plasticising cylinder — 46
3.5.2 Non-return valve — 48
3.6 General information on wear and tear — 48
3.7 Unit hardening treatment — 49
3.8 The nozzle — 49
3.9 Clamping units — 51
3.9.1 Differential piston system — 56
3.9.2 Mould weights — 57
3.10 Selection of the clamping unit — 57
3.11 Mould clamping force — 59
3.11.1 Mould clamping force level — 59
3.11.2 Mould clamping force and mould rigidity — 60
3.11.3 Setting mould closing and clamping force — 61
3.11.3.1 The clamping force — 61
3.11.3.2 Second clamping force — 61
3.12 Data for mould closing — 62
3.13 Other considerations — 64
3.14 International standard for the designation of injection moulding machines — 65
3.15 Injection moulding machine: drive technology — 67

4 Injection mould tooling basics — 69
4.1 Types of moulds — 69
4.1.1 Two-plate mould — 69
4.1.2 Stripper mould — 69

4.1.3 Slide mould — 69
4.1.4 Three-plate mould — 70
4.2 The feed system — 72
4.2.1 Introduction — 72
4.2.2 The runner — 72
4.2.3 Runner shape — 74
4.2.4 Runner layout — 75
4.2.4.1 Standard-runner — 75
4.2.4.2 Cold-runner — 76
4.2.4.3 Hot-runner — 76
4.3 Gate design — 81
4.3.1 Sprue gate — 81
4.3.2 Restricted gate — 81
4.3.3 Side or edge gate — 82
4.3.4 Flash gate — 83
4.3.5 Fan gate — 83
4.3.6 Tab gate — 84
4.3.7 Diaphragm gate — 85
4.3.8 Spider gate — 85
4.3.9 Ring gate — 85
4.3.10 Hot tip gating — 86
4.4 Mould temperature control — 87
4.5 Ejection systems — 90
4.6 Venting — 92
4.7 Conclusion — 92
Suggested further reading — 93

5 Process control systems — 95
5.1 Introduction — 95
5.2 Explanation of the different concepts in control and regulation technology — 95
5.2.1 Hydraulic or electric systems? — 95
5.2.1.1 Pump — 95
5.2.2 Motor — 96
5.2.3 Cylinder — 96
5.2.4 Directional valves — 96
5.2.5 Pressure valves — 98
5.2.6 Flow-regulator valves — 100
5.2.7 Location and setting of proportional valves — 100
5.2.7.1 Valve bodies — 101
5.2.7.2 Function of the volume proportional valve — 101
5.2.7.3 Function of the pressure proportional valve — 102

5.2.8 Check valves — 103
5.2.9 Receivers — 103
5.3 General information regarding control units, regulators, position regulation and injection process regulation — 104
5.3.1 Control unit — 104
5.3.2 Regulator — 105
5.3.3 Screw with position regulator — 105
5.3.4 Injection process regulation — 106
5.4 Electrical systems — 109
5.5 Hybrid machines — 111
5.6 The user interface — 112

6 Amorphous and semi-crystalline thermoplastics — 115
6.1 Introduction — 115
6.2 Amorphous plastics — 116
6.2.1 Overview and common properties — 117
6.2.2 Standard polystyrene homopolymer — 117
6.2.3 Styrene copolymers — 119
6.2.4 Modified polyphenylene oxide — 120
6.2.5 Polyvinyl chloride — 121
6.2.6 Cellulose materials — 123
6.2.7 Polymethyl methacrylate — 123
6.2.8 Polycarbonate — 124
6.2.9 Polyacrylates — 128
6.2.10 Polysulfones — 129
6.2.11 Polyetherimide — 130
6.2.12 Polyamide imide — 132
6.3 Semi-crystalline plastics — 132
6.3.1 Overview and common properties — 133
6.3.2 Polyethylene — 136
6.3.3 Polypropylene — 136
6.3.4 Polyamides — 138
6.3.5 Polyacetals — 139
6.3.6 Polyterephthalates (linear polyesters) — 142
6.3.7 Polyphenylene sulfide – typical characteristics and applications — 143
6.3.8 Polyfluorolefins — 144
6.3.9 Polyacrylic acid and polyarylamide — 146
6.3.10 Polyacryl and ether ketones — 148
6.3.11 Liquid crystalline polymers — 149
6.4 Conclusion — 152

7 Processing thermoset, liquid silicone rubber and ceramic materials — 153
7.1 Thermosets — 153
7.1.1 Overview and common properties — 153
7.1.2 Materials for screw injection moulding machines — 154
7.1.3 Processing procedures for thermoset plastics — 156
7.1.3.1 Compression moulding — 156
7.1.3.2 Injection moulding — 156
7.1.4 Screw injection machines for thermosets — 157
7.1.5 Mould — 158
7.1.6 Guide values for cylinder and mould temperature settings — 158
7.1.7 The injection unit for granulated thermosets — 160
7.1.8 The injection unit for processing moist polyester — 160
7.1.9 Nozzle temperature (if Nozzle Heating is Applied) — 161
7.1.10 Common thermoset materials: Properties and applications — 161
7.1.10.1 Phenol formaldehyde compounds — 161
7.1.10.2 Urea formaldehyde compounds — 162
7.1.10.3 Melamine formaldehyde compounds — 163
7.1.10.4 Unsaturated polyester — 164
7.1.10.5 Epoxide compounds — 165
7.2 Elastomer injection moulding compounds — 167
7.2.2 Processing procedures for elastomeric materials — 167
7.2.2.1 Compression moulding — 167
7.2.2.2 Injection moulding — 167
7.2.2.3 Injection moulding machines for rubber compounds — 168
7.2.2.4 Peripheral device — 168
7.2.2.5 Mould — 168
7.2.3 Silicone elastomers – liquid silicone rubber systems — 168
7.2.3.1 Classification — 169
7.2.3.2 Crosslinking — 170
7.2.3.3 Processing of two-component liquid silicone rubber — 170
7.2.3.4 Advantages of processing liquid silicone rubber materials — 171
7.2.3.5 Injection process — 171
7.2.3.6 Configuration of injection moulding machines and processing data — 171
7.2.3.7 Specific properties — 173
7.2.3.8 Crosslinking reaction — 173
7.2.3.9 Structural viscosity — 174
7.2.3.10 Vulcanisation — 176
7.2.3.11 Internal mould pressure — 176
7.2.3.12 Shrinkage — 176
7.2.3.13 Tempering — 176

7.2.3.14 Preparation of liquid silicone rubber — **177**
7.2.4 Processing components for liquid injection moulding — **177**
7.2.4.1 Dosing equipment for liquid silicone rubber — **177**
7.2.4.2 Machine technology — **180**
7.2.4.3 Injection unit — **182**
7.2.4.4 Cylinder module — **182**
7.2.4.5 Non-return valve — **181**
7.2.4.6 Auxiliary heating control circuits — **182**
7.2.4.7 Interface for brush and cleaner units — **182**
7.2.4.8 Handling interface — **182**
7.2.4.9 User-programmable inputs/outputs — **183**
7.2.4.10 Air blast equipment with pressure reducer — **183**
7.2.4.11 Control unit for vacuum pump — **183**
7.2.4.12 Hydraulic/pneumatic cold-runner control — **183**
7.2.4.13 Protective screens made of polycarbonate — **183**
7.2.4.14 Simple cold-runner nozzle — **183**
7.2.4.15 Cold-runner head — **184**
7.2.4.16 Mould technology — **185**
7.2.5 Application of liquid silicone rubber parts in food production — **190**
7.2.6 Summary — **191**
7.3 Processing of ceramic and metal powder materials — **193**
7.3.1 Introduction — **193**
7.3.2 Binder — **194**
7.3.3 Processing — **195**
7.3.3.1 Compression moulding — **195**
7.3.3.2 Injection moulding — **196**
7.3.4 Configuration of injection moulding machines — **196**
7.3.4.1 Peripheral devices — **196**
7.3.4.2 Mould — **196**
7.3.4.3 Wear — **197**
7.3.5 Process requirements — **197**
7.3.5.1 Debinding and sintering — **197**
7.4 A growing market for moulders — **197**
Further reading — **199**
Reference — **199**

8 Guide values and processing instructions for the most important thermoplastic injection moulding compounds — 201
8.1 Predrying material — **201**
8.2 Examples of the moulding parameters of selected materials — **201**
8.3 Parameters of the injection moulding process and the quality of moulded parts — **202**

8.4 Injection and mould cavity pressure — 207
8.5 Injection pressure and injection time — 211
8.6 General information on filling speed — 211
8.6.1 Initial injection speed — 211
8.7 Filling speed and orientation — 212
8.8 Effects of excessive filling speed — 213
8.9 Setting the initial injection speed — 214
8.10 Plasticising — 215
8.10.1 Compound temperature – general information — 215
8.10.2 Cylinder temperatures — 216
8.10.3 Nozzle temperature — 217
8.10.4 Temperature profile guideline for the plasticising cylinder — 218
8.10.4.1 Horizontal — 218
8.10.4.2 Ascending — 218
8.10.4.3 Descending — 219
8.10.4.4 Ascending and descending at the nozzle — 219
8.10.5 Temperatures for the cylinder and mould — 219
8.10.6 Measuring the compound temperature — 222
8.10.7 Screw speed — 223
8.10.8 Back pressure — 223
8.11 The injection stage — 226
8.11.1 Filling to packing — 226
8.11.2 The mould — 226
8.11.2.1 Mould temperature: general information — 226
8.11.2.2 Mould temperature levels — 229
8.11.2.3 Uniformity of mould temperatures — 229
8.11.2.4 Mould temperature patterns — 230
8.11.2.5 Temperature control devices — 231
8.11.2.6 Matching temperature control units and mould maintenance — 233
8.11.2.7 Measuring the mould temperature – checking the uniformity of the mould temperature control — 234
8.12 Recommended values for holding pressure time and remaining cooling time — 234
8.13 Cycle time — 235
8.14 Setting the injection moulding machine — 236

9 Practical applications using injection moulding technology — 239
9.1 Introduction — 239
9.2 Troubleshooting and guidance — 239
9.2.1 Detection and classification of defects — 240
Physical Cause — 241
9.2.2 Flow diagrams for troubleshooting — 241

9.2.3 Sink marks — 262
Physical cause — 262
Correcting sink marks — 262
9.2.4 Streaks — 262
Signs of burnt streaks — 263
Signs of moisture streaks — 264
Signs of air streaks — 266
9.2.4.1 Burnt streaks (brown or silver) — 266
9.2.4.1.1 Physical cause — 266
9.2.4.1.2 Correcting burnt streaks (brown or silver) — 266
9.2.4.2 Moisture streaks — 266
9.2.4.2.1 Physical cause — 266
9.2.4.2.2 Possible causes for moisture streaks — 267
9.2.4.2.3 Correcting moisture streaks — 267
9.2.4.3 Colour streaks — 267
9.2.4.3.1 Physical cause — 267
9.2.4.3.2 Correcting colour streaks — 268
9.2.5 Air streaks/air hooks — 268
Physical cause — 268
Correcting air streaks/air hooks — 269
9.2.6 Glass fibre streaks — 269
Physical cause — 269
Correcting glass fibre streaks — 269
9.2.7 Gloss/gloss differences — 269
Physical cause — 269
Correcting gloss/gloss differences — 270
9.2.8 Weld line (visible notch or colour change) — 270
Physical cause — 270
Improving a weld line (visible notch or colour change) — 273
9.2.9 Jetting — 273
Physical cause — 273
Correcting jetting — 274
9.2.10 Diesel effect (burns) — 275
Physical cause — 275
Correcting the diesel effect (burns) — 276
9.2.11 Record grooves effect — 276
Physical cause — 276
Correcting the record grooves effect — 278
9.2.12 Stress whitening/stress cracks — 278
Physical cause — 278
Correcting stress whitening/stress cracks — 279

9.2.13 Incompletely filled parts — 279
Physical cause — 279
Correcting incompletely filled parts — 280
9.2.14 Oversprayed parts (flashes) — 280
Physical cause — 280
Correcting oversprayed parts (flashes) — 281
9.2.15 Visible ejector marks — 281
Physical cause — 282
Correcting visible ejector marks — 282
9.2.16 Deformation during demoulding — 282
Physical cause — 283
Correcting deformation during demoulding — 284
9.2.17 Flaking of the surface layer — 284
Physical cause — 285
Correcting flaking of the surface layer — 285
9.2.18 Cold slugs/cold flow lines — 285
Physical cause — 285
Correcting cold slug/cold flow lines — 286
9.2.19 Entrapped air (blister formation) — 287
Physical cause — 287
Correcting entrapped air (blister formation) — 287
9.2.20 Dark spots — 287
Physical cause — 287
Correcting dark spots — 288
9.2.21 Dull spots near the sprue — 288
Physical cause — 288
Correcting Dull Spots Near the Sprue — 289
9.3 Data acquisition record — 289
9.3.1 Using the data acquisition record — 289
9.3.2 Data acquisition record for optimising moulded parts — 290
9.3.2.1 Moulded part data — 290
9.3.2.2 Machine settings and defect evaluation — 291
9.4 Experiences with injection moulded components — 295
9.4.1 Threaded connecting sleeves for ink-drafting apparatus — 295
9.4.2 Meter cases — 295
9.4.3 Wristwatch glass — 296
9.4.4 Alarm clock glass — 297
9.4.5 Glass cover for a digital gauge — 297
9.4.6 Plug boards with insert pins — 299
9.4.7 Hair slides — 299
9.4.8 Toothbrush components — 300
9.4.9 Screw cap with conical nipple — 302

9.4.10 Switch housing — 302
9.4.11 Battery housing — 304

10 Advanced processing techniques — 305
10.1 Introduction — 305
10.2 Multicomponent moulding — 305
10.2.1 Co-injection moulding — 305
10.2.2 Bi-Injection moulding — 305
10.2.3 Interval injection moulding — 307
10.2.4 Injection moulding/additive manufacturing hybrid processes — 307
10.3 Assisted moulding — 308
10.4 Multi-Shot moulding — 308
10.5 Over-moulding — 308
10.6 Micromoulding — 308
10.7 Business trends — 309
10.8 Material selection — 311
10.9 Process technology — 315
10.9.1 Multicomponent injection moulding — 315
10.9.2 co-injection moulding — 315
10.9.2.1 Material selection for co-injection moulding — 317
10.9.2.2 Process sequence — 318
10.9.2.3 Co-injection moulding: different techniques — 318
10.9.2.4 Part design and tooling requirements for co-injection moulding — 324
10.9.2.5 Rheology and mould filling: why and how co-injection moulding works — 325
10.9.2.6 Setting optimum parameters — 328
10.9.2.7 Co-Injection moulded application case studies — 329
10.9.2.8 Recycling and legislation — 329
10.9.2.9 Discussion and conclusions — 330
10.9.3 Bi-Injection — 330
10.9.4 Interval injection moulding — 331
10.10 Assisted moulding — 332
10.10.1 Gas injection moulding technology — 332
10.10.2 Process technology — 333
10.10.3 Patent situation — 333
10.10.4 Advantages and disadvantages of gas injection moulding technology — 333
10.10.5 Process Variations in the application of gas injection moulding technology — 335
10.10.5.1 Gas injection through the machine nozzle — 335
10.10.5.2 Gas injection through an injector module in the mould — 336

10.10.5.3 Gas injection in the moulded part — **336**
10.10.5.4 Melt blow moulding technology — **337**
10.10.5.5 Melt back pressure technology/gas injection in the moulded part — **337**
10.10.5.6 Melt extrusion technology/gas injection in the moulded part — **338**
10.10.5.7 Core pull technology — **338**
10.10.5.8 Systems technology for the implementation of gas injection moulding technology — **342**
10.10.5.9 Configuration guidelines for gas injection moulding technology — **343**
10.10.6 KoolGas™ — **345**
10.10.7 Water-assisted injection moulding process — **346**
10.11 Multi-shot moulding — **346**
10.11.1 Machine technology — **348**
10.11.1.1 Injection unit configurations — **348**
10.11.2 Core back moulding — **349**
10.11.3 Rotating tool — **352**
10.11.4 Transfer moulding — **353**
10.11.5 Multi-shot using a single injection unit — **355**
10.11.6 Materials for multi-shot moulding — **357**
10.11.6.1 Material selection for multi-shot moulding — **357**
10.11.6.2 Material process order — **358**
10.11.6.3 Using thermoset materials — **358**
10.11.6.4 Liquid silicone rubber — **358**
10.11.6.5 Thermoplastic elastomers — **359**
10.11.7 Multi-shot application case studies — **360**
10.11.7.1 Trio knob — **360**
10.11.7.2 Stanley screwdriver — **361**
10.11.8 Limitations to multi-shot — **362**
10.12 Over-moulding — **362**
10.12.1 Insert moulding — **362**
10.12.2 Lost core moulding — **363**
10.13 A final word on energy efficiency — **364**
10.14 The future? — **365**
References — **365**
Further reading — **366**

Abbreviations — 367

Appendix — 369

Index — 373