

Contents

A Personal Foreword VII

Preface to the First Edition XIII

Acknowledgment XV

1	Introduction	1
1.1	Motivation	1
1.2	Definition of Optical Pump and Probe	4
1.3	Guideline	4
1.4	Matrix of Laser Effects and Applications	5
1.5	Historical Survey of Optical Ultra-fast Metrology	6
1.5.1	Metrology Techniques Before the Advent of Laser	6
1.5.2	Ultra-fast Pump and Probe Metrology	7
2	Ultra-fast Engineering Working Tools	11
2.1	Ultra-fast Laser Sources	11
2.1.1	General Aspects for Ultra-precise Engineering	12
2.1.2	General Aspects on Ultra-fast Lasers for Ultra-fast Metrology	13
2.1.3	Laser Oscillator	15
2.1.3.1	Rod and Disk Solid-State Laser	15
2.1.3.2	Fiber Oscillator	16
2.1.4	Amplifier	18
2.1.4.1	Amplification Media	18
2.1.4.2	Chirped-Pulse Amplification (CPA)	18
2.1.4.3	Optical Parametric Chirped-Pulse Amplification (OPCPA)	19
2.1.4.4	Amplifier Designs	20
2.1.4.5	Commercial Systems	24
2.1.5	Facilities	25
2.2	Focusing of Ultra-fast Laser Radiation	26
2.2.1	Ultra-small Laser Focus	26
2.2.2	Gaussian Beam	27
2.2.3	Beam Parameters of Gaussian Radiation	29
2.2.4	Pulse Duration	32
2.2.5	Beam Stability	34

2.2.6	Key Parameters for Ultra-precision Machining and Diagnostics	35
2.2.6.1	Ultra-precise Machining	35
2.2.6.2	Ultra-fast Pump and Probe Diagnostics for Mechanical Engineering	36
2.3	Beam Positioning and Scanning	36
2.3.1	Positioning	37
2.3.2	Scanning Systems	39
2.4	New Challenges to Ultra-fast Metrology	41
2.4.1	Temporal Domain	42
2.4.2	Spatial Domain	42
2.5	Domains of Optical Pump and Probe Techniques for Process Diagnosis	43
3	Fundamentals of Laser Interaction	45
3.1	Linear to Non-linear Optics	45
3.1.1	Linear Optics: Group Velocity Dispersion and Chirp	45
3.1.2	Non-linear Processes	48
3.1.2.1	Non-linear Polarization	48
3.1.2.2	Self-focusing	49
3.1.2.3	Spectral Broadening by Self-phase Modulation	51
3.1.2.4	Catastrophic Self-focusing	53
3.2	High-Power Photon–Matter Interaction	54
3.2.1	Absorption of Laser Radiation in Matter	54
3.2.2	Energy Transfer from Electrons to Matter	56
3.2.3	Melting and Vaporization	58
3.2.4	Melt Dynamics	60
3.2.5	Onset of Ablation	62
3.2.6	Ionization	63
3.3	Matching of Plasma Dynamics on Ultra-fast Time-Scale	64
3.3.1	Absorption of Radiation in a Plasma	64
3.3.1.1	Electromagnetic Waves in Plasmas	64
3.3.1.2	Inverse Bremsstrahlung	66
3.3.2	Plasma Heating	69
3.3.3	Ionization of a Plasma	72
3.3.3.1	Cross-Section and Collision Frequency	73
3.3.4	Electron Transitions and Energy Transport	74
3.3.4.1	The Total Emission	76
3.3.4.2	The Opacity	76
3.3.5	Dielectric Function of a Plasma	77
3.3.6	Ponderomotive Force	78
4	Fundamentals of Pump and Probe	81
4.1	Ultra-fast Laser Radiation	81
4.1.1	Beam Propagation	82
4.1.2	Dispersion	82
4.1.3	Coherence	83

4.2	Preparation of States and Conditions for Probe Beams	85
4.2.1	Preparation of States	86
4.2.2	Preparation of States by Spectro-Temporal Shaping	86
4.2.3	Measurement of States	88
4.2.4	Measurement of Radiation Properties	89
4.2.4.1	Pulse Duration	89
4.2.4.2	Spectral Phase	90
4.3	Imaging with Ultra-fast Laser Radiation	91
4.3.1	Diffraction Theory and Incoherent Illumination	91
4.3.2	Image Formation by Microscopy and Coherent Illumination	95
4.4	Temporal Delaying	97
4.4.1	Mechanical Delay	98
4.4.1.1	Single-Pass Delay Stage	98
4.4.1.2	Multi-Pass Delay Stage	99
4.4.1.3	Mechanical Optoelectronic Scanning	101
4.4.2	Non-mechanical Delay	101
4.4.2.1	Free-Running Lasers	102
4.4.2.2	Synchronized Lasers	103
5	Examples for Ultra-fast Detection Methods	105
5.1	Non-imaging Detection	106
5.1.1	Transient Absorption Spectroscopy (TAS)	106
5.1.1.1	Principle and Setup	106
5.1.1.2	Characterization of the White-Light Continuum	108
5.1.1.3	Measurement by TAS	112
5.1.2	Temporal Shaped Pulses	113
5.1.2.1	Principle and Setup	113
5.1.2.2	Characterization of the Si-K α -Radiation Source	115
5.2	Imaging Detection	118
5.2.1	Non-coherent Methods	119
5.2.1.1	Shadowgraphy	119
5.2.1.2	Transient Quantitative Phase Microscopy (TQPm)	120
5.2.2	Coherent Methods	124
5.2.2.1	Mach-Zehnder Micro-Interferometry	124
5.2.2.2	Speckle Microscopy	127
5.2.2.3	Nomarsky Microscopy	129
6	Applications of Pump and Probe Metrology	133
6.1	Drilling of Metals	134
6.1.1	Introduction	134
6.1.2	Measurement of Ejected Plasma, Vapor and Melt	134
6.2	Microstructuring of Metals	137
6.2.1	Introduction	137
6.2.2	Detection of Plasma Dynamics	138
6.3	Marking of Glass	140
6.3.1	Introduction	140

6.3.2	Detection of Laser-Induced Defects	141
6.3.3	Detection of Refractive-Index Changes and Cracking	143
6.4	Welding of Technical Glasses and Silicon	145
6.4.1	Introduction	145
6.4.2	Detection of Laser-Induced Melting	146
7	Perspectives for the Future	151
7.1	Laser and Other Sources	152
7.2	Methodology	153
7.2.1	Scanning Technology	153
7.2.1.1	Spatial Scanning	153
7.2.1.2	Temporal Scanning	153
7.2.2	Beam Shaping	153
7.2.2.1	Spatial Shaping	153
7.2.2.2	Temporal Shaping	154
8	Summary	155
Appendix A Lock-in Amplifier		159
Appendix B Onset on Optics		161
B.1	Abbe Sine Condition	161
B.2	Quantitative Phase Microscopy	162
Appendix C Plasma Parameters		165
C.1	Transport Coefficients	165
C.1.1	Electrical Conductivity	165
C.1.2	Thermal Conductivity	165
C.1.3	Diffusivity of Electrons	166
C.1.4	Viscosity	167
C.2	Debye Length	168
C.3	Plasma Oscillations and Waves	169
C.4	Coupling Between Electrons and Ions	171
C.5	Hydrodynamic Instabilities	172
Appendix D Facilities		173
Appendix E List of Abbreviations and Symbols		177
E.1	Abbreviations	177
E.2	Symbols	178
References		183
Glossary		195
Index		199