

Contents

Optics for Engineers

Daniel Malacara-Hernández	1
1. Introduction	1
2. Geometrical Optics Principles	1
2.1. Fermat's Principle and the Law of Refraction	1
2.2. First-Order Optics	3
2.3. Aberrations	7
3. Wave-Optics Fundamentals	12
3.1. Young's Double Slit	12
3.2. Michelson Interferometer	13
3.3. Coherence and Light Sources	14
4. Main Interferometers Used in Optical Engineering	15
4.1. Fizeau Interferometer and Newtons Rings	16
4.2. Twyman-Green Interferometer	19
4.3. Ronchi and Lateral-Shear Interferometers	22
4.4. Talbot Interferometer and Moiré Deflectometry	26
4.5. Foucault Test and Schlieren Techniques	27
4.6. Two-Wavelength Interferometry	28
4.7. Holographic Principles	29
5. Summary	31
References	31

Introduction to Engineering Mechanics

Anand Asundi	33
1. Introduction	33
2. Basic Concepts	34
2.1. Stress	34
2.2. Stress Transformation	35
2.3. Stress Transformation Using Mohr's Circle	36
2.4. Displacement and Strain	37
2.5. Strain Transformation	39
2.6. Stress-Strain Relations	40
2.7. Boundary Conditions	41
3. Theory of Elasticity Approach	42
3.1. Plane Stress Formulation	44
3.2. Plane Strain Formulation	45

4. Strength of Materials Approach	46
5. Examples	47
5.1. Axial Loading	47
5.2. Bending of Beams	49
5.3. Combined Bending and Axial Load	52
6. Conclusion	53
Further Reading	54

Fringe Analysis

Yves Surrel	55
1. Introduction	55
2. Phase Evaluation	57
2.1. Local and Global Strategies	57
2.2. Local Phase detection	58
2.3. Global Phase Detection	77
2.4. Residual Phase Errors	81
2.5. Effect of Additive Noise	84
3. Phase Unwrapping	86
3.1. Spatial Approach	87
3.2. Temporal Approach	89
4. Conclusion	94
References	99

Principles of Holographic Interferometry and Speckle Metrology

Pramod K. Rastogi	103
1. Holographic Interferometry	103
1.1. Types of Holographic Interferometry	104
1.2. Thermoplastic Camera	107
1.3. Mapping of the Resolved Part of Displacement	109
1.4. Determination of the Wavefront Phase Using Phase-shifting Interferometry	110
1.5. Out-of-plane Displacement Measurement	111
1.6. In-plane Displacement Measurement	112
1.7. Holographic Shearing Interferometry	115
1.8. Comparative Holographic Interferometry	117
1.9. Vibration Analysis	119
2. Speckle Metrology	124
2.1. Focused Speckle Photography	125
2.2. Defocused Speckle Photography	128
2.3. Speckle Shearing Photography	129
2.4. Speckle Interferometry	131
2.5. Speckle Shearing Interferometry	140

3. Conclusions	145
References	145

Moiré Methods for Engineering and Science – Moiré Interferometry and Shadow Moiré

Daniel Post, Bongtae Han, and Peter G. Ifju	151
---	-----

1. Introduction	151
2. Moiré Interferometry	152
2.1. Basic Concepts	152
2.2. Equipment	156
2.3. Specimen Gratings	157
2.4. Bithermal Loading (Isothermal Loading)	158
2.5. Fringe Counting	158
2.6. Strain Analysis	160
2.7. Carrier Fringes	160
2.8. Out-of-Plane Deformation	162
3. Advanced Techniques in Moiré Interferometry	164
3.1. Microscopic Moiré Interferometry	164
3.2. Curved Surfaces	166
3.3. Replication of Deformed Gratings	170
4. Diverse Applications of Moiré Interferometry	171
4.1. Thermal Deformations of Microelectronics Devices	171
4.2. Textile Composites	173
4.3. Fracture Mechanics	176
4.4. Micromechanics: Grain Deformations	177
5. Shadow Moiré	180
5.1. Basic Concepts	180
5.2. Additional Considerations	183
6. Increased Sensitivity, Shadow Moiré	184
6.1. Phase Stepping (or Quasi-heterodyne) Method	184
6.2. Optical/Digital Fringe Multiplication (O/DFM)	185
7. Applications of Shadow Moiré	185
7.1. Post-buckling Behavior of a Composite Column	185
7.2. Pre-buckling Behavior of an Aluminum Channel	189
7.3. Warpage of Electronic Devices	191
References	194

Digital Photoelasticity

Terry Y. Chen	197
---------------------	-----

1. Basic Principles of Photoelasticity	197
1.1. Light and Complex Notation	197
1.2. Polarization of Light	198
1.3. Retardation	200
1.4. Optical Media	200
1.5. The Stress-Optic Law	202

1.6. Plane Polariscope	204
1.7. Circular Polariscope	207
2. Computer Evaluation of Photoelastic Fringe Patterns	210
2.1. Digital Image Processing	211
2.2. Extraction of Fringe Point	213
2.3. Fringe Multiplication	213
2.4. Determination of the Isochromatic Fringe Order	215
2.5. Determination of Principal Stress Direction	222
3. Applications of Evaluated Data	226
3.1. Stress Analysis	226
3.2. Examples	227
4. System and Error Assessment	227
5. Conclusions	230
References	230

Optical Fiber Strain Sensing in Engineering Mechanics

James S. Sirkis	233
1. Intrinsic Fabry-Perot Sensor	234
1.1. Optical Arrangement	234
1.2. Response to Strain and Temperature	236
1.3. Sensor Multiplexing	239
2. Extrinsic Fabry-Perot Strain Sensor	239
2.1. Optical Arrangement	241
2.2. Response to Strain and Temperature	242
2.3. Self-temperature Compensation	243
2.4. EFP Sensor Variants	244
2.5. Sensor Multiplexing	246
3. Bragg Grating Strain Sensor	246
3.1. Bragg Grating Fabrication	247
3.2. Strain and Temperature Response	250
3.3. Effects of Gradients	250
3.4. Bragg Grating Reliability	251
3.5. Sensor Multiplexing	251
4. Fiber-Optic Coatings and Cables	253
5. Commercial Packaging	256
6. Sensor Bonding Techniques	257
7. Demodulation	258
7.1. Serrodyne Fringe Counting (IFP Sensors)	259
7.2. White Light Cross-Correlator (EFP Sensors)	260
7.3. Scanning Fabry-Perot Filter (Bragg Grating Sensors)	262
7.4. Spectral Interrogation (EFP Sensors)	263
7.5. Other Demodulators	266
8. Sensor Comparison	266
References	269

Long-Gage Fiber-Optic Sensors for Structural Monitoring

Daniele Inaudi	273
1. Introduction: Monitoring versus Measuring Structures	273
2. Long-Gage versus Short-Gage Sensors	274
3. Interferometric Sensors	275
3.1. Optical Arrangements	276
3.2. Strain and Temperature Sensitivity	276
3.3. Demodulation Techniques	277
3.4. Sensor Packaging	280
3.5. Application Example: Monitoring the Versoix Bridge	283
4. Intensity-Based Sensors	284
5. Brillouin-Scattering Sensors	286
5.1. Principles	286
5.2. Measurement Techniques	287
5.3. Sensor Packaging	289
5.4. Application Example: Temperature Monitoring of the Luzzzone Dam	290
6. Outlook	291
7. Conclusions	291
References	292

Techniques for Non-Birefringent Objects:**Coherent Shearing Interferometry and Caustics**

Sridhar Krishnaswamy	295
1. Introduction	295
2. Elasto-Optic Relations	297
2.1. Optical Phase Shift due to Transmission through an Optically Isotropic Linear Elastic Medium	297
2.2. Optical Phase-Shift due to Reflection from a Polished Surface	298
3. Shearing Interferometry	299
3.1. A Dual-Grating Shearing Interferometer – The Coherent Gradient Sensor (CGS)	300
3.2. A Polarization-Based Shearing Interferometer: Compact Polariscope / Shearing Interferometer (PSI)	304
4. Optical Caustics	309
5. Applications	311
5.1. Compressive Line Load on the Edge of a Plate	312
5.2. Fracture Mechanics	315
6. Conclusion	319
References	319

Advances in Two-Dimensional

and Three-Dimensional Computer Vision

Michael A. Sutton, Stephen R. McNeill, Jeffrey D. Helm,

and Yuh J. Chao 323

1. Introduction	323
2. Theory and Numerical Implementation	326
2.1. Two-Dimensional Video Image Correlation	326
2.2. Three-Dimensional Video Image Correlation	334
3. Applications	343
3.1. Two-Dimensional Video Image Correlation	343
3.2. Three-Dimensional Video Image Correlation	354
4. Discussion	366
5. Summary	367
References	368

Laser Doppler and Pulsed Laser Velocimetry

in Fluid Mechanics

Jeremy M. Coupland 373

1. Introduction	373
1.1. The Scattering and Dynamic Properties of Seeding Particles .	375
2. Laser Doppler Velocimetry (LDV)	376
2.1. Fundamentals of LDV	376
2.2. Fourier Optics Model of LDV	381
2.3. The Doppler Signal and Signal Processing	386
2.4. LDV Measurements in Practice	389
3. Planar Doppler Velocimetry (PDV)	391
4. Pulsed Laser Velocimetry	395
4.1. Particle Image Velocimetry (PIV)	395
4.2. Removal of Directional Ambiguity	399
4.3. PIV Measurements in Practice	400
4.4. Three-Dimensional PIV	402
4.5. Holographic Particle Image Velocimetry (HPIV)	402
5. Conclusions, Discussion and Future Development	408
References	410

Surface Characterization and Roughness Measurement

in Engineering

David J. Whitehouse 413

1. General	413
1.1. Historical	413
1.2. Nature and Importance of Surfaces	414
1.3. Trends	416
2. Instrumentation	419
2.1. General Points	419

2.2. The Stylus	422
2.3. Basic Instrument	425
2.4. The Stylus Method (Mechanical)	427
2.5. The Optical Methods	428
2.6. Other Conventional Methods	433
2.7. Non-conventional Methods	433
3. Pre-Processing and Filtering	433
3.1. Levelling	433
3.2. Curve Fitting for Form	433
3.3. Filtering for Waviness	434
4. Parameters	439
4.1. General	439
4.2. Height Parameters (see [36] for example)	440
4.3. Peak Parameters	441
4.4. Spacing Parameters	442
4.5. Peak Parameters (Statistical)	443
4.6. Hybrid Parameters	445
4.7. Effects of Filtering on Parameter Values	445
5. Random Process Analysis in Surface Metrology	446
5.1. General	446
5.2. Height Information	446
5.3. Spacing Information	447
6. Areal (or Three-Dimensional) Parameters	453
6.1. General	453
6.2. Comments on Areal Measurement	454
7. Conclusions	458
References	459
Index	463