

Contents

Foreword — V

1 Introduction — 1

- 1.1 Definitions — 1
- 1.1.1 Spectrometry for material analysis for research and production — 2
- 1.2 About the history of atomic emission spectrometry — 3
- 1.2.1 First observations of atomic emission spectra — 3
- 1.2.2 Fundamental work by Bunsen and Kirchhoff dealing with atomic emission spectrometry — 4
- 1.2.3 Development of atomic emission spectrometry for quantitative analysis — 4
- 1.2.4 Development of atomic emission spectrometry with excitation using electrical arc — 7
- 1.2.5 Atomic emission spectrometry with spark excitation — 8
- Bibliography — 9

2 Atomic emission spectrometry: fundamentals — 11

- 2.1 Researching the hydrogen spectrum in the nineteenth century — 11
- 2.2 Hydrogen spectrum and Bohr's atomic model — 12
- 2.3 Schrödinger equation and quantum numbers — 13
- 2.4 Quantum mechanically explained rough spectrum for hydrogen — 14
- 2.5 The fine structure of the hydrogen atom spectrum — 19
- 2.5.1 Splitting of the energy levels — 19
- 2.5.2 Origin of the spectral background — 22
- 2.6 The spectra for atoms with multiple electrons — 23
- 2.6.1 Hydrogen-like atoms and ions — 23
- 2.6.2 Atoms with multiple outer electrons — 25
- 2.6.3 Selection rules and metastable states — 27
- 2.7 Russell-Saunders term symbols — 28
- 2.8 Characteristics of emitted spectral signals — 29
- Bibliography — 31

3 Hardware for spark and arc spectrometers — 33

- 3.1 Construction of emission spectrometers for the analysis of solid materials — 35
- 3.2 Excitation generators — 42
- 3.2.1 Arc excitation and arc generators — 42
- 3.2.1.1 The physics of the DC arc — 44
- 3.2.1.2 Construction of arc generators — 52

3.2.1.3	Characteristics of the electric arc as an excitation source —	55
3.2.2	Spark excitation and spark generators —	59
3.2.2.1	The physics of the spark —	60
3.2.2.2	Construction of a modern spark generator —	65
3.2.2.3	Characteristics of the spark as an excitation source —	67
3.2.3	The laser as an excitation source —	77
3.2.3.1	Basic operation of a solid-state laser —	77
3.2.3.2	Lasers with quality switches —	79
3.2.3.3	Fiber laser —	81
3.2.3.4	Ablation and excitation using a laser with a quality switch —	87
3.2.3.5	Commercially available LIBS systems —	92
3.3	Arc and spark spectrometer sample stands —	94
3.3.1	Spark stands —	95
3.3.2	Sample stands for arc instruments —	98
3.3.3	Sample stands for the rotrode —	100
3.4	Operating gas systems —	101
3.4.1	Commercially available operating gases —	102
3.4.2	Argon supply forms and transport of the gas to the spectrometer —	103
3.4.3	Argon purifying systems —	104
3.4.4	The spectrometer's internal argon system —	105
3.4.5	Exhaust system —	107
3.5	Spectrometer optics —	108
3.5.1	Rowland circle concave grating optics with photomultiplier tubes (PMT) as radiation detectors —	110
3.5.2	Optics with Rowland circle gratings and detector arrays for detection —	117
3.5.3	Optics with corrected concave gratings —	120
3.5.4	Echelle optics with two-dimensional detector arrays —	122
3.5.5	Optical components —	124
3.5.5.1	Gratings —	124
3.5.5.2	Fiber optics —	128
3.5.5.3	Slits and the smallest optimum slit width —	130
3.5.5.4	Mirrors, lenses, windows and refractors —	132
3.5.5.5	Optic housing —	134
3.5.6	The importance of absolute intensity levels —	135
3.6	Optoelectronic detectors for atomic emission spectrometers —	137
3.6.1	Photomultiplier tubes —	137
3.6.2	Semiconductor-based sensor arrays —	142
3.6.2.1	Photodiode arrays —	144
3.6.2.2	Charge transfer devices —	147
3.6.2.3	CMOS detectors —	153

3.6.2.4	Comparison of CCD, CID and CMOS arrays —	155
3.7	Measuring electronics —	157
3.7.1	Measuring electronics for photomultiplier tubes —	157
3.7.2	Measuring electronics for multichannel semiconductor detectors —	163
3.8	Superordinate computer —	165
3.9	Spectrometer software —	165
3.9.1	Calculation of the line intensities from the spectra —	165
3.9.1.1	Interpolation of spectra —	165
3.9.1.2	Virtual exit slits —	166
3.9.2	Wavelength calibrations and profiling —	168
3.9.2.1	Profiling an optic equipped with exit slits —	168
3.9.2.2	Wavelength calibration of optics equipped with semiconductor detectors —	168
3.9.3	Background correction —	169
3.9.4	Calculating intensity ratios —	169
3.9.5	Calculating calibration functions —	170
3.9.5.1	Line interferences —	171
3.9.5.2	Interelement interferences —	173
3.9.5.3	Calculating the calibration function —	173
3.9.5.4	Recording high- and low-sample expected values for recalibration purposes —	174
3.9.5.5	Combining calibration functions into methods —	175
3.9.6	Recalibration —	176
3.9.6.1	One- and two-point recalibration —	177
3.9.6.2	Complete spectrum recalibration —	178
3.9.6.3	Type recalibration —	186
3.9.7	Line switches —	187
3.9.8	100% calculation —	188
3.9.9	Calculating the concentrations from PMT raw intensities or from complete spectra —	188
	Bibliography —	189
4	Sampling and sample preparation —	195
4.1	Basic requirements for spectrometer samples —	195
4.2	Sampling from liquid melts —	196
4.2.1	Sampling from pig iron —	197
4.2.1.1	Sampling with the ladle —	197
4.2.1.2	Sampling with the dipping mold —	197
4.2.1.3	Sampling with the immersion probe —	197
4.2.2	Sampling from liquid steel —	198
4.2.3	Sampling from molten cast iron —	199

4.2.4	Sampling from aluminum melts and other metal bases —	202
4.3	Sample preparation —	203
	Bibliography —	205
5	Analytical performance for the most important metals —	207
5.1	Analysis of iron-based materials —	210
5.1.1	Details for the analysis of steels —	211
5.1.2	Details for the analysis of cast iron —	212
5.2	Analysis of aluminum-based materials —	214
5.3	Analysis of copper-based metals —	217
5.4	Analysis of nickel and nickel alloys —	219
5.5	Analysis of zinc and zinc alloys —	221
5.6	Analysis of lead and lead-based alloys —	222
5.7	Analysis of tin and tin-based alloys —	223
5.8	Analysis of titanium-based alloys —	224
5.9	Analysis of magnesium-based alloys —	225
5.10	Analysis of cobalt-based alloys —	227
5.11	Analysis of precious metals —	228
5.12	Other metals —	228
5.12.1	Refractory metals —	228
5.12.2	Low-melting heavy metals —	228
	Bibliography —	230
6	Analysis of inclusions in metal —	233
6.1	Introduction —	233
6.2	Inclusions and their origins —	233
6.3	Reference methods for the determination of inclusions in steels —	237
6.3.1	Classical analytical procedures —	237
6.3.2	Microscopic testing methods —	238
6.4	Influence of the inclusions on the spark discharge —	239
6.5	Measuring methods and evaluation —	242
6.5.1	Peak integration method and related methods —	243
6.5.2	Pulse distribution analysis —	244
6.5.3	Single spark analysis —	245
6.5.4	Determination of the particle size —	247
6.5.5	Possibilities and limitations of inclusion analysis —	249
	Bibliography —	249

7 Mobile spectrometers — 253

- 7.1 Excitation generators in mobile spectrometers — 255
- 7.1.1 Features of the ignition — 256
- 7.1.2 Arc generators for mobile spectrometers — 257
- 7.1.3 Spark generators for mobile spectrometers — 257
- 7.1.4 Laser sources for handheld instruments — 258
- 7.2 Spark probes — 262
- 7.3 Probe hoses — 266
- 7.4 Optical systems for mobile spectrometers — 269
- 7.4.1 Optics coupled via fiber optic cable — 269
- 7.4.2 Optical systems for handheld devices — 270
- 7.4.3 Probe optics for the VUV spectral range — 273
- 7.5 Housing, transport trolley and battery — 274
- 7.6 Inert gas systems in mobile spectrometers — 278
- 7.7 Software for mobile spectrometers — 279
- 7.7.1 The analysis mode — 279
- 7.7.2 Calculating the contents using fingerprint algorithms — 280
- 7.7.3 Checking the analysis for a match with a target material — 283
- 7.7.4 Grade identification — 283
- 7.7.5 Sorting — 288
- 7.8 Calibration, sample preparation and sampling — 291
- 7.8.1 Sample preparation and selection of the measuring position — 292
- 7.8.2 Measurements in spark mode — 295
- 7.8.3 Measurements in arc mode — 298
- Bibliography — 303

8 Statistics and quality assurance — 307

- 8.1 Statistical indicators and their determination — 308
- 8.1.1 Working range — 308
- 8.1.2 Detection limit of a method — 308
- 8.1.3 Limit of quantification — 310
- 8.1.4 Accuracy — 310
- 8.1.5 Precision — 310
- 8.1.5.1 Repeatability and repetition limit r — 311
- 8.1.5.2 Reproducibility and reproducibility limit R — 313
- 8.1.6 Bias — 314
- 8.1.7 Recovery rate — 315
- 8.1.8 Selectivity/specificity — 316
- 8.1.9 Robustness — 316
- 8.1.10 Linearity — 317
- 8.1.11 Measurement uncertainty — 318
- 8.2 Reference materials — 319

XII — Contents

8.3	Quality control charts — 321
8.4	Validation — 323
8.5	Quality management systems — 325
8.6	Accreditation — 328
	Bibliography — 330

Index — 333
