

Contents

Preface — V

1	Raw materials — 1
1.1	Polymer latex or polymer solution? — 1
1.1.1	Natural rubber latex — 2
1.1.2	Styrene-butadiene rubber latex — 6
1.1.3	Acrylonitrile-butadiene rubber latex — 6
1.1.4	Polychloroprene latex — 8
1.1.5	Artificial latices — 9
1.1.5.1	Synthetic <i>cis</i> -1,4-polyisoprene latex — 9
1.1.5.2	Isoprene-isobutylene rubber (or butyl rubber) latex — 10
1.1.5.3	Chlorosulfonated polyethylene latex — 11
1.1.5.4	Polyurethane — 11
1.1.5.5	Ethylene-propylene rubber latex — 11
1.1.6	Other naturally occurring latices — 12
1.2	Alkalis — 12
1.3	Surfactants — 13
1.4	Accelerators — 15
1.4.1	Health and safety of accelerators — 15
1.4.2	Types of accelerators — 16
1.4.2.1	Dithiocarbamates — 16
1.4.2.2	Thiuram disulfides and polysulfides — 18
1.4.2.3	Thiazoles — 19
1.4.2.4	Xanthates — 20
1.4.2.5	Thioureas — 21
1.4.2.6	Guanidines — 21
1.5	Other vulcanisation materials — 21
1.5.1	Sulfur — 21
1.5.2	Peroxides — 22
1.5.3	Zinc oxide — 23
1.5.4	Zinc carbonate — 23
1.5.5	Other materials that can activate vulcanisation — 24
1.6	Rubber antioxidants — 24
1.6.1	Phenolic antioxidants — 25
1.6.1.1	Antioxidant 2246 — 25
1.6.1.2	Antioxidant 425 — 25
1.6.1.3	Wingstay L — 26
1.6.1.4	Butylated hydroxytoluene — 26
1.6.2	Liquid antioxidants — 26
1.6.3	Para-phenylene diamines — 26

1.6.4	Network-bound antioxidants —	27
1.6.5	Synergistic enhancement of antioxidant activity —	27
1.7	Antiozonants —	28
1.8	Fillers and pigments —	28
1.8.1	Fillers —	28
1.8.2	Pigments and dyes —	29
1.9	Testing of raw materials —	30
1.9.1	Latex —	30
1.9.1.1	Mechanical stability time —	31
1.9.1.2	Measurement of pH —	31
1.9.1.3	Measurement of viscosity —	32
1.9.2	Other raw materials —	32
1.10	Storage of raw materials —	32
1.10.1	Latex —	33
1.10.2	Other raw materials —	34
1.10.2.1	Sulfur —	34
1.10.2.2	Accelerators —	34
1.10.2.3	Ammonia —	34
1.10.2.4	Acids —	35
1.10.2.5	Other raw materials —	35
1.10.2.6	Time-expired materials —	35
	References —	35

2	Latex compounding —	37
2.1	Introduction —	37
2.2	Compounding equipment —	38
2.3	Raw material preparation – liquid materials —	39
2.4	Raw material preparation – solid materials —	40
2.4.1	Ball mill —	44
2.4.2	Attrition mill —	46
2.4.3	Vibration mill —	47
2.4.4	Bead mill/sand mill —	47
2.4.5	High-shear mixers —	48
2.5	Measurement of particle size —	48
2.6	Storage of dispersions —	49
2.7	Compounding procedure —	50
2.7.1	Representation of a latex formulation —	50
2.7.2	Addition of compounding ingredients —	54
2.7.3	Latex prevulcanisation —	56
2.7.4	Measurement of prevulcanisation —	59
2.8	Storage of compounded latex —	63
	References —	63

3	Vulcanisation — 65
3.1	Introduction — 65
3.2	Brief overview of the mechanism of sulfur vulcanisation — 65
3.3	Other vulcanisation procedures — 68
3.4	Effect of vulcanisation on physical properties — 70
	References — 71
4	Degradation of elastomers — 73
4.1	Introduction — 73
4.2	Mechanism of oxidative degradation — 74
4.2.1	Initiation — 74
4.2.2	Propagation — 75
4.2.3	Termination — 75
4.3	Mechanism of ozone degradation — 76
	References — 78
5	Reinforcement of latex systems by the use of fillers — 79
5.1	Introduction — 79
5.2	Mechanism of reinforcement — 80
5.3	Comparisons with dry rubber — 81
5.4	The effect of vulcanisation — 81
5.5	Materials used as fillers — 82
5.5.1	Silicone dioxide (Silicas) — 82
5.5.2	Clays — 84
5.5.3	Other inorganic materials — 85
5.5.4	Polymeric particles — 86
5.5.5	Graft copolymers — 86
5.5.6	Polyurethane dispersions — 87
5.5.7	Proteins — 87
5.6	Conclusions — 88
	References — 89
6	Latex stability and film-forming — 91
6.1	Latex stability — 91
6.1.1	Introduction — 91
6.1.2	Electrostatic repulsion — 93
6.1.3	Steric repulsion — 93
6.1.4	Solvation stabilisation — 94
6.1.5	Depletion stabilisation — 94
6.1.6	Controlling latex stability — 95
6.1.7	Measuring latex stability — 96
6.1.8	Using latex stability — 96

- 6.1.9 Zinc oxide thickening — 97
- 6.1.10 Final thoughts on latex stability — 97
- 6.2 Latex film-forming — 97
 - 6.2.1 Introduction — 97
 - 6.2.2 Film-forming — 98
 - 6.2.3 Effect of shrinkage and uneven pick-up — 100
 - 6.2.4 'Orange peel' — 103
 - References — 103

7 Latex dipping — 105

- 7.1 Introduction — 105
- 7.2 Straight dipping — 105
 - 7.2.1 Former entry into the latex — 107
 - 7.2.2 Former exit from the latex — 107
 - 7.2.3 Drying — 109
 - 7.2.4 Subsequent dips — 110
 - 7.2.5 Beading — 111
 - 7.2.6 Vulcanisation — 114
 - 7.2.7 Leaching — 114
 - 7.2.8 Stripping — 116
 - 7.2.9 Former clean — 117
- 7.3 Coagulant dipping — 118
 - 7.3.1 Former preheat — 119
 - 7.3.2 Coagulant dip — 120
 - 7.3.3 Coagulant dry — 122
 - 7.3.4 Latex dip — 122
 - 7.3.5 Latex drying — 124
 - 7.3.6 Subsequent dips — 125
 - 7.3.7 Flocking — 125
 - 7.3.8 Beading — 126
 - 7.3.9 Leach — 127
 - 7.3.10 Vulcanising — 127
 - 7.3.11 Prestrip soak — 128
 - 7.3.12 Stripping — 128
 - 7.3.13 Former clean — 128
- 7.4 Heat-sensitised dipping — 129
- 7.5 Electrodeposition — 130
- 7.6 Spray coating — 130
 - References — 131

8 Wetting — 133

- 8.1 Wetting of a solid surface by a liquid — 133

8.2	Measurement of wetting — 136
	References — 137
9	Latex dipping tanks — 139
9.1	Chain plants – general — 139
9.1.1	Entry/exit mechanisms on a chain plant — 139
9.2	Batch dipping plants — 142
9.3	Latex dipping tank construction — 143
9.4	Latex dipping tank design — 143
9.4.1	Dipping tanks for straight dipping — 143
9.4.2	Dip tanks for coagulant dipping — 147
9.4.3	Dip tanks for heat-sensitised dipping — 148
	Reference — 148
10	Formers for latex dipping — 149
10.1	Former materials — 149
10.2	Former design — 150
10.3	Former mounting — 151
11	Finishing operations for dipped latex products — 155
11.1	Introduction — 155
11.2	Halogenation — 155
11.3	Powdering — 158
11.4	Silicone oil — 160
11.5	Polymer coating — 160
11.6	Other approaches to finishing — 161
	References — 161
12	Troubleshooting in latex dipping — 163
12.1	Introduction — 163
12.2	Sampling — 164
12.3	Examination of any defects — 164
12.4	Collection of data — 167
12.5	Corrective action — 168
12.6	Some types of defect and suggested corrective and preventive actions — 169
12.6.1	Mechanical damage — 169
12.6.2	Other causes of holes — 171
12.6.3	Coagulum and cream — 172
12.6.4	Bubbles — 173
12.6.5	Foreign bodies — 174
12.6.6	Damaged formers — 176

12.6.7	Stuck work (also known as 'Flats' or 'Stickies') —	177
12.6.8	Unwetted marks (also known as 'Fish Eyes') —	178
12.6.9	Bead defects —	178
12.6.10	Discolouration —	180
12.6.11	Double imaging —	180
12.7	Conclusion —	181
	References —	181
13	Quality control in latex dipping —	183
13.1	Introduction —	183
13.2	Analysis of data —	184
13.3	Data considerations – variables data or attributes data? —	185
13.4	Control charts —	186
13.4.1	Control charts for variables —	186
13.4.2	Control charts for attributes —	188
13.5	Process capability —	188
13.5.1	Relative precision index —	189
13.5.2	Cp and cpk indices —	189
13.6	Cumulative sum charts —	191
13.7	Pareto analysis —	195
	References —	197
14	Process validation —	199
14.1	Introduction —	199
14.2	Design qualification —	200
14.3	Installation qualification —	200
14.4	Operational qualification —	200
14.5	Process qualification —	201
14.6	Reporting —	201
14.7	Revalidation —	202
14.8	Concurrent and retrospective validation —	202
14.8.1	Concurrent validation —	202
14.8.2	Retrospective validation —	203
14.9	Example of a process validation —	203
14.9.1	Installation qualification —	204
14.9.2	Operational qualification —	204
14.9.3	Process qualification —	205
	Reference —	205
15	Some analytical methods used in latex dipping operations —	207
	Reference —	208

16	Allergies, proteins and <i>N</i>-nitrosamines — 209
16.1	Allergic reactions — 209
16.2	Extractable latex proteins — 209
16.3	<i>N</i> -nitrosamines — 211
	References — 213
17	Potential future trends in the latex dipping industry — 215
17.1	Introduction — 215
17.2	Possible manufacturing processes — 215
17.2.1	Spray coating — 215
17.2.2	Electrodeposition — 216
17.2.3	Drying and vulcanisation — 216
17.3	Possible new materials — 217
17.3.1	New latices — 217
17.3.2	Fillers — 217
17.3.3	Nanotechnology — 217
17.4	Increasing regulatory requirements — 218
17.5	Increasing environmental requirements — 218
17.6	Drug delivery — 219
17.7	Specialised coatings — 219
17.8	New materials — 220
17.9	Reducing costs — 220
17.10	Improving measurement processes — 220
17.10.1	Measuring the extent of prevulcanisation — 220
17.10.2	Predicting the 'dippability' of latices — 221
	References — 222

Abbreviations — 223

Index — 225