

Contents

Index of Tables	X
---------------------------	---

Notation	XII
--------------------	-----

Chronological Table	XV
-------------------------------	----

Chapter 1 Universal Jointed Driveshafts for Transmitting Rotational Movements	1
--	----------

1.1 Early Reports on the First Joints	1
1.1.1 Hooke's Universal Joints	1
1.2 Theory of the Transmission of Rotational Movements by Hooke's Joints	5
1.2.1 The Non-uniformity of Hooke's Joints According to Poncelet	5
1.2.2 The Double Hooke's Joint to Avoid Non-uniformity	8
1.2.3 D'Ocagne's Extension of the Conditions for Constant Velocity	10
1.2.4 Simplification of the Double Hooke's Joint	10
1.2.4.1 Fenaille's Tracta Joint	12
1.2.4.2 Various Further Simplifications	14
1.2.4.3 Bouchard's One-and-a-half Times Universal Joint	15
1.2.5 Developments Towards the Plunging Joint	15
1.3 First Applications of the Science of Strength of Materials to Driveshafts	19
1.3.1 Designing Crosses Against Bending	20
1.3.2 Designing Crosses Against Surface Stress	22
1.3.3 Designing Driveshafts for Durability	26
1.4 Literature to Chapter 1	27

Chapter 2 Theory of Constant Velocity Joints	29
---	-----------

2.1 The Origin of Constant Velocity Joints	30
2.2 Weiss and Rzeppa Ball Joints	33
2.3 First Indirect Method of Proving Constant Velocity According to Metzner	38
2.3.1 Effective Geometry with Straight Tracks	41
2.3.2 Effective Geometry with Circular Tracks	43
2.4 Second, Direct Method of Proving Constant Velocity by Orain	45
2.4.1 Polypode Joints	49
2.4.2 The Free Tripode Joint	53
2.5 Literature to Chapter 2	56

Chapter 3 Hertzian Theory and the Limits of Its Application	57
--	-----------

3.1 Systems of Coordinates	58
3.2 Equations of Body Surfaces	59
3.3 Calculating the Coefficient $\cos \tau$	60
3.4 Calculating the Deformation δ at the Contact Face	63

3.5	Solution of the Elliptical Single Integrals J_1 to J_4	67
3.6	Calculating the Elliptical Integrals K and E	70
3.7	Semiaxes of the Elliptical Contact Face for Point Contact	71
3.8	The Elliptical Coefficients μ and ν	73
3.9	Width of the Rectangular Contact Surface for Line Contact	75
3.10	Deformation and Surface Stress at the Contact Face	76
3.10.1	Point Contact	76
3.10.2	Line Contact	77
3.11	Literature to Chapter 3	78
Chapter 4	Designing Joints and Driveshafts	79
4.1	Design Principles	79
4.1.1	Comparison of Theory and Practice by Franz Karas 1941	80
4.1.2	Static Stress	81
4.1.3	Dynamic Stress and Durability	81
4.1.4	Universal Torque Equation for Joints	84
4.2	Hooke's Joints and Hooke's Jointed Driveshafts	85
4.2.1	The Static Torque Capacity M_o	86
4.2.2	The Dynamic Torque Capacity M_d	89
4.2.3	Mean Equivalent Compressive Force P_m	90
4.2.4	Approximate Calculation of the Equivalent Compressive Force P_m	92
4.2.5	Dynamic Transmission Parameter CR	95
4.2.5.1	Example of a Calculation for a Hooke's Jointed Driveshaft	97
4.2.6	Motor Vehicle Driveshafts	98
4.2.6.1	Example Showing the Calculation Methods for Hooke's Jointed Driveshafts of Commercial Vehicles	101
4.2.7	Maximum Values for Speed and Articulation Angle	102
4.2.8	Critical Speed and Shaft Bending Vibration	104
4.2.9	Double Hooke's Joints	107
4.3	Forces on the Support Bearings of Hooke's Jointed Driveshafts	112
4.3.1	Interaction of Forces in Hooke's Joints	112
4.3.2	Forces on the Support Bearings of a Driveshaft in the W-Configuration	113
4.3.3	Forces on the Support Bearings of a Driveshaft in the Z-Configuration	116
4.4	Ball Joints	117
4.4.1	Static and Dynamic Torque Capacity	117
4.4.2	Rzeppa Type Fixed Joints	120
4.4.2.1	AC Fixed Joints	121
4.4.2.2	RF Fixed Joints	124
4.4.2.3	UF Fixed Joints	126
4.4.3	Rzeppa-type Plunging Joints	126
4.4.3.1	DO Joints	126
4.4.3.2	VL Joints	127
4.4.3.3	Calculation of a Driveshaft with Ball Joints	128
4.4.4	Service Life of Joints Using the Palmgren/Miner Rule	133
4.4.5	Example of a Calculation for the Driveshafts of a Four Wheel Drive Passenger car	135
4.4.6	Weiss Type Ball Joints	144
4.4.6.1	Fixed Joints	144
4.4.6.2	Plunging Joints	145
4.4.7	Variation of the Pressure Angle α with Articulation	146
4.5	Podé Joints	150
4.5.1	Bipode Plunging Joints	153
4.5.2	Tripode Joints	154
4.5.2.1	Static Torque Capacity of the Non-articulated Tripode Joint	154

4.5.2.2	Torque Capacity of the Articulated Tripode Joint	158
4.5.2.3	Calculation for the Tripode Jointed Driveshaft of a Passenger Car	163
4.6	Basic Procedure for the Applications Engineering of Driveshafts	165
4.7	Literature to Chapter 4	168
Chapter 5	Joint and Driveshaft Configurations	170
5.1	Hooke's Jointed Driveshafts	171
5.1.1	End Connections	172
5.1.2	Hooke's Joints	176
5.1.3	Plunging Elements	179
5.1.4	Designs of Driveshaft	181
5.1.4.1	Driveshafts for Machinery and Motor Vehicles	181
5.1.4.2	Driveshafts for Steer Drive Axles	185
5.1.4.3	American Style Driveshafts	186
5.1.4.4	Driveshafts for Agricultural Machinery	190
5.1.4.5	Automotive Steering Assemblies	199
5.1.4.6	Driveshafts to DIN 808	201
5.1.4.7	Grooved Spherical Ball Jointed Driveshafts	204
5.2	Ball Jointed Driveshafts	205
5.2.1	End Connections	205
5.2.2	Ball Joints	207
5.2.2.1	Shape of the Tracks	207
5.2.2.2	Steering the Balls	210
5.2.2.3	Checking for Perturbations of Motion in Ball Joints	212
5.2.3	Rzeppa Type Fixed Joints	213
5.2.3.1	Configuration and Torque Capacity	214
5.2.3.2	Materials and Manufacture	216
5.2.3.3	Lubrication and Sealing	219
5.2.3.4	Uses and Outlook	220
5.2.4	Rzeppa Type Plunging Joints	222
5.2.4.1	Configuration and Torque Capacity	224
5.2.4.2	Materials and Manufacture	226
5.2.4.3	Sealing	227
5.2.4.4	Uses	228
5.2.5	Weiss Type Fixed Joints	231
5.2.5.1	Configuration and Torque Capacity	231
5.2.5.2	Materials and Manufacture	231
5.2.6	Weiss Type Plunging Joints	234
5.2.6.1	Materials and Manufacture	234
5.2.7	Balancing Ball Jointed Driveshafts	235
5.3	Podé Jointed Driveshafts	235
5.3.1	End Connections	237
5.3.2	GE Fixed Tripode Joints	237
5.3.3	GI Plunging Tripode Joints	239
5.3.4	Triplan Ball Joints	240
5.3.4.1	Materials and Manufacture	240
5.3.5	Tripode Jointed Driveshaft Designs	241
5.4	Design and Configuration Guidelines to Optimise the Drivetrain	243
5.5	Literature to Chapter 5	244
Name Index	245	
Subject Index	249	