

Contents

List of Contributors XIII

1	Crystallization: Introduction	1
	<i>Wolfgang Beckmann</i>	
2	Mechanisms of Crystallization	7
	<i>Wolfgang Beckmann</i>	
2.1	Crystal Lattice	7
2.1.1	Arrangement of Building Blocks and Symmetries	7
2.1.2	Unit Cell	9
2.1.3	Miller Indices to Describe Crystal Faces	11
2.1.4	Lattice Defects	12
2.1.5	Equilibrium, Growth, and Dissolution Form of Crystals	14
2.1.6	Morphology and Habit	16
2.2	Nucleation of Crystals	17
2.2.1	Mechanism of Primary Nucleation	18
2.2.2	Metastable Zone and Induction Time for Nucleation	20
2.2.3	Form Crystallized: Ostwald's Law of Stages	25
2.3	Growth and Growth Rate of Crystals	25
2.3.1	Kink Position and F, S, and K Faces	26
2.3.2	Growth of Ideal Crystals	27
2.3.3	Growth of Real Crystals	28
2.3.4	Transport Phenomena	32
	Further Reading	33
3	Solubility and Solution Equilibria in Crystallization	35
	<i>Heike Lorenz</i>	
3.1	Phase Equilibria and Phase Diagrams: General Issues	36
3.1.1	Phases, Phase Rule, and Binary Systems	36
3.1.2	Melt and Solution Equilibria	38
3.1.3	Thermodynamic Description of SLE: Liquidus Curve in the Phase Diagram	39
3.1.4	Phase Diagrams of Ternary and Quaternary Systems	42

3.2	Melt Phase Diagrams	44
3.2.1	Types of Phase Diagrams and Their Occurrence	44
3.2.2	Measurement of Melt Phase Diagrams	46
3.2.2.1	Methods	46
3.2.2.2	DSC and How to Measure and Interpret DSC Data	47
3.2.3	Example of a Diastereomeric System	50
3.3	Solution Equilibria	53
3.3.1	Solubility and Concentration Units	53
3.3.2	Solubility Curves of Inorganic and Organic Substances	54
3.3.2.1	Inorganic Substances	55
3.3.2.2	Organic Substances	57
3.3.3	Solvates, Polymorphs, and Cocrystals	58
3.3.4	Influence of Solvents and Impurities	60
3.3.5	Measurement of Solubilities and Corroboration	62
3.3.5.1	Ensuring Equilibrium Conditions	63
3.3.5.2	Excess Method as a Classical Isothermal Method	64
3.3.5.3	Polythermal Measurements	65
3.3.5.4	Prediction and Correlation of Solubilities	67
3.3.6	Oiling-Out	68
3.3.7	Ternary Solution Equilibria: Case of Enantiomers	70
3.3.8	Quaternary Systems: Case of Reciprocal Salt Pairs	72
	References	74
4	Agglomeration during Crystallization	75
	<i>Wolfgang Beckmann</i>	
4.1	Mechanisms and Kinetics of Agglomeration	75
4.1.1	Process of Agglomeration	75
4.1.2	Kinetics of Agglomeration	77
4.2	Parameters Influencing Agglomeration	77
4.3	Agglomeration during Crystallization	80
4.3.1	Agglomeration during Crystallization	80
4.3.2	Spherical Agglomeration	83
4.4	Mechanical Properties of Agglomerates	83
	References	84
5	Polymorphism of Crystalline Systems	85
	<i>Rolf Hilfiker</i>	
5.1	Introduction and Definitions	85
5.2	Occurrence and Properties of Polymorphs and Solvates	86
5.3	Thermodynamics of Polymorphs of Solid-State Forms	87
5.3.1	Basics	87
5.3.2	Energy–Temperature Diagrams	88
5.3.3	Rules to Predict Thermodynamic Relationships	90
5.4	Thermodynamics of Hydrates	91
5.5	Experimental Techniques to Elucidate Thermodynamics	94

5.5.1	DSC	94
5.5.2	Suspension Equilibration	94
5.5.3	Solubility Measurements	95
5.5.4	Other Methods	96
5.6	Formation of Various Polymorphs and Solid-State Forms-Polymorph Screens	97
5.6.1	Principles	97
5.6.2	Crystallization Methods and Choice of Solvent	99
5.6.3	Types of Polymorph Screens	100
5.7	Selection of Optimal Form for Development	101
	Symbols	102
	References	102
6	The Influence of Additives and Impurities on Crystallization	105
	<i>Christiane Schmidt, Matthew J. Jones, and Joachim Ulrich</i>	
6.1	Influence of Additives and Impurities on Crystallization	105
6.1.1	Solubility	105
6.1.1.1	Common Ion Effect	106
6.1.1.2	Thermodynamic Basis of Solubility and the Influence of Additives	106
6.1.1.3	Complex Formation	106
6.1.2	Rate of Nucleation and Crystal Growth	107
6.1.2.1	Nucleation Rates	107
6.1.2.2	Crystal Growth Rates	111
6.1.3	Habit Modification	114
6.2	Influence of Impurities: Modeling	116
6.2.1	Calculating Crystal Habit	116
6.2.1.1	Surface Energy Model	117
6.2.2	Molecular Modeling	118
6.2.3	Modeling of Additives	120
6.3	Tailor-Made Additives	122
6.4	Modeling the Influence of Solvents	122
	References	124
7	Purification by Crystallization	129
	<i>Heike Lorenz and Wolfgang Beckmann</i>	
7.1	Introduction	129
7.2	Mechanisms of Impurity Incorporation and Purification	131
7.2.1	Solubility in the Solid State	132
7.2.2	Fractional Crystallization	133
7.2.3	Inclusion and Surface Adsorption of Impurities	134
7.2.4	Influence of Crystallization Conditions	136
7.2.4.1	Product Yield	136
7.2.4.2	Crystallization Technique and Rate of Crystallization	137
7.2.4.3	Solvent Applied	139
7.2.4.4	Mixing	142

7.2.5	Downstream Processes	142
7.2.5.1	Solid–Liquid Separation and Sweating	143
7.2.5.2	Reslurrying and Washing	144
7.2.6	Workflow to “Manage” Impurities in Process Development	146
	References	147
8	Characterization of Crystalline Products	149
	<i>Rolf Hilfiker</i>	
8.1	Introduction	149
8.2	Characterization of Intrinsic Properties of a Solid	149
8.2.1	Crystal Structure	150
8.2.1.1	X-Ray Powder Diffraction (XRPD)	150
8.2.1.2	Vibrational Spectroscopy (Raman, IR, NIR, THz)	151
8.2.1.3	Solid-State NMR (ssNMR)	152
8.2.2	Thermodynamic Properties	154
8.2.2.1	Differential Scanning Calorimetry (DSC)	154
8.2.2.2	Isothermal Microcalorimetry	157
8.2.3	Composition	158
8.2.3.1	Thermogravimetry (TG, TG-FTIR, and TG-MS)	158
8.2.3.2	Dynamic Vapor Sorption (DVS)	158
8.3	Characterization of Particle Shape and Size	161
8.3.1	Particle Size Distribution: Characteristic Values and Graphs	161
8.3.2	Overview of Available Methods	162
8.3.2.1	Microscopy	163
8.3.2.2	Laser Light Diffraction	163
8.3.2.3	Sieving	165
8.4	Powder Flow Properties	165
8.5	In-Process Characterization	167
8.5.1	Turbidity	167
8.5.2	Raman	168
8.5.3	FBRM and PVM	169
	References	171
9	Basics of Industrial Crystallization from Solution	173
	<i>Wolfgang Beckmann</i>	
9.1	Generation of Supersaturation in a Crystallizer	173
9.2	Mass and Population Balance for Growth from Suspension	176
9.2.1	Mass Balance	176
9.2.2	Population Balance	176
9.3	Operation of a Continuous Crystallizer: Basics	178
9.3.1	Concept and Design of Continuous Crystallizers	178
9.3.2	Mass Balance in a Continuous Crystallizer	178
9.3.3	Population Balance in a Continuous Crystallizer	178
9.3.4	Mean Particle Size	180
9.3.5	Secondary Nucleation	180

9.4	Operation of a Batch Crystallizer: Basics	183
9.4.1	Concept and Design of Batch Crystallizers	183
9.4.2	Mass and Population Balance in a Batch Crystallizer	184
10	Development of Batch Crystallizations	187
	<i>Dierk Wieckhusen</i>	
10.1	Setting Goals	187
10.2	Crystallization of Organic Moieties	188
10.3	Generation of Supersaturation in Batch Crystallizations	189
10.3.1	Cooling	189
10.3.2	Use of Antisolvent	190
10.3.3	Evaporation	191
10.4	Initiation of Crystallization – Nucleation Phase	192
10.5	Seeded Batch Crystallizations	193
10.5.1	Seeding Strategy	194
10.5.2	Designing a Seeding Process	194
10.5.2.1	Quality of Seeds	195
10.5.2.2	Quantity of Seeds	195
10.5.2.3	Preparation of Seeds	196
10.5.2.4	Supersaturation at the Start of Crystallization	197
10.5.2.5	Holding Time After Seeding	197
10.6	Crystallization Period	197
10.7	Scale-Up Considerations	198
10.7.1	Process Time – Rate of crystallization	198
10.7.2	Stirring	199
10.7.3	Operational Aspects	200
10.8	Manipulating Particle Shape	201
11	Continuous Crystallization	203
	<i>Günter Hofmann and Christian Melches</i>	
11.1	Concept and Design of Continuous Crystallizers	204
11.1.1	Importance of Secondary Nucleation	204
11.1.2	Control of Supersaturation	205
11.1.3	Adjustment of the Granulometry – Mean Crystal Size and Crystal Size Distribution	209
11.1.4	Energy Input and Retention Time	212
11.1.5	Which Type of Crystallizer to Select?	215
11.1.6	Seeding of DTB and Oslo Crystallizers	216
11.2	Various Continuous Crystallizers	218
11.2.1	FC Group	218
11.2.2	DTB Group	220
11.2.3	Group of Fluidized Bed Crystallizers	222
11.2.4	Comments on Population Balance and Modeling	223
11.2.5	Manipulation of Crystal Size Distributions	225
11.3	Periphery	226

11.4	Special Features of the Process	229
11.4.1	Surface Cooling Crystallization	229
11.4.2	Vacuum Cooling Crystallization	230
11.4.3	Vacuum Evaporation Crystallization	230
11.5	Adjustment of Suspension Densities	232
	References	233
12	Precipitation	235
	<i>Wolfgang Beckmann</i>	
12.1	Precipitation from Solution by Mixing Two Streams	235
12.1.1	Devices and Mixing Schemes	235
12.2	Semi-Batch Precipitations	236
12.3	Model of Mixing during Precipitation	238
12.4	Precipitations Using Supercritical Fluids	239
12.5	Crystal Issues	241
12.5.1	Polymorphism of Precipitates	241
12.5.2	Crystal Perfection	243
12.5.3	Agglomeration	244
12.6	Particle Size as a Function of Operating Conditions	244
13	Mixing in Crystallization Processes	247
	<i>Bernd Nienhaus</i>	
13.1	Mixing in Batch and Continuous Crystallization Processes	247
13.2	Basic Mixing Tasks – Mixing Tasks in Crystallization	248
13.3	Impellers and Agitation Systems	249
13.3.1	General Overview and Selection Criteria	250
13.3.2	Axial Impellers	250
13.3.2.1	Propeller	250
13.3.2.2	Pitched Blade Turbine	250
13.3.2.3	Helical Ribbon Impeller	252
13.3.3	Radial Impellers	252
13.3.3.1	Flat Blade Disk Turbine	252
13.3.3.2	Disperser Disk	252
13.3.4	Tangential Impellers	253
13.4	Power Consumption of an Impeller System [2]	253
13.4.1	Diameter Ratio	255
13.4.2	Bottom Clearance	256
13.4.3	Filling Level	256
13.4.4	Multistage Impellers	256
13.5	Blending	256
13.5.1	Degree of Homogeneity	256
13.5.2	Turbulent Blending	257
13.5.3	Significance of Circulation Rate	258
13.5.4	Laminar Blending	258
13.6	Suspending	259

13.6.1	Suspending Criteria and Different States of Suspension	259
13.6.2	Power Requirement for the Suspension of Solids	262
13.6.3	Models and Mechanisms for the Suspension of Solids	263
13.6.4	Determination of the Shaft Speed Necessary for Suspending	264
13.6.4.1	Physical Parameters of Liquids and Solids	265
13.6.4.2	Solids Concentration	265
13.6.4.3	Geometry	266
13.6.5	Distribution of Solids	266
13.6.6	Influence on Mass Transfer	267
13.6.7	Influence on Blend Times	267
13.7	Scale-Up of a Crystallization Process	268
13.7.1	Model Tests	269
13.7.2	“Scale-Up” Rules	270
13.7.3	Blending	270
13.7.4	Suspension	270
13.7.5	Dispersing	271
13.7.6	Heat Transfer	272
13.7.7	Special Scale-Up Considerations	272
13.7.8	Summary	273
	References	273
14	Downstream Processes	275
	<i>Dierk Wieckhusen and Wolfgang Beckmann</i>	
14.1	Transfer of Suspension and Filter Cake	275
14.2	Solid–Liquid Separation	275
14.2.1	Cake Forming Filtration	276
14.2.2	Centrifugation	277
14.2.3	Characterization of Filterability in the Laboratory	277
14.2.4	Improving Filterability	278
14.2.5	Washing	280
14.3	Drying	280
14.3.1	Phases of the Drying Process	281
14.3.2	Drying of Hydrates and Solvates	282
14.3.3	Characterizing the Drying Behavior in the Laboratory	284
14.3.4	Amorphization during Drying	284
14.3.5	Effect of Drying on the Particle Size Distribution	285
	References	288
15	Melt Crystallization	289
	<i>Joachim Ulrich and Torsten Stelzer</i>	
15.1	Characteristics of Melt Crystallization	289
15.1.1	Definitions	289
15.1.2	Benefits of Melt Crystallization	290
15.2	Processes of Melt Crystallization	292
15.2.1	Solid Layer Crystallization	292

15.2.2	Suspension Crystallization	294
15.3	Postcrystallization Treatments	295
15.3.1	Sweating	297
15.3.2	Washing	298
15.3.3	Choices	299
15.3.4	Wash Columns	299
15.4	Laboratory Techniques	301
15.4.1	Bottle Test	301
15.4.2	Cold Finger Experiments	301
15.4.3	Zone Melting	303
	References	304
16	Examples of Realized Continuous Crystallization Processes	305
	<i>Günter Hofmann and Christian Melches</i>	
16.1	Choosing the Drain Point in Process Design	305
16.2	Example Crop Crystallization for Organic Compounds	310
16.2.1	Fields of Application for the Crop Principle	310
16.2.2	Definition of Task	311
16.2.3	Selection of the Process Design	312
16.3	Example Crystallization of Table Salt	316
16.3.1	Introduction	316
16.3.2	Performance Requirements	318
16.3.3	Process Design	318
16.3.4	Description of the Plant Function	321
16.4	Results	323
17	Design Examples of Melt Crystallization	325
	<i>Joachim Ulrich and Torsten Stelzer</i>	
17.1	Concepts of Melt Crystallization	325
17.1.1	Solid Layer Crystallization	325
17.1.2	Suspension Crystallization	331
17.2	Outlook	334
	References	335
	Index	337