

# Contents

|                                                                                    |     |
|------------------------------------------------------------------------------------|-----|
| <b>Preface</b> .....                                                               | V   |
| <b>Contents</b> .....                                                              | VII |
| <b>1 Requirements for Efficient Troubleshooting</b> .....                          | 1   |
| 1.1 Instrumentation .....                                                          | 1   |
| 1.2 Understanding the Extrusion Process .....                                      | 2   |
| 1.3 Collection and Analysis of Historical Data (Time Line) .....                   | 2   |
| 1.4 Team Building .....                                                            | 4   |
| 1.5 Condition of the Equipment .....                                               | 5   |
| 1.6 Information about the Feed Stock .....                                         | 5   |
| 1.7 Problem-Solving Techniques .....                                               | 6   |
| <b>2 Tools for Troubleshooting</b> .....                                           | 9   |
| 2.1 Temperature Measurement Devices .....                                          | 9   |
| 2.2 Data Acquisition Systems .....                                                 | 10  |
| 2.2.1 Portable Data Collectors/Machine Analyzers .....                             | 10  |
| 2.2.2 Fixed-Station Data Acquisition Systems .....                                 | 11  |
| 2.3 Light Microscopy .....                                                         | 13  |
| 2.4 Thermochromic Materials .....                                                  | 14  |
| 2.5 Thermal Analysis, IR Spectroscopy, and Rheometry .....                         | 15  |
| 2.5.1 Differential Thermal Analysis and Differential Scanning<br>Calorimetry ..... | 15  |
| 2.5.2 Thermogravimetric Analysis .....                                             | 17  |
| 2.5.3 Fourier Transform Infrared Spectroscopy .....                                | 18  |
| 2.5.4 Thermomechanical Analysis .....                                              | 19  |
| 2.5.5 Torque Rheometry .....                                                       | 19  |
| 2.5.6 High Pressure Capillary Rheometry .....                                      | 20  |
| 2.5.7 Other Thermal Characterization Techniques .....                              | 22  |
| 2.6 Miscellaneous Tools .....                                                      | 23  |
| 2.6.1 Infrared Thermography .....                                                  | 23  |
| 2.6.2 Power Measurements .....                                                     | 24  |

|          |                                                         |    |
|----------|---------------------------------------------------------|----|
| <b>3</b> | <b>Systematic Troubleshooting</b>                       | 27 |
| 3.1      | Upsets versus Development Problems                      | 27 |
| 3.2      | Machine-Related Problems                                | 27 |
| 3.2.1    | The Drive System                                        | 27 |
| 3.2.2    | The Feed System                                         | 27 |
| 3.2.3    | The Heating and Cooling System                          | 29 |
| 3.2.4    | Wear Problems                                           | 30 |
| 3.2.4.1  | Wear Mechanisms                                         | 31 |
| 3.2.4.2  | Test Methods for Wear                                   | 32 |
| 3.2.4.3  | Causes of Wear                                          | 36 |
| 3.2.4.4  | Solutions to Wear Problems                              | 41 |
| 3.2.4.5  | Rebuilding Worn Screws and Barrels                      | 46 |
| 3.2.5    | Screw Binding                                           | 50 |
| 3.2.5.1  | Extrusion of Fluoropolymers                             | 50 |
| 3.2.5.2  | The Mechanics of Screw Binding                          | 51 |
| 3.2.5.3  | Changes in Clearance Due to Temperature Differences     | 51 |
| 3.2.5.4  | Analysis of Temperature Distribution in Extruder Screws | 53 |
| 3.2.5.5  | Change in Clearance Due to Compressive Load             | 54 |
| 3.2.5.6  | Results from Analysis                                   | 55 |
| 3.3      | Polymer Degradation                                     | 55 |
| 3.3.1    | Types of Degradation                                    | 56 |
| 3.3.1.1  | Thermal Degradation                                     | 56 |
| 3.3.1.2  | Mechanical Degradation                                  | 56 |
| 3.3.1.3  | Chemical Degradation                                    | 57 |
| 3.3.2    | Degradation in Extrusion                                | 59 |
| 3.3.2.1  | Residence Time Distribution                             | 59 |
| 3.3.2.2  | Temperature Distribution Simple Calculations            | 63 |
| 3.3.2.3  | Temperature Distribution Numerical Calculations         | 68 |
| 3.3.2.4  | Reducing Degradation                                    | 75 |
| 3.4      | Extrusion Instabilities                                 | 76 |
| 3.4.1    | Frequency of Instability                                | 77 |
| 3.4.1.1  | High-Frequency Instabilities                            | 77 |
| 3.4.1.2  | Screw Frequency Instabilities                           | 81 |
| 3.4.1.3  | Low-Frequency Instabilities                             | 82 |

|          |                                                          |            |
|----------|----------------------------------------------------------|------------|
| 3.4.1.4  | Very Slow Fluctuations .....                             | 83         |
| 3.4.1.5  | Random Fluctuations .....                                | 83         |
| 3.4.2    | Functional Instabilities .....                           | 84         |
| 3.4.2.1  | Solids-Conveying Instabilities .....                     | 85         |
| 3.4.2.2  | Plasticating Instabilities .....                         | 85         |
| 3.4.2.3  | Melt-Conveying Instabilities .....                       | 86         |
| 3.4.2.4  | Devolatilization Instabilities .....                     | 86         |
| 3.4.2.5  | Mixing Related Instabilities .....                       | 87         |
| 3.4.2.6  | Distributive Mixing Sections .....                       | 87         |
| 3.4.2.7  | Dispersive Mixing Sections .....                         | 91         |
| 3.4.2.8  | Solving Mixing Problems .....                            | 97         |
| 3.4.3    | Solving Extrusion Instabilities .....                    | 99         |
| 3.5      | Air Entrapment .....                                     | 101        |
| 3.6      | Gel Problems .....                                       | 102        |
| 3.6.1    | Measuring Gels .....                                     | 103        |
| 3.6.2    | Gels Created in the Extrusion Process .....              | 104        |
| 3.6.3    | Removing Gels Produced in Polymerization .....           | 104        |
| 3.7      | Die-Flow Problems .....                                  | 105        |
| 3.7.1    | Melt Fracture .....                                      | 106        |
| 3.7.2    | Die-Lip Buildup ("Die Drool") .....                      | 108        |
| 3.7.3    | V- or W-Patterns .....                                   | 109        |
| 3.7.4    | Specks and Discoloration .....                           | 109        |
| 3.7.5    | Lines in Extruded Product .....                          | 111        |
| 3.7.5.1  | Weld Lines .....                                         | 111        |
| 3.7.6    | Optical and Appearance Properties .....                  | 112        |
| <b>4</b> | <b>Case Studies .....</b>                                | <b>115</b> |
| 4.1      | Film Coextrusion — Degradation in the Middle Layer ..... | 115        |
| 4.1.1    | Description of the Problem .....                         | 115        |
| 4.1.2    | Analysis of the Problem .....                            | 115        |
| 4.1.3    | Solution .....                                           | 117        |
| 4.2      | Film Coextrusion with Interfacial Problems .....         | 118        |
| 4.2.1    | Description of the Problem .....                         | 118        |
| 4.2.2    | Analysis of the Problem .....                            | 118        |
| 4.2.3    | Solution .....                                           | 118        |

|        |                                                                |     |
|--------|----------------------------------------------------------------|-----|
| 4.3    | Lines in the Extruded Film .....                               | 119 |
| 4.3.1  | Description of the Problem .....                               | 119 |
| 4.3.2  | Analysis of the Problem .....                                  | 120 |
| 4.3.3  | Solution .....                                                 | 120 |
| 4.4    | Color Variation in Polypropylene Carpet Fiber .....            | 121 |
| 4.4.1  | Description of the Problem .....                               | 121 |
| 4.4.2  | Analysis of the Problem .....                                  | 121 |
| 4.4.3  | Solution .....                                                 | 121 |
| 4.5    | Plastic Film with Poor Transparency .....                      | 123 |
| 4.5.1  | Description of the Problem .....                               | 123 |
| 4.5.2  | Analysis of the Problem .....                                  | 124 |
| 4.5.3  | Solution .....                                                 | 125 |
| 4.6    | Wear Problem in Film Extrusion .....                           | 126 |
| 4.6.1  | Description of the Problem .....                               | 126 |
| 4.6.2  | Solution .....                                                 | 126 |
| 4.7    | Multilayer Film — Several Appearance Problems .....            | 127 |
| 4.7.1  | Problem Description .....                                      | 127 |
| 4.7.2  | Analysis of the Problem .....                                  | 127 |
| 4.7.3  | Solution .....                                                 | 128 |
| 4.8    | Dispersion Problem in a High-Density Polyethylene Bottle ..... | 128 |
| 4.8.1  | Description of the Problem .....                               | 128 |
| 4.8.2  | Analysis of the Problem .....                                  | 129 |
| 4.8.3  | Solution .....                                                 | 130 |
| 4.9    | Polymer Degradation .....                                      | 131 |
| 4.9.1  | Description of the Problem .....                               | 131 |
| 4.9.2  | Analysis of the Problem .....                                  | 131 |
| 4.9.3  | Solution .....                                                 | 132 |
| 4.10   | Heat-Sealing Problems in a Coextruded Film .....               | 133 |
| 4.10.1 | Problem Description .....                                      | 133 |
| 4.10.2 | Analysis of the Problem .....                                  | 133 |
| 4.10.3 | Solution .....                                                 | 136 |
| 4.11   | Output Problem in a Blown Film Line .....                      | 137 |
| 4.11.1 | Description of the Problem .....                               | 137 |
| 4.11.2 | Analysis of the Problem .....                                  | 137 |
| 4.11.3 | Solution .....                                                 | 138 |

|        |                                                                    |     |
|--------|--------------------------------------------------------------------|-----|
| 4.12   | Master Batch Selection .....                                       | 140 |
| 4.12.1 | Description of the Problem .....                                   | 140 |
| 4.12.2 | Analysis of the Problem .....                                      | 141 |
| 4.12.3 | Solution .....                                                     | 142 |
| 4.13   | Pipe Extrusion Problem .....                                       | 142 |
| 4.13.1 | Description of the Problem .....                                   | 142 |
| 4.13.2 | Analysis of the Problem .....                                      | 143 |
| 4.13.3 | Solution .....                                                     | 143 |
| 4.14   | Gel Formation in a Coextruded Film .....                           | 145 |
| 4.14.1 | Description of the Problem .....                                   | 145 |
| 4.14.2 | Analysis of the Problem .....                                      | 145 |
| 4.14.3 | Solution .....                                                     | 146 |
| 4.15   | Agglomerates and Grammage Variation in a PP Sheet .....            | 146 |
| 4.15.1 | Description of the Problem .....                                   | 146 |
| 4.15.2 | Analysis of the Problem .....                                      | 146 |
| 4.15.3 | Solution .....                                                     | 148 |
| 4.16   | Insufficient Melting and Mixing in a Plasticating Unit .....       | 149 |
| 4.16.1 | Description of the Problem .....                                   | 149 |
| 4.16.2 | Analysis of the Problem .....                                      | 150 |
| 4.16.3 | Solution .....                                                     | 152 |
| 4.17   | High Melt Temperature and Insufficient Output in Coextrusion ..... | 153 |
| 4.17.1 | Description of the Problem .....                                   | 153 |
| 4.17.2 | Analysis of the Problem .....                                      | 153 |
| 4.17.3 | Solution .....                                                     | 155 |
| 4.18   | Deficient Solids Conveying and Dispersion .....                    | 157 |
| 4.18.1 | Description of the Problem .....                                   | 157 |
| 4.18.2 | Analysis of the Problem .....                                      | 158 |
| 4.18.3 | Solution .....                                                     | 159 |
| 4.19   | Instability of Formation at the Die .....                          | 160 |
| 4.19.1 | Description of the Problem .....                                   | 160 |
| 4.19.2 | Analysis of the Problem .....                                      | 161 |
| 4.19.3 | Solution .....                                                     | 162 |
| 4.20   | Intermittent Pumping in a Vented Extruder .....                    | 166 |
| 4.20.1 | Description of the Problem .....                                   | 166 |

|                      |                                                      |            |
|----------------------|------------------------------------------------------|------------|
| 4.20.2               | Analysis of the Problem .....                        | 167        |
| 4.20.3               | Solution .....                                       | 168        |
| 4.21                 | Melt Fracture or Sharkskin in m-PE .....             | 170        |
| 4.21.1               | Description of the Problem .....                     | 170        |
| 4.21.2               | Analysis of the Problem .....                        | 170        |
| 4.21.3               | Solution .....                                       | 171        |
| <b>Appendix 1</b>    | <b>Systematic Problem Solving .....</b>              | <b>173</b> |
| <b>Appendix 2</b>    | <b>Machine Troubleshooting and Maintenance .....</b> | <b>175</b> |
| A2.1                 | Check the Oil .....                                  | 175        |
| A2.2                 | Unusual Noises .....                                 | 175        |
| A2.3                 | Vibration Monitoring .....                           | 176        |
| A2.4                 | Drive Motors and Belts .....                         | 177        |
| A2.5                 | Spare Parts .....                                    | 177        |
| A2.6                 | Screw and Barrel .....                               | 177        |
| A2.7                 | Extruder Maintenance Checklist .....                 | 178        |
| <b>Appendix 3</b>    | <b>Setting Extruder Temperatures .....</b>           | <b>181</b> |
| <b>References</b>    | <b>.....</b>                                         | <b>183</b> |
| <b>Subject Index</b> | <b>.....</b>                                         | <b>190</b> |