

Contents

Foreword	V
The Author	VII
Acknowledgement	IX
How to Use This Book	XVII
1 Introduction	1
2 Mould Types	3
2.1 Simple Open/Close Mould	3
2.1.1 Classic Structure of an Open/Close Mould	6
2.1.2 Guiding Elements	7
2.1.3 Backing Plate	10
2.2 Moulds with Moving Elements	11
2.2.1 Undercut	11
2.2.2 Slide	12
2.2.3 Slide Operation	13
2.2.4 Latch, Clip Lock	14
2.2.5 Inclined Ejector	15
2.2.6 Forced Demoulding	17
2.2.7 Mould Size	18
2.3 Mould for Threads	19
2.3.1 External Threads	20
2.3.2 Internal Threads	22
2.3.3 Drive Types for De-spindling	23
2.3.3.1 Hydraulic Unscrewing Unit	23
2.3.3.2 Gear Rack	24
2.3.3.3 High-Helix Lead Screw	25
2.3.3.4 Multi-cavity Moulds	27

2.4	Multi-component Injection Moulds	28
2.4.1	Material Pairings	28
2.4.2	Mould Technology	29
2.4.2.1	Shifting Technology	29
2.4.2.2	Rotary Table Technology	32
2.4.2.3	Sealing Slide Technology	35
2.4.2.4	Further Technologies	35
2.5	Stack Mould	35
2.5.1	Material Combinations	36
2.5.2	Hot Runner	36
2.5.3	Opening and Closing	37
2.5.4	Toggle Lever	40
2.5.5	Ejection	41
2.5.6	General Information on the Stack Mould	41
2.6	Further Literature	42
3	Preparation	43
3.1	CAD System	43
3.2	Data Transfer, Procedure, and Processing	44
3.2.1	Data Transfer	45
3.2.2	Formats	45
3.2.2.1	IGES	45
3.2.2.2	STEP	46
3.2.2.3	STL	46
3.2.3	Data Size	48
3.2.4	Shrinkage	48
3.2.4.1	Material Selection	48
3.2.4.2	Shrinkage (Physical Process)	49
3.2.4.3	Influencing Variables	49
3.2.5	Calculation and Impact	51
3.2.5.1	Free Shrinkage, Constrained Shrinkage	53
3.2.5.2	Warping	56
3.3	Specifications	59
3.3.1	Location of the Component inside the Injection Mould	59
3.3.1.1	Demoulding Direction	59
3.3.2	Number of Cavities	63
3.3.3	Arrangement of Cavities	66
3.4	Material Selection for Injection Moulds	71
3.5	Mould Size	74

3.6	Plate Thickness	77
3.7	Demoulding	78
3.7.1	Basic Principle of Demoulding	78
3.7.2	Draft Angles	78
3.7.2.1	Definition	79
3.7.2.2	Effect on the Opening of the Mould	80
3.7.2.3	Draft Angle in the Split Line Face	81
3.7.2.4	Demoulding Problems and Solutions	83
3.8	Split Line Face	87
3.8.1	Plain Split Line Face	87
3.8.2	Contour-Forming Split Line Face	88
3.8.3	Jumping Split Line Face	88
3.8.4	Wear Plates in the Split	90
3.8.5	Visible Split Line	91
3.9	Injection	93
3.9.1	Injection and Feed Point	93
3.9.2	Simulation	95
3.9.3	Sprue System, Sprue Type	101
3.9.3.1	Cold Runner	101
3.9.3.2	Hot Runner	102
3.9.4	Runner	103
3.9.5	Sprue on the Part	105
3.9.6	Tunnel Gate	106
3.9.7	Film Gate	111
3.9.8	Diaphragm Gate	112
3.9.9	Hot Runner Single Nozzle	114
3.9.10	Hot Runner Distributor	116
3.9.11	Hot Runner Distribution System with Needle Valve	118
3.9.11.1	Integral Hinge	122
3.9.12	Three-Plate Mould	123
3.9.13	Tunnel Gate Inserts	126
3.10	Ventilation	127
3.10.1	General Information about Ventilation	127
3.10.2	Ventilation via Components	130
3.10.3	Geometric Design of Ventilation	132
3.11	Further Literature	134

4	Components	135
4.1	Mould Inserts/Mould Cores	135
4.1.1	Mould Inserts	135
4.1.2	Mould Cores	140
4.2	Slides	144
4.2.1	Application Areas of Slides	144
4.2.2	Design of a Slide	146
4.2.2.1	Mould Contour	147
4.2.2.2	Split Line on Slide	148
4.2.2.3	Slide Body and Guiding	150
4.2.2.4	Operation of Slides	152
4.2.2.5	Locking in the End Position	157
4.2.2.6	Cooling in Slide	161
4.2.3	Further Slide Concepts	162
4.2.3.1	Slide in Slide	163
4.2.3.2	“Backpack” Slide	165
4.3	Ejectors	167
4.3.1	Types of Ejectors	169
4.3.2	Ejectors as Auxiliary Tools	174
4.3.3	Inclined Ejectors	176
4.3.4	Stripper Plate	178
4.3.5	Two-Stage Ejectors	180
4.3.6	Collapsible Cores	182
4.3.7	Forced Demoulding	183
4.4	Cooling System	183
4.4.1	Cooling Type and Auxiliary Equipment	186
4.4.1.1	Drilled Cooling	188
4.4.1.2	Redirection of Cooling Circuits	190
4.4.1.3	Copper Cores	195
4.4.1.4	Heating Cartridges	196
4.4.1.5	Connection of circuits	197
4.4.2	Connection and Sealing of Cooling Holes	198
4.5	Components and Marking	200
4.6	Surface	202
4.6.1	Rough Surface	203
4.6.2	EDM	204
4.6.3	Graining	206
4.6.4	Laser Texturing	207
4.6.5	Polishing	208

4.7	Systematic Design Approach	209
4.7.1	Strategy	209
4.7.2	Standard Parts	211
4.7.3	Manufactured Parts	213
4.8	Further Literature	215
5	Assembly	217
5.1	Systematic Assembly	217
5.2	Spotting	222
5.3	Connection of Components	224
5.4	Check the Cooling for Leaks	227
5.5	Further Literature	229
6	Further Knowledge	231
6.1	Process Chain in Mould Making	231
6.2	Quality Assurance	233
6.3	Fits and Play in the Mould: What Must Fit?	235
6.4	Heat Treatment	239
6.4.1	Annealing	240
6.4.2	Hardening	241
6.4.3	Nitriding	243
6.5	Coatings	245
6.6	Changes: What Is to Be Considered?	246
6.7	Further Literature	248
7	The Finished Mould	249
7.1	Mould Validation	249
7.1.1	Clamping and Connecting the Media	249
7.1.2	Filling of the Mould	252
7.1.2.1	Balancing Cavities	254
7.1.2.2	Optimising the Parameters	256
7.1.2.3	Influence on the Injection Process	257
7.1.3	Parameters during Injection	257
7.1.4	Forces Acting in the Mould during the Injection Process	258
7.1.5	Initial Sample Inspection Report	260
7.2	Labels on the Mould	261
7.3	Further Literature	262

8	Maintenance and Repair	263
8.1	Maintenance Schedule	263
8.2	Welding	264
8.2.1	Tungsten Inert Gas Welding (TIG)	264
8.2.2	Laser Beam Welding	265
8.3	Component Replacement	266
8.4	Further Literature	267
9	Manufacturing Technologies	269
9.1	Milling	269
9.1.1	3-Axis Milling	271
9.1.2	4- and 5-Axis Milling	273
9.1.2.1	4-Axis Milling	273
9.1.2.2	5-Axis Milling	274
9.1.2.3	3+2-Axis Milling	275
9.1.2.4	Simultaneous 5-Axis Milling	276
9.1.3	CAM Programming	278
9.2	EDM	282
9.2.1	Sinker EDM	283
9.2.2	Wire EDM	285
9.3	Grinding/Profile Grinding	286
9.4	Drilling/Deep Hole Drilling	287
9.5	Turning	289
9.6	New Technologies	290
9.6.1	LaserCUSING®/Laser Sintering	290
9.6.2	Vacuum Soldering	291
9.7	Polishing	293
9.8	Further Literature	293
10	Practical Guidelines	295
10.1	Design Check List	297
10.2	Design Colour Chart	298
10.3	Sequential Function Chart	299
10.4	Maintenance Schedule	300
10.5	Formulas and Calculations	301
	Index	303