

Contents

Part I	General information about paint analysis	11
1	The surface	11
2	Why paint analysis?	14
3	Relevance of modern analytical techniques to paint analysis	15
4	General considerations	16
5	Chemical mapping	19
	5.1 Infrared microscopy mapping	20
	5.2 TOF-SIMS imaging	21
	5.3 SEM-EDS mapping	22
6	Depth profiling	22
7	Instrumentation	24
Part II	Coating failure analysis	
1	The bumpy road to knowledge	25
2	The analytical procedure	27
	2.1 Inquiry	28
	2.2 Inspection	29
	2.2.1 Macroscopic inspection	29
	2.2.2 Microscopic inspection	29
	2.3 Informed guess	30
	2.4 Instrument selection	32
	2.5 Investigation	34
	2.6 Interpretation	34
	2.7 Iterance	37
	2.8 Implementation	38
	2.9 Incumbency	39
3	The power of sampling	40
	3.1 The role of sampling in the analytical procedure	40
	3.2 Random sampling and representativeness	40
	3.3 Targeted sampling	45
	3.4 Non-destructive sampling	45
	3.4.1 Wipe sampling	45
	3.4.2 Rinse sampling	46
	3.4.3 Abrasive sampling	48
	3.5 Typical sampling failures	49
	3.5.1 Wrong sample collection	49
	3.5.2 Non-representative sampling	50
	3.5.3 Selecting the wrong amount of samples	50
	3.5.4 Application of a wrong sampling procedure	51
	3.5.5 Inappropriate sampling tools and containers	51
	3.5.6 Insufficient storing and shipping of samples	52
	3.6 Microsampling	53
4	Paint failures and their analytical approach	54
	4.1 Some considerations on failure reasons	54
	4.1.1 Insufficient workpiece preparation	55
	4.1.2 Handling failures	60

4.1.3	Application conditions	60
4.1.4	Environment and climate	62
4.2	Investigation of adhesion failures	63
4.2.1	Delamination due to substrate contamination	66
4.2.2	Adhesion defects caused by migration processes	69
4.2.3	Delamination caused by moulding conditions	71
4.2.4	Delamination due to application faults	73
4.2.5	Delamination due to insufficient pretreatment	77
4.3	Paint cratering and "fisheyes"	78
4.3.1	Cratering caused by contamination of the paint material	82
4.3.2	Craters and pinholes caused by substrate contaminants	84
4.3.3	Craters caused by paint additive agglomeration	86
4.3.4	Cratering caused by the application conditions	88
4.4	Bubbles and blisters	90
4.5	Discolouration	93
4.6	Hazes and stains	97
4.7	Paint spots	102
4.8	Orange peel	108
4.9	References	109
Part III	Quality control and process analysis	111
1	Quality control of raw material	112
1.1	Binders	113
1.1.1	Identity check	114
1.1.2	Detection of trace contaminants	115
1.2	Solvents	117
1.3	Pigments and fillers	121
2	Quality control of paint production	124
2.1	Analysis of filter residues	124
2.1.1	SEM/EDS analysis of filter residues	125
2.1.2	FT-IR analysis of filter residues	127
2.2	Analysis of fogging residues	130
2.3	Quality check of finished and semi-finished products	132
2.3.1	ATR-FT-IR screening	133
2.3.2	TOF-SIMS analysis	135
2.3.3	Headspace GC-MS analysis	135
2.4	Paint quality tests	135
3	Field analysis	140
3.1	Process analysis of paint shops	141
3.2	Aerosol analysis	144
3.3	Operating test	145
3.4	Sampling of the painting air	147
3.5	Monitoring of pretreatment steps	149
3.6	Investigation of the degree of crosslinking in 2-pack paints	152
3.7	Investigation of paint additive migration	155
3.8	Marine and aircraft coating inspection	157
3.9	Handhelds and portables	158
3.10	References	160

Part IV	Methods of coating analysis	161
1	Optical light microscopy	161
1.1	Extended focus imaging (EFI)	161
1.2	Differential interference contrast (DIC)	164
2	Fluorescence microscopy	164
3	Infrared spectroscopy	165
3.1	Physical background	165
3.2	Characteristic absorptions	166
3.3	Instrumentation	168
3.4	Sample preparation	169
3.5	Spectrum representation	170
3.6	Quantification	170
3.7	Data analysis and evaluation	172
3.7.1	Data processing	173
3.7.2	Use of databases	174
4	Surface infrared spectroscopy	176
4.1	ATR-FT-IR spectroscopy	177
4.1.1	Physical background	179
4.1.2	Depth of penetration	179
4.1.3	Information depth	180
4.1.4	Effective path length	181
4.1.5	Quantification	181
4.1.6	Detection limit	182
4.1.7	Instrumentation	184
4.1.8	Sample preparation	187
4.2	Reflection infrared spectroscopy	188
4.2.1	Physical background	188
4.2.2	External reflection	190
4.2.3	Instrumentation	196
4.3	Diffuse reflection spectroscopy	196
4.3.1	Physical background	197
4.3.2	Penetration depth	199
4.3.3	Influences of variable parameters on the spectrum	199
4.3.4	Sample preparation	201
4.3.5	Instrumentation	202
4.3.6	Quantification	202
4.3.7	Optimization of the measuring parameters	203
4.3.8	Repeatability	203
5	Infrared microscopy	204
5.1	Instrumentation	205
5.2	Sample preparation	207
5.3	Infrared microscopy, infrared transmission mode	207
5.4	Infrared microscopy, reflection mode	207
5.5	Infrared microscopy, ATR mode	210
5.6	Line-scan und mapping analyse	213
6	Raman spectroscopy	215
6.1	Physical background	216
6.2	Instrumentation	217