

Contents

About the authors — V

Abstract — VII

Foreword — IX

Chapter 1

History of the development of physical metallurgy — 1

- 1.1 Physical and applied metallurgy — 1
- 1.2 The history of the development of physical metallurgy — 1
- 1.3 Course content — 9

Chapter 2

Phase diagrams — 11

- 2.1 The phase rule — 11
- 2.2 Thermodynamic justification for constructing phase diagrams — 12
- 2.3 Unlimited solubility diagram: the lever rule — 14
- 2.4 A eutectic diagram — 18
- 2.5 Experimental construction of phase diagrams — 21
- 2.6 A diagram with limited solubility in the solid state — 23
- 2.7 A peritectic diagram — 25
- 2.8 Diagrams with intermediate phase — 26
- 2.9 Diagrams with transformations at solid state — 28
- 2.10 Ternary phase diagrams — 31
- 2.11 T - P phase diagrams — 37
- 2.12 Metastable diagrams — 39

Chapter 3

Crystallization — 43

- 3.1 The liquid and solid states of a metal — 43
- 3.2 The theory of homogeneous nucleation — 44
- 3.3 Heterogeneous nucleation — 47
- 3.4 Crystallization kinetics — 48
 - 3.4.1 Growth kinetics of nucleus centers — 48
 - 3.4.2 Growth mechanisms — 50
 - 3.4.3 Formal kinetics — 51
 - 3.4.4 About grain size — 53
- 3.5 Dendritic growth — 54
- 3.6 Concept of ingot structure — 55

- 3.7 Segregation — 57
- 3.8 Eutectic crystallization — 58
- 3.9 Amorphous alloys — 59

Chapter 4

Diffusion in metals — 65

- 4.1 Phenomenological theory of diffusion: Fick's laws — 65
- 4.2 The diffusion coefficient — 66
- 4.3 Examples of solving diffusion problems — 67
 - 4.3.1 Evaluation of diffusion paths — 69
- 4.4 Diffusion in a stress field — 70
- 4.5 Atomic diffusion theory: diffusion coefficient — 71
 - 4.5.1 Random movements and diffusion coefficient — 71
- 4.6 Atomic diffusion mechanisms — 73
 - 4.6.1 An interstitial mechanism — 73
 - 4.6.2 The vacancy diffusion mechanism — 74
 - 4.6.3 Diffusion along interstitials by a replacement mechanism: a clustering mechanism (crowdion) — 75
 - 4.6.4 The ring diffusion mechanism — 76
- 4.7 Paths of accelerated diffusion — 77
 - 4.7.1 Nonequilibrium (excessive) vacancies — 77
 - 4.7.2 Dislocations — 78
 - 4.7.3 Grain boundaries — 79
 - 4.7.4 Surface — 81
- 4.8 Diffusion and equilibrium diagrams — 82
 - 4.8.1 Diffusion coefficient in binary alloys — 82
 - 4.8.2 About driving forces of diffusion: Darken's experiment — 84
 - 4.8.3 About diffusion growth of phases — 84
 - 4.8.4 The Kirkendall effect — 86

Chapter 5

Plastic deformation and recrystallization — 89

- 5.1 Elastic and plastic deformation: definitions — 89
- 5.2 Plastic deformation of single crystals — 90
 - 5.2.1 Slip — 90
 - 5.2.2 Schmid's law — 91
 - 5.2.3 Twinning — 92
 - 5.2.4 Kink bands — 94
 - 5.2.5 Stress-strain curves — 95
- 5.3 Plastic deformation of polycrystals — 96
- 5.4 Large plastic deformations — 98
- 5.5 The formation of point defects during deformation — 101

- 5.6 Deformation textures — 103
- 5.7 The influence of plastic deformation on the properties of metals — 104
- 5.8 Phenomena in deformed metals during heating — 106
- 5.9 Recovery: relaxation and polygonization — 107
- 5.10 Recrystallization — 111
- 5.11 Primary recrystallization — 112
- 5.12 Collective and secondary recrystallization — 118
- 5.13 Recrystallization textures — 120
- 5.14 Dynamic recrystallization — 120
- 5.15 The influence of relaxation and recrystallization on the properties of metals — 121

Chapter 6

Phase transformations in the solid state — 125

- 6.1 First- and second-order phase transitions — 125
- 6.2 Martensitic transformations — 127
 - 6.2.1 Thermodynamics of martensitic transformations — 127
 - 6.2.2 Kinetics of martensitic transformations — 129
 - 6.2.3 The problem of nucleation at martensitic transformations — 134
 - 6.2.4 Phenomenological crystallographic theory of martensitic transformations — 134
 - 6.2.5 Microstructure of martensite — 139
 - 6.2.6 Effects of shape memory. Superelasticity. Reactive stresses — 139
 - 6.2.7 Massive transformations — 144
- 6.3 Decomposition of supersaturated solid solutions — 145
 - 6.3.1 Continuous and spinodal decomposition — 147
 - 6.3.2 Formation of microstructure — 150
 - 6.3.3 Discontinuous decomposition — 154
- 6.4 Ordering — 156

Chapter 7

Transformations in steel — 163

- 7.1 Iron–cementite diagram — 163
- 7.2 Diagrams of the decomposition of supercooled austenite (TTT diagrams) — 164
- 7.3 Main transformations in steels — 166
- 7.4 Pearlite transformation — 167
- 7.5 Martensitic transformation — 171
- 7.6 Intermediate (bainitic) transformation — 182

XIV — Contents

7.7 Tempering of hardened steel — **187**

7.8 Austenite formation — **195**

Conclusion — 205

Bibliography — 207

Index — 209