

Contents

Preface	V
About the Authors	VII
1 Troubleshooting Methodology	1
1.1 Troubleshooting	1
1.2 What Makes an Effective Troubleshooter?	1
1.3 What Makes an Ineffective Troubleshooter?	3
1.4 Troubleshooting Methodology	3
1.4.1 STOP: Systematically	4
1.4.2 STOP: Think	6
1.4.3 STOP: Observe	7
1.4.4 STOP: Proceed	10
1.4.5 STOP: Troubleshooting Cycle	12
1.4.6 Hard Fix versus Processing around Problem	13
1.4.7 Troubleshooting Tools	13
1.4.8 Troubleshooting Methodology Summary	18
2 Troubleshooting Tool Kit	21
2.1 Lockout/Tagout	21
2.2 Hand Tools	21
2.3 Pyrometer	22
2.4 Spotting Blue	22
2.5 Measurement Tools	22
2.6 Multimeter	22
2.7 Process Monitoring Equipment	23
2.8 Moisture Analyzer	23

2.9	Dew Point Meter	23
2.10	Flashlight	24
2.11	Microscope/Magnifying Glass	24
2.12	Silly Putty	24
2.13	Inspection Mirror	24
2.14	Thermal Imaging Camera	25
2.15	Aluminum Tape	25
2.16	Dial Indicator	25
2.17	Purging Compound	25
2.18	Grinder/Stones	26
2.19	Camera	26
2.20	Material Data	26
2.21	Scale	26
2.22	Flow Meter	27
2.23	Mold Cleaning Supplies	27
2.24	Miscellaneous Supplies	27
3	Decoupled® or Scientific Molding	29
4	Gating Details	33
4.1	Gating	33
4.2	Gate Size, Shape, and Taper	35
4.3	Mental Picture Volume versus Pressure	40
5	Mold Hydraulics	41
5.1	Hydraulic Uses	41
5.2	Set and Pull Pressure	41
5.3	Cylinder Sizing	42
5.4	Hydraulic Cores or Slides	44
5.5	Multiple Sequences	44
5.6	Mounting	45
5.7	Switches	45

6	Mold Texture and Polish	47
6.1	Mold Texture	47
6.2	Mold Polish	50
7	Venting	53
7.1	Venting Basics	53
7.2	Alternate Venting	58
7.3	Venting Conclusion	61
8	Machine Performance	63
8.1	Load Sensitivity	65
8.2	Dynamic Check Valve Study	66
8.3	Velocity Linearity	67
8.4	10-Cycle Overlay	70
8.5	Cycle Variation	72
8.6	Velocity to Pressure Transfer	74
	8.6.1 Machine Control	77
8.7	Machine Documentation	80
9	Drying	83
9.1	Introduction	83
9.2	Keys to Drying	83
	9.2.1 Temperature	85
	9.2.2 Dry Air	85
	9.2.3 Air Flow	87
	9.2.4 Time	87
9.3	Moisture Analysis	88
9.4	Material Handling	90
9.5	Material Concerns	92
10	Purging	93
10.1	Purging Impact	93
10.2	Purging Method Example	94
10.3	Purging Compounds	95

11	Hot Runners	97
11.1	Hot Runner Advantages	97
11.2	Heaters and Thermocouples	97
11.3	Hang Up Areas	98
11.4	Hot Drop Tips	98
11.5	Drooling, Stringing, and Sprue Sticking	99
11.6	Freeze Off	99
11.7	Orifice Size	99
11.8	Leakage	100
11.9	Zones and Wiring	101
11.10	Hot Runner Troubleshooting	101
12	Cavity Balance	103
12.1	Flow Length	105
12.2	Flow Diameter	105
12.3	Shear	105
12.4	Cooling	107
12.5	Venting	108
12.6	Clamp Pressure	108
12.7	Cavity Fill Balance Study	109
12.8	Artificial Balance	110
12.8.1	Family Molds	111
13	Cavity Instrumentation	113
13.1	Cavity Pressure Technology	113
13.2	Cavity Thermocouples	120
13.3	Process Documentation	123
13.4	Process Control	124
13.5	Additional Monitoring Options	125
14	Mold Cooling	127
14.1	Mold Cooling Importance	127
14.2	Water Flow	128
14.3	Documentation	129
14.4	Tooling Techniques	130

14.5	Additive Manufacturing	132
14.6	Other Cooling Concerns	134
15	Black or Brown Specks	135
15.1	Description	135
15.2	Black Specks Troubleshooting Chart	136
15.3	Black Specks Troubleshooting	136
15.3.1	Black Specks Troubleshooting Molding Process Issues	136
15.3.2	Black Specks Troubleshooting Mold Issues	137
15.3.3	Black Specks Troubleshooting Machine Issues	139
15.3.4	Black Specks Troubleshooting Material Issues	141
16	Blush	145
16.1	Description	145
16.2	Blush Troubleshooting Chart	146
16.3	Blush Troubleshooting	146
16.3.1	Blush Troubleshooting Molding Process Issues	146
16.3.2	Blush Troubleshooting Tooling Issues	149
16.3.3	Blush Troubleshooting Machine Issues	152
16.3.4	Blush Troubleshooting Material Issues	153
17	Brown Streaks	155
17.1	Description	155
17.2	Brown Streak Troubleshooting Chart	156
17.3	Brown Streak Troubleshooting	156
17.3.1	Brown Streak Troubleshooting Molding Process Issues	156
17.3.2	Brown Streak Troubleshooting Mold Issues	160
17.3.3	Brown Streak Troubleshooting Machine Issues	163
17.3.4	Brown Streak Troubleshooting Material Issues	166
18	Bubbles	169
18.1	Description	169
18.2	Bubbles Troubleshooting Chart	170
18.3	Bubbles Troubleshooting	170
18.3.1	Bubbles Troubleshooting Molding Process Issues	171
18.3.2	Bubbles Troubleshooting Mold Issues	172
18.3.3	Bubbles Troubleshooting Machine Issues	174
18.3.4	Bubbles Troubleshooting Material Issues	175

19	Buildup	179
19.1	Description	179
19.2	Buildup Troubleshooting Chart	180
19.3	Buildup Troubleshooting	180
19.3.1	Buildup Troubleshooting Molding Process Issues	180
19.3.2	Buildup Troubleshooting Mold Issues	181
19.3.3	Buildup Troubleshooting Machine Issues	183
19.3.4	Buildup Troubleshooting Material Issues	183
20	Burns	187
20.1	Description	187
20.2	Burns Troubleshooting Chart	188
20.3	Burns Troubleshooting	188
20.3.1	Burns Troubleshooting Molding Process Issues	188
20.3.2	Burns Troubleshooting Mold Issues	191
20.3.3	Burns Troubleshooting Machine Issues	192
20.3.4	Burns Troubleshooting Material Issues	195
21	Cloudiness	199
21.1	Description	199
21.2	Cloudiness Troubleshooting Chart	200
21.3	Cloudiness Troubleshooting	200
21.3.1	Cloudiness Troubleshooting Molding Process Issues	200
21.3.2	Cloudiness Troubleshooting Mold Issues	202
21.3.3	Cloudiness Troubleshooting Machine Issues	203
21.3.4	Cloudiness Troubleshooting Material Issues	204
22	Color Swirls	207
22.1	Description	207
22.2	Color Swirls Troubleshooting Chart	208
22.3	Color Swirls Troubleshooting	208
22.3.1	Color Swirls Troubleshooting Molding Process Issues	208
22.3.2	Color Swirls Troubleshooting Mold Issues	210
22.3.3	Color Swirls Troubleshooting Machine Issues	210
22.3.4	Color Swirls Troubleshooting Material Issues	212
23	Contamination	217
23.1	Description	217

23.2	Contamination Troubleshooting Chart	218
23.3	Contamination Troubleshooting	218
23.3.1	Contamination Troubleshooting Molding Process Issues	218
23.3.2	Contamination Troubleshooting Mold Issues	220
23.3.3	Contamination Troubleshooting Machine Issues	223
23.3.4	Contamination Troubleshooting Material Issues	225
24	Cracking	231
24.1	Description	231
24.2	Cracking Troubleshooting Chart	232
24.3	Cracking Troubleshooting	232
24.3.1	Cracking Troubleshooting Molding Process Issues	232
24.3.2	Cracking Troubleshooting Mold Issues	236
24.3.3	Cracking Troubleshooting Machine Issues	237
24.3.4	Cracking Troubleshooting Material Issues	238
25	Delamination	241
25.1	Description	241
25.2	Delamination Troubleshooting Chart	242
25.3	Delamination Troubleshooting	242
25.3.1	Delamination Troubleshooting Molding Process Issues	242
25.3.2	Delamination Troubleshooting Mold Issues	243
25.3.3	Delamination Troubleshooting Machine Issues	244
25.3.4	Delamination Troubleshooting Material Issues	245
26	Dimensions	247
26.1	Description	247
26.2	Dimensions Troubleshooting Chart	247
26.3	Dimensions Troubleshooting	248
26.3.1	Dimensions Troubleshooting Molding Process Issues	248
26.3.2	Dimensions Troubleshooting Mold Issues	253
26.3.3	Dimensions Troubleshooting Machine Issues	256
26.3.4	Dimensions Troubleshooting Material Issues	259
27	Excessive Cycle Time	263
27.1	Description	263
27.2	Excessive Cycle Time Troubleshooting Chart	263
27.3	Excessive Cycle Time Troubleshooting	264

27.3.1	Excessive Cycle Time Troubleshooting Molding Process Issues	264
27.3.2	Excessive Cycle Time Troubleshooting Mold Issues	267
27.3.3	Excessive Cycle Time Troubleshooting Machine Issues	271
27.3.4	Excessive Cycle Time Troubleshooting Material Issues	273
28	High Fill Pressure	275
28.1	Description	275
28.2	High Fill Pressure Troubleshooting Chart	275
28.3	High Fill Pressure Troubleshooting	276
28.3.1	High Fill Pressure Troubleshooting Molding Process Issues ..	276
28.3.2	High Fill Pressure Troubleshooting Mold Issues	277
28.3.3	High Fill Pressure Troubleshooting Machine Issues	280
28.3.4	High Fill Pressure Troubleshooting Material Issues	284
29	Flaking	287
29.1	Description	287
29.2	Flaking Troubleshooting Chart	288
29.3	Flaking Troubleshooting	288
29.3.1	Flaking Troubleshooting Molding Process Issues	288
29.3.2	Flaking Troubleshooting Mold Issues	288
29.3.3	Flaking Troubleshooting Machine Issues	290
29.3.4	Flaking Troubleshooting Material Issues	290
30	Flash	291
30.1	Description	291
30.2	Flash Troubleshooting Chart	292
30.3	Flash Troubleshooting	292
30.3.1	Flash Troubleshooting Molding Process Issues	293
30.3.2	Flash Troubleshooting Mold Issues	297
30.3.3	Flash Troubleshooting Machine Issues	302
30.3.4	Flash Troubleshooting Material Issues	306
31	Flow Lines	309
31.1	Description	309
31.2	Flow Lines Troubleshooting Chart	309
31.3	Flow Lines Troubleshooting	310
31.3.1	Flow Lines Troubleshooting Molding Process Issues	310

31.3.2	Flow Lines Troubleshooting Mold Issues	312
31.3.3	Flow Lines Troubleshooting Machine Issues	314
31.3.4	Flow Lines Troubleshooting Material Issues	316
32	Glass Fibers on Surface	319
32.1	Description	319
32.2	Glass Fibers on Surface Troubleshooting Chart	320
32.3	Glass Fibers on Surface Troubleshooting	320
32.3.1	Glass Fibers on Surface Troubleshooting Molding Process Issues	320
32.3.2	Glass Fibers on Surface Troubleshooting Mold Issues	322
32.3.3	Glass Fibers on Surface Troubleshooting Machine Issues	324
32.3.4	Glass Fibers on Surface Troubleshooting Material Issues	325
33	Gloss Variation	329
33.1	Description	329
33.2	Gloss Variation Troubleshooting Chart	330
33.3	Gloss Variation Troubleshooting	330
33.3.1	Gloss Variation Troubleshooting Molding Process Issues	330
33.3.2	Gloss Variation Troubleshooting Mold Issues	334
33.3.3	Gloss Variation Troubleshooting Machine Issues	338
33.3.4	Gloss Variation Troubleshooting Material Issues	338
34	Jetting	341
34.1	Description	341
34.2	Jetting Troubleshooting Chart	342
34.3	Jetting Troubleshooting	342
34.3.1	Jetting Troubleshooting Molding Process Issues	343
34.3.2	Jetting Troubleshooting Mold Issues	344
34.3.3	Jetting Troubleshooting Machine Issues	346
34.3.4	Jetting Troubleshooting Material Issues	346
35	Part Sticking on Cover	347
35.1	Description	347
35.2	Part Sticking on Cover Troubleshooting Chart	347
35.3	Part Sticking on Cover Troubleshooting	348
35.3.1	Part Sticking on Cover Troubleshooting Molding Process Issues	348

35.3.2	Part Sticking on Cover Troubleshooting Mold Issues	349
35.3.3	Part Sticking on Cover Troubleshooting Machine Issues	353
35.3.4	Part Sticking on Cover Troubleshooting Material Issues	353
36	Part Sticking on Ejector	357
36.1	Description	357
36.2	Part Sticking on Ejector Troubleshooting Chart	358
36.3	Part Sticking on Ejector Troubleshooting	358
36.3.1	Part Sticking on Ejector Molding Process Issues	358
36.3.2	Part Sticking on Ejector Troubleshooting Mold Issues	361
36.3.3	Part Sticking on Ejector Troubleshooting Machine Issues	363
36.3.4	Part Sticking on Ejector Troubleshooting Material Issues	364
37	Pin Push	367
37.1	Description	367
37.2	Pin Push Troubleshooting Chart	368
37.3	Pin Push Troubleshooting	368
37.3.1	Pin Push Troubleshooting Molding Process Issues	368
37.3.2	Pin Push Troubleshooting Mold Issues	370
37.3.3	Pin Push Troubleshooting Machine Issues	372
37.3.4	Pin Push Troubleshooting Material Issues	373
38	Read-through	375
38.1	Description	375
38.2	Read-through Troubleshooting Chart	376
38.3	Read-through Troubleshooting	376
38.3.1	Read-through Troubleshooting Molding Process Issues	376
38.3.2	Read-through Troubleshooting Mold Issues	377
38.3.3	Read-through Troubleshooting Machine Issues	380
38.3.4	Read-through Troubleshooting Material Issues	380
39	Scuffs and Scratches	381
39.1	Description	381
39.2	Scuffs and Scratches Troubleshooting Chart	382
39.3	Scuffs and Scratches Troubleshooting	382
39.3.1	Scuffs and Scratches Troubleshooting Molding Process Issues	382
39.3.2	Scuffs and Scratches Troubleshooting Mold Issues	385

39.3.3	Scuffs and Scratches Troubleshooting Machine Issues	387
39.3.4	Scuffs and Scratches Troubleshooting Material Issues	387
40	Short Shot	389
40.1	Description	389
40.2	Short Shot Troubleshooting Chart	390
40.3	Short Shot Troubleshooting	390
40.3.1	Short Shot Troubleshooting Molding Process Issues	390
40.3.2	Short Shot Troubleshooting Mold Issues	397
40.3.3	Short Shot Troubleshooting Machine Issues	401
40.3.4	Short Shot Troubleshooting Material Issues	405
41	Sink	409
41.1	Description	409
41.2	Sink Troubleshooting Chart	410
41.3	Sink Troubleshooting	410
41.3.1	Sink Troubleshooting Molding Process Issues	410
41.3.2	Sink Troubleshooting Mold Issues	416
41.3.3	Sink Troubleshooting Machine Issues	420
41.3.4	Sink Troubleshooting Material Issues	423
42	Splay	425
42.1	Description	425
42.2	Splay Troubleshooting Chart	426
42.3	Splay Troubleshooting	426
42.3.1	Splay Troubleshooting Molding Process Issues	427
42.3.2	Splay Troubleshooting Mold Issues	432
42.3.3	Splay Troubleshooting Machine Issues	437
42.3.4	Splay Troubleshooting Material Issues	439
43	Sprue Sticking	443
43.1	Description	443
43.2	Sprue Sticking Troubleshooting Chart	444
43.3	Sprue Sticking Troubleshooting	444
43.3.1	Sprue Sticking Troubleshooting Molding Process Issues	444
43.3.2	Sprue Sticking Troubleshooting Mold Issues	447
43.3.3	Sprue Sticking Troubleshooting Machine Issues	451
43.3.4	Sprue Sticking Troubleshooting Material Issues	453

- 44 Stringers 455**
 - 44.1 Description 455
 - 44.2 Stringers Troubleshooting Chart 456
 - 44.3 Stringers Troubleshooting 456
 - 44.3.1 Stringers Troubleshooting Molding Process Issues 456
 - 44.3.2 Stringers Troubleshooting Mold Issues 458
 - 44.3.3 Stringers Troubleshooting Machine Issues 460
 - 44.3.4 Stringers Troubleshooting Material Issues 462
- 45 Voids 463**
 - 45.1 Description 463
 - 45.2 Voids Troubleshooting Chart 464
 - 45.3 Voids Troubleshooting 464
 - 45.3.1 Voids Troubleshooting Molding Process Issues 464
 - 45.3.2 Voids Troubleshooting Mold Issues 466
 - 45.3.3 Voids Troubleshooting Machine Issues 468
 - 45.3.4 Voids Troubleshooting Material Issues 468
- 46 Warp 469**
 - 46.1 Description 469
 - 46.2 Warp Troubleshooting Chart 469
 - 46.3 Warp Troubleshooting 470
 - 46.3.1 Warp Troubleshooting Molding Process Issues 471
 - 46.3.2 Warp Troubleshooting Mold Issues 477
 - 46.3.3 Warp Troubleshooting Machine Issues 479
 - 46.3.4 Warp Troubleshooting Material Issues 480
- 47 Weld Lines 483**
 - 47.1 Description 483
 - 47.2 Weld Lines Troubleshooting Chart 484
 - 47.3 Weld Lines Troubleshooting 484
 - 47.3.1 Weld Lines Troubleshooting Molding Process Issues 485
 - 47.3.2 Weld Lines Troubleshooting Mold Issues 487
 - 47.3.3 Weld Lines Troubleshooting Machine Issues 489
 - 47.3.4 Weld Lines Troubleshooting Material Issues 490
- Index 493**