

Contents

Chapter 1

Introduction to FA — 1

Chapter 2

Why is FA important? — 7

Chapter 3

Planning out an FA — 11

Chapter 4

Typical types of failure mechanisms — 17

Chapter 5

Destructive versus nondestructive analysis — 29

Chapter 6

Optical Microscopy (OM) — 33

Chapter 7

Scanning Acoustic Microscopy/Tomography (SAM or SAT) — 37

Chapter 8

X-ray imaging (2D and 3D) — 43

Chapter 9

Time Domain Reflectometry (TDR) — 47

Chapter 10

Selecting the path before destructive analysis begins — 51

Chapter 11

Destructive work — 55

Chapter 12

Electrical Failure Analysis (EFA) — 61

Chapter 13

EMMI/OBIRCH/IR — 67

VIII — Contents

Chapter 14

Cross sections (X-sections) — 73

Chapter 15

Parallel lapping (p-lap) — 83

Chapter 16

Focused Ion Beam (FIB) — 89

Chapter 17

Scanning Electron Microscopy (SEM) — 93

Chapter 18

Transmission Electron Microscopy (TEM) — 97

Chapter 19

Energy Dispersive X-ray spectroscopy (EDX) — 101

Chapter 20

Use of additional materials analytical techniques and processes — 105

Chapter 21

How should these results be used? — 111

References — 113

Appendix — 115

List of figures — 117

Index — 121