

Contents

1	Introduction	1
	Technologically most important systems listed in the present book	3
	References for 1	5
2	Characterization Techniques for Amorphous Alloys	6
2.1	Structural Characterization Technique	6
2.1.1	X-ray Diffractometry	6
2.1.2	Anomalous X-ray Scattering	7
2.1.3	X-ray Absorption Spectroscopy (XAS)	8
2.1.4	Small-Angle X-ray (SAX) or Neutron (SAN) Scattering	9
2.1.5	Extended X-ray Absorption Fine Structure (EXAFS)	9
2.1.6	X-ray Photoelectron Spectroscopy (XPS)	9
2.1.7	Mössbauer Spectroscopy	9
2.2	General Physical Properties	10
2.2.1	Density, Volume and Thermal Expansion Coefficient	10
2.2.2	Viscosity	10
2.2.3	Thermal Stability	11
2.2.3.1	Differential Thermal Analysis (DTA)	11
2.2.3.2	Differential Scanning Calorimetry (DSC)	11
2.2.3.3	Differential Isothermal Calorimetry	12
2.3	Mechanical Properties	13
2.3.1	Hardness Tests	13
2.3.1.1	Vickers Test	13
2.3.1.2	Vickers Microhardness	13
2.3.1.3	Knoop Hardness	14
2.3.2	Uniaxial Tensile (Compressive) Test	14
2.3.3	Bend Test	15
2.3.4	Fatigue Testing	15
2.3.5	Creep	15
2.4	Magnetic Properties	16
2.4.1	General Description	16
2.4.2	Magnetostriction	17
2.5	Electrical Properties	17
2.5.1	Electrical Resistance	17
2.5.2	Hall Effect	18
2.5.3	Superconductivity	18
2.6	Corrosion Behaviour	19
2.6.1	General Aspects	19
2.6.2	Types of Corrosion	19
	References for 2	20

3	List of Ternary Amorphous Alloys	21
4	Graphical and Numerical Data	24
	List of Properties Surveyed	24
	List of Symbols and Abbreviations	26
Ag-Al-Ca		37
2.4	DSC/DTA Curve and Glass Formation	37
2.4.1	Glass Transition Temperature	37
2.5	Crystallization Temperature	37
3.5	Hardness	37
	References	37
Ag-Al-La (001)		38
Ag-Al-Mg (002)		39
1.2	X-ray Diffraction Profile	39
2.4	DSC/DTA Curve and Glass Formation	39
2.5	Crystallization Temperature	39
2.7.1	Transition Temperature	40
5.1	Resistivity and Conductivity	40
5.1.2	Temperature Dependence of Resistivity	40
	References	40
Ag-Ca-Mg		41
1.2	X-ray Diffraction Profile	41
2.4	DSC/DTA Curve and Glass Formation	41
2.4.1	Glass Transition Temperature	42
2.4.2	Reduced Glass Transition Temperature	42
2.5	Crystallization Temperature	43
2.6	Supercooled Liquid Range	43
2.7.1	Transition Temperature	43
2.8	Critical Quantities for Formation of Amorphous Phase	43
	References	43
Ag-Ce-Cu (003)		44
1.2	X-ray Diffraction Profile	44
2.5	Crystallization Temperature	45
2.7	Phase diagram	45
3.5	Hardness	45
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	46
	References	46
Ag-Cu-Fe (004)		47
1.2	X-ray Diffraction Profile	47
1.3	Interference Function	47
1.4	Radial Distribution Function	48
1.5	Radial Structure Function	49
1.8.4	Extended X-ray Absorption Fine Structure	50
1.8.5	X-ray Absorption Near-Edge Structure	52
2.4	DSC/DTA Curve and Glass Formation	53
2.5.1	Heat of Crystallization or Relaxation	53
4.1	Thermomagnetic Curve	53
4.2	Hysteresis Loop	54
4.2.1	Coercive Force	55
4.2.2	Remanence	55

4.3.1	Magnetic Moment and Magnetic Anisotropy	55
4.8	Mössbauer Spectra	56
4.8.2	Magnetic Hyperfine Field and Line Splitting	56
	References	56
Ag-Cu-Ge (005)		57
1.1	Density and Volume	57
1.2	X-ray Diffraction Profile	58
2.1.1	Electronic Heat Capacity	58
2.1.3	Debye Temperature	59
2.5	Crystallization Temperature	59
5.1	Resistivity and Conductivity	60
5.1.2	Temperature Dependence of Resistivity	61
5.3	Hall Effect	62
5.3.1	Hall Mobility	63
5.3.2	Temperature Dependence of Hall Coefficient	63
	References	63
Ag-Cu-Mg (006)		64
5.1	Resistivity and Conductivity	64
5.4	Thermoelectric Power	64
	References	64
Ag-Cu-P (007)		65
2.5	Crystallization Temperature	65
2.7	Phase diagram	65
5.1	Resistivity and Conductivity	65
5.1.2	Temperature Dependence of Resistivity	67
5.2	Change of the Resistivity by Deformation	67
5.4	Thermoelectric Power	67
	References	67
Ag-Cu-Zr		68
1.2	X-ray Diffraction Profile	68
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	68
2.4	DSC/DTA Curve and Glass Formation	68
2.4.1	Glass Transition Temperature	69
2.4.2	Reduced Glass Transition Temperature	70
2.5	Crystallization Temperature	70
2.6	Supercooled Liquid Range	71
2.7.1	Transition Temperature	72
3.1	Stress-Strain Curve	72
	References	72
Ag-Mg-Y (008)		73
Ag-Pd-Si (009)		74
1.2	X-ray Diffraction Profile	74
2.1	Heat Capacity	74
2.4.1	Glass Transition Temperature	75
2.5	Crystallization Temperature	75
2.5.1	Heat of Crystallization or Relaxation	76
3.9	Viscosity	76
	References	76
Al-Au-La (010)		77
2.4.1	Glass Transition Temperature	77

2.5	Crystallization Temperature	77
2.6	Supercooled Liquid Range	77
	References	77
Al-B-Co (011)		78
2.5	Crystallization Temperature	78
3.5	Hardness	78
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	78
	References	78
Al-B-Fe (012)		79
2.4	DSC/DTA Curve and Glass Formation	79
2.5	Crystallization Temperature	79
3.5	Hardness	80
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	80
	References	80
Al-B-Ni (013)		81
2.5	Crystallization Temperature	81
3.5	Hardness	81
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	81
	References	81
Al-Be-Ti (014)		82
2.5	Crystallization Temperature	82
	References	82
Al-Ca-Co (015)		83
2.5	Crystallization Temperature	83
3.5	Hardness	83
	References	83
Al-Ca-Cu (016)		84
2.4	DSC/DTA Curve and Glass Formation	84
2.4.1	Glass Transition Temperature	84
2.5	Crystallization Temperature	84
3.4	Elastic Moduli	85
3.5	Hardness	85
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	85
	References	85
Al-Ca-Fe (017)		86
1.1	Density and Volume	86
2.5	Crystallization Temperature	86
3.4	Elastic Moduli	86
3.5	Hardness	87
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	87
	References	87
Al-Ca-Ga (018)		88
1.1	Density and Volume	88
2.1.1	Electronic Heat Capacity	88
2.1.3	Debye Temperature	88
5.1	Resistivity and Conductivity	89
	References	89
Al-Ca-Mg (019)		90
1.2	X-ray Diffraction Profile	90

2.1.1	Electronic Heat Capacity	90
2.4.1	Glass Transition Temperature	90
2.5	Crystallization Temperature	91
2.5.1	Heat of Crystallization or Relaxation	91
2.7.1	Transition Temperature	91
2.8	Critical Quantities for Formation of Amorphous Phase	92
3.1	Stress-Strain Curve	92
3.3	Yield Strength	92
3.4	Elastic Moduli	92
3.5	Hardness	93
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	93
5.1	Resistivity and Conductivity	93
6	Corrosion Behaviour	93
	References	94
Al-Ca-Ni (020)		95
1.1	Density and Volume	95
2.5	Crystallization Temperature	95
3.2	Tensile Strength and Strain	95
3.4	Elastic Moduli	96
3.5	Hardness	96
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	96
	References	96
Al-Ca-Zn (021)		97
2.4.1	Glass Transition Temperature	97
2.5	Crystallization Temperature	97
3.4	Elastic Moduli	97
3.5	Hardness	97
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	98
	References	98
Al-Ce-Co (022)		99
2.4	DSC/DTA Curve and Glass Formation	99
2.5	Crystallization Temperature	99
3.5	Hardness	99
	References	100
Al-Ce-Cr (023)		101
2.4	DSC/DTA Curve and Glass Formation	101
2.5	Crystallization Temperature	101
3.5	Hardness	101
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	102
	References	102
Al-Ce-Cu (024)		103
1.1	Density and Volume	103
1.2	X-ray Diffraction Profile	103
2.4	DSC/DTA Curve and Glass Formation	104
2.4.1	Glass Transition Temperature	105
2.4.2	Reduced Glass Transition Temperature	105
2.5	Crystallization Temperature	105
2.6	Supercooled Liquid Range	106
2.7.1	Transition Temperature	106
2.8	Critical Quantities for Formation of Amorphous Phase	106
3.4	Elastic Moduli	106

3.5	Hardness	107
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	107
5.1	Resistivity and Conductivity	107
	References	107
Al-Ce-Fe (025)		108
1.4	Radial Distribution Function	108
1.5	Radial Structure Function	108
1.6	Lattice Parameter	108
1.8.6	X-ray Photoelectron Spectroscopy	109
2.4	DSC/DTA Curve and Glass Formation	110
2.5	Crystallization Temperature	110
3.2	Tensile Strength and Strain	110
3.3	Yield Strength	111
3.4	Elastic Moduli	111
3.5	Hardness	111
4.5	Susceptibility and Cooling Effect	111
4.8	Mössbauer Spectra	112
6	Corrosion Behaviour	113
6.1	Potentiostatic and Potentiodynamic Polarization Curves	114
	References	114
Al-Ce-Mn (026)		115
2.4	DSC/DTA Curve and Glass Formation	115
2.5	Crystallization Temperature	115
3.5	Hardness	115
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	115
	References	116
Al-Ce-Nb (027)		117
2.5	Crystallization Temperature	117
3.5	Hardness	117
	References	117
Al-Ce-Ni (028)		118
1.2	X-ray Diffraction Profile	118
1.8.1	Atom Probe Field Ion Microscopy	118
2.1	Heat Capacity	119
2.4	DSC/DTA Curve and Glass Formation	120
2.4.1	Glass Transition Temperature	121
2.5	Crystallization Temperature	121
2.5.1	Heat of Crystallization or Relaxation	121
3.1	Stress-Strain Curve	122
3.2	Tensile Strength and Strain	122
3.4	Elastic Moduli	122
3.5	Hardness	123
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	123
3.9	Viscosity	124
5.1	Resistivity and Conductivity	124
	References	125
Al-Ce-V (029)		126
2.4	DSC/DTA Curve and Glass Formation	126
2.5	Crystallization Temperature	126
3.5	Hardness	126

3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	126
	References	127
Al-Co-Fe (030)		128
3.5	Hardness	128
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	128
	References	128
Al-Co-Gd		129
1.2	X-ray Diffraction Profile	129
2.4	DSC/DTA Curve and Glass Formation	129
2.4.1	Glass Transition Temperature	129
2.4.2	Reduced Glass Transition Temperature	129
2.5	Crystallization Temperature	130
2.6	Supercooled Liquid Range	130
2.7	Phase Diagram	130
2.7.1	Transition Temperature	130
2.8	Critical Quantities for Formation of Amorphous Phase	130
3.1	Stress-Strain Curve	131
3.4	Elastic Moduli	131
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	131
4.3	Magnetization Curve and Saturation Magnetic Moment	131
	References	132
Al-Co-Ge (031)		133
2.5	Crystallization Temperature	133
3.5	Hardness	133
5.1	Resistivity and Conductivity	133
	References	133
Al-Co-La (032)		134
Al-Co-Mn (033)		135
2.5	Crystallization Temperature	135
3.5	Hardness	135
5.1	Resistivity and Conductivity	135
	References	135
Al-Co-Ni (034)		136
1.2	X-ray Diffraction Profile	136
2.4	DSC/DTA Curve and Glass Formation	136
2.7.1	Transition Temperature	137
3.4	Elastic Moduli	137
3.5	Hardness	137
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	137
	References	137
Al-Co-Si (035)		138
2.5	Crystallization Temperature	138
2.5.1	Heat of Crystallization or Relaxation	138
3.5	Hardness	138
5.1	Resistivity and Conductivity	139
	References	139
Al-Co-Y		140
1.2	X-ray Diffraction Profile	140
2.4	DSC/DTA Curve and Glass Formation	140
2.4.1	Glass Transition Temperature	140

2.4.2	Reduced Glass Transition Temperature	140
2.5	Crystallization Temperature	141
2.6	Supercooled Liquid Range	141
2.7.1	Transition Temperature	141
2.8	Critical Quantities for Formation of Amorphous Phase	141
	References	141
Al-Co-Zr (036)		142
1.2	X-ray Diffraction Profile	142
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	142
2.4	DSC/DTA Curve and Glass Formation	143
2.4.1	Glass Transition Temperature	144
2.4.2	Reduced Glass Transition Temperature	145
2.5	Crystallization Temperature	145
2.6	Supercooled Liquid Range	146
2.7.1	Transition Temperature	147
2.8	Critical Quantities for Formation of Amorphous Phase	147
3.2	Tensile Strength, Compressive Strength and Strain	148
	References	148
Al-Cr-Ge (037)		149
2.4	DSC/DTA Curve and Glass Formation	149
2.5	Crystallization Temperature	149
2.5.1	Heat of Crystallization or Relaxation	149
3.5	Hardness	149
5.1	Resistivity and Conductivity	150
5.1.2	Temperature Dependence of Resistivity	150
	References	150
Al-Cr-La (038)		151
Al-Cr-Si (039)		152
2.5	Crystallization Temperature	152
2.5.1	Heat of Crystallization or Relaxation	152
3.5	Hardness	153
5.1	Resistivity and Conductivity	153
	References	153
Al-Cr-Zr (040)		154
Al-Cu-Fe (041)		155
1.2	X-ray Diffraction Profile	155
2.4	DSC/DTA Curve and Glass Formation	156
4.8	Mössbauer Spectra	156
4.8.1	Quadrupole Splitting and Isomer Shift	156
	References	157
Al-Cu-Gd (042)		158
1.6	Lattice Parameter	158
2.5	Crystallization Temperature	158
2.4	DSC/DTA Curve and Glass Formation	158
4.5	Susceptibility and Cooling Effect	158
	References	158
Al-Cu-Hf (043)		159
1.2	X-ray Diffraction Profile	159
2.4	DSC/DTA Curve and Glass Formation	159
2.4.1	Glass Transition Temperature	159

2.4.2 Reduced Glass Transition Temperature	159
2.5 Crystallization Temperature	160
2.5.1 Heat of Crystallization or Relaxation	160
2.6 Supercooled liquid range	160
2.7.1 Transition Temperature	160
3.1 Stress-Strain Curve	160
References	160
Al-Cu-La (044)	161
2.1 Heat Capacity	161
2.4 DSC/DTA Curve and Glass Formation	161
2.4.1 Glass Transition Temperature	161
2.4.2 Reduced Glass Transition Temperature	162
2.5 Crystallization Temperature	162
2.6 Supercooled Liquid Range	163
2.7.1 Transition Temperature	163
2.8 Critical Quantities for Formation of Amorphous Phase	163
3.3 Yield Strength	164
3.4 Elastic Moduli	164
3.5 Hardness	164
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	164
3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	165
5.1 Resistivity and Conductivity	165
5.8 Superconductivity	165
References	165
Al-Cu-Mm	166
2.4 DSC/DTA Curve and Glass Formation	166
References	166
Al-Cu-Mn (045)	167
4.2 Hysteresis Loop	167
4.3 Magnetization Curve and Saturation Magnetic Moment	167
4.3.1 Magnetic Moment and Magnetic Anisotropy	167
4.5 Susceptibility and Cooling Effect	168
References	168
Al-Cu-Nd (046)	169
2.5 Crystallization Temperature	169
3.5 Hardness	169
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	169
5.1 Resistivity and Conductivity	169
References	170
Al-Cu-Ti (047)	171
1.2 X-ray Diffraction Profile	171
1.3 Interference Function	171
1.4 Radial Distribution Function	172
1.6 Lattice Parameter	172
1.7 Coordination Number, Valence Electron Number and Interatomic Distances	173
2.4 DSC/DTA Curve and Glass Formation	173
2.5 Crystallization Temperature	174
2.5.1 Heat of Crystallization or Relaxation	174
2.7.1 Transition Temperature	175
3.2 Tensile Strength, Compressive Strength and Strain	175
5.1 Resistivity and Conductivity	175

5.1.2	Temperature Dependence of the Resistivity	175
5.3	Hall Effect	176
	References	176
Al-Cu-V (048)		177
1.2	X-ray Diffraction Profile	177
1.4	Radial Distribution Function	178
1.7	Coordination Number, Valence Electron Number and Interatomic Distances . . .	179
2.4	DSC/DTA Curve and Glass Formation	179
2.5	Crystallization Temperature	179
2.5.1	Heat of Crystallization or Relaxation	180
3.4	Elastic Moduli	180
3.5	Hardness	180
5.1	Resistivity and Conductivity	181
5.1.2	Temperature Dependence of Resistivity	181
	References	181
Al-Cu-Y (049)		182
1.1	Density and Volume	182
1.8.6	X-ray Photoelectron Spectroscopy	182
2.1.1	Electronic Heat Capacity	182
2.5	Crystallization Temperature	183
5.1	Resistivity and Conductivity	183
5.1.2	Temperature Dependence of the Resistivity	183
5.3	Hall Effect	183
	References	184
Al-Cu-Zr (050)		185
1.1	Density and Volume	185
1.2	X-ray Diffraction Profile	186
1.3	Interference Function	188
1.4	Radial Distribution Function	188
1.7	Coordination Number, Valence Electron Number and Interatomic Distances . . .	188
1.8.4	Extended X-ray Absorption Fine Structure	189
2.1.1	Electronic Heat Capacity	189
2.4	DSC/DTA Curve and Glass Formation	190
2.4.1	Glass Transition Temperature	193
2.4.2	Reduced Glass Transition Temperature	195
2.5	Crystallization Temperature	196
2.5.1	Heat of Crystallization or Relaxation	197
2.6	Supercooled Liquid Range	197
2.7	Phase Diagram	198
2.7.1	Transition Temperature	199
2.7.2	Thermal Gravity Analysis	200
2.8	Critical Quantities for Formation of Amorphous Phase	200
3.1	Stress-Strain Curve	201
3.2	Tensile Strength, Compressive Strength and Strain	202
3.4	Elastic Moduli	203
3.5	Hardness	204
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	204
3.9	Viscosity	205
6.1	Potentiostatic and Potentiodynamic Polarization Curve	206
	References	206
Al-Fe-Gd (051)		208
1.6	Lattice Parameter	208

2.4	DSC/DTA Curve and Glass Formation	208
2.5	Crystallization Temperature	209
4.3	Magnetization Curve and Saturation Magnetic Moment	209
	References	209
Al-Fe-Ge (052)		210
2.5	Crystallization Temperature	210
3.5	Hardness	210
5.1	Resistivity and Conductivity	210
	References	210
Al-Fe-La (053)		211
Al-Fe-Nd		212
1.2	X-ray Diffraction Profile	212
2.4	DSC/DTA Curve and Glass Formation	212
2.4.1	Glass Transition Temperature	213
2.4.2	Reduced Glass Transition Temperature	213
2.5	Crystallization Temperature	213
2.6	Supercooled Liquid Range	213
2.7	Phase Diagram	213
2.7.1	Transition Temperature	214
2.8	Critical Quantities for Formation of Amorphous Phase	214
4.1	Thermomagnetic Curve	214
4.2	Hysteresis Loop	215
4.2.1	Coercive Force	215
4.2.2	Remanence	216
4.3	Magnetization Curve and Saturation Magnetic Moment	216
	References	217
Al-Fe-Ni (054)		218
1.2	X-ray Diffraction Profile	218
2.4	DSC/DTA Curve and Glass Formation	219
3.5	Hardness	219
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	220
4.8	Mössbauer Spectra	220
4.8.1	Quadrupole Splitting and Isomer Shift	220
	References	221
Al-Fe-P (055)		222
2.4.1	Glass Transition Temperature	222
2.5.1	Heat of Crystallization or Relaxation	222
2.5	Crystallization Temperature	222
2.7.1	Transition Temperature	222
4.1.1	Curie Temperature	222
	References	222
Al-Fe-Pr		223
2.4	DSC/DTA and Glass Formation	223
2.4.1	Glass Transition Temperature	223
2.4.2	Reduced Glass Transition Temperature	223
2.5	Crystallization Temperature	223
2.7.1	Transition Temperature	223
2.8	Critical Quantities for Formation of Amorphous Phase	223
	References	224

Al-Fe-Si (056)	225
2.5 Crystallization Temperature	225
2.5.1 Heat of Crystallization or Relaxation	225
3.5 Hardness	225
4.2.1 Coercive Force	225
4.2.3 Permeability	226
4.2.2 Remanence	226
4.3 Magnetization Curve and Saturation Magnetic Moment	227
5.1 Resistivity and Conductivity	227
References	227
Al-Fe-Sm	228
2.4 DSC/DTA and Glass Formation	228
2.4.1 Glass Transition Temperature	228
2.4.2 Reduced Glass Transition Temperature	228
2.5 Crystallization Temperature	228
2.7.1 Transition Temperature	228
2.8 Critical Quantities for Formation of Amorphous Phase	228
References	228
Al-Fe-Tb (057)	229
1.2 X-ray Diffraction Profile	229
2.4 DSC/DTA Curve and Glass Formation	229
4.2.1 Coercive Force	229
4.3 Magnetization Curve and Saturation Magnetic Moment	230
4.6 Magnetostriction	230
References	230
Al-Fe-Y	231
2.4 DSC/DTA Curve and Glass Formation	231
2.4.1 Glass Transition Temperature	232
2.4.2 Reduced Glass Transition Temperature	232
2.5 Crystallization Temperature	232
2.6 Supercooled Liquid Range	232
2.7.1 Transition Temperature	232
2.8 Critical Quantities for Formation of Amorphous Phase	232
References	232
Al-Fe-Zr (058)	233
4.1.1 Curie Temperature	233
References	233
Al-Ga-Mg (059)	234
1.1 Density and Volume	234
3.2 Tensile Strength, Compressive Strength and Strain	234
3.4 Elastic Moduli	235
3.5 Hardness	235
5.4 Thermoelectric Power	235
References	235
Al-Gd-Ni (060)	236
1.2 X-ray Diffraction Profile	236
1.7 Coordination Number, Valence Electron Number and Interatomic Distances	236
2.4 DSC/DTA Curve and Glass Formation	236
2.4.1 Glass Transition Temperature	237
2.4.2 Reduced Glass Transition Temperature	237
2.5 Crystallization Temperature	237

2.6	Supercooled Liquid Range	237
2.7	Phase Diagram	238
2.7.1	Transition Temperature	238
2.8	Critical Quantities for Formation of Amorphous Phase	238
3.1	Stress-Strain Curve	238
3.4	Elastic Moduli	239
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	239
4.3	Magnetization Curve and Saturation Magnetic Moment	239
	References	239
Al-Gd-Si (061)		240
Al-Ge-Mn (062)		241
1.2	X-ray Diffraction Profile	241
2.1	Heat Capacity	242
2.4	DSC/DTA Curve and Glass Formation	242
2.5	Crystallization Temperature	242
2.5.1	Heat of Crystallization or Relaxation	242
3.5	Hardness	243
5.1	Resistivity and Conductivity	243
5.1.2	Temperature Dependence of Resistivity	243
	References	243
Al-Ge-Ni (063)		244
1.4	Radial Distribution Function	244
1.5	Radial Structure Function	244
2.5	Crystallization Temperature	244
3.5	Hardness	244
5.1	Resistivity and Conductivity	244
	References	245
Al-Ge-V (064)		246
2.5	Crystallization Temperature	246
3.5	Hardness	246
5.1	Resistivity and Conductivity	246
	References	246
Al-Hf-Ni (065)		247
2.4	DSC/DTA Curve and Glass Formation	247
2.4.1	Glass Transition Temperature	247
2.5	Crystallization Temperature	247
	References	247
Al-La-Mn (066)		248
Al-La-Mo (067)		249
2.5	Crystallization Temperature	249
5.8	Superconductivity	249
	References	249
Al-La-Nb (068)		250
2.5	Crystallization Temperature	250
5.8	Superconductivity	250
	References	251
Al-La-Ni (069)		252
1.2	X-Ray Diffraction Profile	252
1.3	Interference Function	253

1.4	Radial Distribution Function	254
1.7	Coordination Number, Valence Electron Number and Interatomic Distances . . .	255
1.8.6	X-ray Photoelectron Spectroscopy	255
2.1	Heat Capacity	256
2.4	DSC/DTA Curve and Glass Formation	258
2.4.1	Glass Transition Temperature	261
2.4.2	Reduced Glass Transition Temperature	262
2.5	Crystallization Temperature	262
2.5.1	Heat of Crystallization or Relaxation	264
2.6	Supercooled Liquid Range	265
2.7.1	Transition Temperature	266
2.8	Critical and Maximum Quantities for Formation of Amorphous Phase	267
3.1	Stress-Strain Curves	268
3.2	Tensile Strength, Compressive Strength and Strain	269
3.4	Elastic Moduli	270
3.5	Hardness	270
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	270
3.9	Viscosity	271
3.11	Thermomechanical Analysis and Dynamic Mechanical Analysis	275
4.9.3	Neutron Magnetic Resonance	278
5.1	Resistivity and Conductivity	278
5.8	Superconductivity	279
	References	279
Al-La-Pt (070)		281
Al-La-Zn (071)		281
Al-La-Zr (072)		282
2.5	Crystallization Temperature	282
5.8	Superconductivity	282
	References	282
Al-Mg-Pd (073)		283
1.1	Density and Volume	283
1.2	X-ray Diffraction Profile	283
2.1.1	Electronic Heat Capacity	284
2.5	Crystallization Temperature	284
5.1	Resistivity and Conductivity	284
	References	285
Al-Mg-Ti (074)		286
1.2	X-ray Diffraction Profile	286
6.1	Potentiostatic and Potentiodynamic Polarization Curve	286
	References	287
Al-Mg-Zn (075)		288
1.2	X-ray Diffraction Profile	288
2.5	Crystallization Temperature	288
	References	288
Al-Mm-Ni (076)		289
1.2	X-ray Diffraction Profile	289
2.3	Thermal Expansion and Volume Change	289
2.4	DSC/DTA Curve and Glass Formation	289
2.7	Phase Diagram	290
3.2	Tensile Strength, Compressive Strength and Strain	290

3.4	Elastic Moduli	291
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	291
3.7	Wear Resistance	292
3.9	Viscosity	292
	References	292
Al-Mn-Ni (077)		294
Al-Mn-Si (078)		295
1.2	X-ray Diffraction Profile	295
1.4	Radial Distribution Function	295
1.5	Radial Structure Function	295
1.6	Lattice Parameter	296
2.4	DSC/DTA Curve and Glass Formation	296
2.5	Crystallization Temperature	296
2.5.1	Heat of Crystallization or Relaxation	297
3.5	Hardness	297
5.1	Resistivity and Conductivity	298
5.1.2	Temperature Dependence of the Resistivity	298
	References	298
Al-Mn-Zr (079)		299
Al-Mo-Ni (080)		300
1.2	X-ray Diffraction Profile	300
	References	300
Al-Mo-Si (081)		301
Al-Nb-Ni (082)		301
Al-Nb-Ti (083)		301
Al-Nd-Ni (084)		302
1.2	X-ray Diffraction Profile	302
2.4	DSC/DTA Curve and Glass Formation	302
2.5	Crystallization Temperature	303
2.5.1	Heat of Crystallization or Relaxation	303
3.5	Hardness	303
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	304
	References	304
Al-Ni-Si (085)		305
2.5	Crystallization Temperature	305
2.5.1	Heat of Crystallization or Relaxation	305
3.5	Hardness	306
5.1	Resistivity and Conductivity	306
5.1.2	Temperature Dependence of the Resistivity	307
	References	307
Al-Ni-Sm (086)		308
Al-Ni-Ti (087)		309
1.2	X-ray Diffraction Profile	309
1.3	Interference Function	309
1.4	Radial Distribution Function	310
1.6	Lattice Parameter	310
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	311
2.4	DSC/DTA Curve and Glass Formation	311

3.5	Hardness	312
5.1	Resistivity and Conductivity	312
5.1.2	Temperature Dependence of Resistivity	312
5.3	Hall Effect	313
6	Corrosion Behaviour	313
6.1	Potentiostatic and Potentiodynamic Polarization Curve	314
	References	314
Al-Ni-Y (088)		316
1.2	X-ray Diffraction Profile	316
1.4	Radial Distribution Function	316
1.6	Lattice Parameter	316
2.1	Heat Capacity	317
2.3	Thermal Expansion and Volume Change	317
2.4	DSC/DTA Curve and Glass Formation	317
2.4.1	Glass Transition Temperature	318
2.4.2	Reduced Glass Transition Temperature	319
2.5	Crystallization Temperature	319
2.6	Supercooled Liquid Range	320
2.7.1	Transition Temperature	320
3.2	Tensile Strength, Compressive Strength and Strain	320
3.4	Elastic Moduli	321
3.5	Hardness	322
3.7	Wear Resistance	322
3.9	Viscosity	322
5.1	Resistivity and Conductivity	323
5.1.2	Temperature Dependence of Resistivity	323
	References	323
Al-Ni-Zr (089)		325
1.1	Density and Volume	325
1.2	X-ray Diffraction Profile	325
1.3	Interference Function	326
1.4	Radial Distribution Function	327
1.6	Lattice Parameter	327
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	328
1.8.4	Extended X-ray Absorption Fine Structure	330
2.1	Heat Capacity	330
2.1.1	Electronic Heat Capacity	331
2.3	Thermal Expansion and Volume Change	331
2.4	DSC/DTA Curve and Glass Formation	332
2.4.1	Glass Transition Temperature	333
2.4.2	Reduced Glass Transition Temperature	333
2.5	Crystallization Temperature	334
2.5.1	Heat of Crystallization or Relaxation	335
2.6	Supercooled Liquid Range	335
2.7.1	Transition Temperature	336
2.8	Critical Quantities for Formation of Amorphous Phase	336
3.2	Tensile Strength, Compressive Strength and Strain	337
3.4	Elastic Moduli	338
3.5	Hardness	338
3.6	Fatigue strength, Fracture and Critical Fracture Temperature	339
3.7	Wear Resistance	340
3.11	Thermomechanical Analysis and Dynamic Mechanical Analysis	340
5.1	Resistivity and Conductivity	341

5.1.2	Temperature Dependence of Resistivity	344
5.2	Change of Resistivity by Deformation	345
5.3	Hall Effect	345
5.4	Thermoelectric Power	346
5.8	Superconductivity	347
	References	347
Al-O-Zr (090)		349
Al-Si-Zr (091)		349
As-Ge-Te (092)		350
5.1	Resistivity and Conductivity	350
	References	350
As-P-Pd (093)		351
Au-B-Er (094)		352
4.2	Hysteresis Loop	352
4.2.1	Coercive Force	352
4.3.1	Magnetic Moment and Magnetic Anisotropy	352
4.5	Susceptibility and Cooling Effect	353
5.1	Resistivity and Conductivity	353
	References	353
Au-B-Fe (095)		354
2.5	Crystallization Temperature	354
4.1	Thermomagnetic Curve	354
4.1.1	Curie Temperature	355
4.3	Magnetization Curve and Saturation Magnetic Moment	355
4.3.1	Magnetic Moment and Magnetic Anisotropy	355
	References	355
Au-B-Gd (096)		356
Au-B-Pr (097)		357
4.2.1	Coercive Force	357
4.3	Magnetization Curve and Saturation Magnetic Moment	357
4.3.1	Magnetic Moment and Magnetic Anisotropy	358
5.1	Resistivity and Conductivity	358
	References	358
Au-B-Th (098)		359
Au-Cu-La (099)		360
1.4	Radial Distribution Function	360
1.6	Lattice Parameter	360
	References	360
Au-Cu-Mg (100)		361
1.1	Density and Volume	361
2.2	Atomic Diffusivity	361
5.1	Resistivity and Conductivity	361
8	Quantum Correlations to the Conductivity	362
	References	362
Au-Cu-Si		363
2.4.1	Glass Transition Temperature	363
2.4.2	Reduced Glass Transition Temperature	363

2.5	Crystallisation Temperature	363
2.7.1	Transition Temperature	363
2.8	Critical Quantities for Formation of Amorphous Phase	363
	References	364
Au-Ge-Si (101)		365
1.1	Density and Volume	365
2.1	Heat Capacity	365
2.1.3	Debye Temperature	366
2.2	Atomic Diffusivity	366
2.4.1	Glass Transition Temperature	366
2.4.2	Reduced Glass Transition Temperature	367
2.5	Crystallization Temperature	367
2.5.1	Heat of Crystallization or Relaxation	367
2.6	Supercooled Liquid Range	367
2.7.1	Transition Temperature	368
2.8	Critical Quantities for Formation of Amorphous Phase	368
2.9	Configuration Entropy	368
3.9	Viscosity	368
	References	369
Au-Mg-Zn (102)		370
1.1	Density and Volume	370
2.2	Atomic Diffusivity	370
5.1	Resistivity and Conductivity	370
8	Quantum Correlations to the Conductivity	370
	References	371
Au-Pb-Sb (103)		372
2.1	Heat Capacity	372
2.4	DSC/DTA Curve and Glass Formation	373
2.4.1	Glass Transition Temperature	373
3.9	Viscosity	373
3.11	Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	374
5.8	Superconductivity	374
	References	375
Au-Pd-Si (104)		376
1.2	X-ray Diffraction Profile	376
2.2	Atomic Diffusivity	376
2.4	DSC/DTA Curve and Glass Formation	377
2.4.1	Glass Transition Temperature	377
2.5	Crystallization Temperature	379
2.6	Heat of Crystallization or Relaxation	380
3.8	Internal Friction	381
3.9	Viscosity	381
	References	382
B-Be-Fe (105) ... Co-W-Zr (221)		See Subvolume III/37B2
Cr-Fe-P (222) ... Si-W-Zr (351)		See Subvolume III/37B3