

Contents

1	Introduction	1
	Technologically most important systems listed in the present book	3
	References for 1	5
2	Characterization Techniques for Amorphous Alloys	6
2.1	Structural Characterization Technique	6
2.1.1	X-ray Diffractometry	6
2.1.2	Anomalous X-ray Scattering	7
2.1.3	X-ray Absorption Spectroscopy (XAS)	8
2.1.4	Small-Angle X-ray (SAX) or Neutron (SAN) Scattering	9
2.1.5	Extended X-ray Absorption Fine Structure (EXAFS)	9
2.1.6	X-ray Photoelectron Spectroscopy (XPS)	9
2.1.7	Mössbauer Spectroscopy	9
2.2	General Physical Properties	10
2.2.1	Density, Volume and Thermal Expansion Coefficient	10
2.2.2	Viscosity	10
2.2.3	Thermal Stability	11
2.2.3.1	Differential Thermal Analysis (DTA)	11
2.2.3.2	Differential Scanning Calorimetry (DSC)	11
2.2.3.3	Differential Isothermal Calorimetry	12
2.3	Mechanical Properties	13
2.3.1	Hardness Tests	13
2.3.1.1	Vickers Test	13
2.3.1.2	Vickers Microhardness	13
2.3.1.3	Knoop Hardness	14
2.3.2	Uniaxial Tensile (Compressive) Test	14
2.3.3	Bend Test	15
2.3.4	Fatigue Testing	15
2.3.5	Creep	15
2.4	Magnetic Properties	16
2.4.1	General Description	16
2.4.2	Magnetostriction	17
2.5	Electrical Properties	17
2.5.1	Electrical Resistance	17
2.5.2	Hall Effect	18
2.5.3	Superconductivity	18
2.6	Corrosion Behaviour	19
2.6.1	General Aspects	19
2.6.2	Types of Corrosion	19
	References for 2	20

3	List of Ternary Amorphous Alloys	21
4	Graphical and Numerical Data	24
	List of Properties Surveyed	24
	List of Symbols and Abbreviations	26
Ag-Al-Ca ... Au-Pd-Si (104) See Subvolume III/37B1		
B-Be-Fe (105)		37
1.1	Density and Volume	37
3.3	Yield Strength	37
3.5	Hardness	37
	References	37
B-Be-Sc (106)		38
1.1	Density and Volume	38
3.3	Yield Strength	38
3.5	Hardness	38
	References	38
B-Be-Ti (107)		39
1.1	Density and Volume	39
3.3	Yield Strength	39
3.5	Hardness	39
	References	39
B-C-Co (108)		40
4.1	Thermomagnetic Curve	40
4.1.1	Curie Temperature	40
4.3	Magnetization Curve and Saturation Magnetic Moment	41
	References	41
B-C-Fe (109)		42
1.1	Density and Volume	42
1.3	Interference Function	42
1.3	Radial Distribution Function	42
1.6	Lattice Parameter	43
2.1	Heat Capacity	43
2.2	Atomic Diffusivity	43
2.5	Crystallization Temperature	43
2.5.1	Heat of Crystallization or Relaxation	44
2.7.1	Transition Temperature	44
2.8	Critical Quantities for Formation of Amorphous Phase	45
4.1.1	Curie Temperature	45
4.2.1	Coercive Force	46
4.3	Magnetization Curve and Saturation Magnetic Moment	47
	References	48
B-C-N (110)		49
B-C-Ni (111)		50
5.1	Resistivity and Conductivity	50
5.1.2	Temperature Dependence of the Resistivity	50
	References	50

B-Co-Cr (112)	51
1.1 Density and Volume	51
2.5 Crystallization Temperature	51
5.1 Resistivity and Conductivity	51
6 Corrosion Behaviour	52
6.1 Potentiostatic and Potentiodynamic Polarization Curves	52
References	52
B-Co-Er (113)	53
1.4 Radial Distribution Function	53
1.5 Radial Structure Function	53
References	53
B-Co-Fe (114)	54
1.2 X-ray Diffraction Profile	54
1.3 Interference Function	54
1.6 Lattice Parameter	54
2.3 Thermal Expansion and Volume Change	55
2.4.1 Glass Transition Temperature	55
2.5 Crystallization Temperature	55
2.5.1 Heat of Crystallization or Relaxation	56
2.7.1 Transition Temperature	56
3.5 Hardness	56
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	57
4.2.3 Permeability	57
4.6 Magnetostriction	58
5.1 Resistivity and Conductivity	59
References	59
B-Co-Mn (115)	60
1.1 Density and Volume	60
2.1 Heat Capacity	60
2.7 Phase diagram	61
4.1 Thermomagnetic Curve	62
4.1.1 Curie Temperature	62
4.3.1 Magnetic Moment and Magnetic Anisotropy	63
4.5 Susceptibility and Cooling Effect	64
5.1 Resistivity and Conductivity	64
References	65
B-Co-Nb (116)	66
2.5 Crystallization Temperature	66
4.1 Thermomagnetic Curve	66
4.3 Magnetization Curve and Saturation Magnetic Moment	66
4.1.1 Curie Temperature	67
4.6 Magnetostriction	67
6.1 Potentiostatic and Potentiodynamic Polarization Curve	68
References	68
B-Co-Ni (117)	69
4.6 Magnetostriction	69
References	69
B-Co-P (118)	70

B-Co-Si (119)	71
1.1 Density and Volume	71
1.4 Radial Distribution Function	71
1.5 Radial Structure Function	71
1.6 Lattice Parameter	72
1.7 Coordination Number, Valence Electron Number and Interatomic Distances	72
2.3 Thermal Expansion and Volume Change	72
2.4 DSC/DTA Curve and Glass Formation	72
2.5 Crystallization Temperature	73
2.5.1 Heat of Crystallization or Relaxation	74
2.7 Phase Diagram	74
2.8 Critical Quantities for Formation of Amorphous Phase	75
3.1 Stress-Strain Curve	75
3.2 Tensile Strength, Compressive Strength and Strain	75
3.4 Elastic Moduli	76
3.5 Hardness	76
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	77
3.8 Internal Friction	77
3.12 Magnetomechanical Coupling	78
4.1 Thermomagnetic Curve	78
4.1.1 Curie Temperature	79
4.3 Magnetization Curve and Saturation Magnetic Moment	80
4.3.1 Magnetic Moment and Magnetic Anisotropy	80
4.6 Magnetostriction	81
5.1 Resistivity and Conductivity	81
References	81
B-Co-Ti (120)	83
2.4 DSC/DTA Curve and Glass Formation	83
2.5 Crystallization Temperature	83
3.5 Hardness	84
4.1.1 Curie Temperature	84
4.2.1 Coercive Force	84
4.2.3 Permeability	85
4.3 Magnetization Curve and Saturation Magnetic Moment	85
4.3.1 Magnetic Moment and Magnetic Anisotropy	85
4.6 Magnetostriction	85
5.1 Resistivity and Conductivity	86
5.4 Corrosion Behaviour	86
5.5 Thermoelectric Power	87
References	87
B-Co-V (121)	88
2.5 Crystallization Temperature	88
4.1.1 Curie Temperature	88
4.3.1 Magnetic Moment and Magnetic Anisotropy	88
5.1 Resistivity and Conductivity	88
5.4 Thermoelectric Power	89
References	89
B-Co-Y (122)	90
2.4 DSC/DTA Curve and Glass Formation	90
5.1 Resistivity and Conductivity	90
References	90

B-Co-Zr (123)	91
1.2 X-ray Diffraction Profile	91
2.4 DSC/DTA Curve and Glass Formation	91
2.5 Crystallization Temperature	91
4.1.1 Curie Temperature	92
4.2.1 Coercive Force	92
4.2.2 Remanence	92
4.3.1 Magnetic Moment and Magnetic Anisotropy	92
4.12 Hard Magnetic Properties	92
References	93
B-Cr-Fe (124)	94
1.2 X-ray Diffraction Profile	94
1.6 Lattice Parameter	94
2.3 Thermal Expansion and Volume Change	94
2.4 DSC/DTA Curve and Glass Formation	95
2.5 Crystallization Temperature	95
2.5.1 Heat of Crystallization or Relaxation	96
2.7.1 Transition Temperature	96
3.4 Elastic Moduli	96
3.5 Hardness	97
3.12 Magnetomechanical Coupling	97
4.1 Thermomagnetic Curve	98
4.1.1 Curie Temperature	98
4.3 Magnetization and Saturation Magnetic Moment	99
4.3.1 Magnetic Moment and Magnetic Anisotropy	99
4.6 Magnetostriction	100
4.8 Mössbauer Spectra	100
4.8.1 Quadrupole Splitting and Isomer Shift	101
4.8.2 Magnetic Hyperfine Field and Line Splitting	102
4.12 Hard Magnetic Properties	102
5.1 Resistivity and Conductivity	103
6 Corrosion Behaviour	104
6.1 Potentiostatic and Potentiodynamic Polarization Curves	104
References	105
B-Cr-Ni (125)	106
2.5 Crystallization Temperature	106
6 Corrosion Behaviour	106
6.1 Potentiostatic and Potentiodynamic Polarization Curve	106
References	106
B-Cu-Fe (126)	107
1.6 Lattice Parameter	107
2.5 Crystallization Temperature	107
2.5.1 Heat of Crystallization or Relaxation	107
2.7.1 Transition Temperature	107
References	107
B-Cu-Ni (127)	108
B-Cu-Zr (128)	108
B-F-Fe (129)	109
1.2 X-ray Diffraction Profile	109
4.1 Thermomagnetic Curve	109
5.3.1 Hall Mobility	110

7	Optical Properties	110
	References	110
B-Fe-Ga (130)		111
2.5	Crystallization Temperature	111
4.1.1	Curie Temperature	111
	References	111
B-Fe-Ge (131)		112
1.6	Lattice Parameter	112
2.5	Crystallization Temperature	112
2.5.1	Heat of Crystallization or Relaxation	112
2.7.1	Transition Temperature	113
4.1.1	Curie Temperature	113
	References	113
B-Fe-Hf (132)		114
1.6	Lattice Parameter	114
2.4	DSC/DTA Curve and Glass Formation	114
4.2.1	Coercive Force	115
4.2.3	Permeability	115
4.2.4	Core Loss	116
4.3	Magnetization Curve and Saturation Magnetic Moment	116
4.6	Magnetostriction	117
5.1	Resistivity and Conductivity	118
	References	118
B-Fe-Ho (133)		119
4.1	Thermomagnetic Curve	119
4.1.1	Curie Temperature	119
4.3.1	Magnetic Moment and Magnetic Anisotropy	120
	References	120
B-Fe-La (134)		121
B-Fe-Mn (135)		122
1.2	X-ray Diffraction Profile	122
1.6	Lattice Parameter	122
2.5	Crystallization Temperature	122
2.5.1	Heat of Crystallization or Relaxation	123
2.7.1	Transition Temperature	123
4.1	Thermomagnetic Curve	123
4.1.1	Curie Temperature	123
4.2	Hysteresis Loop	123
4.3	Magnetization Curve and Saturation Magnetic Moment	124
4.8	Mössbauer Spectra	124
4.8.1	Quadrupole Splitting and Isomer Shift	125
4.8.2	Magnetic Hyperfine Field and Line Splitting	125
5.1	Resistivity and Conductivity	126
	References	126
B-Fe-Mo (136)		127
2.3	Thermal Expansion and Volume Change	127
2.4	DSC/DTA Curve and Glass Formation	127
2.5	Crystallization Temperature	128
2.5.1	Heat of Crystallization or Relaxation	128
3.4	Elastic Moduli	128

3.5	Hardness	128
3.6	Fatigue strength, Fracture and Critical Fracture Temperature.	129
3.8	Internal Friction	129
4.1	Thermomagnetic Curve	129
4.1.1	Curie Temperature	129
4.3	Magnetization Curve and Saturation Magnetic Moment	130
4.3.1	Magnetic Moment and Magnetic Anisotropy	130
4.8	Mössbauer Spectra	130
4.8.2	Magnetic Hyperfine Field and Line Splitting	132
5.1	Resistivity and Conductivity	133
5.1.2	Temperature Dependence of Resistivity	133
5.3	Hall Effect	133
	References	133
B-Fe-N (137)		135
1.2	X-ray Diffraction Profile	135
1.8.5	X-ray Absorption Near Edge Structure	135
2.5	Crystallization Temperature	135
4.1.1	Curie Temperature	136
4.2	Hysteresis Loop	136
4.2.1	Coercive Force	136
4.2.3	Permeability	136
4.3	Magnetization Curve and Saturation Magnetic Moment	137
4.3.1	Magnetic Moment and Magnetic Anisotropy	137
4.10	Magnetostriction	138
5.1	Resistivity and Conductivity	138
7	Optical Properties	139
	References	139
B-Fe-Nb (138)		140
1.2	X-ray Diffraction Profile	140
1.6	Lattice Parameter	140
2.4	DSC/DTA Curve and Glass Formation.	140
4.2.1	Coercive Force	141
4.2.3	Permeability	142
4.2.4	Core Loss	143
4.3	Magnetization Curve and Saturation Magnetic Moment	143
4.6	Magnetostriction	144
5.1	Resistivity and Conductivity	145
5.4	Thermoelectric Power	146
	References	146
B-Fe-Nd (139)		147
1.2	X-ray Diffraction Profile	147
1.3	Interference Function	148
1.4	Radial Distribution Function	148
1.8.6	X-ray Photoelectron Spectroscopy	149
2.3	Thermal Expansion and Volume Change.	150
2.4	DSC/DTA Curve and Glass Formation.	150
2.5	Crystallization Temperature	151
2.6	Supercooled Liquid Range	151
2.8	Critical Quantities for Formation of Amorphous Phase.	152
3.5	Hardness	152
3.9	Viscosity	152
4.1	Thermomagnetic Curve	153

4.1.1	Curie Temperature	153
4.2	Hysteresis Loop	154
4.2.1	Coercive Force	154
4.2.2	Remanence	155
4.3	Magnetization Curve and Saturation Magnetic Moment	156
4.3.1	Magnetic Moment and Magnetic Anisotropy	157
4.7	Polarization Curve	157
4.8	Mössbauer Spectra	157
4.8.2	Magnetic Hyperfine Field and Line Splitting	158
	References	159
B-Fe-Ni (140)		160
1.1	Density and Volume	160
1.2	X-ray Diffraction Profile	160
1.3	Interference Function	161
1.4	Radial Distribution Function	161
1.6	Lattice Parameter	162
2.1	Heat Capacity	163
2.2	Atomic Diffusivity	163
2.3	Thermal Expansion and Volume Change	166
2.4	DSC/DTA Curves and Glass Formation	167
2.4.1	Glass Transition Temperature	168
2.5	Crystallization Temperature	169
2.5.1	Heat of Crystallization or Relaxation	170
2.7.1	Transition Temperature	172
3.1	Stress-Strain Curve	172
3.2	Tensile Strength and Strain	173
3.4	Elastic Moduli	174
3.5	Hardness	175
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	176
3.8	Internal Friction	177
3.10	Embrittlement	178
4.1	Thermomagnetic Curve	178
4.1.1	Curie Temperature	180
4.2.1	Coercive Force	180
4.2.2	Remanence	181
4.5	Susceptibility	181
4.6	Magnetostriction	182
4.8	Mössbauer Spectra	182
5.1	Resistivity and Conductivity	183
5.1.2	Temperature Dependence of Resistivity	185
5.3	Hall Effect	185
5.4	Thermoelectric Power	185
6	Corrosion Behaviour	186
	References	186
B-Fe-P (141)		189
2.4.1	Glass Transition Temperature	189
2.5	Crystallization Temperature	189
2.5.1	Heat of Crystallization or Relaxation	189
2.8	Critical Quantities for Formation of Amorphous Phase	190
3.1	Stress-Strain Curve	190
3.5	Hardness	190
3.10	Embrittlement	190
4.1	Thermomagnetic Curve	191

4.1.1	Curie Temperature	191
4.3.1	Magnetic Moment and Magnetic Anisotropy	192
4.8	Mössbauer Spectra	193
5.1	Resistivity and Conductivity	193
5.4.1	Potentiostatic and Potentiodynamic Polarization Curve	193
	References	193
B-Fe-Pd (142)		195
2.5	Crystallization Temperature	195
4.1.1	Curie Temperature	195
4.3	Magnetization Curve and Saturation Magnetic Moment	195
	References	195
B-Fe-Pt (143)		196
2.4	DSC/DTA Curve and Glass Transition	196
2.5	Crystallization Temperature	196
4.1.1	Curie Temperature	196
4.3	Magnetization and Saturation Magnetic Moment	196
4.8.2	Magnetic Hyperfine Field and Line Splitting	197
	References	197
B-Fe-Si (144)		198
1.1	Density and Volume	198
1.2	X-ray Diffraction Profile	199
1.3	Interference Function	200
1.4	Radial Distribution Function	201
1.5	Radial Structure Function	201
1.6	Lattice Parameter	201
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	202
1.8.2	Auger Electron Spectroscopy	202
1.8.6	X-ray Photoelectron Spectroscopy	202
2.1	Heat Capacity	202
2.2	Atomic Diffusivity	203
2.3	Thermal Expansion and Volume Change	204
2.4	DSC/DTA Curves and Glass Formation	205
2.4.1	Glass Transition Temperature	206
2.5	Crystallization Temperature	207
2.5.1	Heat of Crystallization or Relaxation	210
2.7	Phase Diagram	212
2.7.1	Transition Temperature	212
2.8	Critical Quantities for Formation of Amorphous Phase	212
3.1	Stress-Strain Curve	213
3.2	Tensile Strength, Compressive Strength and Strain	214
3.4	Elastic Moduli	216
3.5	Hardness	218
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	220
3.8	Internal Friction	221
3.9	Viscosity	221
3.10	Embrittlement	222
3.12	Magnetomechanical Coupling	223
4.1	Thermomagnetic Curve	223
4.1.1	Curie Temperature	224
4.2	Hysteresis Loop	225
4.2.1	Coercive Force	226
4.2.2	Remanence	228

4.2.3	Permeability	230
4.2.4	Core Loss	231
4.3	Magnetization and Saturation Magnetic Moment.	233
4.3.1	Magnetic Moment and Magnetic Anisotropy	235
4.6	Magnetostriction	235
4.8	Mössbauer Spectra	236
4.8.1	Quadrupole Splitting and Isomer Shift	241
4.8.2	Magnetic Hyperfine Field and Line Splitting.	242
4.14	Quadrupole Splitting and Isomer Shift	243
4.9.1	Ferromagnetic Resonance	246
5.1	Resistivity and Conductivity	247
	References	248
B-Fe-Sm (145)		252
4.3	Magnetization Curve and Saturation Magnetic Moment	252
4.6	Magnetostriction	252
	References	252
B-Fe-Sn (146)		253
1.6	Lattice Parameter	253
2.5	Crystallization Temperature	253
2.5.1	Heat of Crystallization or Relaxation.	253
2.7.1	Transition Temperature	253
	References	253
B-Fe-Ta (147)		254
2.4	DSC/DTA Curve and Glass Formation.	254
	References	254
B-Fe-Tb (148)		255
2.4	DSC/DTA Curve and Glass Formation.	255
4.1	Thermomagnetic Curve	255
4.1.1	Curie Temperature	255
4.3	Magnetization Curve and Saturation Magnetic Moment	256
4.6	Magnetostriction	256
	References	256
B-Fe-Ti (149)		257
2.4	DSC/DTA Curve and Glass Formation.	257
2.5	Crystallization Temperature	257
2.5.1	Heat of Crystallization or Relaxation.	258
2.7.1	Transition Temperature	258
3.5	Hardness	258
4.1	Thermomagnetic Curve	258
4.1.1	Curie Temperature	258
4.3	Magnetization Curve and Saturation Magnetic Moment	259
5.1.2	Temperature Dependence of Resistivity	259
	References	259
B-Fe-V (150)		260
1.6	Lattice Parameter	260
2.4	DSC/DTA Curve and Glass Formation.	260
2.5	Crystallization Temperature	260
2.5.1	Heat of Crystallization or Relaxation.	261
2.7.1	Transition Temperature	261
4.8.2	Magnetic Hyperfine Field and Line Splitting.	261
	References	261

B-Fe-W (151)	262
2.4 DSC/DTA Curve and Glass Formation	262
3.5 Hardness	262
4.1.1 Magnetoresistivity	262
5.1.2 Temperature Dependence of Resistivity	263
References	263
B-Fe-Y	264
1.2 X-ray Diffraction Profile	264
2.4 DSC/DTA Curve and Glass Formation	264
References	264
B-Fe-Zr (152)	265
1.1 Density and Volume	265
1.2 X-ray Diffraction Profile	265
1.4 Radial Distribution Function	268
1.6 Lattice Parameter	268
2.4 DSC/DTA Curve and Glass Formation	269
2.4.1 Glass Transition Temperature	270
2.5 Crystallization Temperature	270
2.5.1 Heat of Crystallization or Relaxation	271
2.6 Supercooled Liquid Range	271
3.2 Tensile Strength, Compressive Strength and Strain	271
3.4 Elastic Moduli	271
3.5 Hardness	272
4.1 Thermomagnetic Curve	272
4.1.1 Curie Temperature	273
4.2 Hysteresis Loop	274
4.2.1 Coercive Force	275
4.2.3 Permeability	276
4.2.4 Core Loss	278
4.3 Magnetization Curve and Saturation Magnetic Moment	279
4.3.1 Magnetic Moment and Magnetic Anisotropy	281
4.5 Susceptibility and Cooling Effect	282
4.6 Magnetostriction	282
4.8 Mössbauer Spectra	283
4.8.1 Quadrupole Splitting and Isomer Shift	284
4.8.2 Magnetic Hyperfine Field and Line Splitting	284
5.1 Resistivity and Conductivity	286
5.1.2 Temperature Dependence of Resistivity	287
References	287
B-Ga-Gd (153)	289
B-Mo-Ni (154)	290
1.1 Density and Volume	290
3.5 Hardness	290
References	290
B-Mo-P (155)	291
4.3 Magnetization Curve and Saturation Magnetic Moment	291
5.7 Dielectric Properties	291
5.8 Superconductivity	291
References	291
B-Mo-Rh (156)	292

B-Mo-Ru (157)	293
1.4 Radial Distribution Function	293
1.8.7 Small-Angle X-ray Scattering and Small-Angle Neutron Scattering	293
5.1 Resistivity and Conductivity	293
5.8 Superconductivity	295
References	295
B-Mo-Si (158)	296
2.5 Crystallization Temperature	296
3.5 Hardness	296
5.8 Superconductivity	296
References	298
B-Nb-Ni (159)	299
B-Nb-Si (160)	300
3.5 Hardness	300
5.8 Superconductivity	300
References	300
B-Ni-P (161)	301
2.5 Crystallization Temperature	301
2.5.1 Heat of Crystallization or Relaxation	301
3.4 Elastic Moduli	301
5.1 Resistivity and Conductivity	301
5.3 Hall Effect	302
5.4 Thermoelectric Power	302
References	302
B-Ni-Si (162)	303
1.2 X-ray Diffraction Profile	303
1.4 Radial Distribution Function	304
1.5 Radial Structure Function	304
1.6 Lattice Parameter	304
2.1 Heat Capacity	304
2.3 Thermal Expansion and Volume Change	305
2.4 DSC/DTA Curve and Glass Formation	307
2.5 Crystallization Temperature	308
2.5.1 Heat of Crystallization or Relaxation	310
2.7 Phase Diagram	310
2.8 Critical Quantities for Formation of Amorphous Phase	310
3.1 Stress-Strain Curve	311
3.2 Tensile Strength, Compressive Strength and Strain	312
3.3 Yield Strength	312
3.4 Elastic Moduli	313
3.5 Hardness	314
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	316
3.8 Internal Friction	316
3.9 Viscosity	317
3.10 Embrittlement	318
3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	318
4.1.1 Curie Temperature	318
5.1 Resistivity and Conductivity	319
5.1.2 Temperature Dependence of the Resistivity	320
5.4 Thermoelectric Power	321

6.1	Potentiostatic and Potentiodynamic Polarization Curves	322
	References	322
B-Ni-Ta (163)		324
B-Ni-Ti (164)		325
2.4	DSC/DTA Curve and Glass Formation	325
2.5	Crystallization Temperature	325
3.5	Hardness	325
	References	325
B-Ni-W (165)		326
B-Ni-Zr (166)		327
3.5	Hardness	327
	References	327
B-Pd-Si (167)		328
2.4	DSC/DTA Curve and Glass Formation	328
	References	328
B-Ru-W (168)		329
1.4	Radial Distribution Function	329
2.4.1	Glass Transition Temperature	329
3.4	Elastic Moduli	329
3.5	Hardness	329
	References	329
B-Si-W (169)		330
2.5	Crystallization Temperature	330
3.5	Hardness	330
5.1	Resistivity and Conductivity	330
5.8	Superconductivity	330
	References	331
Ba-Cu-La (170)		332
2.4	DSC/DTA Curve and Glass Formation	332
2.5	Crystallization Temperature	332
2.5.1	Heat of Crystallization or Relaxation	332
	References	332
Ba-Cu-Y (171)		333
Ba-Cu-Yb (172)		333
Be-Cu-Zr		334
1.1	Density and Volume	334
1.2	X-ray Diffraction Profile	334
2.4	DSC/DTA Curve and Glass Formation	334
2.4.1	Glass Transition Temperature	335
2.4.2	Reduced Glass Transition Temperature	335
2.5	Crystallization Temperature	335
2.5.1	Heat of Crystallization or Relaxation	336
2.6	Supercooled Liquid Range	336
2.7.1	Transition Temperature	336
2.8	Critical Quantities for Formation of Amorphous Phase	337
3.1	Stress-Strain Curve	337
3.4	Elastic Moduli	337
3.9	Viscosity	337

3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	338
References	338
Be-Hf-Zr (173)	339
Be-Nb-Zr (174)	340
1.1 Density and Volume	340
2.4.1 Glass Transition Temperature	340
5.1 Resistivity and Conductivity	340
5.8 Superconductivity	341
References	342
Be-Si-Ti (175)	343
1.1 Density and Volume	343
2.4 DSC/DTA Curve and Glass Formation	343
3.3 Yield Strength	343
3.5 Hardness	344
References	344
Be-Ti-Zr (176)	345
1.1 Density and Volume	345
1.2 X-ray Diffraction Profile	345
2.1.3 Debye Temperature	345
2.3 Thermal Expansion and Volume Change	345
2.4 DSC/DTA Curve and Glass Formation	346
2.4.1 Glass Transition Temperature	348
2.4.2 Reduced Glass Transition Temperature	348
2.5 Crystallization Temperature	348
2.5.1 Heat of Crystallization or Relaxation	349
2.6 Supercooled Liquid Range	350
2.7.1 Transition Temperature	350
2.8 Critical Quantities for Formation of Amorphous Phase	351
3.1 Stress-Strain Curve	351
3.3 Yield Strength	351
3.4 Elastic Moduli	352
3.5 Hardness	352
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	352
3.10 Embrittlement	353
5.1 Resistivity and Conductivity	353
References	354
C-Co-Cr (177)	355
C-Co-Mo (178)	355
C-Co-Si (179)	356
1.2 X-ray Diffraction Profile	356
2.5 Crystallization Temperature	356
3.1 Stress-Strain Curve	356
3.5 Hardness	356
4.1.1 Curie Temperature	357
4.2.1 Coercive Force	357
4.3 Magnetization Curve and Saturation Magnetic Moment	357
5.1 Resistivity and Conductivity	357
References	357

C-Co-W (180)	358
1.2 X-ray Diffraction Profile	358
3.5 Hardness	358
References	358
C-Cr-Fe (181)	359
1.2 X-ray Diffraction Profile	359
2.4 DSC/DTA Curve and Glass Formation	359
2.5 Crystallization Temperature	359
3.5 Hardness	360
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	360
5.1 Resistivity and Conductivity	360
6 Corrosion Behaviour	361
6.1 Potentiostatic and Potentiodynamic Polarization Curves	361
References	361
C-Cr-H (182)	362
1.5 Radial Structure Function	362
References	362
C-Fe-Mo (183)	363
1.2 X-ray Diffraction Profile	363
1.6 Lattice Parameter	363
2.4 DSC/DTA Curve and Glass Formation	363
2.5 Crystallization Temperature	363
2.7.1 Transition Temperature	364
3.5 Hardness	364
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	364
6 Corrosion Behaviour	364
6.1 Potentiostatic and Potentiodynamic Polarization Curves	365
References	365
C-Fe-P (184)	366
1.1 Density and Volume	366
1.2 X-ray Diffraction Profile	366
1.3 Interference Function	366
1.4 Radial Distribution Function	367
1.5 Radial Structure Function	368
1.6 Lattice Parameter	368
2.1 Heat Capacity	368
2.2 Atomic Diffusivity	369
2.3 Thermal Expansion and Volume Change	369
2.4 DSC/DTA Curve and Glass Formation	369
2.4.1 Glass Transition Temperature	370
2.5 Crystallization Temperature	370
2.5.1 Heat of Crystallization or Relaxation	371
2.6 Supercooled Liquid Range	372
2.7 Phase Diagram	372
2.7.1 Transition Temperature	372
2.8 Critical Quantities for Formation of Amorphous Phase	373
3.1 Stress-Strain Curve	373
3.2 Tensile Strength, Compressive Strength and Strain	374
3.4 Elastic Moduli	375
3.5 Hardness	375
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	376
3.8 Internal Friction	377

3.9	Viscosity	377
3.12	Magnetomechanical Coupling	378
4.1	Thermomagnetic Curve	378
4.2	Hysteresis Loop	379
4.1.1	Curie Temperature	380
4.2.1	Coercive Force	380
4.2.3	Permeability	381
4.3	Magnetization Curve and Saturation Magnetic Moment	381
4.6	Magnetostriction	383
4.8	Mössbauer Spectra	383
4.8.1	Quadrupole Splitting and Isomer Shift	384
4.8.2	Magnetic Hyperfine Field and Line Splitting	384
5.1	Resistivity and Conductivity	384
6.1	Potentiostatic and Potentiodynamic Polarization Curves	385
	References	385
C-Fe-Si (185)		387
1.2	X-ray Diffraction Profile	387
2.5	Crystallization Temperature	387
2.5.1	Heat of Crystallization or Relaxation	387
3.2	Tensile Strength and Strain	387
3.4	Elastic Moduli	387
3.5	Hardness	388
4.1.1	Curie Temperature	388
4.2.1	Coercivity	388
4.3	Magnetization Curve and Saturation Magnetic Moment	388
5.1	Resistivity and Conductivity	389
	References	389
C-Fe-W (186)		390
2.5	Crystallization Temperature	390
3.5	Hardness	390
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	390
	References	390
C-Mo-Ni (187)		391
2.5	Crystallization Temperature	391
3.5	Hardness	391
	References	391
C-Nb-Si (188)		392
5.8	Superconductivity	392
	References	392
C-Ni-Si (189)		393
3.1	Stress-Strain Curve	393
3.5	Hardness	393
	References	393
C-Si-Zr (190)		394
Ca-Cu-La (191)		395
2.4	DSC/DTA Curve and Glass Formation	395
2.5	Crystallization Temperature	395
2.5.1	Heat of Crystallization or Relaxation	395
	References	395

Ca-Cu-Mg (192)	396
1.1 Density and Volume	396
1.2 X-ray Diffraction Profile	396
2.1.1 Electronic Heat Capacity	397
2.1.3 Debye Temperature	398
2.4 DSC/DTA Curve and Glass Formation	398
2.4.1 Glass Transition Temperature	399
2.4.2 Reduced Glass Transition Temperature	400
2.5 Crystallization Temperature	400
2.5.1 Heat of Crystallization or Relaxation	400
2.6 Supercooled Liquid Range	401
2.7.1 Transition Temperature	401
2.8 Critical Quantities for Formation of Amorphous Phase	402
3.2 Tensile Strength, Compressive Strength and Strain	403
3.4 Elastic Moduli	403
3.5 Hardness	403
5.1 Resistivity and Conductivity	403
5.3 Hall Effect	404
5.4 Thermoelectric Power	404
References	405
Ca-Ga-Mg (193)	406
1.1 Density and Volume	406
1.8.6 X-ray Photoelectron Spectroscopy	406
2.1.1 Electronic Heat Capacity	406
2.1.3 Debye Temperature	407
5.1 Resistivity and Conductivity	407
References	407
Ca-Ge-Li	408
1.2 X-ray Diffraction Profile	408
2.4 DSC/DTA Curve and Glass Formation	408
References	408
Ca-Mg-Ni	409
2.8 Critical Quantities for Formation of Amorphous Phase	409
References	409
Ca-Mg-Zn	410
1.2 X-ray Diffraction Profile	410
2.4 DSC/DTA Curve and Glass Formation	411
2.4.1 Glass Transition Temperature	413
2.4.2 Reduced Glass Transition Temperature	414
2.5 Crystallization Temperature	415
2.5.1 Heat of Crystallization or Relaxation	415
2.6 Supercooled Liquid Range	416
2.7.1 Transition Temperature	416
2.8 Critical Quantities for Formation of Amorphous Phase	417
References	419
Ca-Mg-Zr (194)	420
Ce-Cu-Mg (195)	420
Ce-Cu-Yb (196)	421
1.2 X-ray Diffraction Profile	421
2.1 Heat Capacity	421

2.4	DSC/DTA Curve and Glass Formation	421
4.3.1	Magnetic Moment and Magnetic Anisotropy	422
4.5	Susceptibility and Cooling Effect	422
5.1	Resistivity and Conductivity	422
	References	422
Ce-Mg-Ni (197)		423
1.2	X-ray Diffraction Profile	423
2.5	Crystallization Temperature	423
2.5.1	Heat of Crystallization or Relaxation	424
3.4	Elastic Moduli	424
3.5	Hardness	424
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	425
	References	425
Ce-Mg-Zn (198)		426
2.4	DSC/DTA Curve and Glass Formation	426
3.1	Stress-Strain Curve	426
	References	426
Co-Cr-P (199)		427
Co-Cr-Zr (200)		428
2.1	Heat Capacity	428
2.3	Thermal Expansion and Volume Change	428
2.5	Crystallization Temperature	428
3.5	Hardness	428
4.1.1	Curie Temperature	428
4.2.1	Coercive Force	429
4.2.3	Permeability	429
4.3	Magnetization Curve and Saturation Magnetic Moment	430
4.6	Magnetostriction	430
5.1	Resistivity and Conductivity	430
5.3	Hall Effect	431
6	Corrosion Behaviour	431
6.1	Potentiostatic and Potentiodynamic Polarization Curves	431
	References	432
Co-Fe-Nb (201)		433
1.1	Density and Volume	433
2.5	Crystallization Temperature	433
4.1	Thermomagnetic Curve	433
4.1.1	Curie Temperature	434
4.3	Magnetization Curve and Saturation Magnetic Moment	434
4.3.1	Magnetic Moment and Magnetic Anisotropy	434
4.6	Magnetostriction	435
	References	435
Co-Fe-Tb (202)		436
4.2.1	Coercive Force	436
	References	436
Co-Fe-Zr (203)		437
1.1	Density and Volume	437
2.1	Heat Capacity	437
2.1.1	Electronic Heat Capacity	438
2.3	Thermal Expansion and Volume Change	438

2.4	DSC/DTA Curve and Glass Formation	438
2.5.1	Heat of Crystallization or Relaxation	439
4.1.1	Curie Temperature	439
4.3	Magnetization Curve and Saturation Magnetic Moment	440
4.3.1	Magnetic Moment and Magnetic Anisotropy	440
4.6	Magnetostriction	441
4.8	Mössbauer Spectra	442
4.8.1	Quadrupole Splitting and Isomer Shift	442
4.8.2	Magnetic Hyperfine Field and Line Splitting	442
5.1	Resistivity and Conductivity	442
	References	443
Co-Gd-Mo (204)		444
4.1	Thermomagnetic Curve	444
4.1.1	Curie Temperature	444
4.3.1	Magnetic Moment and Magnetic Anisotropy	444
	References	444
Co-Hf-P (205)		445
2.5	Crystallization Temperature	445
2.5.1	Heat of Crystallization or Relaxation	445
2.7.1	Transition Temperature	445
	References	445
Co-Hf-Si (206)		446
2.4	DSC/DTA Curve and Glass Formation	446
2.5	Crystallization Temperature	446
2.5.1	Heat of Crystallization or Relaxation	446
2.7.1	Transition Temperature	446
	References	446
Co-Mn-Nb (207)		447
2.5	Crystallization Temperature	447
4.1.1	Curie Temperature	447
4.3	Magnetization Curve and Saturation Magnetic Moment	447
4.6	Magnetostriction	447
	References	447
Co-Mn-Zr (208)		448
Co-Mo-Zr (209)		449
2.3	Thermal Expansion and Volume Change	449
2.5	Crystallization Temperature	449
3.5	Hardness	449
4.1.1	Curie Temperature	449
4.2.1	Coercive Force	449
4.2.3	Permeability	450
4.3	Magnetization Curve and Saturation Magnetic Moment	450
5.1	Resistivity and Conductivity	450
	References	451
Co-Nb-Ni (210)		452
4.3	Magnetization Curve and Saturation Magnetic Moment	452
4.6	Magnetostriction	452
	References	452

Co-Nb-Zr (211)	453
4.2 Hysteresis Loop	453
4.2.1 Coercive Force	453
4.2.3 Permeability	453
4.3.1 Magnetic Moment and Magnetic Anisotropy	455
References	455
Co-Ni-P (212)	456
5.1 Resistivity and Conductivity	456
References	456
Co-Ni-Ta (213)	457
Co-Ni-Zr (214)	458
1.2 X-ray Diffraction Profile	458
2.1.1 Electronic Heat Capacity	458
2.1.2 UV Photoelectron Spectroscopy	459
2.1.3 Debye Temperature	459
4.2 Hysteresis Loop	460
4.5 Susceptibility and Cooling Effect	460
5.1 Resistivity and Conductivity	460
5.8 Superconductivity	461
References	461
Co-P-Zr (215)	462
2.5 Crystallization Temperature	462
5.8 Superconductivity	462
References	463
Co-Pd-Si (216)	464
1.4 Radial Distribution Function	464
1.5 Radial Structure Function	464
1.8.7 Small-Angle X-ray Scattering and Small-Angle Neutron Scattering	464
2.4.1 Glass Transition Temperature	464
2.5 Crystallization Temperature	465
References	465
Co-Pd-Zr (217)	466
1.8.6 X-ray Photoelectron Spectroscopy	466
References	466
Co-Si-Ti (218)	467
1.2 X-ray Diffraction Profile	467
References	467
Co-Si-Zr (219)	468
2.5 Crystallization Temperature	468
3.4 Elastic Moduli	468
3.5 Hardness	468
References	468
Co-V-Zr (220)	469
2.5 Crystallization Temperature	469
3.5 Hardness	469
4.2.1 Coercive Force	469
4.6 Permeability	469
4.3 Magnetization Curve and Saturation Magnetic Moment	469

5.1 Resistivity and Conductivity	469
References	469
Co-W-Zr (221)	470
2.5 Crystallization Temperature	470
3.5 Hardness	470
4.1.1 Curie Temperature	470
4.2.1 Coercive Force	470
4.2.3 Permeability	470
4.3 Magnetization Curve and Saturation Magnetic Moment	470
5.1 Resistivity and Conductivity	470
References	470
Cr-Fe-P (222) ... Si-W-Zr (351)	See Subvolume III/37B3
Survey of Volume LB III/37	472
Definitions, Units and Conversion Factors	473