

Contents

1	Introduction	1
	Technologically most important systems listed in the present book	3
	References for 1	5
2	Characterization Techniques for Amorphous Alloys	6
2.1	Structural Characterization Technique	6
2.1.1	X-ray Diffractometry	6
2.1.2	Anomalous X-ray Scattering	7
2.1.3	X-ray Absorption Spectroscopy (XAS)	8
2.1.4	Small-Angle X-ray (SAX) or Neutron (SAN) Scattering	9
2.1.5	Extended X-ray Absorption Fine Structure (EXAFS)	9
2.1.6	X-ray Photoelectron Spectroscopy (XPS)	9
2.1.7	Mössbauer Spectroscopy	9
2.2	General Physical Properties	10
2.2.1	Density, Volume and Thermal Expansion Coefficient	10
2.2.2	Viscosity	10
2.2.3	Thermal Stability	11
2.2.3.1	Differential Thermal Analysis (DTA)	11
2.2.3.2	Differential Scanning Calorimetry (DSC)	11
2.2.3.3	Differential Isothermal Calorimetry	12
2.3	Mechanical Properties	13
2.3.1	Hardness Tests	13
2.3.1.1	Vickers Test	13
2.3.1.2	Vickers Microhardness	13
2.3.1.3	Knoop Hardness	14
2.3.2	Uniaxial Tensile (Compressive) Test	14
2.3.3	Bend Test	15
2.3.4	Fatigue Testing	15
2.3.5	Creep	15
2.4	Magnetic Properties	16
2.4.1	General Description	16
2.4.2	Magnetostriction	17
2.5	Electrical Properties	17
2.5.1	Electrical Resistance	17
2.5.2	Hall Effect	18
2.5.3	Superconductivity	18
2.6	Corrosion Behaviour	19
2.6.1	General Aspects	19
2.6.2	Types of Corrosion	19
	References for 2	20

3	List of Ternary Amorphous Alloys	21
4	Graphical and Numerical Data	24
	List of Properties Surveyed	24
	List of Symbols and Abbreviations	26
Ag-Al-Ca ... Au-Pd-Si (104)		See Subvolume III/37B1
B-Be-Fe (105) ... Co-W-Zr (221)		See Subvolume III/37B2
Cr-Fe-P (222)		37
2.4	DSC/DTA Curve and Glass Formation	37
2.4.1	Glass Transition Temperature	37
2.5	Crystallization Temperature	38
3.9	Viscosity	38
3.11	Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	39
4.8	Mössbauer Data	39
4.8.1	Quadrupole Splitting and Isomer Shift	40
6	Corrosion Behaviour	40
6.1	Potentiostatic and Potentiodynamic Polarization Curves	41
	References	41
Cr-Fe-Zr (223)		43
2.3	Thermal Expansion and Volume Change	43
4.1.1	Curie Temperature	43
4.3	Magnetization Curve and Saturation Magnetic Moment	44
4.3.1	Magnetic Moment and Magnetic Anisotropy	44
4.6	Magnetostriction	45
6	Corrosion Behaviour	45
6.1	Potentiostatic and Potentiodynamic Polarization Curves	45
	References	45
Cr-Ge-Pd (224)		46
4.1	Thermomagnetic Curve	46
4.5	Susceptibility and Cooling Effect	46
4.11	Magnetoresistivity	46
5.1	Resistivity and Conductivity	47
	References	47
Cr-Mo-Ni (225)		48
1.2	X-ray Diffraction Profile	48
1.8.6	X-ray Photoelectron Spectroscopy	48
6	Corrosion Behaviour	48
6.1	Potentiostatic and Potentiodynamic Polarization Curves	49
	References	49
Cr-Ni-P (226)		50
1.2	X-ray Diffraction Profile	50
2.5	Crystallization Temperature	50
3.5	Hardness	51
5.1	Resistivity and Conductivity	51
6	Corrosion Behaviour	51
6.1	Potentiostatic and Potentiodynamic Polarization Curves	53
	References	57

Cr-Ni-Zr (227)	58
2.1.1 Electronic Heat Capacity.	58
2.1.2 UV Photoelectron Spectroscopy.	58
2.1.3 Debye Temperature.	59
5.1 Resistivity and Conductivity	59
References	59
Cr-Pd-Si (228)	60
2.5 Crystallization Temperature.	60
4.1 Thermomagnetic Curve.	60
4.3.1 Magnetic Moment and Magnetic Anisotropy.	60
4.5 Susceptibility and Cooling Effect	61
4.11 Magnetoresistivity	61
5.1 Resistivity and Conductivity	62
References	63
Cr-Si-Zr (229)	64
2.5 Crystallization Temperature.	64
3.4 Elastic Moduli	64
3.5 Hardness	64
References	64
Cu-Fe-Ti (230)	65
1.6 Lattice Parameter	65
2.4 DSC/DTA Curve and Glass Formation	65
2.5 Crystallization Temperature.	65
4.8 Mössbauer Spectra	66
4.8.1 Quadrupole Splitting and Isomer Shift	66
References	66
Cu-Fe-Zr (231)	67
2.5 Crystallization Temperature.	67
4.8 Mössbauer Spectra	67
4.8.1 Quadrupole Splitting and Isomer Shift	67
References	68
Cu-Ga-Zr	69
2.4 Glass Transition Temperature	69
2.4.1 Reduced Glass Transition Temperature.	69
2.5 Crystallization Temperature.	69
2.7.1 Transition Temperature	69
2.8 Critical Quantities for Formation of Amorphous Phase	70
References	70
Cu-Gd-Mg	71
1.2 X-ray Diffraction Profile.	71
2.4 DSC/DTA Curve and Glass Formation	71
2.4.1 Glass Transition Temperature	71
3.2 Tensile Strength, Compressive Strength and Strain	72
3.4 Elastic Moduli	72
References	72
Cu-H-Ti (232)	73
1.2 X-ray Diffraction Profile.	73
2.4 DSC/DTA Curve and Glass Formation	73
References	74

Cu-Hf-Nb (233)	75
2.4 DSC/DTA Curve and Glass Formation	75
2.5 Crystallization Temperature	75
3.5 Hardness	75
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	75
5.8 Superconductivity	76
References	76
Cu-Hf-Ni (234)	77
2.4 DSC/DTA Curve and Glass Formation	77
2.4.1 Glass Transition Temperature	77
2.5 Crystallization Temperature	77
3.2 Tensile Strength, Compressive Strength and Strain	78
3.4 Elastic Moduli	78
3.5 Hardness	78
References	78
Cu-Hf-Ti	79
1.2 X-ray Diffraction Profile	79
2.4 DSC/DTA Curve and Glass Formation	79
2.4.1 Glass Transition Temperature	80
2.4.2 Reduced Glass Transition Temperature	80
2.5 Crystallisation Temperature	80
2.6 Supercooled Liquid Range	80
2.7.1 Transition Temperature	80
3.1 Stress-Strain Curve	81
3.2 Tensile Strength, Compressive Strength and Strain	81
3.3 Yield Strength	81
3.4 Elastic Moduli	81
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	81
6.1 Potentiostatic and Potendiodynamic Polarization Curve	82
References	82
Cu-La-Mg (235)	83
Cu-La-Sr (236)	84
1.2 X-ray Diffraction Profile	84
2.4 DSC/DTA Curve and Glass Formation	84
2.5 Crystallization Temperature	84
2.5.1 Heat of Crystallization or Relaxation	85
References	85
Cu-Mg-Nd (237)	86
Cu-Mg-Tb	87
1.1 Density and Volume	87
1.2 X-ray Diffraction Profile	87
2.4 DSC/DTA Curve and Glass Formation	87
2.4.1 Glass Transition Temperature	87
2.4.2 Reduced Glass Transition Temperature	87
2.5 Crystallization Temperature	88
2.5.1 Heat of Crystallization or Relaxation	88
2.6 Supercooled Liquid Range	88
2.7.1 Transition Temperature	88
2.8 Critical Quantities for Formation of Amorphous Phase	88
3.4 Elastic Moduli	89

3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	89
	References	89
Cu-Mg-Y (238)		90
1.1	Density and Volume	90
1.2	X-ray Diffraction Profile	90
1.4	Radial Distribution Function	91
1.5	Radial Structure Function	92
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	93
1.8.6	X-ray Photoelectron Spectroscopy	94
2.1	Heat Capacity	94
2.1.1	Electronic Heat Capacity	96
2.1.3	Debye Temperature	96
2.4	DSC/DTA Curve and Glass Formation	96
2.4.1	Glass Transition Temperature	98
2.4.2	Reduced Glass Transition Temperature	99
2.5	Crystallization Temperature	100
2.5.1	Heat of Crystallization or Relaxation	101
2.6	Supercooled Liquid Range	101
2.7	Phase Diagram	102
2.7.1	Transition Temperature	103
2.8	Critical Quantities for Formation of Amorphous Phase	104
3.1	Stress-Strain Curve	105
3.2	Tensile Strength, Compressive Strength and Strain	106
3.3	Yield Strength	107
3.4	Elastic Moduli	107
3.5	Hardness	107
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	108
3.10	Embrittlement	108
5.1	Resistivity and Conductivity	109
5.1.2	Temperature Dependence of Resistivity	109
5.3	Hall Effect	109
5.4	Thermoelectric Power	109
	References	109
Cu-Mo-Zr		111
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	111
2.4.1	Glass Transition Temperature	111
2.4.2	Reduced Glass Transition Temperature	111
2.5	Crystallization Temperature	111
2.6	Supercooled Liquid Range	111
2.7.1	Transition Temperature	111
	References	111
Cu-Nb-Sn (239)		112
2.4	DSC/DTA Curve and Glass Formation	112
	References	112
Cu-Nb-Ti (240)		113
2.5	Crystallization Temperature	113
3.5	Hardness	113
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	113
5.8	Superconductivity	113
	References	114

Cu-Nb-Zr (241)	115
1.2 X-ray Diffraction Profile	115
1.7 Coordination Number, Valence Electron Number and Interatomic Distances	115
2.4 DSC/DTA Curve and Glass Formation	115
2.4.1 Glass Transition Temperature	116
2.4.2 Reduced Glass Transition Temperature	116
2.5 Crystallization Temperature	116
2.6 Supercooled Liquid Range	116
2.7.1 Transition Temperature	116
3.5 Hardness	116
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	117
5.8 Superconductivity	117
References	117
Cu-Ni-P (242)	118
1.2 X-ray Diffraction Profile	118
2.4 DSC/DTA Curve and Glass Formation	119
2.5 Crystallization Temperature	120
2.5.1 Heat of Crystallization or Relaxation	120
5.1 Resistivity and Conductivity	120
6.1 Potentiostatic and Potentiodynamic Polarization Curves	120
5.6 Dielectric Properties	121
References	121
Cu-Ni-Ti (243)	122
1.2 X-ray Diffraction Profile	122
2.1 Heat Capacity	122
2.3 Thermal Expansion and Volume Change	122
2.4 DSC/DTA Curve and Glass Formation	123
2.4.1 Glass Transition Temperature	123
2.4.2 Reduced Glass Transition Temperature	123
2.5 Crystallization Temperature	124
2.5.1 Heat of Crystallization or Relaxation	124
2.7.1 Transition Temperature	125
2.8 Critical Quantities for Formation of Amorphous Phase	125
3.1 Stress-Strain Curve	125
3.2 Tensile Strength, Compressive Strength and Strain	126
3.4 Elastic Moduli	126
3.5 Hardness	126
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	126
5.1 Resistivity and Conductivity	127
5.1.2 Temperature Dependence of Resistivity	127
References	127
Cu-Ni-Zr (244)	129
2.1.1 Electronic Heat Capacity	129
2.1.2 UV Photoelectron Spectroscopy	129
2.1.3 Debye Temperature	130
2.4 DSC/DTA Curve and Glass Formation	130
2.4.1 Glass Transition Temperature	130
2.5 Crystallization Temperature	130
2.5.1 Heat of Crystallization or Relaxation	131
3.4 Elastic Moduli	131
3.5 Hardness	131
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	131

5.1	Resistivity and Conductivity	131
5.8	Superconductivity	132
	References	132
Cu-P-Pd (245)		133
1.1	Density and Volume	133
1.8.6	X-ray Photoelectron Spectroscopy	133
2.1	Heat Capacity	133
2.1.3	Debye Temperature	133
2.4	DSC/DTA Curve and Glass Formation	134
2.4.1	Glass Transition Temperature	134
2.4.2	Reduced Glass Transition Temperature	134
2.5	Crystallization Temperature	134
2.5.1	Heat of Crystallization or Relaxation	135
2.6	Supercooled Liquid Range	135
2.7	Phase Diagram	135
2.7.1	Transition Temperature	135
3.4	Elastic Moduli	136
4.7	Susceptibility and Cooling Effect	136
	References	136
Cu-P-Pt		137
2.4	DSC/DTA Curve and Glass Formation	137
2.4.1	Glass Transition Temperature	137
2.4.2	Reduced Glass Transition Temperature	137
2.5	Crystallization Temperature	138
2.6	Supercooled Liquid Range	138
3.9	Viscosity	138
	References	138
Cu-P-Zr (246)		139
6	Corrosion Behaviour	139
6.1	Potentiostatic and Potentiodynamic Polarization Curves	139
	References	139
Cu-Pb-Zn (247)		140
6	Corrosion Behaviour	140
	References	140
Cu-Pd-Si (248)		141
1.1	Density and Volume	141
1.3	Interference Function	143
1.4	Radial Distribution Function	144
1.8.6	X-ray Photoelectron Spectroscopy	144
2.1	Heat Capacity	144
2.1.2	UV Photoelectron Spectroscopy	147
2.1.3	Debye Temperature	147
2.2	Atomic Diffusivity	147
2.3	Thermal Expansion and Volume Change	148
2.4	DSC/DTA Curve and Glass Formation	149
2.4.1	Glass Transition Temperature	149
2.4.2	Reduced Glass Transition Temperature	150
2.5	Crystallization Temperature	151
2.5.1	Heat of Crystallization or Relaxation	152
2.6	Supercooled Liquid Range	153
2.7	Phase Diagram	153

2.7.1	Transition Temperature	153
2.8	Critical Quantities for Formation of Amorphous Phase	154
3.1	Stress-Strain Curve	155
3.2	Tensile Strength, Compressive Strength and Strain	157
3.3	Yield Strength	157
3.4	Elastic Moduli	158
3.5	Hardness	160
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	161
3.8	Internal Friction	161
3.9	Viscosity	164
5.1	Resistivity and Conductivity	165
5.1.2	Temperature Dependence of Resistivity	166
	References	166
Cu-Si-Zr (249)		169
2.5	Crystallization Temperature	169
3.4	Elastic Moduli	169
	References	169
Cu-Sn-Zr		170
1.2	X-ray Diffraction Profile	170
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	170
2.4	DSC/DTA Curve and Glass Formation	170
2.4.1	Glass Transition Temperature	171
2.4.2	Reduced Glass Transition Temperature	171
2.5	Crystallization Temperature	171
2.6	Supercooled Liquid Range	171
2.7.1	Transition Temperature	171
	References	171
Cu-Ta-Zr		172
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	172
2.4.1	Glass Transition Temperature	172
2.4.2	Reduced Glass Transition Temperature	172
2.5	Crystallization Temperature	172
2.6	Supercooled Liquid Range	172
2.7.1	Transition Temperature	172
	References	172
Cu-Ti-Zr (250)		173
1.2	X-ray Diffraction Profile	173
1.8.1	Atom Probe Field Ion Microscopy	174
2.1	Heat Capacity	174
2.4	DSC/DTA Curve and Glass Formation	174
2.4.1	Glass Transition Temperature	176
2.4.2	Reduced Glass Transition Temperature	177
2.5	Crystallisation Temperature	178
2.6	Supercooled Liquid Range	178
2.7.1	Transition Temperature	179
2.8	Critical Quantities for Formation of Amorphous Phase	180
3.1	Stress-Strain Curve	180
3.2	Tensile Strength, Compressive Strength and Strain	181
3.3	Yield Strength	181
3.4	Elastic Moduli	181
3.5	Hardness	182
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	182

6	Corrosion Behaviour.	182
6.1	Potentiostatic and Potendiodynamic Polarization Curve.	183
	References	183
D-Ni-Zr (251)		184
1.4	Radial Distribution Function	184
1.5	Radial Structure Function	184
	References	184
Dy-Fe-Zr (252)		185
2.7	Phase Diagram	185
4.2.1	Coercive Force.	185
4.3	Magnetization Curve and Saturation Magnetic Moment.	185
4.5	Susceptibility and Cooling Effect.	186
	References	186
Fe-Ga-Gd (253)		187
Fe-Gd-Zr (254)		188
4.2.1	Coercive Force.	188
4.3	Magnetization Curve and Saturation Magnetic Moment.	188
4.5	Susceptibility and Cooling Effect.	188
	References	188
Fe-Ge-Zr (255)		189
3.4	Elastic Moduli	189
4.1.1	Curie Temperature	189
	References	189
Fe-Hf-O (256)		190
1.2	X-ray Diffraction Profile	190
2.4	DSC/DTA Curve and Glass Formation	191
4.2.1	Coercive Force.	191
4.2.3	Permeability.	191
4.3	Magnetization Curve and Saturation Magnetic Moment.	192
5.1	Resistivity and Conductivity	192
	References	192
Fe-Hf-Ta (257)		193
2.7	Phase Diagram	193
4.1	Thermomagnetic Curve.	193
4.5	Susceptibility and Cooling Effect.	194
4.8	Mössbauer Spectra	194
4.8.2	Magnetic Hyperfine Field and Line Splitting	194
	References	195
Fe-Hf-Zr (258)		196
1.4	Radial Distribution Function	196
	References	196
Fe-Ir-Zr (259)		197
Fe-La-Zr (260)		198
2.7	Phase Diagram	198
4.2.1	Coercive Force.	198
4.3	Magnetization Curve and Saturation Magnetic Moment.	198
4.5	Susceptibility and Cooling Effect.	199
	References	199

Fe-Mn-P (261)	200
2.4 DSC/DTA Curve and Glass Formation	200
2.4.1 Glass Transition Temperature	200
2.5 Crystallization Temperature	201
3.4 Elastic Moduli	201
3.8 Internal Friction	202
3.9 Viscosity	202
3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	203
References	204
Fe-Mn-Zr (262)	205
4.1.1 Curie Temperature	205
4.2 Hysteresis Loop	206
4.3 Magnetization Curve and Saturation Magnetic Moment	206
4.3.1 Magnetic Moment and Magnetic Anisotropy	207
4.5 Susceptibility and Cooling Effect	207
4.8 Mössbauer Spectra	207
4.8.2 Magnetic Hyperfine Field and Line Splitting	208
References	209
Fe-Mo-P (263)	210
2.4 DSC/DTA Curve and Glass Formation	210
2.4.1 Glass Transition Temperature	210
2.5 Crystallization Temperature	210
3.9 Viscosity	210
3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	211
References	211
Fe-Ni-P (264)	212
1.4 Radial Distribution Function	212
1.8.6 X-ray Photoelectron Spectroscopy	212
1.8.7 Small-Angle X-ray Scattering and Small-Angle Neutron Scattering	213
2.1 Heat Capacity	213
2.4 DSC/DTA Curve and Glass Formation	214
2.4.1 Glass Transition Temperature	215
2.5 Crystallization Temperature	215
2.5.1 Heat of Crystallization or Relaxation	215
2.8 Critical Quantities for Formation of Amorphous Phase	215
3.10 Embrittlement	215
4.1.1 Curie Temperature	216
5.1 Resistivity and Conductivity	216
5.1.2 Temperature Dependence of Resistivity	216
References	217
Fe-Ni-Zr (265)	218
2.1 Heat Capacity	218
2.1.1 Electronic Heat Capacity	219
2.1.2 UV Photoelectron Spectroscopy	220
2.1.3 Debye Temperature	220
2.3 Thermal Expansion and Volume Change	220
2.4 DSC/DTA Curve and Glass Formation	220
2.4.1 Glass Transition Temperature	221
2.5 Crystallization Temperature	221
2.5.1 Heat of Crystallization or Relaxation	222
3.4 Elastic Moduli	222
3.5 Hardness	222

6	Corrosion Behaviour.	182
6.1	Potentiostatic and Potendiodynamic Polarization Curve.	183
	References	183
D-Ni-Zr (251)		184
1.4	Radial Distribution Function	184
1.5	Radial Structure Function	184
	References	184
Dy-Fe-Zr (252)		185
2.7	Phase Diagram	185
4.2.1	Coercive Force.	185
4.3	Magnetization Curve and Saturation Magnetic Moment.	185
4.5	Susceptibility and Cooling Effect.	186
	References	186
Fe-Ga-Gd (253)		187
Fe-Gd-Zr (254)		188
4.2.1	Coercive Force.	188
4.3	Magnetization Curve and Saturation Magnetic Moment.	188
4.5	Susceptibility and Cooling Effect.	188
	References	188
Fe-Ge-Zr (255)		189
3.4	Elastic Moduli	189
4.1.1	Curie Temperature	189
	References	189
Fe-Hf-O (256)		190
1.2	X-ray Diffraction Profile.	190
2.4	DSC/DTA Curve and Glass Formation	191
4.2.1	Coercive Force.	191
4.2.3	Permeability.	191
4.3	Magnetization Curve and Saturation Magnetic Moment.	192
5.1	Resistivity and Conductivity	192
	References	192
Fe-Hf-Ta (257)		193
2.7	Phase Diagram	193
4.1	Thermomagnetic Curve.	193
4.5	Susceptibility and Cooling Effect.	194
4.8	Mössbauer Spectra	194
4.8.2	Magnetic Hyperfine Field and Line Splitting	194
	References	195
Fe-Hf-Zr (258)		196
1.4	Radial Distribution Function	196
	References	196
Fe-Ir-Zr (259)		197
Fe-La-Zr (260)		198
2.7	Phase Diagram	198
4.2.1	Coercive Force.	198
4.3	Magnetization Curve and Saturation Magnetic Moment.	198
4.5	Susceptibility and Cooling Effect.	199
	References	199

Fe-Mn-P (261)	200
2.4 DSC/DTA Curve and Glass Formation	200
2.4.1 Glass Transition Temperature	200
2.5 Crystallization Temperature	201
3.4 Elastic Moduli	201
3.8 Internal Friction	202
3.9 Viscosity	202
3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	203
References	204
Fe-Mn-Zr (262)	205
4.1.1 Curie Temperature	205
4.2 Hysteresis Loop	206
4.3 Magnetization Curve and Saturation Magnetic Moment	206
4.3.1 Magnetic Moment and Magnetic Anisotropy	207
4.5 Susceptibility and Cooling Effect	207
4.8 Mössbauer Spectra	207
4.8.2 Magnetic Hyperfine Field and Line Splitting	208
References	209
Fe-Mo-P (263)	210
2.4 DSC/DTA Curve and Glass Formation	210
2.4.1 Glass Transition Temperature	210
2.5 Crystallization Temperature	210
3.9 Viscosity	210
3.11 Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	211
References	211
Fe-Ni-P (264)	212
1.4 Radial Distribution Function	212
1.8.6 X-ray Photoelectron Spectroscopy	212
1.8.7 Small-Angle X-ray Scattering and Small-Angle Neutron Scattering	213
2.1 Heat Capacity	213
2.4 DSC/DTA Curve and Glass Formation	214
2.4.1 Glass Transition Temperature	215
2.5 Crystallization Temperature	215
2.5.1 Heat of Crystallization or Relaxation	215
2.8 Critical Quantities for Formation of Amorphous Phase	215
3.10 Embrittlement	215
4.1.1 Curie Temperature	216
5.1 Resistivity and Conductivity	216
5.1.2 Temperature Dependence of Resistivity	216
References	217
Fe-Ni-Zr (265)	218
2.1 Heat Capacity	218
2.1.1 Electronic Heat Capacity	219
2.1.2 UV Photoelectron Spectroscopy	220
2.1.3 Debye Temperature	220
2.3 Thermal Expansion and Volume Change	220
2.4 DSC/DTA Curve and Glass Formation	220
2.4.1 Glass Transition Temperature	221
2.5 Crystallization Temperature	221
2.5.1 Heat of Crystallization or Relaxation	222
3.4 Elastic Moduli	222
3.5 Hardness	222

3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	223
4.1	Thermomagnetic Curve.	223
4.1.1	Curie Temperature	223
4.3.1	Magnetic Moment and Magnetic Anisotropy.	225
4.8	Mössbauer Spectra	225
5.1	Resistivity and Conductivity	226
5.8	Superconductivity.	227
	References	229
Fe-P-Pd (266)		230
1.4	Radial Distribution Function	230
2.1.3	Debye Temperature.	230
2.4.1	Glass Transition temperature	231
3.4	Elastic Moduli	231
	References	231
Fe-P-Si (267).		232
2.4.1	Glass Transition Temperature	232
2.5	Crystallization Temperature.	232
2.8	Critical Quantities for Formation of Amorphous Phase	232
3.10	Embrittlement	232
5.1	Resistivity and Conductivity	232
	References	233
Fe-P-V (268).		234
2.4	DSC/DTA Curve and Glass Formation	234
3.9	Viscosity	234
3.11	Thermomechanical Analysis (TMA) and Dynamic Mechanical Analysis (DMA)	234
	References	234
Fe-Pd-Si (269).		235
1.5	Radial Structure Function	235
2.4.1	Glass Transition Temperature	235
2.5	Crystallization Temperature.	235
3.2	Tensile Strength, Compressive Strength and Strain	235
3.6	Stress-Strain and Stress-Elongation	236
4.8	Mössbauer Spectra	236
4.8.1	Quadrupole Splitting and Isomer Shift	236
	References	236
Fe-Pd-Zr (270)		237
Fe-Pr-Zr (271)		238
4.2.1	Coercive Force.	238
4.3	Magnetization Curve and Saturation Magnetic Moment.	238
4.5	Susceptibility and Cooling Effect.	238
	References	238
Fe-Rh-Zr (272).		239
Fe-Ru-Zr (273).		240
4.3	Magnetization Curve and Saturation Magnetic Moment.	240
4.5	Susceptibility and Cooling Effect.	240
4.5	Susceptibility and Cooling Effect.	241
4.8.2	Magnetic Hyperfine Field and Line Splitting	241
	References	241

Fe-Sc-Zr (274)	242
5.1 Resistivity and Conductivity	242
5.1.2 Temperature Dependence of Resistivity	242
5.3 Hall Effect	243
5.6 Dielectric Properties	243
References	243
Fe-Si-Tb (275)	244
1.2 X-ray Diffraction Profile	244
2.4 DSC/DTA Curve and Glass Formation	244
4.2.1 Coercive Force	244
4.3 Magnetization Curve and Saturation Magnetic Moment	245
4.6 Magnetostriction	245
References	246
Fe-Si-Ti (276)	247
2.5 Crystallization Temperature	247
3.5 Hardness	247
References	247
Fe-Si-Zr (277)	248
1.4 Radial Distribution Function	248
2.5 Crystallization Temperature	248
3.4 Elastic Moduli	248
4.1.1 Curie Temperature	248
References	249
Fe-Sn-Zr	250
4.13 Mössbauer Spectra	250
References	250
Fe-V-Zr (278)	251
4.1.1 Curie Temperature	251
References	251
Ga-Ni-Zr	252
1.4 Radial Distribution Function	252
References	252
Ge-La-Ni	253
1.2 X-ray Diffraction Profile	253
2.4 DSC/DTA Curve and Glass Formation	253
References	253
Ge-Mn-Pd (279)	254
4.5 Susceptibility and Cooling Effect	254
5.1 Resistivity and Conductivity	254
References	254
Ge-Mo-Zr (280)	255
3.4 Elastic Moduli	255
References	255
Ge-Nb-Si (281)	256
5.8 Superconductivity	256
References	256
Ge-Nb-Zr (282)	257
2.5 Crystallization Temperature	257

3.4	Elastic Moduli	257
3.5	Hardness	257
5.1	Resistivity and Conductivity	258
5.1.2	Temperature Dependence of Resistivity	258
5.8	Superconductivity	258
	References	260
Ge-Pd-Si (283)		261
1.6	Lattice Parameters	261
2.4.1	Glass Transition Temperature	261
2.5	Crystallization Temperature	261
2.5.1	Heat of Crystallization or Relaxation	262
	References	262
Ge-Ta-Zr (284)		263
3.4	Elastic Moduli	263
	References	263
Ge-Ti-Zr (285)		264
3.4	Elastic Moduli	264
	References	264
Ge-V-Zr (286)		265
3.4	Elastic Moduli	265
	References	265
H-In-Ti (287)		266
1.2	X-ray Diffraction Profile	266
2.4	DSC/DTA Curve and Glass Formation	266
2.5	Crystallization Temperature	267
2.5.1	Heat of Crystallization or Relaxation	267
	References	267
H-Ni-Zr (288)		268
2.2	Atomic Diffusivity	268
4.9.3	Neutron Magnetic Resonance	268
5.1	Resistivity and Conductivity	269
	References	270
H-Pd-Zr (289)		271
1.2	X-ray Diffraction Profile	271
1.8.7	Small Angle X-ray Scattering and Small Angle Neutron Scattering	271
5.8	Superconductivity	271
	References	271
H-Tb-Zr (290)		272
1.5	Radial Structure Function	272
	References	272
H-Y-Zr (291)		273
Hf-Nb-Si (292)		274
2.4	DSC/DTA Curve and Glass Formation	274
2.5	Crystallization Temperature	274
3.4	Elastic Moduli	274
3.5	Hardness	274
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	275
5.8	Superconductivity	275
	References	276

Hf-Ni-P (293)	277
2.5 Crystallization Temperature	277
2.5.1 Heat of Crystallization or Relaxation	277
2.7.1 Transition Temperature	277
References	278
Hf-Ni-Pd	279
1.2 X-ray Diffraction Profile	279
2.4 DSC/DTA Curve and Glass Formation	279
2.4.1 Glass Transition Temperature	279
2.5 Crystallization Temperature	280
References	280
Hf-Si-V (294)	281
2.4 DSC/DTA Curve and Glass Formation	281
2.5 Crystallization Temperature	281
3.4 Elastic Moduli	281
3.5 Hardness	281
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	282
5.8 Superconductivity	282
References	282
Hf-Si-Zr (295)	283
2.5 Crystallization Temperature	283
3.4 Elastic Moduli	283
3.5 Hardness	283
References	283
In-Mg-Zn (296)	284
5.4 Thermoelectric Power	284
References	284
Ir-Nb-Ni (297)	285
6.1 Potentiostatic and Potentiodynamic Polarization Curves	285
References	285
Ir-Ni-Ta (298)	286
6.1 Potentiostatic and Potentiodynamic Polarization Curves	286
References	286
Ir-P-Pd (299)	287
6.1 Potentiostatic and Potentiodynamic Polarization Curves	287
References	287
La-Mg-Ni (300)	288
1.1 Density and Volume	288
1.3 Interference Function	288
1.4 Radial Distribution Function	289
1.8.6 X-ray Photoelectron Spectroscopy	289
1.8.7 Small-Angle X-ray Scattering and Small-Angle Neutron Scattering	289
2.1 Heat Capacity	290
2.1.1 Electronic Heat Capacity	291
2.1.3 Debye Temperature	292
2.4 DSC/DTA Curve and Glass Formation	293
2.4.1 Glass Transition Temperature	293
2.5 Crystallization Temperature	294
2.5.1 Heat of Crystallization or Relaxation	294
2.8 Critical Quantities for Formation of Amorphous Phase	295

2.9	Configuration Entropy	295
5.1	Resistivity and Conductivity	295
5.1.2	Temperature Dependence of Resistivity	296
5.3	Hall Effect	296
5.4	Thermoelectric Power	296
	References	297
La-Mg-Zn (301)		298
2.4	DSC/DTA Curve and Glass Formation	298
2.5	Crystallization Temperature	298
3.1	Stress-Strain Curve	298
3.2	Tensile Strength, Compressive Strength and Strain	299
3.4	Elastic Moduli	299
3.5	Hardness	299
	References	299
Mg-Mm-Y (302)		300
3.1	Stress-Strain Curve	300
3.2	Tensile Strength, Compressiv Strength and Strain	300
3.5	Hardness	300
	References	300
Mg-Nd-Ni (303)		301
1.2	X-ray Diffraction Profile	301
2.2	Atomic Diffusivity	301
2.4	DSC/DTA Curve and Glass Formation	302
2.4.1	Glass Transition Temperature	302
2.4.2	Reduced Glass Transition Temperature	302
2.5	Crystallization Temperature	303
2.6	Supercooled Liquid Range	303
2.7.1	Transition Temperature	303
2.8	Critical Quantities for Formation of Amorphous Phase	303
3.9	Viscosity	304
	References	304
Mg-Ni-Pr		305
1.2	X-ray Diffraction Profile	305
2.4	DSC/DTA Curve and Glass Formation	305
2.4.1	Glass Transition Temperature	305
2.4.2	Reduced Glass Transition Temperature	305
2.5	Crystallization Temperature	306
2.6	Supercooled Liquid Range	306
2.7.1	Transition Temperature	306
	References	306
Mg-Ni-Y (304)		307
2.4	DSC/DTA Curve and Glass Formation	307
2.4.1	Glass Transition Temperature	307
2.5	Crystallization Temperature	308
2.6	Supercooled Liquid Range	308
3.2	Tensile Strength, Compressive Strength and Strain	308
3.4	Elastic Moduli	309
3.5	Hardness	309
	References	310

Mg-Sn-Zn (305)	311
5.4 Thermoelectric Power	311
References	311
Mn-Ni-Zr (306)	312
2.1.1 Electronic Heat Capacity	312
2.1.2 UV Photoelectron Spectroscopy	312
2.1.3 Debye Temperature	313
5.1 Resistivity and Conductivity	313
5.1.2 Temperature Dependence of Resistivity	314
References	314
Mn-P-Pd (307)	315
1.1 Density and Volume	315
References	315
Mn-P-Si (308)	316
1.4 Radial Distribution Function	316
1.5 Radial Structure Function	317
1.6 Lattice Parameter	317
References	317
Mn-Pd-Si (309)	318
4.1 Thermomagnetic Curve	318
4.3.1 Magnetic Moment and Magnetic Anisotropy	318
4.5 Susceptibility and Cooling Effect	319
4.11 Magnetoresistivity	319
5.1 Resistivity and Conductivity	319
References	320
Mn-Si-Zr (310)	321
2.5 Crystallization Temperature	321
References	321
Mo-Nb-Si (311)	322
2.5 Crystallization Temperature	322
3.5 Hardness	322
5.8 Superconductivity	322
References	323
Mo-Ni-P (312)	324
6 Corrosion Behaviour	324
6.1 Potentiostatic and Potentiodynamic Polarization Curves	324
References	325
Mo-P-Rh (313)	326
Mo-P-Ru (314)	327
1.2 X-ray Diffraction Profile	327
2.4 DSC/DTA Curve and Glass Formation	327
4.3 Magnetization Curve and Saturation Magnetic Moment	327
4.5 Susceptibility and Cooling Effect	328
5.1 Resistivity and Conductivity	328
5.8 Superconductivity	328
References	329
Mo-Si-Zr (315)	330
2.5 Crystallization Temperature	330
3.4 Elastic Moduli	330

3.5	Hardness	331
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	331
	References	331
Nb-Ni-Pd (316)		332
Nb-Ni-Pt (317)		333
1.2	X-ray Diffraction Profile	333
1.8.3	Electron Probe Micro Analysis and EDX Spectra	333
1.8.6	X-ray Photoelectron Spectroscopy	333
	References	333
Nb-Ni-Sn		334
1.2	X-ray Diffraction Profile	334
2.4	DSC/DTA Curve and Glass Formation	334
2.4.1	Glass Transition Temperature	334
2.5	Crystallization Temperature	335
2.7.1	Transition Temperature	335
3.2	Tensile Strength, Compressive Strength and Strain	335
3.3	Yield Strength	336
3.4	Elastic Moduli	336
3.5	Hardness	336
3.9	Viscosity	336
	References	337
Nb-Ni-Ta (318)		338
1.2	X-ray Diffraction Profile	338
2.4	DSC/DTA Curve and Glass Formation	338
2.4.1	Glass Transition Temperature	338
2.4.2	Reduced Glass Transition Temperature	338
2.5	Crystallization Temperature	339
2.7.1	Transition temperature	339
2.8	Critical Quantities for Formation of Amorphous Phase	339
3.1	Stress-Strain Curve	339
5.4	Corrosion Behaviour	340
	References	340
Nb-Ni-Ti		341
1.2	X-ray Diffraction Profile	341
2.4	DSC/DTA Curve and Glass Formation	341
2.4.1	Glass Transition Temperature	341
2.4.2	Reduced Glass Transition Temperature	341
2.5	Crystallization Temperature	341
2.8	Critical Quantities for Formation of Amorphous Phase	341
6	Corrosion Behaviour	342
	References	342
Nb-Ni-Y		343
1.2	X-ray Diffraction Profile	343
2.4	DSC/DTA Curve and Glass Formation	343
	References	343
Nb-Ni-Zr		344
1.2	X-ray Diffraction Profile	344
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	345
2.4	DSC/DTA Curve and Glass Formation	345
2.4.1	Glass Transition Temperature	346

2.4.2	Reduced Glass Transition Temperature	346
2.5	Crystallization Temperature	347
2.5.1	Heat of Crystallization or Relaxation	347
2.6	Supercooled Liquid Range	348
2.7	Phase Diagram	348
2.7.1	Transition Temperature	349
2.8	Critical Quantities for Formation of Amorphous Phase	349
3.1	Stress –Strain Curve	349
3.5	Hardness	350
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	350
	References	351
Nb-Si-Ta (319)		352
2.5	Crystallization Temperature	352
3.5	Hardness	352
5.8	Superconductivity	352
	References	352
Nb-Si-Ti (320)		353
1.1	Density and Volume	353
2.4	DSC/DTA Curve and Glass Formation	353
2.5	Crystallization Temperature	354
3.1	Stress-Strain Curve	354
3.2	Tensile Strength, Compressive Strength and Strain	354
3.4	Elastic Moduli	355
3.5	Hardness	356
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	356
5.8	Superconductivity	356
6.1	Potentiostatic and Potentiodynamic Polarization Curves	359
	References	359
Nb-Si-V (321)		360
2.5	Crystallization Temperature	360
3.5	Hardness	360
5.8	Superconductivity	360
	References	360
Nb-Si-W (322)		361
2.5	Crystallization Temperature	361
3.5	Hardness	361
5.8	Superconductivity	361
	References	361
Nb-Si-Zr (323)		362
1.1	Density and Volume	362
2.1.1	Electronic Heat Capacity	362
2.1.3	Debye Temperature	362
2.4	DSC/DTA Curve and Glass Formation	363
2.5	Crystallization Temperature	363
3.3	Yield Strength	364
3.4	Elastic Moduli	364
3.5	Hardness	365
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	365
5.1	Resistivity and Conductivity	366
5.1.2	Temperature Dependence of Resistivity	366

5.8	Superconductivity	366
	References	370
Ni-P-Pd (324)		371
1.1	Density and Volume	371
1.2	X-Ray Diffraction Profile	371
1.4	Radial Distribution Function	372
1.5	Radial Structure Function	374
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	375
1.8.6	X-ray Photoelectron Spectroscopy	375
2.1	Heat Capacity	377
2.1.3	Debye Temperature	380
2.2	Atomic Diffusivity	380
2.4	DSC/DTA Curve and Glass Formation	380
2.4.1	Glass Transition Temperature	384
2.4.2	Reduced Glass Transition Temperature	385
2.5	Crystallization Temperature	386
2.5.1	Heat of Crystallization or Relaxation	387
2.7	Phase Diagram	389
2.7.1	Transition Temperature	389
2.8	Critical Quantities for Formation of Amorphous Phase	390
2.9	Configuration Entropy	390
3.1	Stress-Strain Curves	390
3.2	Tensile Strength, Compressive Strength and Strain	392
3.3	Yield Strength	393
3.4	Elastic Moduli	393
3.5	Hardness	394
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	395
3.9	Viscosity	395
3.11	Thermomechanical Analysis and Dynamic Mechanical Analysis	398
4.8	Mössbauer Spectra	399
5.1	Resistivity and Conductivity	400
6.1	Potentiostatic and Potentiodynamic Polarization Curves	400
	References	400
Ni-P-Pt (325)		403
1.1	Density and Volume	403
1.2	X-ray Diffraction Profile	403
1.3	Interference Function	404
1.4	Radial Distribution Function	404
1.6	Lattice Parameter	405
1.7	Coordination Number, Valence Electron Number and Interatomic Distances	405
2.1	Heat Capacity	406
2.1.3	Debye Temperature	406
2.4.1	Glass Transition Temperature	406
2.4.2	Reduced Glass Transition Temperature	407
2.5	Crystallization Temperature	407
2.6	Supercooled Liquid Range	408
2.7.1	Transition Temperature	408
3.4	Elastic Moduli	409
3.5	Hardness	409
3.9	Viscosity	409
3.11	Thermomechanical Analysis and Dynamic Mechanical Analysis	410
4.8	Mössbauer Spectra	410

4.8.1	Quadrupole Splitting and Isomer Shift	410
	References	410
Ni-P-Ta (326)		412
Ni-P-Ti (327)		413
2.5	Crystallization Temperature.	413
3.5	Hardness	413
5.1	Resistivity and Conductivity	413
6.1	Potentiostatic and Potentiodynamic Polarization Curves	413
	References	414
Ni-P-W (328)		415
6	Corrosion Behaviour.	415
6.1	Potentiostatic and Potentiodynamic Polarization Curves	415
	References	416
Ni-P-Zr (329)		417
2.4	DSC/DTA Curve and Glass Formation	417
2.5	Crystallization Temperature.	417
2.5.1	Heat of Crystallization or Relaxation	418
3.5	Hardness	418
	References	418
Ni-Pd-Si (330)		419
1.1	Density and Volume	419
1.3	Interference Function	420
1.4	Radial Distribution Function	420
1.6	Lattice Parameter	420
2.1	Heat Capacity.	421
2.4	DSC/DTA Curve and Glass Formation	422
2.4.1	Glass Transition Temperature	422
2.5	Crystallization Temperature.	423
2.5.1	Heat of Crystallization or Relaxation	423
3.1	Stress-Strain Curve.	423
3.6	Fatigue Strength, Fracture and Critical Fracture Temperature	424
5.1	Resistivity and Conductivity	424
6.1	Potentiostatic and Potentiodynamic Polarization Curves	425
	References	426
Ni-Pd-Ta (331)		427
Ni-Pd-Zr (332)		427
Ni-Ru-Ta (333)		428
6.1	Potentiostatic and Potentiodynamic Polarization Curves	428
	References	428
Ni-Si-Ti (334)		429
2.4	DSC/DTA Curve and Glass Formation	429
2.5	Crystallization Temperature.	429
3.5	Hardness	430
	References	430
Ni-Si-Zr (335)		431
2.5	Crystallization Temperature.	431
2.5.1	Heat of Crystallization or Relaxation	431
3.4	Elastic Moduli	432

3.5 Hardness	432
References	432
Ni-Ti-Zr (336)	433
1.5 Radial Structure Function	433
2.1.1 Electronic Heat Capacity	433
2.1.3 Debye Temperature	434
2.1.2 UV Photoelectron Spectroscopy	434
5.1 Resistivity and Conductivity	435
5.8 Superconductivity	435
References	435
Ni-V-Zr (337)	436
1.4 Radial Distribution Function	436
1.5 Radial Structure Function	436
1.8.7 Small-Angle X-ray Scattering and Small-Angle Neutron Scattering	437
2.1.1 Electronic Heat Capacity	437
2.1.2 UV Photoelectron Spectroscopy	438
2.1.3 Debye Temperature	438
5.1 Resistivity and Conductivity	439
5.8 Superconductivity	439
References	439
P-Pd-Ti (338)	440
6 Corrosion Behaviour	440
6.1 Potentiostatic and Potentiodynamic Polarization Curves	441
References	441
P-Ru-W (339)	442
1.4 Radial Distribution Function	442
References	442
Pd-Rh-Si (340)	443
2.4.1 Glass Transition Temperature	443
2.5 Crystallization Temperature	443
References	443
Pd-Sb-Si (341)	444
2.4.1 Glass Transition Temperature	444
2.5 Crystallization Temperature	444
References	444
Pd-Si-U (342)	445
1.4 Radial Distribution Function	445
1.5 Radial Structure Function	445
5.1 Resistivity and Conductivity	446
5.3 Hall Effect	446
5.4 Thermoelectric Power	446
References	446
Pd-Si-V	447
5.1 Resistivity and Conductivity	447
References	447
Pd-Si-Zr (343)	448
Ru-Si-Zr (344)	448
Si-Sn-Zr (345)	448

Si-Ta-Ti (346)	449
2.4 DSC/DTA Curve and Glass Formation	449
2.5 Crystallization Temperature	449
3.2 Tensile Strength, Compressive Strength and Strain	449
3.4 Elastic Moduli	450
3.5 Hardness	450
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	450
5.8 Superconductivity	450
References	451
Si-Ta-Zr (347)	452
2.5 Crystallization Temperature	452
3.3 Yield Strength	452
3.4 Elastic Moduli	452
3.5 Hardness	453
References	453
Si-Ti-V (348)	454
2.4 DSC/DTA Curve and Glass Formation	454
2.5 Crystallization Temperature	454
3.2 Tensile Strength, Compressive Strength and Strain	454
3.4 Elastic Moduli	455
3.5 Hardness	455
3.6 Fatigue Strength, Fracture and Critical Fracture Temperature	455
5.8 Superconductivity	456
References	457
Si-Ti-Zr (349)	458
2.5 Crystallization Temperature	458
3.3 Yield Strength	458
3.4 Elastic Moduli	458
3.5 Hardness	459
References	460
Si-V-Zr (350)	461
2.5 Crystallization Temperature	461
3.3 Yield Strength	461
3.4 Elastic Moduli	461
3.5 Hardness	462
References	462
Si-W-Zr (351)	463
2.5 Crystallization Temperature	463
3.5 Hardness	463
References	463
Survey of Volume LB III/37	464
Definitions, Units and Conversion Factors	465