

Preface	V
About the Author	VII
1 Injection Unit: Screw	1
1.1 Prepares the Melt	1
1.2 Flows the Melt	2
1.3 Pressurizes the Melt	3
1.4 Sections of the Screw	3
1.4.1 Feed Zone	3
1.4.2 Transition or Compression Zone	4
1.4.3 Metering Zone	4
1.5 L/D or Length/Diameter	4
1.6 Compression Ratio	4
1.7 Profile	6
1.8 Injection Pressure	6
1.9 Injection High Limit Fill Time	7
1.10 Injection Pack Pressure/Time	7
1.11 Injection Hold Pressure/Time	7
1.12 Non-return Valve Function	8
1.13 Different Styles of Non-return Valves	9
1.14 Decompression/Pull Back/Suck Back	10
1.15 Screw Rotate Delay	10
1.16 Mixing Head on a Reciprocating Screw	11
1.17 Barrier Screws	11

2	Injection Unit: Barrel	13
2.1	Barrel	13
2.2	Thermocouples	14
2.3	Heater Bands	17
2.4	Spacing of Heater Bands	19
2.5	Wattage	19
2.6	Worn Barrel	20
2.7	Feed Throat	21
2.8	Venting of the Barrel	21
2.9	Hopper	22
2.10	Hopper Dryer Diagram	24
2.11	Filter Packs/Dispersion Disks/Screen Packs	25
3	Clamping Unit	27
3.1	Hydraulic	27
3.2	Toggle	28
3.3	Weakness	28
3.4	Tie-Bar-Less	28
3.5	Single Point	29
3.6	Platen Wrap	30
3.7	Mold Coverage Area	31
3.8	Cleanliness of the Platens	31
3.9	Care of Bolt Holes	32
3.10	Proper Bolt Location	33
3.11	Weight of Mold Calculations	34
3.12	Mold Height	35
3.13	Calculating Clamp Tonnage for a Press	35
4	Ejectors/Controllers, Human Machine Interface (HMI)	37
4.1	Ejector Pattern and Spacing	37
4.2	Ejector Spacing	37
4.3	Controllers	40
4.3.1	Open Loop	40
4.3.2	Closed Loop	40
4.4	Key Pads	41

5	Machine Performance Testing	43
5.1	Rear Barrel Zone Optimization	43
5.2	Load Sensitivity	44
5.2.1	Purge Disk	45
5.3	Pressure Response	46
5.4	Dynamic Non-return Valve Test (FILL)	48
5.5	Static Non-return Valve Test (PACK/HOLD)	49
5.6	Injection Speed Linearity	50
6	Process Development Test	53
6.1	Tonnage Calculation/Projected Area	53
6.2	On Machine Rheology Curve (Viscosity Curve) or Fill Time Study	56
6.3	Construction of Viscosity Curve Graph	57
6.4	Least Pressure Curve	60
6.5	Plastic Flow Rate (Qp)	60
6.6	Shear Rates	60
6.7	Gate Freeze, Gate Seal, or Gate Stabilization	64
6.8	Runner Weight Study	67
6.9	Range Finding for Gate Seal	68
6.10	Manifold Imbalance and Balance of Fill Analysis	68
6.11	Cooling Optimization Study	70
6.12	Pressure Loss Study	71
7	Plastic Temperature	73
7.1	Molecular Structure of Common Materials	73
7.2	Morphology	74
7.2.1	Amorphous Resin Morphology	74
7.2.2	Semi-Crystalline Resin Morphology	74
7.3	Glass Transition Temperature (Tg)	75
7.4	Melt Transition Temperature (Tm)	75
7.5	Shrinkage	76
7.5.1	Isotropic Shrinkage	76
7.5.2	Anisotropic Shrinkage	77
7.6	Melt Density versus Solid Density	78
7.7	Advantages/Disadvantages of Hot Runner versus Cold Runner	79
7.8	Induced Shear through a Hot or Cold Runner System	80

8	Plastic Flow	81
8.1	Fountain Flow	81
8.2	Flow of Plastic	82
8.3	How to Calculate Flow Rate (Q_p)	82
8.4	Calculating Volume of Shot Size	83
8.5	Blocking a Cavity	84
8.6	Flow through a Mold	85
8.7	Orientation	85
8.8	Transfer/Cut-Off Position	86
8.9	Viscosity Changes	86
8.10	Intensifying Ratio (R_i)	87
8.11	Pressure Limited Process	88
8.12	Safe Start-Up Shot Size	89
8.13	Runner Sizing	91
9	Plastic Pressure (Pack/Hold)	93
9.1	Plastic Pressure	93
9.2	Dynamic versus Static	93
9.3	Viscosity Changes	93
9.4	End of Cavity Pressure Loss	94
9.5	Part Shrinkage versus Cavity Pressure	94
9.6	Maximum Average Pressure at Parting Line before Flashing	95
10	Cooling	99
10.1	Plastic Cooling	99
10.2	Turbulent versus Laminar Flow	99
10.3	Reynolds Number	101
10.4	Water Lines	102
10.5	Area of Water Line	103
10.6	Series/Parallel	103
10.7	Cooling Rate	105
10.8	Ineffective Cooling	106
10.9	Cooling Time	106
10.10	Depth, Diameter, and Pitch	106

10.11 Baffles/Bubblers	108
10.12 How a Thermolator/Mold Heater Works	108
11 Benchmarking the Injection Molding Process	111
12 Process Troubleshooting	115
12.1 Black Specks	115
12.2 Blush	117
12.3 Brittleness	118
12.4 Burns	119
12.5 Burns in Gates	121
12.6 Cloudy Parts	121
12.7 Color Streaks	122
12.8 Deformation: Ejector Pin Marks	123
12.9 Degraded Polymer	124
12.10 Design	124
12.11 Fish Hooks	125
12.12 Flash	126
12.13 Flow Lines	128
12.14 Hot Tip Drool	129
12.15 Jetting	130
12.16 Long Gates	131
12.17 Nozzle Drool	133
12.18 Parts Sticking in Mold	133
12.19 Pulls	134
12.20 Shorts/Non-Fills	134
12.21 Sinks	135
12.22 Splay	137
12.23 Sprue Sticking	138
12.24 Surface Imperfections	139
12.25 Voids	140
12.26 Warpage	141
12.27 Weld Lines	143

13	Effects of Making Specific Changes to the Process	145
13.1	Cooling Time	145
13.2	Cut-Off/Transfer Position	146
13.3	Screw Speed	147
13.4	Back Pressure	148
13.5	Injection Velocity	149
13.6	Injection Pressure	150
13.7	Melt Temperature	151
13.8	Decompression/Suck Back	151
13.9	Hot Tip Temperature	152
13.10	Manifold Temperature	153
13.11	Pack Pressure	154
13.12	Pack Time	155
13.13	Hold Pressure	155
13.14	Hold Time	156
13.15	Feed Throat Temperature	157
14	What is Important on a Set-Up Sheet?	159
15	Commonly Used Conversion Factors and Formulas	163
15.1	Conversion Factors	163
15.2	Common Formulas for Injection Molding	164
16	Machine Set-Up	167
17	Things That Hurt the Bottom Line of a Company	171
18	Terms and Definitions	173
19	Reference List for Further Courses and Reading	187
19.1	Courses	187
19.2	Reading	187
	Index	189