

Contents

1 Introduction and Background. By T. Egami and W.L. Johnson (With 14 Figures)	1
1.1 Background	1
1.2 Liquid-to-Crystal Transition: Undercooling and Nucleation	4
1.2.1 Thermodynamics and Kinetics of Solidification	4
1.2.2 Undercooling	5
1.2.3 Phase Diagram for Metastable States	6
1.3 Metallic Glasses	8
1.3.1 Glass Formation by Rapid Quenching	8
1.3.2 Glass-Forming Composition	8
1.3.3 Crystallization and Structural Relaxation	10
1.3.4 Atomic Structure of Metallic Glasses	11
1.4 Metastable Crystalline Phases	13
1.4.1 Non-Equilibrium in Crystalline Phases	13
1.4.2 Two Examples of Solubility Extension. The Ag–Cu and Ti–Cu Systems	14
1.4.3 Metastable Crystalline Phases Not Present in Equilibrium – Examples	18
References	20
2 Synthesis and Processing. By N.J. Grant, H. Jones, and E.J. Lavernia (With 24 Figures)	23
2.1 Heat Transfer and Solidification Kinetics	24
2.2 Droplet Methods	29
2.3 Spinning Methods	35
2.4 Surface Melting Technologies	38
2.5 Consolidation Technologies	42
References	46
3 Structure and Characterization of Rapidly Solidified Alloys By C.N.J. Wagner, M.A. Otooni, and W. Krakow (With 32 Figures) .	49
3.1 Characterization Techniques	49
3.1.1 Structural Characterization	49
3.1.2 X-Ray Radial Distribution Function	50

3.1.3 High-Resolution Electron Microscopy	52
3.1.4 Differential Scanning Calorimetry – Phase Transformation and Separation	55
3.1.5 Electrical Resistivity	57
3.1.6 Microhardness Measurements	61
3.1.7 Mössbauer Spectroscopy	61
3.2 Total Scattering Intensity from Amorphous and Nanocrystalline Alloys	62
3.2.1 Atomic Distribution Functions	63
3.2.2 Scattered Intensity	63
3.2.3 Reduced Atomic Distribution Functions	64
3.2.4 Coordination Numbers in Binary Amorphous Alloys	67
3.2.5 Topological and Chemical Order in Binary Solutions	67
3.3 Diffraction Theory of Powder Pattern Peaks from Nanocrystalline Materials	68
3.3.1 Fourier Analysis of the Peak Profiles	68
3.3.2 Integral Breadth of Powder Pattern Peaks	70
3.4 Experimental Diffraction Techniques	72
3.4.1 Radiation Sources	72
3.4.2 Diffraction Methods	72
3.4.3 Variable 2θ Method	72
3.4.4 Variable λ Method	73
3.4.5 Analysis of the Diffraction Pattern	73
a) Total Diffracted Intensity from Amorphous and Nanocrystalline Samples	73
b) Fourier Analysis of the Profiles of Powder Pattern Peaks	74
3.5 Structure of Amorphous and Nanocrystalline Alloys	74
3.5.1 Amorphous Beryllium Alloys	75
3.5.2 Amorphous and Nanocrystalline Vanadium Alloys	77
3.5.3 Amorphous and Nanocrystalline Tungsten Alloys	79
3.6 Selected Examples of Electron-Microscopy Analysis	84
References	90
 4 Atomic Transport and Relaxation in Rapidly Solidified Alloys	
By H. Kronmüller and P. Scharwaechter (Appendix) (With 36 Figures)	93
4.1 Basic Equations of Diffusion	94
4.2 Self-Diffusion in Amorphous Alloys	96
4.2.1 Radiotracer Technique	96
4.2.2 Non-Equilibrium and Quasi-Equilibrium of Diffusional Properties	98
4.2.3 Review of Diffusion Data	100
4.2.4 Diffusion Mechanisms in Amorphous Alloys	102
4.3 Theory of Diffusion in Disordered Media	106
4.3.1 The Effective-Medium Approximation	106

4.3.2	Explicite Solutions	106
4.3.3	The Effective-Medium Approximation for Direct Diffusion Mechanisms	107
4.3.4	Applications of the "Effective-Medium Approximation" ...	110
4.3.5	Molecular Dynamics Simulations and Diffusion Mechanisms	112
4.4	Diffusion of Hydrogen Isotopes and Light Particles in Amorphous Alloys	115
4.5	Magnetic After-Effects and Induced Anisotropies Due to Double-Well Systems in Amorphous Alloys	118
4.6	Viscosity and Internal Friction of Amorphous Alloys	124
4.6.1	Viscosity Measurements	125
4.6.2	Internal Friction Measurements	127
	Appendix: Microsectioning by Ion-Beam Sputtering – A Powerful Method to Determine Diffusion Profiles	130
	References	131
5	Mechanical Properties and Behaviour. By H. Jones and E.J. Lavernia (With 17 Figures)	135
5.1	Elastic and Anelastic Behaviour	135
5.2	Plastic Flow and Fracture Behaviour	137
5.3	Strength and Hardness	138
5.4	Fatigue and Wear Behaviour	142
5.5	Creep and Hot Deformation Behaviour	146
	References	151
6	Magnetic and Electronic Properties of Rapidly Quenched Materials By R.C. O'Handley and H.H. Liebermann (With 23 Figures)	153
6.1	Rapidly Quenched Alloys	155
6.1.1	Amorphous Alloys	155
6.1.2	Nanocrystalline Alloys	156
6.2	Fundamental Magnetic Properties	157
6.2.1	Magnetic Moments and Curie Temperatures	157
6.2.2	Magnetic Anisotropy	160
6.2.3	Magnetostriction	161
6.3	Domains and Technical Properties of Amorphous Alloys	163
6.3.1	Domains	163
6.3.2	Coercivity	165
6.3.3	Magnetic Hardening	166
6.3.4	Induced Anisotropy	167
6.4	Magnetism and Short-Range Order	169
6.4.1	Ingredients of Short-Range Order	169
6.4.2	Random Local Anisotropy	170

6.5 Electronic Structure of Amorphous Alloys	172
6.5.1 Chemical Bonding	172
6.5.2 Split <i>d</i> Bands and <i>p-d</i> Bonding	173
6.5.3 Electron Transport	177
6.6 Applications	179
6.6.1 Distribution Transformers	182
6.6.2 Electronic Article Surveillance Sensors	182
6.6.3 Magnetic Recording Media	183
6.6.4 Permanent Magnets	184
6.7 Conclusion, Outlook	184
References	185
 7 Chemical Properties of Amorphous Alloys. By K. Hashimoto (With 22 Figures)	 187
7.1 Corrosion-Resistant Alloys in Aqueous Solutions	187
7.1.1 High Corrosion Resistance of Amorphous Fe–Cr Alloys ..	187
7.1.2 Factors Determining the High Corrosion Resistance of Amorphous Alloys	188
a) High Activity of Amorphous Alloys	188
b) Homogeneous Nature of Amorphous Alloys	191
c) Beneficial Effect of Phosphorus in Amorphous Alloys ..	192
7.1.3 Recent Efforts in Tailoring Corrosion-Resistant Alloys ...	195
a) Aluminum-Refractory Metal Alloys	195
b) Chromium-Refractory Metal Alloys	196
7.2 Corrosion-Resistant Alloys at High Temperatures	200
7.3 Electrodes for Electrolysis of Aqueous Solutions	202
7.3.1 Electrode Materials	202
7.3.2 Preparation of Electrodes	205
7.4 Catalysts for Prevention of the Greenhouse Effect and Saving the Ozone Layer	209
7.4.1 CO ₂ Recycling	210
7.4.2 Catalysts for the Decomposition of NO _x	213
7.4.3 Catalysts for the Decomposition of Chlorofluorocarbons ..	214
7.5 Concluding Remarks	214
References	215
 8 Selected Examples of Applications. By H.H. Liebermann, N.J. Grant, and T. Ando (With 8 Figures)	 217
8.1 Improvement of Mechanical Properties	218
8.1.1 Size Refinement	218
8.1.2 Extended Solid Solubility	222
8.1.3 Chemical Homogeneity	224
8.2 Magnetic Applications	225
8.2.1 Magnetic Properties and Applications	226

8.2.2 Power Magnetic Applications	227
8.2.3 Specialty Magnetic Applications	227
8.3 Joining Applications	229
8.4 Current Limitations and Future Directions	231
Further Reading	235
9 Glossary of Important Terms. By T. Egami, M.A. Otooni, and W. Dmoswki	237
Subject Index	243