

Contents

Prologue 1

Chapter 1. Background and General Applications 11

1.1. How the Laser Works 11

 1.1.1. Construction 11

 1.1.2. Stimulated Emission Phenomenon 15

1.2. Types of Industrial Lasers 20

 1.2.1. Carbon Dioxide Lasers 20

 1.2.2. Carbon Monoxide Lasers 25

 1.2.3. Solid State Lasers 25

 1.2.4. Diode Lasers 29

 1.2.5. Excimer Lasers 31

1.3. Comparison Between Lasers 32

1.4. Applications of Lasers 34

 1.4.1. Powerful Light 35

 1.4.2. Alignment 35

 1.4.3. Measurement of Length 35

 1.4.4. Pollution Detection 38

 1.4.5. Velocity Measurement 39

 1.4.6. Holography 42

 1.4.7. Speckle Interferometry 45

 1.4.8. Inspection 45

 1.4.9. Analytic Technique 46

 1.4.10 Recording 46

 1.4.11. Communications 49

 1.4.12. Heat Source 50

 1.4.13. Medical 50

 1.4.14. Printing 53

 1.4.15. Isotope Separation 54

 1.4.16. Atomic Fusion 54

1.5. Market for Laser Applications 54

Chapter 2. Basic Laser Optics58

2.1. The Nature of Electromagnetic Radiation	58
2.2. Interaction of Electromagnetic Radiation with Matter	62
2.2.1. Non Linear Effects	64
2.3. Reflection (or Absorption)	66
2.3.1. Wavelength	68
2.3.2. Temperature	68
2.3.3. Surface Films	68
2.3.4. Angle of Incidence	70
2.3.5. Material and Surface Roughness	71
2.4. Refraction	71
2.4.1.	73
2.5. Interference.....	74
2.6. Diffraction.	75
2.7. Laser Beam Characteristics	75
2.7.1. Wavelength	75
2.7.2. Coherence	76
2.7.3. Mode and Beam Diameter	76
2.7.4. Polarisation	79
2.8. Focussing with a Single Lens	79
2.8.1. Focal Spot Size	79
2.8.2. Depth of Focus	91
2.9. Optical Components	92
2.9.1. Lens Doublets.....	92
2.9.2. Depolarisers	92
2.9.3. Collimators	93
2.9.4. Metal Optics	93
2.9.5. Diffractive Optical Elements.	95
2.9.6. Laser Scanning Systems.	95
2.9.7. Fibre Delivery Systems.	96

Chapter 3. Laser Cutting 103

3.1. Introduction	103
3.1.1. Cut quality Characteristics	104
3.1.2. Process Characteristics	104
3.2. The Process - How It Is Done	104
3.3. Methods of Cutting	106
3.3.1. Vaporisation Cutting	106
3.3.2. Fusion Cutting - Melt and Blow	109
3.3.3. Reactive Fusion Cutting	115
3.3.4. Controlled Fracture	116
3.3.5. Scribing	118
3.3.6. Cold Cutting	118

3.3.7.	Burning Stabilised Gas Cutting.	119
3.4.	Theoretical Models of Cutting.....	119
3.5.	Practical Performance	120
3.5.1.	Beam Properties	120
3.5.2.	Transport Properties	124
3.5.3.	Gas Properties	124
3.5.4.	Material Properties	129
3.5.5.	Parctical tips.....	131
3.6.	Examples of Applications	132
3.6.1.	Die Board Cutting.....	133
3.6.2.	Cutting Quartz Tube.....	133
3.6.3.	Profile Cutting.....	133
3.6.4.	Cloth Cutting.....	133
3.6.5.	Aerospace Materials	134
3.6.6.	Cutting Fibre Glass.....	134
3.6.7.	Cutting Kevlar.....	134
3.6.8.	Prototype Car Production.....	134
3.6.9.	Cutting Alumina and Dielectric Boards.....	135
3.6.10.	Furniture Industry	135
3.6.11.	Perforated Irrigation Pipes.....	135
3.6.12.	Perforating Cigarette Paper	135
3.6.13.	Flexographic Print Rolls	135
3.6.14.	Cutting Radioactive Materials	135
3.6.15.	Electronic Applications	136
3.6.16.	Hole drilling.....	136
3.6.17.	Scrap recovery	137
3.6.18.	Laser Machining	137
3.6.19.	Ship Building.....	137
3.6.20.	Laser Punch Press	137
3.6.21.	Manufacture of Bikes and Tubular structures...	138
3.6.22.	Cutting and Welding Railcars.....	138
3.7.	Costed Examples	138
3.8.	Process Variations	139
3.8.1.	Arc Augmented Laser Cutting	139
3.8.2.	Hot Machining	139
3.9.	Future Developments.....	140
3.9.1.	Higher Power Lasers	140
3.9.2.	Additional Energy Sources	140
3.9.3.	Improved Coupling	141
3.9.4.	Smaller Spot Size.....	141
3.9.5.	Increased Drag	141
3.9.6.	Increased Fluidity	141
3.10.	Worked Example of Power Requirements.....	141

Chapter 4. Laser Welding 147

4.1. Introduction.....	147
4.2. Process Arrangement	151
4.3. Process Mechanisms - Keyholes and Plasmas	153
4.4. Operating Characteristics	156
4.4.1. Power	157
4.4.2. Spot Size and Mode	160
4.4.3. Polarisation	160
4.4.4. Wavelength	161
4.4.5. Speed	163
4.4.6. Focal Position	165
4.4.7. Joint Geometries	166
4.4.8. Gas Shroud and Gas Pressure	170
4.4.9. Material Properties.....	175
4.4.10. Gravity	178
4.5. Process Variations	178
4.5.1. Arc Augmented Laser Welding.....	178
4.5.2. Twin Beam Laser Welding	178
4.5.3. Walking Beams	180
4.6. Applications.....	181
4.6.1. Tailored Blanks.....	183
4.7. Costed Example	185

Chapter 5. Heat Flow Theory 190

5.1. Introduction	190
5.2. Analytic Models in One Dimensional Heat Flow	195
5.3. Analytic Models for a Stationary Point Source	198
5.3.1. The Instantaneous Point Source	198
5.3.2. The Continuous Point Source	199
5.3.3. Sources other than Point Sources	200
5.4. Analytic Models for a Moving Point Source	200
5.5. Alternative Surface Heating Models.....	202
5.5.1. Ashby Shercliff - Moving hypersurface line source.....	202
5.5.2. Davis et al. Model - Moving Gaussian Source	202
5.6. Analytic Keyhole Models - Line Source Solution	204
5.7. Analytic Moving Point-Line Source Solution	207
5.8. Finite Difference Models	208
5.9. Semi-Quantitative Models	210
5.10. Flow Models	214
5.11. Stress Models	214
5.12. Conclusions	215
5.13. List of Symbols	215

Chapter 6. Laser Surface Treatment218

6.1. Introduction218

6.2. Laser Heat Treatment218

 6.2.1. Heat Flow227

 6.2.2. Mass Flow by Diffusion229

 6.2.3. Mechanism of Transformation Process229

 6.2.4. Properties of Transformed Steels232

6.3. Laser Surface Melting234

 6.3.1. Solidification Mechanisms238

6.4. Laser Surface Alloying243

 6.4.1. Process Variations244

 6.4.2. Applications244

6.5. Laser Cladding246

 6.5.1. Laser Cladding with Preplaced Powder248

 6.5.2. Blown Powder Laser Cladding248

6.6. Particle Injection252

6.7. Surface Texturing253

6.8. Enhanced Electroplating255

6.9. Laser Chemical Vapour Deposition256

6.10. Laser Physical Vapour Deposition256

6.11. Non Contact Bending256

6.12. Magnetic Domain Control259

6.13. Laser Cleaning and Paint Stripping260

6.14. Surface Roughening261

6.15. Scabbling262

6.16. Micro Machining262

6.17. Laser Marking263

6.18. Shock Hardening264

6.19. Conclusions265

Chapter 7. Rapid prototyping and Low Volume Manufacture 272

7.1. Introduction272

7.2. Range of Processes273

 7.2.1. Styles of Manufacture273

 7.2.2. Classification of RP Techniques274

7.3. CAD File Manipulation274

 7.3.1. General Software Manipulation274

7.4. Layer Manufacturing Issues276

 7.4.1. General276

 7.4.2. Stair Stepping277

 7.4.3. Layer Thickness Selection277

 7.4.4. Accuracy278

 7.4.5. Part Orientation278

7.4.6.	Support Structures	278
7.5.	Individual processes	278
7.5.1.	Stereolithography	278
7.5.2.	Selective Laser Sintering	282
7.5.3.	Laminated Object Manufacture	284
7.5.4.	Laser Direct Casting	286
7.6.	Rapid Manufacturing Technologies	287
7.6.1.	Silicone Rubber Moulding	288
7.6.2.	Investment Casting	288
7.6.3.	Sand Casting	289
7.6.4.	Laser Direct Casting	289
7.6.5.	RP Tooling	289
7.7.	Applications	289
7.8.	Conclusions	290

Chapter 8. Laser Automation and In-Process Sensing293

8.1.	Automation Principles	293
8.2.	In-Process Monitoring	296
8.2.1.	Monitoring Beam Characteristics	297
8.2.2.	Monitoring Work Table Characteristics	307
8.2.3.	Monitoring Workpiece Characteristics	311
8.3.	In-Process Control	314
8.3.1.	In-Process Power Control	315
8.3.2.	In-Process Temperature Control	315
8.4.	"Intelligent" In-Process Control	315
8.5.	Conclusions	317

Chapter 9. Laser Safety321

9.1.	The Dangers	321
9.2.	The Standards	321
9.3.	The Safety Limits	323
9.3.1.	Damage to the Eye	323
9.3.2.	Damage to the Skin	325
9.4.	Laser Classification	326
9.5.	Typical Class 4 Safety Arrangements	326
9.6.	Where Are the Risks in a Properly Set Up Facility?	327
9.7.	Electrical Hazards	328
9.8.	Fume Hazards	328
9.9.	Conclusions	329

Epilogue330

Index335