

Contents

1. Introduction	1
1.1 Brief Historical Survey	1
1.2 Hydrogen Isotopes	2
1.3 Hydrogen in Metals	4
1.4 Helium in Metals	5
1.5 Organization of the Book	5
2. General Aspects of Tritium	7
2.1 Production of Tritium	7
2.1.1 Natural Tritium Production	7
2.1.2 Tritium Production in Nuclear Reactors	8
2.1.3 Tritium Production in Future Fusion Reactors	8
2.1.4 Tritium Production by Nuclear Explosions	9
2.2 Risks Associated with Tritium	10
2.2.1 Incorporation	10
2.2.2 More Indirect Risks	12
2.3 Discharge of Tritium to the Environment	13
2.4 Tritium Handling in Future Fusion Reactors	14
2.4.1 Multiple Containment	15
2.4.2 Pumping and Recycling	15
Pumps and Impurity Removal	16
Hydrogen Isotope Separation	17
2.4.3 Tritium Breeding Materials	17
2.4.4 Planned Tritium Use at JET	17
2.5 Tritium Waste Handling	18
3. Preparation of Metal Tritides	21
3.1 Electrolytical Charging of Metals with Tritium	21
3.2 Breeding of Tritium in Metals	21
3.3 Tritium Charging of Metals	
by Means of Nuclear Reactions and Ion Implantation	22
3.4 Tritium Charging of Metals from the Gas Phase	22
3.4.1 Uranium Tritide Storage Containers	24
3.4.2 A Typical Sample Chamber	25
3.4.3 Capacitance Manometers	26
3.4.4 Glove Boxes	28
3.4.5 Material for the First Containment	30

3.5	Tritium Charging of Metals by Means of Metal Tritides . . .	31
3.6	Metals Employed for Tritium Storage	32
3.6.1	Uranium Tritide	34
3.6.2	Palladium Tritide	34
3.6.3	$\text{LaNi}_{5-x}\text{Al}_x$ Tritides	35
3.6.4	Vanadium Tritide	36
3.6.5	Tritides of Ti, Zr, La and the Rare Earths	36
3.6.6	Stability of Binary and Ternary Metal Tritides	37
3.7	Permeability of Tritium in Metals	38
4.	Analysis of Tritium in Metals	41
4.1	Outgassing and/or Combustion	41
4.2	Gas Release Behaviour of MT_r Samples	42
4.3	Tritium Induced X Rays	43
4.4	Tritium Imaging	45
4.5	Tritium Autoradiography	46
5.	Properties of Protium, Deuterium and Tritium in Selected Metals	48
5.1	Solubility of Protium, Deuterium and Tritium in Palladium	48
5.1.1	Solubility of Protium, Deuterium and Tritium in the α Phase of the Pd-X (X=H, D, T) System	48
5.1.2	Solubility of Protium, Deuterium and Tritium in the α , $\alpha+\beta$ and β Phases of the Pd-X (X=H, D, T) System . . .	59
5.2	Solubility of Protium, Deuterium and Tritium in Palladium Silver Alloys	63
5.2.1	Solubility of Protium, Deuterium and Tritium in Palladium Silver Alloys for Hydrogen Concentrations $r \leq 0.02$. . .	65
5.2.2	Solubility of Protium, Deuterium and Tritium in Palladium Silver Alloys for Hydrogen Concentrations $r \leq 0.50$. . .	69
5.3	Solubility of Protium, Deuterium and Tritium in Lithium and Yttrium	72
5.4	Solubility of Protium and Deuterium in Vanadium	75
5.5	Isotope Dependence of the Phase Boundaries in the Pd-X, V-X and Nb-X (X = H, D, T) Systems	77
5.5.1	Phase Boundaries of the Pd-H, Pd-D and Pd-T Systems . . .	78
5.5.2	The Phase Diagram of the V-T System	80
5.5.3	The Phase Diagram of the Nb-T System	86
5.6	Optical Vibrations of Protium, Deuterium and Tritium in Niobium	87
5.7	Superconductivity of the Pd-H, Pd-D and Pd-T Systems . . .	90
5.8	Isotope Dependence of Phonon Dispersion Curves in $\text{PdD}_{0.63}$ and $\text{PdT}_{0.7}$	92
5.9	Isotope Effect in Dingle Temperatures and Extremal Cross Sections of the Fermi Surface in PdH_r , PdD_r and PdT_r	95

5.10 Diffusion of Protium, Deuterium and Tritium in Selected Metals	96
5.10.1 Diffusion of H, D, T in V, Nb, Ta	98
5.10.2 Diffusion of H, D, T in Dilute Pd-Fe Alloys	101
5.10.3 Diffusion of H, D, T in Cu and Ni	103
5.11 Lattice Dilatation in V, Nb, and Ta Produced by Protium, Deuterium and Tritium	105
6. Properties of Helium-3 in Selected Metals	108
6.1 Basic Properties of Helium in Metals	109
6.1.1 Energetics of Helium in Metals	109
6.1.2 Kinetics of Helium Precipitation in Metals	111
6.2 Helium Release from Metal Tritides	112
6.3 He Bubbles in Metal Tritides	114
6.3.1 NMR Measurements	114
6.3.2 TEM Measurements	114
TEM Measurements of $\text{PdT}_{r_0-c}\text{He}_c$ Samples	115
TEM Measurements of $\text{VT}_{r_0-c}\text{He}_c$ Samples	115
TEM Measurements of $\text{NbT}_{r_0-c}\text{He}_c$ Samples	115
TEM Measurements of $\text{ZrT}_{r_0-c}\text{He}_c$ Samples	116
6.3.3 Observation of Solid-Fluid Transitions of ^3He in the Bubbles of $\text{PdT}_{r_0-c}\text{He}_c$ Samples	119
6.4 Acoustic Emission by Metal Tritides	119
6.5 Swelling of Various Metal Tritides	119
6.6 Lattice Parameter and Width of the Rocking Curves of $\text{TaT}_{r_0-c}\text{He}_c$ Samples in the α Phase	122
6.6.1 X-Ray Diffraction Measurements of $\text{TaT}_{r_0-c}\text{He}_c$	123
6.6.2 Neutron-Scattering Measurements of $\text{TaT}_{r_0-c}\text{He}_c$	126
6.7 Preliminary Results for Helium-3-Induced Effects in Selected Metals	128
6.7.1 Mechanical Properties of Metal Tritides	128
6.7.2 He-Induced Change of the Tritium Diffusion in Dilute Tantalum Tritides	128
6.7.3 Phase Transitions in Metal Tritides	129
6.7.4 Resistivity of Lutetium Tritides	131
6.7.5 Analysis of Metal Tritides Using Positron-Annihilation Techniques	131
6.7.6 Room-Temperature Creep of Metal Tritides	132
7. Conclusion and Outlook	134
References	137
Subject Index	153