

Contents

Preface XIX

Introduction XXI

46	Interferometry	1
46.1	Introduction	3
46.2	Basic Principles of Interference	4
46.2.1	Plane Wave	6
46.2.2	Complex Notation	7
46.2.3	Spherical Wave	8
46.2.4	Vector Sum of Complex Numbers	9
46.2.5	Interference of Two Plane Waves	12
46.2.6	Interference of Two Spherical Waves	14
46.2.7	Interference of Two Waves with Different Wavelengths	18
46.2.8	Coherence and Correlation Function	19
46.2.9	Interference of Two Monochromatic Waves with Statistically Varying Phase	20
46.2.10	Interference of two waves which have a spectrum	21
46.2.11	Interference with Extended Monochromatic Light Sources	27
46.2.12	Interference of Waves having Different Polarization	31
46.2.13	Interference of Non-spherical Wavefronts	33
46.2.14	Interference at Two Plane Parallel Interfaces	37
46.2.15	Haidinger Fringes	40
46.2.16	Newton Fringes	43
46.3	Interferometers	44
46.3.1	Newton Interferometer	45
46.3.2	Fizeau Interferometer	49
46.3.3	Twyman–Green Interferometer	56
46.3.4	Mach–Zehnder Interferometer	62
46.3.5	Point Diffraction Interferometer	67
46.3.6	Shearing Interferometer	72
46.4	Interferometer Designs	81
46.4.1	General Requirements	81

Handbook of Optical Systems: Vol. 5. Metrology of Optical Components and Systems, First Edition. Edited by Herbert Gross.
Copyright © 2012 Wiley-VCH Verlag GmbH & Co. KGaA. Published 2012 by Wiley-VCH Verlag GmbH & Co. KGaA.

46.4.2	Definition of Optical Components and Subassemblies	84
46.5	Detection Techniques and Algorithms	95
46.5.1	General Considerations	95
46.5.2	Least-squares Phase Detection	95
46.3.3	Error Sources	97
46.3.4	Phase-shifting Interferometry	98
46.3.5	Spatial Carrier Frequency Analysis	107
46.3.6	Simultaneous phase-shifting interferometry	112
46.3.7	Unwrapping	114
46.6	Calibration Techniques	120
46.6.1	Reference Elements with Known Residual Error	121
46.6.2	Calibration Procedures Used to Determine Element Deviations	122
46.7	Dynamic Range	140
46.7.1	DR in Surface Topometry	140
46.7.2	Dynamic Range of CCD Sensors in Interferometry and Wavefront Sensing	142
46.7.3	Lateral DR of CCD Sensors in Interferometry and Wavefront Sensing	143
46.7.4	Stitching Technique Used to Extend Lateral DR	145
46.8	Accuracy and Error Sources	148
46.8.1	Environmental Limitations	148
46.8.2	Noise	161
46.8.3	Capability of Measurement Systems	168
46.8.4	Gauge R&R Analysis – Analysis of Repeatability and Reproducibility	170
46.9	Literature	175
47	Non-interferometric Wavefront Sensing	181
47.1	Introduction	183
47.2	Hartmann–Shack Sensor	183
47.2.1	Principle of the HS Sensor	183
47.2.2	Basic Setup	187
47.2.3	Telescope for Diameter Adaptation	189
47.2.4	Detector Relay Lens	190
47.2.5	Layout of a Sensor	190
47.2.6	Signal Processing	193
47.2.7	Dynamic Range	194
47.2.8	Subaperture Effects	195
47.2.9	Accuracy of the HS Sensor	201
47.2.10	Modified Setups and Algorithmic Extensions of the Sensor	205
47.2.11	Comparison with Interferometer Setup	207
47.3	Hartmann Sensor	208
47.3.1	Introduction	208
47.3.2	Accuracy of the Hartmann Method	214
47.3.3	Partial Coherent Illumination and Apodization	216

47.3.4	Hartmann Measurement of an Apodized Profile	218
47.3.5	Modified Hartmann Methods	218
47.4	Phase Space Analyzer	219
47.4.1	Introduction	219
47.4.2	Layout Versions	222
47.4.3	Evaluation of the Data	225
47.4.4	Wave Optical Description	227
47.5	Point Image Filtering Techniques	230
47.6	Other Wavefront Sensor Concepts	239
47.6.1	Pyramid Curvature Sensor	239
47.6.2	Hartmann–Moire Wavefront Sensor	240
47.6.3	Holographic Modal Wavefront Sensor	240
47.6.4	Convolution Solvable Pinhole Mask	241
47.6.5	Talbot–Moire Interferometer	244
47.7	Point Spread Function Retrieval	249
47.7.1	Introduction	249
47.7.2	Transport of Intensity Equation	249
47.7.3	Principle of Phase Retrieval	251
47.7.4	Experimental Settings	253
47.7.5	Model Assumptions	258
47.7.6	Image Processing	262
47.7.7	Pinhole Deconvolution	267
47.7.8	Numerical Evaluation Algorithms	270
47.7.9	Apodization	274
47.7.10	Object Space Defocusing	275
47.7.11	Accuracy of Phase Retrieval	278
47.8	Calculation of Wavefront and Zernike Coefficients	283
47.8.1	Introduction	283
47.8.2	Zonal Methods	284
47.8.3	Modal Methods	285
47.8.4	Modal Fourier Reconstruction	286
47.8.5	Direct Determination of Zernike Coefficients from Slope Measurements	287
47.8.6	Calculating the Zernike Coefficients of a Wavefront	288
47.8.7	Zernike Calculation via Fourier Transform	290
47.8.8	Influence of Normalization Radius on Zernike Coefficients	291
47.8.9	Change in the Zernikes for Decentered, Rotated and Stretched Pupils	292
47.8.10	Propagation Changes in the Zernike Coefficients	294
47.9	Literature	297
48	Radiometry	303
48.1	Introduction	304
48.2	Basic Principles of Radiometry	305
48.2.1	Energy Transport by Electromagnetic Fields	305

48.2.2	Radiometric and Photometric Quantities	308
48.2.3	Fundamentals of Radiation Transfer	321
48.2.4	Fundamentals of Flux Detection	338
48.3	Monochromators	341
48.3.1	Introduction	341
48.3.2	Optical Absorption Filters	342
48.3.3	Fabry–Pérot Etalons	349
48.3.4	Interference Filters	352
48.3.5	Electronically Tunable Filters	359
48.3.6	Prism Monochromators	375
48.3.7	Grating Monochromators	387
48.4	Spectrometers	402
48.4.1	Introduction	402
48.4.2	Basic Principles of Spectrometers	403
48.4.3	Single-Channel Spectrometers	405
48.4.4	Multi-channel Spectrometers	408
48.4.5	Fourier Spectrometers	411
48.4.6	Accuracy and Error Sources	420
48.4.7	Calibration Techniques	423
48.5	Literature	427
49	Image Analysis	431
49.1	Introduction	432
49.2	Basic Principles of Image Analysis	432
49.2.1	System Setup	432
49.2.2	Calibration Principles	435
49.3	Star Test, Slit Test	436
49.3.1	Basic Setups	436
49.3.2	Image Deconvolution	443
49.3.3	Calibration	446
49.3.4	Accuracy and Error Sources	447
49.4	Test Targets, Visual Inspection	450
49.5	Distortion Metrology	452
49.5.1	Basic Setups	452
49.5.2	Correlation Method	456
49.5.3	Calibration	463
49.5.4	Accuracy and Error Sources	463
49.6	Deflectometers	464
49.6.1	Basic Setups	464
49.6.2	Algorithms	469
49.6.3	Calibration	469
49.6.4	Accuracy and Error Sources	470
49.7	Pattern and Fringe Projectors	471
49.7.1	Basic Setups	471
49.7.2	Algorithms	479

49.7.3	Calibration	479
49.7.4	Accuracy and Error Sources	482
49.8	Literature	485
50	Distance and Angle Metrology	489
50.1	Introduction	490
50.2	Long-range Displacement Metrology	490
50.2.1	Displacement-measuring Interferometer	490
50.2.2	Low-coherence Interferometers	499
50.2.3	Femtosecond Frequency Combs	504
50.2.4	Linear Encoders	510
50.3	Short-range Displacement and Thickness Metrology	515
50.3.1	Triangulators	515
50.3.2	Confocal Sensors	517
50.3.3	Coaxial Interferometric Sensors	520
50.4	Angle and Tilt Metrology	524
50.4.1	Angle Encoders	524
50.4.2	Autocollimators	528
50.4.3	Surface-measuring Interferometers	532
50.4.4	Differential Heterodyne Laser Interferometer	534
50.5	Combined Distance and Angle Metrology	540
50.5.1	Theodolites and Total Stations	541
50.5.2	Laser Trackers	544
50.6	Optical Profile Metrology	548
50.6.1	CMMs with Optical Sensors	548
50.6.2	Devices Using Angle Sensors	550
50.7	Literature	555
51	Polarimetry	559
51.1	Introduction	560
51.2	Basic principles of Polarimetry	561
51.2.1	Jones Calculus	561
51.2.2	Stokes/Mueller Calculus	568
51.3	Polarizing Elements	572
51.3.1	Polarizers	572
51.3.2	Retarders	582
51.3.3	Compensators	589
51.3.4	Depolarizers	591
51.3.5	Jones and Mueller Matrix Representations of Selected Optical Components	593
51.4	Polarimeters	597
51.4.1	Measurement of the Jones vector	597
51.4.2	Measurement of the Stokes Vector	600
51.4.3	Measurement of the Jones Matrix	605
51.4.4	Measurement of the Mueller Matrix	616

51.4.5	Polarimeters and Ellipsometers	622
51.5	Calibration Techniques	633
51.6	Accuracy and Error Sources	635
51.7	Literature	641
52	Testing the Quality of Optical Materials	643
52.1	Specifications	644
52.2	Refractive Index	644
52.2.1	Basics	644
52.2.2	Metrology	646
52.3	Transmittance	651
52.3.1	Basics	651
52.3.2	Metrology	652
52.4	Inhomogeneity and Striae	655
52.4.1	Basics	655
52.4.2	Metrology	658
52.5	Birefringence	664
52.5.1	Basics	664
52.5.2	Metrology	666
52.6	Bubbles and Inclusions	673
52.6.1	Basics	673
52.6.2	Metrology	676
52.7	Literature	677
53	Testing the Geometry of Optical Components	679
53.1	Specifications	680
53.2	Radius of Curvature	681
53.2.1	Basics	681
53.2.2	Metrology	682
53.3	Central Thickness	689
53.3.1	Basics	689
53.3.2	Metrology	689
53.4	Surface Form and Figure Irregularities	694
53.4.1	Basics	694
53.4.2	Metrology	707
53.5	Centering	760
53.5.1	Basics	760
53.5.2	Metrology	765
53.6	Diameter and Chamfer	776
53.6.1	Basics	776
53.6.2	Metrology	777
53.7	Literature	779

54 Testing Texture and Imperfections of Optical Surfaces 785

- 54.1 Specifications 786
- 54.2 Surface Texture 786
 - 54.2.1 Basics 786
 - 54.2.2 Metrology 796
- 54.3 Surface Imperfections 823
 - 54.3.1 Basics 823
 - 54.3.2 Metrology 826
- 54.4 Literature 836

55 Testing the Quality of Coatings 839

- 55.1 Introduction 840
- 55.2 Specifications 844
- 55.3 Model Simulation 847
 - 55.3.1 Transfer-matrix Method 847
 - 55.3.2 Material Designation 851
 - 55.3.3 Graded Interfaces 852
 - 55.3.4 Surface Roughness 854
 - 55.3.5 Data Analysis 855
- 55.4 Coating Metrology 858
 - 55.4.1 Basics 859
 - 55.4.2 Spectral Transmittance 861
 - 55.4.3 Spectral Reflectance 866
 - 55.4.4 Spectral Absorptance 875
- 55.5 Literature 878

56 System Testing 881

- 56.1 Introduction 883
 - 56.1.1 System Measurement 883
 - 56.1.2 Description of System Performance 883
 - 56.1.3 Specifications 884
- 56.2 Basic Parameters of Optical Systems 887
 - 56.2.1 Focal Length 887
 - 56.2.2 Focus and Image Location 892
 - 56.2.3 Principal Planes 898
 - 56.2.4 Magnification 900
 - 56.2.5 Pupil Location and Aperture Size 901
 - 56.2.6 Telecentricity 905
 - 56.2.7 Lens Positions and Adjustment 907
 - 56.2.8 Centering 910
- 56.3 Measurement of Image Quality 912
 - 56.3.1 Wavefront Quality 912
 - 56.3.2 Point Spread Function PSF 914
 - 56.3.3 Axial Point Spread Function 918
 - 56.3.4 Edge Spread Function ESF 919

56.3.5	Line Spread Function LSF	923
56.3.6	Analysis of Image Degradations	926
56.3.7	Distortion	929
56.3.8	Chromatical Aberrations	929
56.4	Measurement of the Transfer Function	930
56.4.1	Introduction	930
56.4.2	Test Targets	932
56.4.3	Measurement of the MTF via the Edge Spread Function	933
56.4.4	Measurement of the MTF via the Line Spread Function	936
56.4.5	Grating Imaging Measurement Setup	936
56.4.6	Measurement of the Pupil Autocorrelation Function	939
56.4.7	Special Measurement Aspects	940
56.4.8	Image Quality Criteria Based on the Transfer Function	941
56.5	Miscellaneous System Properties	945
56.5.1	Transmission	945
56.5.2	Spectral Transmission	947
56.5.3	Illumination Distribution	948
56.5.4	Ghost Images and Veiling Glare	950
56.5.5	M^2 Beam Quality and Kurtosis	951
56.5.6	Polarization Aberrations	954
56.6	Literature	960

Index	967
--------------	-----