

Contents

1	Introduction	13
2	Properties of Polymeric Melts	19
2.1	Rheological Behavior	19
2.1.1	Viscous Properties of Melts	19
2.1.1.1	Viscosity and Flow Functions	20
2.1.1.2	Mathematical Description of the Pseudoplastic Behavior of Melts	21
2.1.1.3	Influence of Temperature and Pressure on Flow Behavior	26
2.1.2	Determination of Viscous Flow Behavior	33
2.1.3	Viscoelastic Properties of Melts	37
2.2	Thermodynamic Behavior	42
2.2.1	Density	42
2.2.2	Thermal Conductivity	44
2.2.3	Specific Heat Capacity	45
2.2.4	Thermal Diffusivity	45
2.2.5	Specific Enthalpy	46
3	Fundamental Equations for Simple Flows	51
3.1	Flow through a Pipe	52
3.2	Flow through a Slit	55
3.3	Flow through an Annular Gap	58
3.4	Summary of Simple Equations for Dies	61
3.5	Phenomenon of Wall Slip	68
3.5.1	Model Considering the Wall Slip	69
3.5.2	Instability in the Flow Function – Melt Fracture	73
4	Computations of Velocity and Temperature Distributions in Extrusion Dies	77
4.1	Conservation Equations	77
4.1.1	Continuity Equation	77
4.1.2	Momentum Equations	78
4.1.3	Energy Equation	80
4.2	Restrictive Assumptions and Boundary Conditions	82
4.3	Analytical Formulas for the Solution of Conservation Equations	84
4.4	Numerical Solution of Conservation Equations	88
4.4.1	Finite Difference Method (FDM)	89
4.4.2	Finite Element Method (FEM)	92
4.4.3	Comparison of FDM and FEM	95
4.4.4	Examples of Computations Using the Finite Difference Method	98
4.4.5	Examples of Computations Using the Finite Element Method	104
4.5	Considerations of the Viscoelastic Behavior of the Material	108
4.6	Computation of the Extrudate Swelling	111
5	Monoextrusion Dies for Thermoplastics	119
5.1	Dies with Circular Exit Cross Section	119
5.1.1	Designs and Applications	119
5.1.2	Design	124
5.2	Dies with Slit Exit Cross Section	128
5.2.1	Designs and Applications	129
5.2.2	Design	134
5.2.2.1	Fishtail Manifold	136

5.2.2.2	Coathanger Manifold	137
5.2.2.3	Numerical Procedures	145
5.2.2.4	Considerations for Clam Shelling	147
5.2.2.5	Unconventional Manifolds	148
5.2.2.6	Operating Performance of Wide Slit Dies	150
5.3	Dies with Annular Exit Cross Section	152
5.3.1	Types	153
5.3.1.1	Center-fed Mandrel Support Dies	153
5.3.1.2	Screen Pack Dies	156
5.3.1.3	Side-fed Mandrel Dies	157
5.3.1.4	Spiral Mandrel Dies	158
5.3.2	Applications	159
5.3.2.1	Pipe Dies	159
5.3.2.2	Blown Film Dies	160
5.3.2.3	Dies for the Extrusion of Parisons for Blow Molding	161
5.3.2.4	Coating Dies	167
5.3.3	Design	170
5.3.3.1	Center-fed Mandrel Dies and Screen Pack Dies	170
5.3.3.2	Side-fed Mandrel Dies	173
5.3.3.3	Spiral Mandrel Dies	176
5.3.3.4	Coating Dies	179
5.4	Formulas for the Computation of the Pressure Loss in the Flow Channel Geometries other than Pipe or Slit	182
5.5	Dies with Irregular Outlet Geometry (Profile Dies)	185
5.5.1	Designs and Applications	186
5.5.2	Design	193
5.6	Dies for Foamed Semi-finished Products	200
5.6.1	Dies for Foamed Films and Sheets	201
5.6.2	Dies for Foamed Profiles	202
5.7	Special Dies	204
5.7.1	Dies for Coating of Profiles of Arbitrary Cross Section	204
5.7.2	Dies for the Production of Profiles with Reinforcing Inserts	204
5.7.3	Dies for the Production of Nets	205
5.7.4	Slit Die with Driven Screw for the Production of Slabs	205
6	Coextrusion Dies for Thermoplastics	215
6.1	Designs	215
6.1.1	Externally Combining Coextrusion Dies	215
6.1.2	Adapter (Feedblock) Dies	216
6.1.3	Multi-Manifold Dies	219
6.2	Applications	219
6.2.1	Film and Sheet Dies	219
6.2.2	Blown Film Dies	220
6.2.3	Dies for the Extrusion of Parisons for Blow Molding	220
6.3	Computations of Flow and Design	221
6.3.1	Computation of Simple Multi-layer Flow with Constant Viscosity	224
6.3.2	Computation of Coextrusion Flow by the Explicit Finite Difference Method	227
6.3.3	Computation of Velocity and Temperature Fields by the Finite Difference Method	230
6.3.4	Computation of Velocity Fields in Coextrusion Flows by FEM	232
6.4	Instabilities in Multi-layer Flow	234
7	Extrusion Dies for Elastomers	241
7.1	Designs of Dies for the Extrusion of Elastomers	241
7.2	Fundamentals of Design of Extrusion Dies for Elastomers	242
7.2.1	Thermodynamic Material Data	242

7.2.2	Rheological Material Data	243
7.2.3	Computation of Viscous Pressure Losses	245
7.2.3.1	Formulas for Isothermal Computations	246
7.2.3.2	Approaches to Non-isothermal Computations.	248
7.2.4	Estimation of the Peak Temperatures	248
7.2.5	Consideration of the Elastic Behavior of the Material	248
7.3	Design of Distributor Dies for Elastomers	250
7.4	Design of Slotted Discs for Extrusion Dies for Elastomers	251
7.4.1	Computation of Pressure Losses	251
7.4.2	Extrudate Swelling (Die Swell)	254
7.4.3	Simplified Estimations for the Design of a Slotted Disc	257
8	Heating of Extrusion Dies	265
8.1	Types and Applications	265
8.1.1	Heating of Extrusion Dies with Fluids	265
8.1.2	Electrically Heated Extrusion Dies	266
8.1.3	Temperature Control of Extrusion Dies	267
8.2	Thermal Design	268
8.2.1	Criteria and Degrees of Freedom for the Thermal Design	268
8.2.2	Heat Balance at the Extrusion Die	270
8.2.3	Restrictive Assumptions for the Development of a Model	274
8.2.4	Simulation Methods for the Thermal Design	274
9	Mechanical Design of Extrusion Dies	283
9.1	Mechanical Design of a Breaker Plate	283
9.2	Mechanical Design of a Die with Axially Symmetrical Flow Channels	288
9.3	Mechanical Design of a Slit Die	295
9.4	General Design Rules	298
9.5	Materials for Extrusion Dies	300
10	Handling, Cleaning and Maintaining Extrusion Dies	307
11	Calibration of Pipes and Profiles	311
11.1	Types and Applications	313
11.1.1	Friction Calibration	313
11.1.2	External Calibration with Compressed Air	313
11.1.3	External Calibration with Vacuum	314
11.1.4	Internal Calibration	318
11.1.5	Precision Extrusion Pullforming (The Technoform Process)	319
11.1.6	Special Process with Movable Calibrators	319
11.2	Thermal Design of Calibration Lines.	320
11.2.1	Analytical Computational Model.	321
11.2.2	Numerical Computational Model.	324
11.2.3	Analogy Model	329
11.2.4	Thermal Boundary Conditions and Material Data	332
11.3	Effect of Cooling on the Quality of the Extrudate.	332
11.4	Mechanical Design of Calibration Lines	333
11.5	Cooling Dies, Process for Production of Solid Bars.	333