

Table of Contents

The 500 Series	17	The Repair Job.....	88	The 453	167
The 545 / 545B	19	Belle de Nuit.....	92	Almost a Modern Scope .	167
A True Monster.....	19	Hybrid Technology.....	96	The Mythical 453.....	169
Innovating Ideas	21	3B3 Dual Time Base	98	My 453A.....	170
The Winning Decision	22	So Similar, so Different ..	107	Mod.(ification) 127C.....	172
New 530 Series	25	3A1 Dual Trace	108	Top View	174
545, The Monster	26	Conclusions	118	Golden Bottom	176
The Futuristic 545.....	28	The 300 Series	121	Side View.....	178
From 545 to 545B	30	First portables	123	Lever Switches	182
CRTs and Phosphors.....	32	The 310A	125	Need for Evolution.....	184
Delayed Sweep.....	34	Dream Book.....	128	Some other Details.....	188
Tubes & Tubes.....	36	30 Electron Tubes.....	130	The 456/475	191
Distributed Amplifiers	38	310A ceramic stripes.....	132	They can travel with you .	193
Plug-in Architecture.....	42	The Rear Panel.....	139	Panel Distribution	195
Me and the Monsters	46	Old Style Details.....	141	A Unique Frame	196
Its First Repair	49	The 321A	143	Built From Inside Out? ...	198
Ceramic Strips.....	51	True Jewelry.....	143	New Components.....	200
Which & When.....	52	True Portable	144	For any environment	203
Min vs. Max	54	Triple A	146	Air Conditioning	204
Howard Caesar Vollum.....	56	Vs. Goliath.....	149	Circuitries	206
Howard's Letter	59	A typical '60s.....	151	Vertical Attenuators	208
The Scope Class	61	The Nuvistor.....	152	Vertical Amplifiers.....	210
The 515A	63	Power Supply	154	Trigger and Sweep	214
Versatile and "Portable"	63	Power Supply Circuit	156	Interface Board	219
Specifications.....	64	Memento Homo	158	Power Supply	221
The Delay Line	66	The 400 Series	165	Crisp CRT Traces!	222
The "New" CRT	74			465/475 Bargain	224
A Cyclone.....	80			Recapping the 465	227
The RM561A	83			Fixing attenuators	229
Beautiful, but... Dead!.....	84			Comparing to the 453	230
				Conclusions	232

Table of Contents (cont'd)

The 7000 Series.....235	11403 Boards 302	Those Incredible CRTs ... 387
Everything Changes! 236	Complexity 304	New Approach..... 389
The models 237	Acquisition System..... 306	The Front Panel 391
The Winning Idea 238	Self-Test & Diagnostics.. 316	The Circuitry 392
7000-Series e-book..... 245	Enhanced Accuracy..... 320	Hybrid Circuits 397
	B-Side..... 322	The EAROM..... 398
	Talking to It..... 324	Vertical Attenuators 401
The 5000 Series.....247	On the Market 328	Attenuator 402
Really the Worst?..... 248	Manuals..... 330	a Repair Story..... 402
The 5103N D11 249	Another Monster..... 337	Nobody is Perfect..... 404
Tektronix Quality 256	Using It..... 338	The Power Supply 406
Damned Torpedoes! 258	A Small Repair..... 340	Heat & Fans..... 408
5B10N..... 261	Bewitched Colors 342	Other Boards 410
Time Base..... 261	CRT Degausser 346	Critical Parts..... 412
5A18N Dual Amp 267	Performance..... 348	Final Balance 414
Really Not the Worst!... 268	Plug-ins 351	The 2445B 417
	The 11A52 352	The “B” New Models 418
	Overdrive Recovery..... 357	A Different Logic 420
The 11000 Series..... 271	Seeking New World 360	Simpatico?..... 422
The Future on the Road . 272		Main Board Bricks..... 424
The project..... 273	2400 Series Analog...365	Right Side View 426
The ET Project 276	The 2000-Family..... 367	Counter Timer Trigger.... 428
We Must Do It 278	A (too) Rich Family? 367	Repairs and Roses..... 430
1986, the Launch..... 282	Wikipedia Teaches 369	The 2467 433
Mainframes..... 283	Most Important Models... 370	The Last King..... 433
The 11000 Revolution 284	A Different Classification. 372	
The 4-Traces Wall 286	Analog Models Manuals.. 377	2400-Series Digital...435
Human Interface 288	Quality Issues? 379	The 2430 437
Autosetup & Measur..... 292	The 2465 383	2430, the First..... 437
Automatic Comparisons. 294	A great classic 383	Digital Breaks Out..... 439
11400-Architecture 296	Those Cursors!..... 385	Ends and Starts..... 441
Modularity 298		

Table of Contents (cont'd)

Improved Construction...	442	The 2431L	511	Prices Today.....	568
Main Board Bricks.....	444	Main Board.....	513	2000-Series notes	569
The CCDs	446	Display Board.....	515	Last-minute Bug.....	570
The Circuit	448	Processor Board.....	516	New Knobs.....	572
Front Panel	452	Dallas Memories.....	518	EPROMS	574
Mismatching.....	454	Simplified Rear Panel	520	Manuals.....	576
I've Got It!.....	456	Fixing the HV Board	522	Years and Versions	578
Does Tektronix Lie?.....	458	The 2200 Series	525	Size and Weight.....	580
Averaging, Accuracy etc.	461	The 2230 and 2221.....	527	Acknowledgments	583
Calibration.....	464	The Two Worlds Heroes.	527	The Show Goes On! ..	587
Probes Calibration	466	Become a carver	529		
Calibration/Diagnostics ..	468	The 2221	530		
Accessories	470	Out of the Box.....	533		
Useful!.....	473	2230's Secrets	534		
The 2430A	475	Main Board Bottom.....	537		
Measurements.....	476	Attenuators	538		
Main Board.....	479	Suicidal Diodes	540		
Warning, do not Fry ICs .	480	Fixing 2230's PSU	544		
Accessible	483	Lost Potentiometers	548		
You Can Open It	485	A better solution.....	553		
Power Supply	487	End of the Story	554		
Power Supply Repair	488	Lessons Learnt.....	556		
The Rear Panel.....	490	Finished	558		
The Missing Click	492	2230 Backlash!	560		
The 2440	495				
Main Board.....	497				
Hi-tech Inside.....	498				
Processor Board.....	500				
Sunk by Torpedoes	502				
Performance.....	506				
Collateral Damages.....	508				
The Jokey 2431L	511				