

Contents

1	Production, Properties and Applications of Glassy Metals	1
	Introduction	1
	References	5
2	Most Important Methods for Production of Amorphous Metallic Alloys	9
	The Chill Block Melt Spinning (CBMS) Method	13
	Influence of the Production Parameters upon the Geometric Characteristics of the Amorphous Ribbons by the CBMS Method	14
	Planar Flow Casting (PFC) Method	17
	Relation Between the Production Conditions and the Geometric Characteristics of Wide Amorphous Ribbons by the PFC Method	18
	Production of Bulk Amorphous Metallic Alloys by Rapid Cooling from the Melt and Study of Their Structure	23
	References	27
3	Experimental Methods for Determination of the Magnitude and Temperature Dependence of the Viscosity of Amorphous Metallic Alloys	31
	Experimental Methods for Viscosity Determination of Amorphous Metallic Alloys Under Isothermal and Nonisothermal Conditions	34
	Experimental Techniques for Viscosity Study of Metallic Glasses Under Nonisothermal Conditions	38
	Analysis of the Overall Deformation Curves Obtained Under Continuous Heating Conditions and Viscosity Calculations	42
	Estimation of the Critical Melt Cooling Rate for Obtaining the Alloy in Glassy State	44
	References	50

4	Viscous Flow Behavior of Amorphous Ribbonlike Metallic Alloys Depending on Different Factors	53
	Influence of Chemical Composition Upon the Viscous Flow Behavior and Thermal Stability of Some Binary Glassy Metals	54
	Binary $\text{Ni}_{100-x}\text{Zr}_x$ Glassy Metals	54
	The System $\text{Ni}_{100-x}\text{P}_x$	59
	The System $\text{Fe}_{100-x}\text{P}_x$	64
	Viscous Flow Behavior of Ternary $\text{Fe}_{82-x}\text{TM}_x\text{B}_{18}$ (TM = V, Cr) Amorphous Metallic Alloys	67
	Influence of Vanadium Alloying Additions	68
	Influence of Chromium Alloying Additions	69
	Viscous Flow Behavior of Quaternary $\text{Al}_{85}\text{Ni}_5\text{Co}_2\text{RE}_8$ (RE = Ce, Gd, U) Amorphous Metallic Alloys	71
	Influence of Thermal Prehistory on the Viscous Flow Behavior of Amorphous Metallic Alloys	73
	The Amorphous $\text{Pd}_{82}\text{Si}_{18}$ Alloy	73
	The Amorphous $\text{Fe}_{40}\text{Ni}_{40}\text{B}_{20}$ Alloy	76
	Influence of Technological Production Parameters Upon the Viscous Flow of the Amorphous Metallic Alloy $\text{Fe}_{40}\text{Ni}_{40}\text{Si}_6\text{B}_{14}$	79
	References	83
5	Basic Concepts of the Free Volume Model: Structural Relaxation and Viscosity in the Framework of the Model	85
	Basic Ideas of the Free Volume Model	85
	Structural Relaxation and Atomic Free Volume	87
	Viscosity Temperature Dependence of Amorphous Metallic Alloys in the Framework of the Free Volume Model	88
	The Influence of Structural Relaxation Upon Viscosity: Useful Tool for the Study of the Mechanism and Kinetics of Free Volume Relaxation Changes	90
	Viscosity and Relaxation Under Isothermal Conditions	90
	Viscosity and Relaxation Under Nonisothermal Conditions	93
	References	97
6	Glass Forming Ability, Crystallization, and Viscosity of Rapidly Solidified Amorphous $\text{Co}_{100-x}\text{Zr}_x$ and $\text{Cu}_{100-x}\text{Zr}_x$ Alloys	99
	Glass Forming Ability (GFA) and Melt Fragility Number. Equation of Angell and Moynihan Interpretation	99
	Crystallization, Viscosity, and Glass Forming Ability of Rapidly Solidified Amorphous $\text{Co}_{100-x}\text{Zr}_x$ Alloys	102
	Crystallization, Viscosity, and Glass Forming Ability of Rapidly Solidified Amorphous $\text{Cu}_{100-x}\text{Zr}_x$ Alloys	108
	References	115

7 Bend Stress Relaxation of Amorphous Metallic Alloys Under Isothermal and Nonisothermal Heating	
Conditions	117
Relaxation of Bend Stresses in Ribbonlike Amorphous	
Metallic Alloys: Model Considerations	118
Structural Relaxation in $\text{Fe}_{40}\text{Ni}_{40}\text{Si}_6\text{B}_{14}$ Glassy Alloy	124
Direct Measurement of the High-Temperature	
Viscous Creep Under Nonisothermal Conditions	124
Study upon the Relaxation of Bend Stresses via	
Isothermal and Nonisothermal Measurements	125
References	136
8 Structural Relaxation in Various Amorphous Metallic Alloys Studied via Direct Viscosity and Bend Stress Relaxation	
Measurements	137
The Amorphous Metallic Alloy $\text{Pd}_{77.5}\text{Cu}_6\text{Si}_{16.5}$	138
Direct Viscosity Measurements Under	
Nonisothermal Conditions	138
Bend Stress Relaxation Study Under Isothermal Conditions	138
The Amorphous Metallic Alloy $\text{Al}_{7.5}\text{Cu}_{17.5}\text{Ni}_{10}\text{Zr}_{65}$	142
Direct Viscosity Determination Under Nonisothermal	
Conditions	142
Study of Bend Stress Relaxation Under Isothermal	
and Nonisothermal Conditions	142
The Amorphous Metallic Alloy $\text{Al}_{25}\text{La}_{50}\text{Ni}_{25}$	147
Direct Viscosity Measurements Under Nonisothermal	
Conditions	149
Bend Stress Relaxation Studies Under Isothermal and	
Nonisothermal Conditions	149
Physical Significance of the FVM Model Parameters	155
References	158
9 Thermal Expansion and Heat Capacity of Amorphous Metallic Alloys: Interpretation of Their Anomalous Behavior in the Framework of FVM	161
Anomalies in Thermal Expansion of Amorphous	
Metallic Alloys: Model Consideration	161
Viscous Flow and Thermal Expansion of	
Amorphous Metallic Alloys $\text{Pd}_{82}\text{Si}_{18}$ and $\text{Fe}_{25}\text{Zr}_{75}$	164
Conclusions	167
Specific Heat Anomalies of Amorphous Metallic Alloys:	
Model Interpretation	167
Viscous Flow and Specific Heat of Amorphous	
Metallic Alloy $\text{Fe}_{25}\text{Zr}_{75}$ Under Different Constant	
Heating Rates	169

Viscous Flow, Thermal Expansion, and Specific Heat of $\text{Al}_{25}\text{La}_{50}\text{Ni}_{25}$ Amorphous Alloy	171
Conclusions	175
References	176
10 Relation Between the Density Changes and Thermal Expansion Anomalies in the Amorphous Metallic Alloys	177
Relaxation Changes of Density of Amorphous Metallic Alloys: Free Volume Model Description	179
Relaxation Changes of Density of Amorphous Metallic Alloys: Experimental Proof	180
Free Volume Model Calculations	184
Conclusions	187
References	187
11 Crystallization Kinetics of Bulk Amorphous Metallic Alloys and Its Relation to the Forgoing Relaxation Processes	189
Experimental Approach	191
Crystal Growth and Viscous Flow Behavior of Amorphous $\text{Pd}_{40}\text{Cu}_{30}\text{Ni}_{10}\text{P}_{20}$ Metallic Alloy	192
Crystal Growth Rate Kinetics	192
Relation Between Crystal Growth and Viscous Flow Behavior ...	195
Overall Volume Transformation Kinetics of Bulk Amorphous $\text{Pd}_{40}\text{Cu}_{30}\text{Ni}_{10}\text{P}_{20}$ Alloy	199
Conclusions	204
Crystal Growth Rate Kinetics	204
Overall Volume Crystallization Kinetics	204
References	204
12 Mechanical Properties of Amorphous Metallic Alloys and Their Relation to the Viscosity Characteristic Parameters	207
Unified Equation of Yang	208
Viscous Flow and Mechanical Properties of $\text{Co}_{100-x}\text{Zr}_x$ and $\text{Cu}_{100-x}\text{Zr}_x$ Glassy Alloys	210
References	215
13 Properties and Applications of Amorphous Metallic Alloys	217
Amorphous Metallic Alloys Produced in the USA	218
Amorphous Metallic Alloys Produced in Europe	221
Amorphous Metallic Alloys Produced in Russia	225
Invar-Type Amorphous Metallic Alloys Produced in Russia	227
Classification of Amorphous Metallic Alloys with Respect to Their Application as Soft Magnetic Materials	228
Amorphous Metallic Alloys on Fe Basis for Application in Electrotechnics at Frequencies of 50–60 Hz	229

Power Transformers Working at Frequencies of 400 Hz	230
Applications in Electromotors	230
Application of Amorphous Metallic Alloys on Fe-Ni Basis with Improved High-Frequency Properties: Transformers for Pulse Power Supply Devices (Secondary Sources for Voltage Power Supply)	231
Application of Amorphous Metallic Alloys on Co Basis of Zero Magnetostriction and Good High-Frequency Properties	232
Application of Amorphous Metallic Alloys for the Production of Sensors	233
Sensors for Magnetic Fields	233
Brazing Amorphous Metallic Alloys	236
Prospects	239
References	240
14 Quick Reference to the Viscous Flow Behaviour of Glassy Alloys at a Heating Rate of 20 K/min	243
Viscous Flow Behavior of Binary Amorphous Alloys at Heating Rate of 20 K/min	244
Viscous Flow Behavior of Ternary Amorphous Alloys at Heating Rate of 20 K/min	245
Viscous Flow Behavior of Quaternary Amorphous Alloys at Heating Rate of 20 K/min	246
Appendix 1: Quick Reference to Most Frequently Used Important FVM Related Equations	247
Appendix 2: Concluding Remarks	261