

Contents

1	Introduction to Sensor Technology and Electronic Measurement	
	Technology	1
1.1	Sensor Types	2
1.1.1	Standard Sensors	5
1.1.2	Basic Metrological Concepts	7
1.1.3	Analog and Digital Measuring Instruments	10
1.1.4	Current and Voltage	19
1.1.5	Resistors	24
1.2	Calibration of Measuring and Test Equipment	26
1.3	Analog and Digital Data Acquisition	27
1.3.1	Structure of an Analog Electrode	27
1.3.2	Structure of a Digital Measurement Chain	28
1.3.3	Acquisition and Processing of Measurement Data	29
1.3.4	Control, Regulation, and Visualization	33
1.4	Measurement Error	39
1.4.1	Types of Errors	40
1.4.2	Sources of Error	48
1.4.3	Influence Errors	50
1.4.4	Error Propagation	54
1.4.5	Selection Criteria for Measuring Instruments	59
2	Components of the Electronic Data Acquisition	63
2.1	Analog Amplifier Families	66
2.1.1	Internal Circuit Design of Operational Amplifiers	67
2.1.2	Operating Modes of an Operational Amplifier	69
2.1.3	Transmission Characteristics of Operational Amplifiers	70
2.1.4	Inverting Mode	72
2.1.5	Non-inverting Operation	75
2.1.6	Voltage-Dependent Current Feedback	78
2.1.7	Current Dependent Voltage Feedback	78
2.1.8	Current Dependent Current Feedback	79

2.2	Linear and Non-linear Amplifier Circuits	80
2.2.1	Adder or Totalizer	80
2.2.2	Operational Amplifier as an Integrator	81
2.2.3	Differentiator with Operational Amplifier	83
2.2.4	Differential Amplifier or Subtractor.	84
2.2.5	Instrumentation Amplifier	87
2.2.6	Voltage and Current Measurement.	89
2.3	Comparator and Schmitt Trigger	90
2.3.1	Simple Voltage Comparator	91
2.3.2	Voltage Comparator in Saturated Amplifier Mode	92
2.3.3	Window Comparator	95
2.3.4	Three-Point Comparator	97
2.3.5	Schmitt Trigger	99
2.3.6	Schmitt Trigger in Non-saturated Mode	104
2.3.7	Comparator with Tilting Behavior	106
2.4	Measuring Bridges	108
2.4.1	Unloaded Voltage Divider	108
2.4.2	Loaded Voltage Divider	109
2.4.3	Bridge Circuit.	110
2.4.4	Simple Capacitance Measuring Bridge	112
2.4.5	Vienna and Vienna-Robinson Bridge.	115
2.4.6	Maxwell Bridge	116
2.4.7	Schering Bridge	118
2.4.8	Maxwell-Vienna Bridge.	119
2.4.9	Frequency-Independent Maxwell Bridge	121
2.5	Analog Switch	122
2.5.1	Switch Functions of the Analog Switches	124
2.5.2	Operational Amplifier with Digital Control.	128
2.5.3	Sample & Hold Circuits.	130
2.6	Analog-to-Digital and Digital-to-Analog Converters	136
2.6.1	The Structure of a Data Collection System	137
2.6.2	Data Acquisition Without a Sample and Hold Unit.	140
2.6.3	Time-Division Multiplexed Data Acquisition with Sample and Hold Unit	142
2.6.4	Simultaneous Acquisition of Measurement Data with a Sample and Hold Unit.	144
2.6.5	Antialiasing Filter	145
2.6.6	Systems for Signal Sampling.	146
2.6.7	Theorem for Signal Sampling	150
2.7	AD- and DA-Converter	152

2.7.1	Natural Binary Code	152
2.7.2	Complementary Binary Code	154
2.7.3	Codes for AD and DA Converters	154
2.7.4	BCD Coding	155
2.7.5	Specifications of Data Converters	157
2.7.6	Relative Accuracy of Transducer Systems	159
2.7.7	Absolute Accuracy of Transducers	163
2.8	Digital to Analog Converter	167
2.8.1	Transfer Function	168
2.8.2	Structure and Function of a DA Converter	172
2.8.3	R2R-DA Converter	173
2.8.4	DA-Converter with External Resistors	175
2.9	Analog to Digital Converter	178
2.9.1	AD Converter According to the Counting Method	178
2.9.2	AD Converter with Overshoot Control	180
2.9.3	AD Converter with Step-by-Step Approximation	182
2.9.4	Single-Slope AD Converter	185
2.9.5	Dual Slope AD Converter	186
2.9.6	Voltage to Frequency Converter	189
3	Temperature Sensors	193
3.1	Basic Information About Temperature Measurement	194
3.1.1	Temperature-Dependent Effects	194
3.1.2	Temperature-Dependent Resistors	196
3.1.3	NTC Resistors or Thermistors	198
3.1.4	Data, Designs, and Technology of Thermistors	200
3.1.5	Linearization of Thermistor Curves	202
3.1.6	Amplifying Circuits for Linearized Thermistors	203
3.1.7	PTC Resistors	205
3.1.8	Protective Circuits with PTC Thermistors	206
3.1.9	Temperature Switches from -10°C to $+100^{\circ}\text{C}$	207
3.1.10	Temperature Switch with Sensor Monitoring	210
3.2	LED Thermometer	215
3.2.1	Integrated Converter ICL7106 and ICL7107	216
3.2.2	External Components of ICL7106 and ICL7107	220
3.2.3	Integrating AD Converters with the ICL7106 and ICL7107	224
3.3	Thermocouples	227
3.3.1	Thermoelectric Effect	227
3.3.2	Measurements with Thermocouples	229
3.3.3	Amplifier for Thermocouples	231
3.4	Resistance Thermometers with Pt100 or Ni100	232
3.4.1	Pt100 Resistance Thermometer	233

3.4.2	Ni100 Resistance Thermometer	235
3.4.3	Silicon Temperature Sensor as Pt100 Replacement	235
3.4.4	Connection of a Resistance Thermometer	237
3.4.5	Avoidance of Electromagnetic Susceptibility	239
3.4.6	Ground Loops, Earthing and Shielded Cables	243
3.4.7	Heat Flow Sensor	245
3.5	Measuring Mechanical Quantities with Temperature Sensors	246
3.5.1	Level Measurement	246
3.5.2	Measurement of Flow Velocity	248
3.5.3	Microbridge Airflow Sensors	251
3.5.4	Hot Film Air Mass Sensor	254
3.5.5	Hot-Wire Air Mass Sensor	255
4	Optical Sensors	259
4.1	Properties and Design	260
4.1.1	Luminous Sensitivity	260
4.1.2	Photodiode Technology	262
4.1.3	Applications of Photodiodes	263
4.1.4	Photoresistance	265
4.1.5	Measuring Circuit with a Photoresistor	266
4.1.6	Twilight Switch	267
4.1.7	Phototransistor	270
4.1.8	Automatic Garage Lighting with a Phototransistor	271
4.1.9	Photoelectric Cell	272
4.2	Active Optoelectronics	275
4.2.1	Emitter Components	276
4.2.2	Laser Diodes (Semiconductor Lasers)	276
4.2.3	Light-Emitting Diodes	280
4.3	Optocoupler	284
4.4	Light Barriers and Optoelectronic Scanning Systems	286
4.4.1	Through-Beam Sensors	287
4.4.2	Special Forms of Through-Beam Sensors	288
4.4.3	Reflection Light Barriers	288
4.4.4	Retro-reflective Sensors	290
4.4.5	Detection of Shiny Objects	292
4.4.6	Photoelectric Proximity Switches with Background Suppression	293
4.4.7	Drill Breakage Control Using Light Barrier	294
4.4.8	Optical Distance Measurement	296
4.5	Optical Angle of Rotation and Position Detection	300
4.5.1	Absolute Rotary Encoder	300
4.5.2	Fork Sensors	302
4.5.3	Incremental Encoders	306
4.5.4	Signal Evaluation	306

5 Humidity Sensors	309
5.1 Physical Measurement Methods	309
5.1.1 Appropriate Measurement Methods	311
5.1.2 Methods of Moisture Content Determination	312
5.1.3 Indirect Measurement Methods	313
5.1.4 Laboratory Measurement Procedures of Higher Accuracy	315
5.2 Physical Relationships	318
5.2.1 Definition of the Water Vapor Partial Pressure	319
5.2.2 Dew Point.	320
5.2.3 Relative Humidity in Gases	320
5.2.4 Relative Humidity in Liquids.	322
5.2.5 Structure and Operation of an Alumina Humidity Sensor.	323
5.2.6 Use of Alumina Humidity Sensors	324
5.2.7 Temperature and Pressure Behavior	328
5.3 Realization of Humidity Measurement	329
5.3.1 Simple Measuring Circuit with Humidity Sensor	329
5.3.2 Humidity Dependent Control.	334
Index.	337