

Contents

1	Introduction	1
1.1	The Machine Tool as a Mechatronic System	3
1.2	Engineering	4
1.3	Current Trends	5
	References	6
2	Feed Axes in Machine Tools	7
2.1	Converters for machine tool feed axes	11
2.1.1	Design of converter systems	11
2.1.2	Control electronics in converters	13
2.1.2.1	Analog control	13
2.1.2.2	Digital control	14
2.1.2.3	Additional functions of digital drive controllers	14
2.1.3	Interfaces to the control system	15
2.1.3.1	Analog interface	16
2.1.3.2	Digital interface	18
2.2	Motors in feed axes	22
2.2.1	Requirements on drive units	22
2.2.2	Direct current motors	24
2.2.3	Synchronous motors	29
2.2.4	Asynchronous motors	34
2.2.5	Design and calculation of electric drives	41
2.2.5.1	Ramp-up without a current limit	42
2.2.5.2	Ramp-up with a current limit	42
2.2.5.3	Numeric determination of the ramp-up for non-linear and discontinuous characteristics	45
2.2.5.4	Selection of motors according to static considerations	45
2.2.6	Designs based on direct current and 3-phase servo drives	46
2.2.6.1	Stepper motors	47
2.2.6.2	Linear motors	49
2.2.7	Current and power measurements on electric motors	53
2.3	Position measuring systems for NC machines	55
2.3.1	Basics of path and angle measurement	56
2.3.1.1	Basic terms	56
2.3.1.2	Measuring principles and measuring methods	56
2.3.2	Measuring systems	58
2.3.2.1	Photoelectric measuring methods	58
2.3.2.2	Interferometers	69
2.3.2.3	Electromagnetic sensors	69
2.3.2.4	Magnetic sensors	73
2.3.3	Interpolation methods and direction detection	75
2.3.3.1	Interpolation with auxiliary phases	76
2.3.3.2	Digital interpolation	78
2.3.3.3	Amplitude analysis	79
2.3.3.4	Direction detection	79
2.3.4	Selecting and installing measuring devices	79
2.3.4.1	Selecting a measuring device	79
2.3.4.2	Place of installation in a system or machine	81
2.3.4.3	Installation notes	81
2.3.4.4	Electrical connection	81
2.4	Mechanical transmission elements	83
2.4.1	Components for converting rotation motion to translation motion	83

2.4.1.1	Ball screw/nut drives	83
2.4.1.2	Rack and pinion drives	90
2.4.1.3	Worm and rack drives	90
2.4.1.4	Toothed belt drives	92
2.4.1.5	Chain drive	92
2.4.2	Feed gear units	93
2.4.2.1	Gear drives	93
2.4.2.2	Toothed belt drives	95
2.4.2.3	Custom feed gear units	96
2.4.3	Couplings	100
2.4.3.1	Self-aligning couplings	100
	References	105
3	Dynamic Behavior of Feed Axes	107
3.1	Control Engineering Principles	110
3.1.1	Linear, Continuous Transfer Systems	112
3.1.1.1	Time Behavior of Control Loop Elements	112
3.1.1.2	Basic Systems of Control Loop Elements and Their Representation	114
3.1.1.3	Structure of a Control Loop	115
3.1.1.4	Signal Flow (Block) Diagram	117
3.1.1.5	Stability of Control Loops	118
3.1.1.6	Rules for Setting Analog Controllers	119
3.1.2	Linear Discrete-Time Transfer Systems	120
3.1.2.1	Representation of Discrete-Time Systems	121
3.1.2.2	Z-Transform	122
3.1.2.3	Linear Difference Equations	122
3.1.2.4	Rules for Setting Discrete-Time Controllers	123
3.1.2.5	Transfer Function in the Z-Domain	123
3.1.3	Feedforward Controller for Tracking Error Correction	125
3.1.4	State Control	126
3.1.4.1	Representation in the State Space	126
3.1.4.2	Design of a State Controller	128
3.2	Closed-Loop Control of Feed Drives	129
3.2.1	Feed Drive as Control Loop	129
3.2.2	Calculation of Continuous Position Control Loops	131
3.2.3	Transmission Behavior of the Linear Position Control Loop	132
3.2.4	Simulation of Feed Drives	134
3.3	Transmission Behavior of the Mechanics	135
3.3.1	Physical Boundaries of the Mechanical and Electrical Systems	136
3.3.2	Transmission Behavior of Electromechanical Drive Systems	137
3.3.2.1	Kinematic Transmission Behavior	137
3.3.2.2	Static Transmission Behavior	137
3.3.2.3	Dynamic Transmission Behavior	138
3.3.3	Transmission Behavior of Linear Motor Drives	140
3.4	Influences of the Measuring System on the Closed-Loop Feed Control	141
3.4.1	Behavior of Electromechanical Axes for Closed-Loop Control via Indirect and Direct Measuring Systems	142
3.4.2	Effect of the Measuring System for Linear Motor Drives	142
3.4.3	Improvement of Closed-Loop Feed Control Using a Ferraris Sensor	144
3.4.4	Shortest Traversable Increment	146
3.5	Static and Dynamic Stiffnesses of Feed Axes	147
3.5.1	Static Stiffness	148
3.5.1.1	Static Stiffness of Electromechanical Drives (Ball Screw Drives)	148
3.5.1.2	Static Stiffness for an Electric Linear Motor Drive	149
3.5.2	Dynamic Stiffness	149
3.5.2.1	Dynamic Stiffness of Electromechanical Feed Axes	149

3.5.2.2	Electric Linear Motor Drive	150
	References	153
4	Feed Drives for Path Generation	155
4.1	Design of Path Controllers	158
4.2	Path Errors on Machine Tools	158
4.2.1	Path Errors in the Interpolator	158
4.2.2	Typical Path Errors of Position Control	158
4.2.3	Effects of Mechanical Transmission Elements	160
4.2.4	Determination of Dynamic Path Deviations	161
4.2.4.1	Corner Smoothing	161
4.2.4.2	Circularity and Diameter Deviations	161
4.2.5	Influence of the K_v Factor on the Path Deviations	163
4.3	Measures to Reduce Path Deviations	165
	References	165
5	Design of Feed Drives	167
5.1	Design of the Motor and Mechanical Components	170
5.1.1	Determining the Requirements and Selecting the Drive Principle	171
5.1.2	Selection and Design of the Mechanical Components	171
5.1.3	Selection and Design of the Drive Motor	172
5.1.3.1	Design in Accordance with Static Parameters	174
5.1.3.2	Dynamic Design	174
5.1.3.3	Optimum Gear Ratio	175
5.2	Design of the Measuring System	175
5.3	Commissioning of the Controller	176
5.3.1	Manual Commissioning	176
5.3.1.1	Adjusting the Rotational Speed Controller	177
5.3.1.2	Adjustment of the Position Controller	179
5.3.2	Automatic Commissioning	180
	References	180
6	Process Monitoring	181
6.1	Introduction	184
6.1.1	Background, Terminology and Objectives	184
6.1.2	Economic Significance of Process Monitoring, Process Control, Diagnostics, and Maintenance Measures	186
6.1.3	Factors Affecting the Function of the Means of Production and Product Quality	187
6.1.4	Strategies and Structure of Monitoring Systems	187
6.1.4.1	Strategies for Monitoring Systems	188
6.1.4.2	The Structure of Monitoring Systems	189
6.1.4.3	Connection and Delimitation Between Process Monitoring and Machine Diagnosis	190
6.1.4.4	Mechanical and Optical Sensors	190
6.1.4.5	Control-Internal Information	190
6.1.5	Principles of Process Control	192
6.2	Signal Processing and Pattern Recognition	193
6.2.1	Analog Signal Processing	194
6.2.2	Digital Pre-Processing	198
6.2.3	Feature Extraction	198
6.2.4	Classification	199
6.2.4.1	Fixed Limits	199
6.2.4.2	Moving Thresholds	200
6.2.4.3	Multi-Dimensional Classification	200
6.3	Technological Process Monitoring and Process Control in Different Manufacturing Processes	202

6.3.1	Turning	202
6.3.1.1	Sensor Systems for Measuring Torque and Cutting Force	202
6.3.1.2	Controlling Force, Torque and Power During Turning	204
6.3.1.3	Automatic Cut Distribution for Turning	208
6.3.1.4	Process Monitoring During Turning	210
6.3.2	Milling	213
6.3.2.1	Sensor Systems and Processes for Process Monitoring During Milling	213
6.3.2.2	Process Monitoring for Milling	214
6.3.2.3	Process Control for Milling	219
6.3.2.4	Process Control When Fettling	224
6.3.2.5	Automatic Chatter Elimination	225
6.3.3	Drilling	231
6.3.3.1	Process Monitoring When Drilling and Deep Drilling	231
6.3.3.2	Process Control for Deep Drilling	234
6.3.4	Grinding	235
6.3.4.1	Process Control	235
6.3.4.2	Dressing Monitoring	237
6.3.5	Electrical Discharge Machining (EDM)	238
6.3.6	Collision Monitoring	242
6.4	Statistical Process Control	245
6.5	Machine Condition Monitoring	247
6.5.1	Service and Maintenance Procedures	247
6.5.1.1	Reactive Maintenance	247
6.5.1.2	Time-Dependent (Preventive) Maintenance	248
6.5.1.3	State-Oriented Maintenance	250
6.5.2	Machine Condition Monitoring	250
6.5.2.1	Parameters	250
6.5.2.2	Sensor-Based State Detection	251
6.5.3	Measured Value Analysis	253
6.5.3.1	Conventional Diagnostic Functions	254
6.5.3.2	Model-Based	257
6.5.3.3	Behavior-Based	257
6.5.3.4	Areas of Application	258
	References	262
7	Automation of Machines and Plants	265
7.1	Definitions	268
7.2	Historical Developments and Reasons for Automating Machine Tools	268
7.3	Control and Automation Technology as a Subtask of Machine Development	270
7.4	Control of Operating Sequences	271
7.4.1	Production Facility Functions that Can be Automated	271
7.4.2	Functional Sequences	271
7.4.3	Control, Programming and Storage Elements	273
7.5	Examples of Automated Functions	274
7.5.1	Path and Switching Information	274
7.5.1.1	Linear Displacement Transducers	274
7.5.1.2	Cam Strips and Switch Panels	275
7.5.1.3	Absolute and Incremental Rotary Encoders for Measuring the Actual Position of a Machine Assembly and for Controlling Rotational Speed	276
7.5.2	Workpiece Transportation and Handling	276
7.5.3	Tool Handling and Storage	279
7.5.4	Process Monitoring, Process Control, Diagnostics and Safety	280
7.5.5	Control Technology	282
7.5.6	Disposal	282
	References	283

8	Mechanical Control Systems	285
8.1	Single-Spindle Automatic Lathe	288
8.2	Multi-Spindle Automatic Lathe	295
8.3	Further Development of the Mechanically Controlled Multi-Spindle Machine	304
8.4	Electronic Line Shaft	305
8.4.1	Operating Principle	306
8.4.2	Application	308
	References	309
9	Basics of Information Processing	311
9.1	Basics	314
9.1.1	Number Systems	314
9.1.2	Data Codes	316
9.1.3	Boolean Algebra	317
9.1.4	Karnaugh Map	321
9.2	Modules	323
9.2.1	Implementing the Basic Functions	323
9.2.2	Extended Functions	325
9.2.2.1	Flip-flop	325
9.2.2.2	Edge-triggered Flip-flops	326
9.2.2.3	1:2 Divider	326
9.2.2.4	Binary Counters	327
9.2.2.5	Half Adder	327
9.2.2.6	Full Adders and Accumulators	328
9.2.2.7	Comparator	329
9.2.2.8	Decoder	330
9.2.2.9	Parity Checker	330
9.2.2.10	A/D Converter	332
9.2.2.11	D/A Converter	333
9.2.3	Integrated Circuits	335
9.2.4	Controls and Displays	336
9.2.5	Computers	337
9.3	Communication in Automation Technology	339
9.3.1	Communication Technology Requirements	339
9.3.2	OSI Reference Model	339
9.3.3	Bus Architectures and Access Methods	341
9.3.4	Bus Systems	342
9.3.5	Industrial Ethernet	343
9.3.6	Wireless Communication	344
9.3.7	Near Field Communication	345
9.3.8	Middleware Protocols	346
	References	347
10	Electrical Controls	349
10.1	Design and Categorization of Electrical Controls	351
10.1.1	Logic Controllers	353
10.1.2	Sequential Controls	353
10.2	Hard-wired Controls	355
10.2.1	Application Areas and Tasks	355
10.2.2	Application Examples	355
10.3	Programmable Logic Controllers (PLCs)	357
10.3.1	Application Areas and Functions	357
10.3.2	Design and Function	359
10.3.2.1	Design	359
10.3.2.2	Operating Principle	361
10.3.3	PLC Programming	363

10.3.3.1	Ladder Diagram Programming	364
10.3.3.2	Continuous Function Chart Programming	365
10.3.3.3	Programming with Instruction List	366
10.3.3.4	Examples of More Complex Program Instructions	366
10.3.3.5	Structured Text (High-level Language Programming)	370
10.3.3.6	Sequential Function Chart	371
10.3.4	Procedure for Systematic Development of Complex PLC Programs	372
10.3.4.1	Specification of the Control Task	373
10.3.4.2	Program Design and Programming	374
10.3.4.3	Program Testing	375
10.4	Safety Controllers	377
10.4.1	Machinery Directive	378
10.4.2	Performance Levels	378
10.4.3	Two-channel, Fault-Detecting Control Structure	379
10.4.4	Three-channel, Fault-tolerant Control Structure	379
10.4.5	Conventional Safety Circuits Using Relay Technology	380
10.4.6	Fail-Safe Process Coupling	380
10.4.6.1	Reliable Evaluation of Process Inputs	380
10.4.6.2	Fail-safe and Fault-Tolerant Process Outputs	382
10.5	Motion Control	384
10.5.1	Basics and Application	384
10.5.2	Design and Operating Principle of MC Systems	385
10.5.2.1	System Architecture of MC Systems	385
10.5.2.2	Fieldbus Systems for Motion Control	385
10.5.3	Programming	386
10.5.3.1	Project Planning of Motion Control Systems	387
	References	388
11	Numerical Controllers	391
11.1	Historical Development of Numerical Controllers	394
11.2	Design and Functional Description of Numerical Controllers	395
11.2.1	General Functional Description	395
11.2.2	Hardware and Interfaces of a Numerical Controller	397
11.2.2.1	Internal Structure	398
11.2.2.2	External Interfaces	400
11.2.3	Numerical Controller Software	401
11.2.4	How a Numerical Controller Works	403
11.2.4.1	NC Interpreter	403
11.2.4.2	Geometrical Data Processing	404
11.2.4.3	Interpolation	404
11.2.4.4	Axis Control	405
11.2.5	Functional Scope of Modern Numerical Controllers	405
11.2.5.1	Standard Functions	405
11.2.5.2	Functions for Controlling Automated Production Cells	409
11.2.6	Openness of Controller Systems	412
11.2.6.1	Motivation and Objectives of Open Controller Systems	412
11.2.6.2	Variants of Open Controller Systems	413
11.2.6.3	Realization of Open Controllers	414
11.2.6.4	Cross-Manufacturer Standards for Open Controllers	416
11.3	Workpiece Programming in NC Production	418
11.3.1	Format of Line-Based NC Program	418
11.3.2	Structure of an Object-Oriented NC Program	420
11.3.3	Coordinate Systems and Reference Points	422
11.3.3.1	Machine Zero Point M	422
11.3.3.2	Reference Point R	422
11.3.3.3	Workpiece Zero Point	423

11.3.3.4	Tool Reference Point E	423
11.3.3.5	Tool Holder N and Carriage Reference Point	425
11.3.3.6	Start Point	425
11.3.3.7	Tool Geometry	425
11.4	NC Programming Methods	425
11.4.1	Manual NC Programming Methods	425
11.4.1.1	Fundamentals and Procedure	425
11.4.1.2	Programming Example (DIN 66025)	428
11.4.1.3	Additional Commands for Program Entry	429
11.4.1.4	Limits of Programming in Accordance with DIN 66025	433
11.4.2	Automatic NC Programming Methods	433
11.4.2.1	CAD/CAP/CAM Coupling	437
11.4.2.2	Programming Example Using the EXAPT System	448
11.4.2.3	Programming Example for an Object-Oriented NC Program (STEP-NC)	455
11.4.2.4	Workshop-Oriented NC Programming	455
11.4.2.5	Workshop-Level Programming with Manual Process Control	458
11.4.2.6	Cost Comparison of Programming Methods	458
11.4.3	Digitization of Workpiece Geometries for NC Data Generation	460
11.4.3.1	Measuring Devices for Digitizing Workpieces	461
11.4.3.2	Sampling Strategies	463
11.4.3.3	Sampling Systems	465
11.4.3.4	Preparation and Processing of Measurement Data	470
11.5	User Interfaces on Machine Tools	472
11.5.1	Control Panels on Machine Tools	472
11.5.2	Manual Process Control	474
11.5.2.1	General Overview	474
11.5.2.2	Controls Required for Process Control	474
11.5.2.3	Alternatives for Realizing a User-Oriented Process Control	476
11.5.2.4	Development Trends	479
11.5.3	User-Oriented Depiction of Process-Related and System-Related Parameters	480
11.5.3.1	Initial Situation	480
11.5.3.2	User-Oriented Communication of Parameters	480
11.5.3.3	Technical Realization and Application Examples	481
	References	484
12	Command Variable Generation and Interpolation	487
12.1	Interpolation	491
12.1.1	Functions for the Velocity and Acceleration Control of Simple Paths Based on NC Lines	491
12.1.1.1	Acceleration and Deceleration Phase	493
12.1.1.2	Constant Velocity Phase	496
12.1.1.3	Brake Application Point Recognition	497
12.1.2	Functions for the Velocity and Acceleration Control of Simple Paths Across NC Lines	498
12.1.2.1	NC Line Transitions	498
12.1.2.2	Proactive Velocity Control	498
12.1.3	Interpolation of Simple Paths	499
12.1.3.1	Linear Interpolation	501
12.1.3.2	Circular Interpolation	502
12.1.4	Spline Interpolation	503
12.1.4.1	Polynomial Splines	504
12.1.4.2	B-splines	507
12.1.4.3	NURBS	509
12.1.4.4	Evaluation of Splines	510
12.1.5	Other Methods	512
12.2	Geometrical Transformations	512

12.2.1	Zero Offsets	513
12.2.2	Tool Corrections	514
12.2.3	Kinematic Transformation for 5-axis Milling	514
12.2.3.1	Serial Kinematics.....	517
12.2.3.2	Parallel Kinematics.....	517
12.3	External Position and Velocity Influencing	519
12.3.1	Compensation of Geometrical Errors	519
12.3.1.1	Compensation of Geometrical Feed Drive Errors	519
12.3.1.2	Compensation of Thermal Displacements	520
12.3.1.3	Compensation of Static Process Loads	524
12.3.1.4	Measurement Control for Grinding Processes.....	529
12.3.2	Feed Override and External Velocity Influencing	529
12.3.2.1	Override.....	529
12.3.2.2	External Velocity Influencing	530
12.3.2.3	Look-ahead Function	530
12.3.3	Reference Point Run	531
	References	531
13	Robots and Robot Controllers	533
13.1	General Functional Description	535
13.2	Robot kinematics and Placement Devices.....	537
13.2.1	Vertical Articulated Arm Robot	539
13.2.2	Horizontal Articulated Arm Robot.....	542
13.2.3	Cartesian Line Gantry Robots	543
13.2.4	Cartesian Area Gantry and Line Gantry with Girder.....	545
13.2.5	Parallel Kinematics.....	545
13.2.5.1	Combined Kinematics.....	545
13.2.5.2	Fully Parallel Kinematics.....	546
13.2.6	Custom Designs	546
13.2.6.1	Cylindrical and Spherical Coordinate Robots	546
13.2.6.2	Hybrid Kinematics	547
13.2.6.3	Collaborative Robot Designs	547
13.3	Coordinate Systems and Reference Points	548
13.4	Coordinate Transformation and Path Generation.....	550
13.5	Operating and Programming Robots	563
13.5.1	Online Programming Methods.....	564
13.5.2	Offline Programming Systems	569
13.5.3	Industrial Robot Language (IRL) as an Example of a Robot Programming Language.....	574
13.6	Communication Interfaces for Robot Controllers	582
13.7	Sensor Data Acquisition and Processing	584
13.8	Gripper Technology in Robotics.....	587
13.8.1	Process Definitions.....	587
13.8.2	Gripping Principles.....	588
13.8.3	Gripper Types	588
13.8.3.1	Mechanical Grippers	588
13.8.3.2	Pneumatic Grippers.....	591
13.8.3.3	Custom Designs	594
13.8.4	Gripper Systems	596
13.9	Development Trends.....	598
	References	602
14	Production Control Technology	605
14.1	Corporate Structure in the CIM Environment	608
14.1.1	CIM Components	608
14.1.1.1	ERP	609

14.1.1.2	CAD.....	610
14.1.1.3	CAP and CAM.....	611
14.1.1.4	CAQ.....	611
14.1.2	Automated Production.....	611
14.1.3	Level Model of an Industrial Manufacturing Business.....	611
14.2	Corporate Level	613
14.2.1	ERP Systems.....	613
14.2.1.1	Functionalities of an ERP System.....	614
14.2.1.2	Modularity of ERP Systems.....	615
14.2.1.3	Introducing an ERP System.....	615
14.2.1.4	Current Developments in ERP Systems.....	616
14.3	Operations Command Level	616
14.3.1	Manufacturing Execution Systems.....	616
14.3.1.1	MES Tasks.....	617
14.3.1.2	Variants and Types of Systems.....	617
14.3.2	Manufacturing Control Systems.....	618
14.3.2.1	Technical System Concepts.....	618
14.3.2.2	DNC (Distributed Numerical Control).....	619
14.3.2.3	Material Flow Control.....	620
14.3.2.4	Organization of Production Resources.....	621
14.3.2.5	Production Data Acquisition and Processing.....	623
14.3.3	Communication in Control Technology.....	628
14.3.3.1	Communication Segments in the Manufacturing Sector.....	628
14.3.3.2	Software Interfaces.....	630
14.4	Process Command Level	630
14.4.1	Electronic Control Station.....	630
14.4.1.1	Tasks of Shop Floor Control Systems.....	630
14.4.2	Production Control Computers.....	631
14.4.2.1	Functional Scope of Production Control Computers.....	631
14.4.3	SCADA Systems.....	633
14.4.3.1	Tasks.....	633
14.4.3.2	Concepts.....	633
14.5	Smart Automation Lab: Industry 4.0 Research Laboratory	633
14.5.1	Product-Centric Control.....	634
14.5.2	Plug & Produce.....	635
14.5.3	Cognitive Assembly.....	635
	References	637
15	Engineering	639
15.1	Software development	641
15.1.1	Development models.....	641
15.1.1.1	Waterfall model.....	641
15.1.1.2	V-model.....	642
15.1.1.3	Agile software development.....	642
15.1.2	Development phases.....	644
15.1.2.1	Planning phase.....	644
15.1.2.2	Definition phase.....	644
15.1.2.3	Design phase.....	644
15.1.2.4	Implementation phase.....	644
15.1.2.5	Acceptance and introduction phase.....	647
15.1.2.6	Maintenance and support phase.....	648
15.1.3	Model-driven software development.....	648
15.2	Electrical design on machine tools	648
15.2.1	Introduction.....	648
15.2.2	Functions of electrical design in machine tools.....	650
15.2.2.1	Provision of power.....	650

15.2.2.2	Realization of control functions.....	650
15.2.2.3	Protective functions for personnel and the system.....	650
15.2.3	Interaction between the electrical and mechanical designs.....	652
15.2.3.1	Interface between the electrical and mechanical designs.....	652
15.2.3.2	Communication tool for specifying the functions of a machine tool.....	653
15.2.4	Components and methods in electrical design	655
15.2.4.1	Standards and regulations for the electrical design of machine tools.....	655
15.2.4.2	Criteria for selecting components.....	656
15.2.4.3	Circuitry documents	657
15.2.4.4	Circuitry documents for a lathe as an example.....	659
15.2.4.5	Methods in electrical design.....	661
15.2.5	Practicable integration of electrical components into machine tools.....	663
15.2.5.1	Energy supply	663
15.2.5.2	Electrical components in machine tools.....	664
15.2.5.3	Operator interface	667
15.2.5.4	Safety devices	669
15.2.5.5	Electrical cabinet design.....	670
	References	676

Supplementary Information

Formelzeichenverzeichnis	680
Index.....	691