

Contents

Preface *xi*

1	Simple Practical Demonstrations	1
1.1	Importance of Loading Mode on Bonded Joint Performance	1
1.1.1	Introduction	1
1.1.2	Equipment	1
1.1.3	Materials	2
1.1.4	Safety Precautions	2
1.1.5	Experimental Procedure	2
1.1.5.1	In Class	2
1.1.5.2	In the Laboratory	3
1.2	Surface Treatments and Methods to Evaluate Surface Energy	6
1.2.1	Introduction	6
1.2.2	Equipment	7
1.2.3	Materials	8
1.2.4	Safety Precautions	8
1.2.5	Experimental Procedure	8
1.2.5.1	In Class	8
1.2.5.2	In Laboratory	9
1.3	Stress Distribution Along the Overlap Length	12
1.3.1	Introduction	12
1.3.2	Equipment	13
1.3.3	Materials	13
1.3.4	Safety Precautions	13
1.3.5	Test Procedure	13
1.4	Visual Identification of Defects in Adhesive Joints	15
1.4.1	Introduction	15
1.4.2	Equipment	17
1.4.3	Materials	17
1.4.4	Safety Precautions	17
1.4.5	Test Procedure	17
1.5	Failure Analysis of Adhesive Joints	19
1.5.1	Introduction	19

- 1.5.2 Equipment 20
- 1.5.3 Materials 20
- 1.5.4 Safety Precautions 20
- 1.5.5 Test Procedure 21

2 Production and Testing 25

- 2.1 Bulk Specimens 25
 - 2.1.1 Introduction 25
 - 2.1.2 Adhesive Pouring Technique 25
 - 2.1.3 Metallic Mold 26
 - 2.1.4 Adhesive Application 30
 - 2.1.5 Curing Procedure 31
 - 2.1.6 Machining Procedure 33
 - 2.1.7 Testing Procedure 35
- 2.2 Thick Adherend Shear Specimens 35
 - 2.2.1 Introduction 35
 - 2.2.2 Metallic Mold 36
 - 2.2.3 Surface Treatment of Adherends 37
 - 2.2.4 Geometrical Control Using Shims 40
 - 2.2.5 Specimen Manufacture 41
 - 2.2.6 Final Specimen Preparation 42
 - 2.2.7 Testing Procedure 42
- 2.3 Fracture Mechanics Specimens 44
 - 2.3.1 Introduction 44
 - 2.3.2 Metallic Mold 48
 - 2.3.3 Surface Treatment of Adherends 49
 - 2.3.4 Adhesive Spacers 50
 - 2.3.5 Specimen Manufacture 50
 - 2.3.6 Final Preparation of Specimens 51
 - 2.3.7 Testing Procedure 52
 - 2.3.8 Data Reduction Schemes 53
- 2.4 Single-Lap Joint Specimens 56
 - 2.4.1 Introduction 56
 - 2.4.2 Surface Treatment of Adherends 56
 - 2.4.3 Joint Manufacture 57
 - 2.4.4 Final Preparation of Specimens 60
 - 2.4.5 Testing Procedure 60

3 Laboratorial Activities and Report Examples 65

- 3.1 Effect of Surface Treatment on the Mechanical Behavior of Adhesively Bonded Joints 65
 - 3.1.1 Introduction 65
 - 3.1.1.1 Joint Strength Prediction 66
 - 3.1.2 Work Description 67
 - 3.1.3 Materials 67

3.1.3.1	Adherends (Tables 3.1 and 3.2)	67
3.1.3.2	Adhesive (Table 3.3)	67
3.1.4	Experimental Work	67
3.1.5	Report	68
3.1.5.1	Introduction	68
3.1.5.2	Experimental Procedure	71
3.1.5.3	Materials	71
3.1.5.4	Failure Load Prediction	72
3.1.5.5	Experimental Results and Discussion	72
3.1.5.6	Conclusions	78
3.2	Effect of Adhesive Type and Overlap Length on the Failure Load of Adhesively Bonded Joints	79
3.2.1	Introduction	79
3.2.2	Work Description	83
3.2.3	Materials	83
3.2.3.1	Adherends	83
3.2.3.2	Adhesives (Table 3.7)	84
3.2.4	Experimental Work	84
3.2.5	Report	84
3.2.5.1	Introduction	84
3.2.5.2	Materials	86
3.2.5.3	Prediction of the Failure Loads	86
3.2.5.4	Experimental Results	90
3.2.5.5	Discussion	94
3.2.5.6	Conclusions	97
3.3	Effect of Adhesive Thickness on the Failure Load of Adhesively Bonded Joints	97
3.3.1	Introduction	97
3.3.2	Work Description	98
3.3.3	Materials	99
3.3.3.1	Adherends:	99
3.3.3.2	Adhesives:	99
3.3.4	Experimental Work	99
3.3.5	Report	99
3.3.5.1	Introduction	100
3.3.5.2	Experimental Details	100
3.3.5.3	Prediction	101
3.3.5.4	Experimental Results	102
3.3.5.5	Failure Surfaces	103
3.3.5.6	Conclusion	103
3.4	Effect of Overlap Length on the Strength and Failure Mechanism of Composite Adhesive Joints	104
3.4.1	Introduction	104
3.4.2	Work Description	105
3.4.3	Materials	105

3.4.3.1	Adherends:	105
3.4.3.2	Adhesives (Table 3.17)	105
3.4.4	Experimental Work	105
3.4.5	Report	106
3.4.5.1	Introduction	106
3.4.5.2	Characterization of the Tested Joints	107
3.4.5.3	Theoretical Prediction of Failure Load	112
3.4.5.4	Comparison with Experimental Results	115
3.4.5.5	Conclusions	116
3.5	Modeling a Single-Lap Joint Using Finite Element Analysis and Cohesive Zone Modeling	117
3.5.1	Introduction	117
3.5.2	Work Description	117
3.5.3	Materials	117
3.5.3.1	Adherends:	117
3.5.3.2	Adhesives (Table 3.25)	118
3.5.4	Modeling Procedure	118
3.5.5	Report	118
3.5.5.1	Introduction	118
3.5.5.2	Module/Part	122
3.5.5.3	Module/Property	124
3.5.5.4	Module/Section	128
3.5.5.5	Module/Step (First Phase)	129
3.5.5.6	Module/Load	131
3.5.5.7	Module/Mesh	132
3.5.5.8	Module/Step (Second Phase)	134
3.5.5.9	Module/Job	136
3.5.5.10	Module/Visualization	137
3.6	Case Study in Joint Design for a Structural Automotive Application	139
3.6.1	Introduction	139
3.6.2	Report	139
3.6.2.1	Introduction	140
3.6.2.2	Design Brief	140
3.6.2.3	Adhesive Selection	142
3.6.2.4	Surface Treatment Selection	145
3.6.2.5	Material Properties	146
3.6.2.6	Joint Design	148
3.6.2.7	Numerical Models	152
3.6.2.8	Design Validation	156
3.6.2.9	Design for Manufacturing	160
3.6.2.10	Quality Control Techniques	162
3.6.2.11	Health and Safety Concerns	163
	References	163

4 Essay and Multi-choice Questions 165

4.1 Essay Questions 165

4.2 Multi-choice Questions 166

Solutions 187

Essay Questions – Example Answers 187

Multi-choice Questions – Solutions 190

Index 191