

1	Powder Coatings	1
1.1	Different Types of Powder Coating	1
1.1.1	Film Former/Binder	1
1.1.2	Thermoplastic Binders	2
1.1.3	Thermoset Binder	3
1.1.4	Epoxides	5
1.1.5	Hybrid	6
1.1.6	Polyester/TGIC	7
1.1.7	Polyester/Hydroxyalkylamide	7
1.1.8	Aromatic Glycidyl Esters	7
1.1.9	Polyurethane	9
1.1.10	Acrylates	10
1.1.11	Methyl-Substituted TGIC	12
1.1.12	Additives	12
1.1.13	Pigments	13
1.1.14	Fillers	14
1.2	Low Bake and Radiation Curing Systems	14
1.2.1	NT Powder Coatings	15
1.2.2	NIR Powder Coatings	16
1.2.3	UV Powder Coatings	16
1.3	Effect Coatings	18
1.3.1	Extrusion	20
1.3.2	Dry Blend	20
1.3.3	Bonding Procedure	20
1.3.4	Safety When Handling Aluminium Pigment Powders	20
1.4	Powder Slurry	23
1.5	Film Formation with Powder Coatings	23
1.5.1	Melt Viscosity and Surface Tension	24
1.6	Powder Coating Production	25
1.7	Storage of Powder Coatings	28

1.8	Measuring and Testing Technology for Powder Coatings	31
1.8.1	Pourability (Flow Behaviour)	32
1.8.2	Fluidisation.	32
1.8.3	Tribological Capability.	33
1.8.4	Grain Size Distribution.	33
1.8.5	Loss on Stoving of Powder Coatings	33
1.9	Economic Importance of Powder Coatings	34
1.9.1	Potentials and Future Developments	35
	References.	35
2	Application	39
2.1	Introduction	39
2.2	Electrostatic Surface Coating.	41
2.3	Physical Principles of Coating Processes	42
2.3.1	Charging Mechanisms	43
2.3.2	Triboelectric Charging	45
2.3.3	Ionisation Charging (Corona Charging)	49
2.3.4	Flight Behaviour of Electrically Charged Particles.	51
2.3.5	Relationship Between Field and Gravity Forces.	52
2.3.6	Separation Behaviour	53
2.3.7	Formation of the Powder Layer	53
2.3.8	Technological Comparison of Sprayers	57
2.4	The Charging Systems in Practice	59
2.4.1	The Corona Charge.	60
2.4.2	Tribo Charging	63
2.4.3	Comparison of Charging Systems	64
2.4.4	The Nozzle Systems	65
2.5	Powder Transport and Conveying	67
2.5.1	Mechanical Properties of the Powder	70
2.5.2	Requirements for the Support System	70
2.5.3	Powder Feeding Systems	70
2.5.4	Separation of the Powder-Air Mixture	81
2.5.5	Powder Preparation	85
2.5.6	Powder Preparation in the Hopper	93
2.5.7	The Hose Guide	98
2.6	System Planning and Design	101
2.6.1	System Concepts	102
2.6.2	Coating Booth	104
2.6.3	The Choice of Cabin Type	105
2.6.4	The Recovery Systems	113

2.6.5	Dimensioning of the System.	116
2.6.6	The Coating Equipment: Guns	117
2.7	The Powder Centre.	122
2.7.1	Powder Centre with Injector Technology	124
2.7.2	Powder Centre with Pump Technology.	125
2.7.3	Integrated Powder Centre	125
2.8	Plant Control and Automation	126
2.8.1	Automation Level 1: Gap Detection	126
2.8.2	Automation Level 2: Height Detection.	126
2.8.3	Automation Level 3: Width Detection	128
2.8.4	Automation Level 4: Vertical Gun Arrangement.	128
2.8.5	Automation Level 5: Dynamic Contour Detection	129
2.8.6	Robotics	130
2.8.7	The Lifting Equipment.	131
2.8.8	Reciprocators or Coating Robots	132
2.8.9	Cabin Systems for Automatic Coating	132
2.9	Piping from the Cabin to the Cyclone	136
2.10	Plant Technology for the Processing of Effect Powder Coatings	137
2.10.1	Recovery Problems.	137
2.10.2	Charging Problems.	137
2.10.3	Spray Pattern Changes	138
2.10.4	Influence of the Nozzle Systems.	138
2.10.5	Short-circuiting Between Gun and Nozzle	140
2.10.6	Short-circuit Formation Due to Layer Formation in the Powder Tube or Powder Hose.	140
2.11	Special Powder Coating Processes	140
2.11.1	Powder Coating Without Guns: Electrostatic Fluidised Bed Process	140
2.11.2	Coil Coating with Powder Coating.	141
2.11.3	Vortex Sintering	144
2.11.4	Round Spray Systems in the Omega Loop	144
2.12	Improving the Efficiency of Electrostatic Spraying Processes	144
2.12.1	Required Safety Installations	146
2.13	Common Failures in Powder Coating and Possible Solutions.	151
2.13.1	The Basics of Powder Coating [35]	163
	References.	164
3	Hangers and Conveyor Technology	167
3.1	Hangers, Product Carriers	167
3.2	Conveying Technology.	169
3.2.1	Requirements and Criteria	169
3.2.2	Conveyed Goods.	170

3.3	The Support Systems in Detail	172
3.3.1	Manual Push: Pull Conveyors.	172
3.3.2	Circular Conveyor	174
3.3.3	Circular Conveyors with Branching Capability	175
3.3.4	Power&Free Systems	176
3.3.5	Electric Monorail System.....	180
3.3.6	Floor Conveyors	180
3.3.7	Skid Systems	183
3.3.8	Immersion Plants	185
3.3.9	Automatic Feeders	187
3.3.10	Circular Table Conveyor.....	188
3.3.11	Cross Bar Conveyors	188
3.3.12	Tapes	189
3.3.13	Roller Conveyors	189
3.3.14	Stacking Machines	189
	References.....	190
4	Curing of Powder Coatings	191
4.1	Types of Dryers	191
4.1.1	Batch Dryer	192
4.1.2	Continuous Dryer.....	192
4.1.3	Special Forms.....	194
4.2	Drying Process.....	195
4.2.1	Convection or Circulating Air Dry off	195
4.2.2	IR Radiation Drying.....	196
4.2.3	Special Procedures	198
4.2.4	Evaluation of Different Curing Methods	200
4.3	Optimization of Paint Dryers.....	201
4.4	Measuring the Curing Temperature.....	202
4.4.1	Basics of Temperature Measurement	202
4.4.2	Application of Temperature Measurement	203
4.4.3	Process Optimization with Temperature Measurement.	206
4.4.4	Optimisation Possibilities in the Area of the Curing Oven....	206
	References.....	207
5	Surface Pretreatment of Metals	209
5.1	Cleaning and Pre-Treatment	209
5.2	Surface Condition Requirements.....	210
5.2.1	Degree of Purity	210
5.2.2	Porosity and Voids	214
5.2.3	Contamination: Dirt on the Surface	214
5.3	Mechanical Pre-Treatment.....	215

5.3.1	Grinding and Brushing	215
5.3.2	Blasting	216
5.4	Liquid Cleaning Procedures.	217
5.4.1	Cleaning Parameters.	218
5.4.2	Purification Mechanism in Aqueous Solutions	219
5.4.3	Types of Cleaner.	224
5.4.4	Pickling	225
5.4.5	Acid Dipping	226
5.4.6	Rinsing	226
5.4.7	Water Quality	227
5.4.8	Electrolyte Maintenance.	227
5.5	Phosphating Process.	229
5.5.1	Layer-Forming Phosphatisation	230
5.5.2	Iron Phosphating	235
5.5.3	Iron Thick Film Phosphating	236
5.5.4	Methods for the Characterisation of Phosphate Layers	237
5.5.5	Defects and Failure Prevention During Phosphating	239
5.6	Chromating	245
5.6.1	Green Chromating: CrIII	246
5.6.2	Yellow Chromate Layers: CrVI	247
5.7	Pre-Treatment of Ferrous Materials.	247
5.8	Zinc and Galvanised Surfaces	247
5.9	Aluminium Alloys	248
5.9.1	Properties of Aluminium as a Material.	248
5.9.2	Pre-Treatment of Aluminium Alloys	249
5.9.3	Pre-Treatment of Aluminium Casting Alloys	252
5.9.4	Conversion Coatings for Aluminium Surfaces	253
5.9.5	Chromium-Free Processes	258
5.10	Magnesium Materials.	267
5.10.1	Pre-Treatment of Magnesium Alloys	267
5.10.2	Conversion or Passivation Process for Magnesium	268
5.11	Quality Assurance Measures	268
5.12	Automatic Bath Analysis and Chemical Replenishment	268
5.13	Preventive System Maintenance	269
5.14	Selection of the Appropriate Pre-Treatment	269
	References.	272

6 Modern Industrial Applications 277

6.1	Powder Coating of Wood and Wood-Based Materials.	277
6.1.1	Material Requirements	277
6.1.2	Application Techniques	279
6.1.3	Powder Coatings.	280

6.2	In-mould Coating	280
6.3	Powder-in-Powder Technology	284
6.3.1	Minimising Mixing Effects.	284
6.3.2	Back Spray Effect Due to High Charge	285
6.3.3	Edge Cover for Better Corrosion Protection.	285
6.3.4	Application.	286
6.3.5	Different Coating Technologies on the Market.	286
6.3.6	Problems with the Layer Structure	289
6.4	Contactless Coating Thickness Measurement Before Baking [13]	289
6.4.1	Possibilities of Coating Thickness Measurement	290
6.5	Tailor-Made System Layout in Wheel Painting	291
	References.	293

7 Measurement and Test Engineering 295

7.1	Tasks of the Test Engineering	295
7.1.1	Testing of Coating Materials	295
7.1.2	Testing the Substrate	296
7.1.3	Checking the Application and Drying (Stoving Process)	296
7.1.4	Testing of the Coating	297
7.2	Appearance	298
7.2.1	Gloss Measurement	298
7.2.2	Haze	301
7.2.3	Waviness: Orange Peel	301
7.2.4	Image Sharpness: Distinctness of Image (DIO)	303
7.2.5	Color.	304
7.2.6	Color Measurement of Metallic Paints	310
7.2.7	Assessment of Color Differences	310
7.3	Adhesion	311
7.3.1	Pull-Off Test.	313
7.3.2	Mandrel Bending Test with Conical Mandrel.	314
7.3.3	Mandrel Bending Test with Cylindrical Mandrel	314
7.3.4	Cross-Cut Test	315
7.3.5	Cross Section with Adhesive Tape Pull Off	316
7.3.6	Ball-Impact Test/Falling Ball Test	317
7.3.7	Shot Peening Test.	317
7.3.8	Stone Impact Test, Single Impact Test	318
7.3.9	Stone Impact Test, Multi-Impact Test.	319
7.3.10	Cupping Test.	319
7.3.11	Star Cut with Impact According to Randel.	320
7.3.12	Scratch Test	321
7.3.13	Eraser Test	321
7.3.14	Scratch Hardness Test.	322

7.3.15	Steam Jet Test.	322
7.3.16	Cooking Test.	322
7.4	Elasticity/Fexibility	323
7.5	Hardness.	323
7.5.1	Pendulum Hardness	323
7.5.2	<i>Buchholz</i> Intendation Test.	324
7.5.3	Universal Hardness Measurement Using the Force-Penetration Method	324
7.6	Layer Thickness.	326
7.6.1	Magnetic Induction Method	326
7.6.2	Eddy Current Method.	327
7.6.3	Measurement of Powder Layer Thickness Before Baking/Crosslinking.	327
7.6.4	Destructive Coating Thickness Measurement: Cross-Section Method	328
7.7	Corrosion Tests	328
7.7.1	Corrosion Test Methods	328
7.7.2	Condensation Test Climates DIN EN ISO 6270	330
7.7.3	Stress in a Condensation Water Alternating Climate with an Atmosphere Containing Sulphur Dioxide DIN EN ISO 3231 . . .	330
7.7.4	Salt Spray Test with Various Sodium Chloride Solutions DIN EN ISO 9227	331
7.7.5	Test of Resistance to Filiform Corrosion	332
7.8	Testing Cross-Linking	333
7.9	Weather Resistance: Outdoor Weathering and Short Term Tests.	334
7.9.1	Outdoor Weathering	334
7.9.2	Short-Term Weathering	336
	References.	339
8	Coating Defects	343
8.1	Disturbances in the Coating Film	344
8.1.1	Crater in the Coating Film	344
8.1.2	Blisters in the Coating Film	347
8.1.3	Pinholes in the Coating Film	348
8.1.4	Bits, Spots and Specks	350
8.1.5	Point-Like Corrosion Phenomena on the Paint Surface	352
8.1.6	Staining Due to External Influences	353
8.1.7	Colour Variations: Poor Hiding Power	355
8.1.8	Loss of Adhesion	356
8.1.9	Chalking of the Paint Surface: Color Change.	358
8.1.10	Gloss-Differences Haze Formation: Blooming Effect	359

8.2	Corrosion of the Metal Surface	359
8.2.1	Description of the Different Types of Corrosion	359
8.2.2	Filiform Corrosion	361
8.3	Examples of Damage Cases from Practice	366
8.3.1	Causes of Defects.	367
8.4	Defects in the Coating Film	374
8.4.1	Spots in the Paint Film	375
8.4.2	Craters in the Coating Film: Flow Disturbances.	377
8.4.3	Staining Due to Packaging	379
8.4.4	Chalking of the Paint Film and Delamination	385
8.4.5	Detachment of the Paint Film	386
8.4.6	Blisters and Craters in the Paint Film	387
8.4.7	“Corrosion” of the Paint Surface	388
8.4.8	Metallic Coating Defects	390
8.4.9	Failure in the Workpiece.	392
8.4.10	Failures Due to Contamination.	392
8.4.11	Weather Resistance.	392
8.4.12	Corrosion Caused by Biological Residues from Pre-treatment	395
8.5	Troubleshooting: Diagrams and Tables	396
	References.	411
9	Paint Stripping	413
9.1	Chemical Paint Stripping	414
9.1.1	Paint Stripper	414
9.1.2	Process Techniques for Paint Stripping	416
9.2	Blasting with Dry Ice	417
9.2.1	Operation Procedure.	418
9.3	High Pressure Water Jet Technology	419
9.4	Paint Stripping with Laser Beam	419
9.5	Paint Stripping with Plasma.	420
9.6	Inductive Paint Stripping/Vortex Paint Stripping.	421
9.7	Choice of Paint Stripping Process	421
	References.	423
10	Environmental and Energy Aspects	425
10.1	Emissions from the Stoving Process [1]	425
10.2	Life Cycle Assessment of a Powder Coating	426
10.2.1	Application Parameters and their Influence	427
10.2.2	Coating Material and Waste	427

10.2.3	Resins	428
10.2.4	Pre-Treatment	429
10.2.5	The Idea of Life Cycle Assessment and its Main Features	429
10.3	Recycling of Powder Coatings [6]	430
10.4	Energy Management in the Paint Shop	431
10.4.1	Analysis of Processes and Optimisation	431
10.4.2	Saving Energy Through System Components and Control Technology	432
10.4.3	Minimising Heat Losses: Heat Recovery	432
10.4.4	Energy Comparison of a Liquid and Powder Coating System [9]	435
	Literature	436