

Table of contents

Semiconductors

Subvolume A2: Impurities and Defects in Group IV Elements, IV-IV and III-V Compounds

Part α : Group IV Elements

(edited by M. Schulz)

List of frequently used symbols and abbreviations; conversion tables	XII
1. Symbols	XII
2. Abbreviations and acronyms	XIV
3. Conversion of units	XVI
1 Introduction	no update
2 Trends of impurity and defect properties	no update
3 Measurement methods	no update
4 Impurity and defect properties in group IV elements	1
4.1 Diamond (C)	1
4.1.1 Impurities (R. SAUER)	1
4.1.2 Defects (R. SAUER)	2
Figures for 4.1.1 and 4.1.2	3
References for 4.1.1 and 4.1.2	4
4.1.3 Paramagnetic centers (C. A. J. AMMERLAAN)	6
4.1.3.1 Introduction	6
4.1.3.2 EPR spectra	8
4.1.3.3 g-values and linewidths of paramagnetic centers in CVD diamond	53
Figures for 4.1.3	54
References for 4.1.3	65
4.2 Silicon	77
4.2.1 Solubility, segregation and distribution coefficients of impurities and defects (H. BRACHT, N. A. STOLWIJK)	77
4.2.1.1 Solubility data of impurities: group IA	77
4.2.1.2 Solubility data of impurities: group IIA	79
4.2.1.3 Solubility data of impurities: group IIIB including rare earth elements	80
4.2.1.4 Solubility data of impurities: group IVB	81
4.2.1.5 Solubility data of impurities: group VB	82
4.2.1.6 Solubility data of impurities: group VIB	83
4.2.1.7 Solubility data of impurities: group VIIB	86
4.2.1.8 Solubility data of impurities: group VIII (iron group)	88
4.2.1.9 Solubility data of impurities: group VIII (cobalt group)	91

4.2.1.10	Solubility data of impurities: group VIII (nickel group)	94
4.2.1.11	Solubility data of impurities: group IB	98
4.2.1.12	Solubility data of impurities: group IIB	105
4.2.1.13	Solubility data of impurities: group VIII (group IIIA)	106
4.2.1.14	Solubility data of impurities and native point defects: group IVA	115
4.2.1.15	Solubility data of impurities: group VA	122
4.2.1.16	Solubility data of impurities: group VIA	131
4.2.1.17	Solubility data of impurities: group VIIIA	136
4.2.1.18	Distribution coefficients at the melting point	137
	Figures for 4.2.1	139
	References for 4.2.1	159
4.2.2	Diffusion of impurities	see Vol. III/33A (book or online-version)
4.2.3	Impurity levels (J. WEBER)	170
4.2.3.1	Ionization energies	170
	Figures for 4.2.3.1	196
	References for 4.2.3.1	198
4.2.3.2	Pressure coefficients	212
	Figures for 4.2.3.2	213
	References for 4.2.3.2	214
4.2.3.3	Capture coefficients and capture cross-sections	214
	Figures for 4.2.3.3	217
	References for 4.2.3.3	217
4.2.3.4	Photoionization cross-sections of impurity levels	218
	Figures for 4.2.3.4	222
	References for 4.2.3.4	222
4.2.4	Excited bound states of acceptors and donors (R. SAUER)	224
4.2.4.1	Acceptors of group III impurities	no update
4.2.4.2	Donors of group V impurities and Li	no update
4.2.4.3	Donors of group VI impurities	224
4.2.4.4	Thermal donors(TDs): Oxygen-related defects	no update
4.2.4.5	Shallow thermal donors (STDs)	224
4.2.4.6	Very shallow centers and deep transitions metal defects	224
4.2.4.7	Acceptors of group II impurities	225
4.2.4.8	Pseudo-donors or pseudo-acceptors	225
	References for 4.2.4	226
4.2.5	Photoluminescence properties of impurities and defects (R. SAUER)	227
4.2.5.1	Excitons bound to neutral acceptors or donors	no update
4.2.5.2	Excitonic luminescence due to defects	227
4.2.5.3	New defect species incorporating hydrogen and rare earth erbium ions, and novel spectroscopic technique using radioactive isotopes	227
4.2.5.4	Er ³⁺ -related luminescence in silicon	227
4.2.5.5	Photoluminescence spectroscopy using radioactive isotopes	228
	Figures for 4.2.5	237
	References for 4.2.5	239
4.2.6	Paramagnetic centers (C. A. J. AMMERLAAN)	244
4.2.6.1	Introduction	no update
4.2.6.2	Symmetry data of defect centers	no update
4.2.6.3	Electron paramagnetic resonance (EPR) data	244
	Figures for 4.2.6	290
	References for 4.2.6	290
4.2.7	Vibrational modes of impurities and defects (R. MURRAY, R. C. NEWMAN)	309
4.2.7.1	Substitutional impurities	309
4.2.7.2	Substitutional impurity complexes	309
4.2.7.3	Oxygen in Si	310

4.2.7.4	Interstitial impurity complexes	311
4.2.7.5	Irradiation defects, general	312
4.2.7.6	Defect concentrations derived from strengths of local vibrational mode absorption lines . . .	313
4.2.7.7	Hydrogen atoms and molecules	314
	Figures for 4.2.7	318
	References for 4.2.7	321
4.2.8	Oxygen-related defects and microdefects (W. ZULEHNER)	324
4.2.8.0	Introduction	324
4.2.8.1	Classification of defects	324
	Figures for 4.2.8.1	325
	References for 4.2.8.1	325
4.2.8.2	Point defects	326
4.2.8.2.1	Vacancies and interstitials	326
	Figures for 4.2.8.2.1	331
4.2.8.2.2	Atomic size effects of impurities	335
	Figure for 4.2.8.2.2	337
4.2.8.2.3	Oxidation effects	337
	Figure for 4.2.8.2.3	338
4.2.8.2.4	Carbon and oxygen	338
4.2.8.2.5	Other impurities	339
	References for 4.2.8.2	339
4.2.8.3	Aggregation phenomena	342
4.2.8.3.1	Complex formation	342
4.2.8.3.2	Homogeneous nucleation	343
	Figures for 4.2.8.3.2	344
4.2.8.3.3	Heterogeneous nucleation	344
4.2.8.3.4	Doping inhomogeneities	345
	Figures for 4.2.8.3.4	346
4.2.8.3.5	Precipitation	347
	Figure for 4.2.8.3.5	348
	References for 4.2.8.3	348
4.2.8.4	Microdefects	350
4.2.8.4.1	Self-point microdefects (swirl defects).	350
	Figures for 4.2.8.4.1	353
4.2.8.4.2	Oxygen-related microdefects	354
	Figures for 4.2.8.4.2	368
4.2.8.4.3	Properties and defects of other impurities	370
	Figures for 4.2.8.4.3	372
4.2.8.4.4	Oxidation-induced stacking faults	372
	Figures for 4.2.8.4.4	373
4.2.8.4.5	Gettering and denuded zones	374
	Figures for 4.2.8.4.5	375
	References for 4.2.8.4	376
4.3	Germanium (Ge)	382
4.3.1	Solubility and segregation of impurities and native point defects (N. A. STOLWIJK, H. BRACHT)	382
4.3.1.1	Solubility and segregation coefficients	382
	Figures for 4.3.1	384
	References for 4.3.1	386
4.3.2	Diffusion of impurities	see Vol. III/33A (book or online version)
4.3.3	Impurity levels (E. E. HALLER)	387
4.3.3.1	Shallow donors binding energies	387
4.3.3.2	Group VI substitutional donors	388

4.3.3.3	Shallow acceptors	389
4.3.3.4	Deep centers	389
4.3.3.4.1	Group II substitutional double acceptors	390
4.3.3.4.2	Group I substitutional triple acceptors and related complexes	390
4.3.3.4.3	Transition metals	391
4.3.4	Capture cross-sections (E. E. HALLER)	392
4.3.5	Photoionization-cross-sections (E. E. HALLER)	392
4.3.6	Deformation potentials	no update
4.3.7	Luminescence of bound excitons (E. E. HALLER)	393
4.3.8	Electron paramagnetic resonance (EPR) (E. E. HALLER)	394
4.3.9	Local vibration modes (E. E. HALLER)	394
	Figures for 4.3.3 – 4.3.9	395
	References for 4.3.3 – 4.3.9	399

Part β: IV-IV and III-V Compounds (to be published)

4.4	Silicon carbide (SiC)
5	Impurity and defect properties in group III-V compounds
6	Impurity and defect properties in ternary compounds
7	Impurity and defect properties in quaternary compounds