

# Table of Contents

## Preface

## Chapter 1: Reliability Assessment and Restoration of Concrete Structures and Elements

|                                                                                                                                                                                          |    |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| <b>Color Stability of Colored Concrete over Time Depending on the Type of Pigment</b><br>M. Utěšená and R. Pernicová                                                                     | 3  |
| <b>Corrosion of Steel Prestressing Reinforcement - The Influence of the Used Construction Technology of Concrete Suspension Footbridges</b><br>V. Vacek and P. Pokorný                   | 9  |
| <b>Corrosion Properties and Bond Strength of Coated (PE/PAK; Pe/PPE; PAD) Reinforcement (B500B) with Normal Strength Concrete</b><br>P. Pokorný, N. Prodanovic, K. Hurtig and M. Holeček | 15 |
| <b>Degradation of Colored Concrete Elements due to Frost</b><br>R. Pernicová, K. Hurtig and M. Utěšená                                                                                   | 21 |
| <b>Resistance of Electrically Conductive Concrete to Sulphate Attack</b><br>I.S. Polyanskikh, A.N. Gumenyuk, A.F. Gordina, I.A. Pudov and G.I. Yakovlev                                  | 27 |
| <b>Corrosion of Zinc Dust in Cement Paste - Evaluation of Hydrogen Gas Evolution Time Period</b><br>P. Pokorný, N. Prodanovic, L. Topolář, L. Pazdera and I. Kusák                       | 35 |

## Chapter 2: Reliability Assessment and Restoration of Architectural Structures

|                                                                                                                                                                             |    |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| <b>Chemical Analysis of the Building Material Coating from Historical Bridge in Prague</b><br>K. Sladká and R. Pernicová                                                    | 43 |
| <b>Rehabilitation of Historic Farmstead near Klecany</b><br>J. Marková, P. Pokorný and P. Marek                                                                             | 49 |
| <b>Investigation of the Effectiveness of the Rehabilitation of Historical Constructions Using Wireless Dehumidification Technologies</b><br>P. Šťastný                      | 55 |
| <b>Long-Term Monitoring Side Chapel Church from the Point of View of Formation and Course of Condensation on its Inner Surface</b><br>L. Kudrnáčová, L. Balík and K. Hurtig | 63 |

## Chapter 3: Persistence to External Factors, Protection, Treatment and Insulation

|                                                                                                                                                                                           |    |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|
| <b>Assessment of Chemical Resistance of Polymer Repair Mortars</b><br>R. Hermann, J. Majerová, R. Drochytka and P. Figala                                                                 | 71 |
| <b>Effect of Carbon-Containing Additives on the Properties of Fluoroanhydrite Compositions Used for Flooring</b><br>D. Kalabina, G.I. Yakovlev, Z. Saidova, G. Pervushin and A.F. Gordina | 77 |
| <b>Experimental Testing Results of a Timber Structure's Fire Resistance in a Combustion Chamber</b><br>T. Žajdlík and K. Šuhajda                                                          | 83 |
| <b>Influence of Moisture and Density of Wood on the Depth of Holes Made by a Kucera's Drilling Machine</b><br>P. Černý, E. Frimlová and V. Heřmánková                                     | 89 |
| <b>Influence of Physical and Chemical Stress on the Properties of CIPP Pipes Based on Vinyl Ester</b><br>J. Hodul, L. Mészárossová and J. Majerová                                        | 95 |

|                                                                                                                                  |     |
|----------------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Study of the Preparation of Micronized Zinc Phosphate Dihydrate with Potential for Application in the Phosphating Process</b> |     |
| A. Zabloudil, N. Prodanovic, P. Pokorný, J. Kolísko and K. Cech Barabaszova                                                      | 103 |
| <b>The Use of Thin-Layer Insulation Material in Technical Installations in Building Reconstructions</b>                          |     |
| P. Vrbová and L. Prokopová                                                                                                       | 111 |

## **Chapter 4: Structural Health Monitoring and Reliability Level Assessment**

|                                                                                                                          |     |
|--------------------------------------------------------------------------------------------------------------------------|-----|
| <b>Comparison of Different Sensors Used in the Assessment of Concrete Elements by Impact-Echo Method</b>                 |     |
| J. Puchýř, R. Dvořák, A. Hubáček and Z. Chobola                                                                          | 121 |
| <b>Detection of Internal Defects and Failures of Concrete Structures Using Non-Destructive Methods</b>                   |     |
| J. Šnédar, V. Bartoň and P. Cikrle                                                                                       | 129 |
| <b>Study of Microstructure of Electrically Conductive Silicate Composites with Graphite-Based Fillers</b>                |     |
| Š. Baránek, L. Mészárossová, R. Drochytka and G.I. Yakovlev                                                              | 135 |
| <b>The Expansion of Defects of Solid Fired Bricks due to their Freezing</b>                                              |     |
| V. Bartoň, J. Šnédar and P. Cikrle                                                                                       | 145 |
| <b>Effect of Target Reliability Level on Partial Factors for Existing Steel Railway Bridges</b>                          |     |
| V. Nadolski, M. Holicky and M. Sýkora                                                                                    | 153 |
| <b>Introductory Chapter to Microbially Induced Deterioration of Concrete – Focus on Groups of Typical Microorganisms</b> |     |
| P. Pokorný                                                                                                               | 163 |